PRE-PURCHASE INSPECTION CHECKLIST

Lexus LX 570

2008–2021 · J200 · URJ200 · 3UR-FE

BOXYTRUCKS

CHECK BEFORE YOU BUY

- [ ] **AHC leaks and behavior**
  Cycle the truck through Low, Normal and High and make sure it levels evenly. The IH8MUD AHC sticky includes a Toyota diagram of leak-prone junctions. Fluid at those points means you're about to learn a lot about hydraulics. A healthy system also lifts an extra inch or so in some low-range recovery situations, one owner reports.
- [ ] **Radiator (2008–2010)**
  Owners of early trucks report cracks in the top plastic tank, next to the molded platform. Look for a wet line or dried pink coolant along the top. Later radiators carry a different part number.
- [ ] **Water pump**
  Forum members say 2008 trucks had water-pump problems that have since been fixed. Look for pink crust at the pump weep hole and ask whether it's been replaced. One high-mileage owner paid about $700.
- [ ] **Valley coolant leak**
  Pink coolant dripping from the top of the transmission hump at the back of the engine usually means the valley leak: the heat-exchanger cover and union pipe under the intake. It's not hard to fix, but it takes a lot of labor.
- [ ] **Driveshaft clunk**
  A 'thunk' when taking off or stopping often points to dry slip yokes and U-joints. Ask when the driveshafts were last greased. One owner paid about $780 for a propeller-shaft assembly to cure it.
- [ ] **Starter**
  Several owners have had the starter solenoid fail with no warning and leave them stranded. On a high-mileage truck, proactive replacement is common.
- [ ] **Records by VIN**
  The IH8MUD FAQ points out that the Toyota and Lexus owner sites show dealer service history once you enter the VIN, which is a good check before buying.
- [ ] **HVAC recirculation door**
  IH8MUD members warn that the recirculation door hinge can be broken by a careless cabin-filter change. Check that the recirc control actually changes the airflow.

YEARS TO KNOW

2008–2010	BEWARE	Most of the radiator-crack reports come from these years (the radiator part number changed after 2010), and owners say 2008s had water-pump issues.

RECALLS TO ASK ABOUT

IS IT THE REAL THING?

- [ ] **Seat-belt tension sensor harness**
  2008–2019 · NHTSA 18V-887
- [ ] **Incorrect airbag fitted**
  2008–2013 · NHTSA 17V-548
- [ ] **Accelerator pedal entrapment by floor mat**
  2008–2011 · NHTSA 11V-113
- [ ] **Low-pressure fuel pump**
  2014–2015 · NHTSA 20V-012
- [ ] **Low-pressure fuel pump (expansion)**
  2018–2019 · NHTSA 20V-682

- [ ] **VIN**
  US trucks start JTJ and carry 7AX in positions 6–8 (e.g. JTJHY7AX). NHTSA's vPIC decoder reads the series as URJ201L with the 3UR-FE, built at Toyota Auto Body's Yoshiwara plant. The 10th character is the model year (8 = 2008 through M = 2021, with no C for 2012).
- [ ] **Which facelift**
  2008–2011: original nose. 2013–2015: first spindle grille. 2016–2021: big spindle, new sheet metal, eight-speed and a new interior.
- [ ] **Seating**
  Two-row, five-seat trucks exist only from 2018 on.
- [ ] **Inspiration Series**
  2019: 500 trucks in Black Onyx with a Moonlight white interior and blacked-out trim. 2021: 500 trucks in Eminent White Pearl or Black Onyx with black-and-Rioja-red leather.
- [ ] **No axle lockers**
  US trucks have a lockable Torsen center diff, A-TRAC and Crawl Control, but no factory front or rear lockers. Any locker is aftermarket.

NOTES

From the full guide at https://boxytrucks.com/models/lexus/lx570/, with sources. Recalls follow the VIN: check at nhtsa.gov/recalls. General information only, not a professional inspection; see boxytrucks.com/about/disclaimer/. © BoxyTrucks