

FAULT ISOLATION MANUAL

**ON A/C ALL

TASK 32-40-00-810-803 PARKING BRAKE, indication discrepancy (Caution) - Fault Isolation

General

- Α. This fault isolation procedure is correct a PARKING BRAKE caution light indication discrepancy in the caution and warning panel (CAWP).
- В. The CAWP usually shows the PARKING BRAKE light on when the EMERG BRAKE lever is in the PARK position.

NOTE: This is not a malfunction condition.

C. There are no related central diagnostic system (CDS) messages.

2. Job Set-Up Information

Subtask 32-40-00-946-033

| REFERENCE | DESIGNATION |
|---------------------------|--|
| AMM TASK 31-51-01-000-801 | Removal of the Caution and Warning Panel |
| AMM TASK 31-51-01-400-801 | Installation of the Caution and Warning Panel |
| WM 32-44-00-1 | Parking Brake System |
| AMM TASK 32-44-00-720-801 | Functional Test of the Parking Brake System |
| AMM TASK 32-44-21-000-801 | Removal of the Parking Brake Control Quadrant |
| AMM TASK 32-44-21-400-801 | Installation of the Parking Brake Control Quadrant |

Fault Confirmation

Subtask 32-40-00-700-005

Confirm the fault as follows:

(1) Do the functional test of the parking brake system (Refer to AMM TASK 32-44-00-720-801).

Print Date: 2025-04-22

- If the PARKING BRAKE caution light is off when the EMERG BRAKE lever is in the OFF position, then no maintenance procedure is necessary. Do the Close Out.
- If the PARKING BRAKE caution light is on when the EMERG BRAKE lever is in the OFF position, do the Fault Isolation.

PSM 1-84-23 **EFFECTIVITY:** See First Effectivity on Page 207 of 32-40-00

32-40-00 Page 201 Nov 05/2021



FAULT ISOLATION MANUAL

4. Fault Isolation

Subtask 32-40-00-810-007

- A. Isolate the fault as follows:
 - (1) Remove and replace the parking brake control quadrant (Refer to AMM TASK 32–44–21–000–801 and AMM TASK 32–44–21–400–801).
 - (2) If the fault still continues, remove and replace the CAWP (Refer to AMM TASK 31–51–01–000–801 and AMM TASK 31–51–01–400–801).
 - (3) If the fault still continues, do a check of the wiring between the parking brake control lever and the CAWP (Refer to WM 32–44–00–1).

| 3241-P12 | 3312-P5 |
|-----------------------|---------|
| (Parking Brake Lever) | CAWP |
| 2 | 16 |

(4) If the wiring is unserviceable, repair the wiring. Do the Close Out.

5. Close Out

Subtask 32-40-00-941-031

A. Make sure that the CAWP PARKING BRAKE caution light is not on when the EMERG BRAKE lever is in the OFF position.

Print Date: 2025-04-22

B. Remove all tools, equipment, and unwanted materials from the work area.

PSM 1-84-23 EFFECTIVITY:

See First Effectivity on Page 207 of 32-40-00

32-40-00

Page 208 Nov 05/2021