

## **FAULT ISOLATION MANUAL**

## MAINTENANCE PRACTICES

\*\*ON A/C ALL

# TASK 31-53-00-810-801 **TOUCHED RUNWAY (Warning) - Fault Isolation**

## General

- A. This fault isolation procedure is for when the TOUCHED RUNWAY warning light on the Caution and Warning Panel (CAWP) is on.
- B. The CAWP can show the TOUCHED RUNWAY warning light on when it senses that the aft-tail fuselage has struck the runway.

### 2. Job Set-Up Information

Subtask 31-53-00-946-005

### Reference Information

REFERENCE	DESIGNATION
AMM05-50-08-210-801	Inspection After a Tail Strike
AMM31-53-00-000-801	Removal of the Tail Strike Switch
AMM31-53-00-400-801	Installation of the Tail Strike Switch
AMM31-53-00-720-801	Functional Test of the Tail Strike Warning System
WM31-53-00	Touched Runway Warning System

#### 3. **Fault Confirmation**

Subtask 31-53-00-810-003

- Do the functional test of the tail strike warning system (Refer to AMM31–53–00–720–801).
  - (1) If the TOUCHED RUNWAY warning light is on, then no maintenance procedure is necessary. Do the Close Out.
  - (2) If the TOUCHED RUNWAY warning light is not on, then do the Fault Isolation.

## Fault Isolation

Subtask 31-53-00-810-004

- Isolate the fault as follows:
  - Inspect the area of the tail strike switch located on the underside of the fuselage on the aircraft center line at station X757.00 (Refer to AMM05-50-08-210-801).
    - If the inspected area shows damage, repair the damage in accordance with the Structural Repair Manual.

PSM 1-84-23 **EFFECTIVITY:** See First Effectivity on Page 201 of 31-53-00

31-53-00 Page 201



# **FAULT ISOLATION MANUAL**

- (b) If the inspected area shows no damage, continue with the fault isolation.
- (2) Remove and replace the tail strike switch (Refer to AMM31–53–00–000–801 and AMM31–53–00–400–801).
- (3) If the fault still continues, do a test of the wiring between the CAWP and ground stud (Refer to WM31–53–00):

3312-P2	(Ground Stud)
(CAWP)	
6	3152-GS1

(4) If the wiring is unserviceable, repair the wiring. Do the Close Out.

# 5. Close Out

Subtask 31-53-00-941-004

- A. Make sure that the TOUCHED RUNWAY warning light on the CAWP is off.
- B. Remove all tools, equipment and unwanted materials from the work area.

PSM 1–84–23 EFFECTIVITY: See First Effectivity on Page 201 of 31–53–00

 $31 - 53 - 00 \quad {\tiny Page 202} \\ \tiny Nov 05/2021$ 

Print Date: 2025-05-11