Table of Contents

Purpose/Policy:.....1

Scope:.....2

Definitions/Acronyms:.....2

Authorities/Responsibilities:.....2

Resources and Materials:.....2

PPE Required:.....3

Procedures:.....3

Setting up the Check Weigher:.....3

Operation of the Check Weigher:.....3

Changeover Guide:.....3

Shutting Down Check Weigher:.....3

Basic Cleaning of the Check Weigher:.....4

Deep Cleaning.....4

Forms:.....4

Reference Documents:.....4

Common Issues:.....4

Document History and Approval:.....5

Purpose/Policy:

The “Check Weigher” standard operating procedure is written to assist with operation, setup, changeover, cleaning, and trouble shooting.

Scope:

The “Check Weigher” has three main areas of focus. The first part section is conveyor on a scale that weighs the cases as they pass over it. The next section of conveyor is where a case that is missing a can will be kicked out into a rejection area. The last part that this SOP will focus on is the HMI panel that controls recipe changeovers.

The purpose of the check weigher is to make sure any case that is missing a can is kicked out and does not make its way onto a finished pallet.

Definitions/Acronyms:

- SOP – Standard Operating Procedure
- PPE – Personal Protective Equipment
- HMI – Human Machine Interface (the touch screen used to control a machine)
- E-Stop – Emergency Stop button
- Check Weigher – Scale conveyor that rejects cases missing a can

Authorities/Responsibilities:

This SOP can be completed by an entry level packaging operator after proper training from a senior member of the can line packaging team. It is the operator’s responsibility to make sure every hour the check weigher is working properly.

Resources and Materials:

Operations:

- One case of each packaging size that is missing a can.

Basic Cleaning:

- Damp cloth.

Deep Clean:

- Refer to SOP Document # CL###
    - Link to document goes here.

Troubleshooting:

- 21lbs weight (for calibration)

PPE Required:

- No formal PPE required, suggested nitrate gloves for cleaning.

Procedures:

Setting up the Check Weigher:

1. When starting up the check weigher make sure the air supply is on.
2. After the air is turned on you want to make sure both E-Stops are pulled out.
3. This should power up the screen for operations.
4. The next step is to run on the check weigher conveyors.
5. The conveyors are controlled by a knob next to the E-Stop which is next to the first section of conveyor.
   5.1 Turn the knob to manual/hand to run the conveyors.

Operation of the Check Weigher:

1. The operation of the check weigher consists of making sure it is kicking cases out that are missing one or more cans.
2. To check to make sure the check weigher is functioning properly take a case that is missing one can of the current size that is being run. If we do not have a case that is already missing a can, you can make one by taking one can out and re-taping the packaging.
3. Put this the case that is missing the can just ahead of the check weigher's first conveyor.
4. Let the case pass through the check weigher. If it is functioning correctly, it will kick out the case.
   4.1 In the event that it doesn't kick out the case please see the trouble shooting section of this SOP.

Changeover Guide:

1. From the main screen click the "ESC" button
2. Select #5 – "Select/Edit Product"
3. Select #2 – "Select/Edit Old Product"
4. Enter the corresponding packaging number.
   4.1 **Note:** See product sheet attached to check weigher.
5. Select "L" – Load this product to run.
6. Select "X" – Return to main menu.
7. Select #1 – Run check Weigher.

Shutting Down Check Weigher:

1. Once we are done using the check weigher for the day press both E-Stops.

1.1 One is located on the side of the HMI, and the other is next to the first conveyor of the check weigher.
2. Turn the conveyor control knob to the neutral position.
3. Now that the machine is E-Stopped and the conveyor is off we can turn off the air to the machine.
4. Make sure nothing is left on the first conveyor of the check weigher.
5. This completes the shutdown of the check weigher.

Basic Cleaning of the Check Weigher:

1. Before starting any cleaning on the check weigher ensure that the machine is E-Stopped, and the air supply is off.
   1.1 Please reference “Shutting Down Check Weigher” section of this SOP.
2. Using a damp cloth wipe down any photo-eyes that might be dirty.
3. Also make sure the conveyor belts are wiped down and are clean.
   3.1 In order to make sure the whole conveyor belts are clean you will need to jog the belts around.
   3.2 To jog the belts around briefly turn the conveyor knob to hand/manual.

Deep Cleaning

Outline the deep cleaning process for the SOP equipment. See below for example:

1. Refer to SOP Document # CL###
   1.1 Link to document goes here.

Forms:

Not Applicable

Reference Documents:

Not Applicable

Common Issues:

1. If the check weigher is not kicking out a case but the alarm sounding like it should be double check to make sure the air supply is turned on.
2. In the event that the conveyor prior to the check weigher won’t run check to make sure there aren’t any cases blocking the rejection area photo-eyes.
3. If the check weigher is kicking out cases that are not missing any cans, try the following solutions.
   3.1 From the main menu press #2 “Check Calibration”.

3.2 Then press “Z” to zero the scale.

3.3 Retest cases to make sure it kicks out cases missing a can and doesn’t kick out full cases.

3.4 If the check weigher is still not properly kicking out correct cases move on to this next fix.

3.4.1 From the main menu press #3 “Calibrate Checkweigher”.

3.4.2 Press #1 “Do Calibration Procedure”.

3.4.3 The check weigher will then ask if the audit trail information is correct.

3.4.4 If it is press “Y”.

3.4.4.1 If it is not press “N” and set the time and date correctly.

3.4.5 It will then ask you to enter your name or initials.

3.4.6 Enter your initials and then press “Enter”

3.4.7 The check weigher will then ask you if the test weight is 21.00 LB. We will be using a 21 LB weight for this calibration.

3.4.8 Press “Y” to confirm the weight is correct.

3.4.9 The next screen will ask that the check weigher is clear of any weight and that none of the conveyors are running. If it is clear and the conveyors are off press “Enter”.

3.4.10 The check weigher will then start calibrating. When prompted press “Enter” to continue.

3.4.11 Then the next step will be to place the test weight on the scale in the middle of the conveyor, which is the first conveyor of the check weigher. Press “Enter” when ready.

3.4.12 After the calibration remove the test weight from the conveyor. Calibration is now complete so press “X” to return to the main menu.

3.4.13 Press #1 to run the machine.

3.4.14 Retest the cases to ensure the check weigher is working correctly.

Document History and Approval:

Revise document history as described in the table and key below.

(Reference to following document: B1C.SOP.P001: Document Control and Approval Procedure Template)

VERSION NO.	VERSION DATE	DESCRIPTION OF CHANGE	AUTHOR NAME/PROJECT MANAGER
001	2024/03/26		Kyle Szymanski
002	2026/10/26	Updated SOP to Newest Layout Version	Kyle Szymanski

Version Approval Number: 002

Approved by: Kyle Szymanski

Position Title: OSCI Manager

Date: 10/26/26