

Solution: Enable USB in the BIOS. This will be accessible under the Integrated Peripherals option. If this does not solve the problem, then assign an IRQ to USB in the BIOS. See the BIOS section of this book for details.



► **Problem:** The USB 2.0 ports aren't supporting USB 2.0 devices at top speed.

Cause: The USB 2.0 ports might not be configured correctly.

Solution: Enable USB 2.0 support in the BIOS and install the correct USB drivers for your motherboard. These drivers are usually provided on the driver CD that accompanies the motherboard, or you can download them from the motherboard manufacturer's Web site.

► **Problem:** A USB pen drive is not recognised by Windows 98, but is recognised by later versions.

Cause: Windows 98 does not have inbuilt support for USB pen drives.

Solution: Install the correct USB driver on the Windows 98 system to enable support for USB pen drives. These drivers will most likely be provided on the driver CD that accompanied the pen drive. You can also download the drivers from the USB drive manufacturer's Web site.

► **Problem:** USB peripherals work when plugged into the computer but not when plugged into a hub.

Cause: External hubs that are bus-powered might not provide enough power for some devices.

Solution: Use the Power dialog box on the "USB hub properties" sheet in Device Manager to see the power requirements for a device and the power available.