

► **Problem:** When you connect your USB camera to your Windows 98 computer, an error that says “STIMON caused an invalid page fault” is displayed. When you access ‘Scanners’ from the Control Panel and select the camera in the window, an error with Sticpl.cpl is displayed.



Cause: The Stimon.exe file on your PC is damaged.

Solution: Press [Ctrl] + [Alt] + [Del] and check if Stimon is running. If it is, end the task. Delete the file from C:\Windows\System\ (where C:\ is the drive Windows is loaded on). Run the Registry Editor and navigate to HKEY_Local_Machine\Software\Microsoft\Windows\CurrentVersion. Look for a value named “StillImageMonitor” under either the “Run” or “RunServices” keys. Delete the value and restart the PC. Now reinstall the drivers for the USB camera. If you still get an error, replace the Sticpl.cpl file as well. To do this, run “sfc” from Start > Run and insert the Windows 98 installation disk. Select the option ‘Extract one file from installation disk’ and click Browse. Locate Sticpl.cpl in the ..\Windows\System\ folder and click Start. Restart the machine after restoring the file.

► **Problem:** Your Web camera just doesn’t activate in Windows 98. You’ve tried reinstalling the drivers, but the installation failed. The camera is not detected when you plug it in either. The USB port is enabled in the BIOS. The Web cam works perfectly on another system.

Cause: Since the possibilities have been narrowed down; the USB port seems to be the culprit.

Solution: To be doubly sure that it is a problem with the USB port, you can try installing a version of Windows with better USB support, such as Windows XP. If the problem persists, your USB port is definitely kaput! You are then left with two options—either buy new USB ports with cables that connect to the USB header on your motherboard (if your motherboard has such headers), or buy a USB PCI card for new USB ports to connect your devices to.