HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
***** Preview Invoice *****

Invoice #0041596 **11/12/2026 1:24 pm**

DJPJ HOLDINGS
15035 E HINSDALE DR. UNIT B
CENTENNIAL, CO 80112
MOBILE:(303) 617-1125
WORK:(303)

2015 BMW 328 SERIES
4-1997 2.0L DOHC
VIN : WBA3X5C59FD561342
Mileage :
Trans :
License :

COLR : WHITE
Unit # XDRIVE GT

Your Service Writer Today Is: SHOP OWNED Center: SHOP OWNED VEHICLE

Service Requests:

Category Summary	Parts	Labor	Job Total
COMMENTS/NOTES	$0.00	$0.00	$0.00
COOLING SYSTEM	$250.55	$274.00	$524.55
ENGINE	$325.90	$137.00	$462.90
INSPECTIONS	$0.00	$274.00	$274.00
LAMPS & BULBS	$272.86	$438.40	$228.96
OIL CHANGE	$313.96	$137.00	$450.96

Technician	Service Description	Parts	Labor	Job Total
TK	**TECHNICIAN NOTES: SCANNED VEHICLE AND FOUND FAULTS 121532, 121201, AND 120408 RELATED TO CHARGE PRESSURE SENSOR PLAUSIBILITY AND BOOST PRESSURE CONTROL.CLEARED FAULTS AND FOUND 121532 RETURNED IMMEDIATELY. MONITORED LIVE DATA WITH KEY ON, ENGINE OFF AND FOUND CHARGE PRESSURE SENSOR BEFORE THROTTLE BODY READING APPROXIMATELY 1300 MBAR WHILE OTHER PRESSURE SENSORS READ APPROXIMATELY 800 MBAR.SWAPPED CHARGE PRESSURE AND INTAKE MANIFOLD PRESSURE SENSORS AND FOUND FAULT REMAINED AT CHARGE PRESSURE SENSOR LOCATION. DISCONNECTING SENSOR RESULTED IN A 3200 MBAR READING.PERFORMED ELECTRICAL TESTING OF SENSOR POWER, GROUND, AND SIGNAL CIRCUITS. VERIFIED APPROXIMATELY 1.32V SIGNAL AT BOTH SENSORS AND CONFIRMED IDENTICAL SIGNAL VOLTAGE DIRECTLY AT DME. NO WIRING OR CONNECTION ISSUES FOUND.FURTHER INVESTIGATION REVEALED THAT ALTHOUGH BOTH SENSORS ARE PHYSICALLY INTERCHANGEABLE, THEY REQUIRE DIFFERENT PART NUMBERS AND PRESSURE CALIBRATIONS. SUSPECTED INCORRECT AFTERMARKET SENSOR INSTALLED IN CHARGE PRESSURE SENSOR LOCATION.REPLACED CHARGE PRESSURE SENSOR WITH CORRECT PART NUMBER. VERIFIED PRESSURE READINGS RETURNED TO NORMAL AND FAULT NO LONGER RETURNS.**REPAIR VERIFIED.****		0.00	
TK	**MANAGER NOTES:** **Manufacturer Safety recall issued on 08/13/2024 NHTSA #24V-608** **Recall #24V-608:474 ENGINE COOLANT PUMP Status: Remedy Available**		0.00	
TK	**USED VEHICLE INSPECTION: ROAD TEST VEHICLE. VISUALLY INSPECT ALL FLUIDS, FILTERS, BELTS, BATTERY AND HOSES. PERFORM FOUR WHEEL BRAKE INSPECTION. LOAD TEST ALL STEERING AND SUSPENSION COMPONENTS. INSPECT BODY OF VEHICLE FOR DAMAGE AND FUNCTIONALITY OF VITAL BODY RELATED COMPONENTS. SCAN FOR DIAGNOSTIC TROUBLE CODES AND PRINT. CHECK FOR OPEN RECALLS AND SERVICE BULLETINS. COMPLETE A 30-PT INSPECTION SHEET WITH BRAKES & TIRE MEASUREMENTS.**		274.00	274.00
TK	**REPLACE BOOST PRESSURE SENSOR BEFORE THROTTLE BODY**	325.90	137.00	462.90
	Part Number / Part Description / Part Price Each / Quantity / Extended			
N	*WP-2930630 BOOST PRESSURE SENSO 325.90 1 325.90*			
TK	**EURO SYNTHETIC OIL CHANGE FILL WITH FACTORY SPECIFIED QUALITY AND AMOUNT OF OIL-EURO FULL SYNTHETIC OIL TYPE: EURO SYNTHETIC.**	313.96	137.00	450.96
	Part Number / Part Description / Part Price Each / Quantity / Extended			
S	*5W40 5W-40 High Mileage Full Synthetic 52.16 5 260.80*			
S	*MSL57327 MicroGard Select Oil Filter 53.16 1 53.16*			
TK	**REPLACE COOLANT HOSE**	250.55	274.00	524.55
	Part Number / Part Description / Part Price Each / Quantity / Extended			

Thank you for your business!

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
***** Preview Invoice *****

Invoice #0041596 **11/12/2026 1:24 pm**

DJPJ HOLDINGS
15035 E HINSDALE DR. UNIT B
CENTENNIAL, CO 80112
MOBILE:(303) 617-1125
WORK:(303)

2015 BMW 328 SERIES
4-1997 2.0L DOHC
VIN : WBA3X5C59FD561342
Mileage :
Trans :
License :

COLR : WHITE
Unit # XDRIVE GT

Your Service Writer Today Is: SHOP OWNED Center: SHOP OWNED VEHICLE

Technician	Service Description				Parts	Labor	Job Total
N	*WP-552122*	*COOLING HOSE PLASTIC*	*160.58*	*1*	*160.58*		
S	*0020*	*COOLANT GOLD PLUS EXT LIFE GALLONS*	*29.99*	*3*	*89.97*		
TK	**REPLACE BOTH LOW BEAM HEADLIGHT BULB**				**79.34**	**164.40**	**243.74**
	Part Number	*Part Description*	*Part Price Each*	*Quantity*	*Extended*		
N	*H7ST/2BP*	*SYLVANIA H7 SilverStar Halogen Head*	*79.34*	*1*	*79.34*		
TK	**REPLACE BOTH PARK LAMP BULBS**				**101.56**	**137.00**	**238.56**
	Part Number	*Part Description*	*Part Price Each*	*Quantity*	*Extended*		
N	*H6W*	*BULB MINIATURE HALOG*	*50.78*	*2*	*101.56*		
	REPLACE BOTH FOG LIGHT BULBS				**91.96**	**137.00**	**228.96**
	Part Number	*Part Description*	*Part Price Each*	*Quantity*	*Extended*		
N	*H8BP*	*FOG LIGHT BULB BASIC*	*45.98*	*2*	*91.96*		

Services Recommended to Customer

STRUTS, RENEW
SHOCK ABSORBERS, RENEW
REPLACE BOTH ENGINE MOUNTS
MOUNT & BALANCE FOUR TIRES
REPLACE WINDSHIELD WIPERS

Parts Recommended To Customer

1	*317 851*	*STRUT ASSEMBLY-FRONT*
1	*317 850*	*STRUT ASSEMBLY-FRONT*
2	*2702-711598*	*STRUT BELLOW-FRONT*
2	*WP-3555746*	*STRUT MOUNT-FRONT*
2	*24-264570*	*SHOCK ABSORBER-REAR*
2	*WP-528303*	*SHOCK MOUNT-REAR*
1	*WP-448382*	*ENGINE MOUNT-LEFT*
1	*WP-440271*	*ENGINE MOUNT-RIGHT*
4	*WW*	*WHEEL WEIGHT*
1	*WP-435821*	*WINDOW WIPER BLADE S*

Authorizations

Approved By:	Approval Given To:	Date	Time	Difference	Total Authorized	Method
DUSTIN JOHNSON		11/10/26	10:48 am	$2,468.88	$2,468.88	By Phone
Reason: DJ						

Repair Order Notes

Thank you for your business!

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
***** Preview Invoice *****

Invoice #0041596 **11/12/2026 1:24 pm**

DJPJ HOLDINGS
15035 E HINSDALE DR. UNIT B
CENTENNIAL, CO 80112
MOBILE:(303) 617-1125
WORK:(303)

2015 BMW 328 SERIES
4-1997 2.0L DOHC
VIN : WBA3X5C59FD561342
Mileage :
Trans :
License :

COLR : WHITE
Unit # XDRIVE GT

Your Service Writer Today Is: SHOP OWNED Center: SHOP OWNED VEHICLE

Technician	Service Description	Parts	Labor	Job Total

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Not responsible for damage or articles left in vehicle theft or any other cause beyond our control.

WARRANTY IS 12 MONTHS OR 12,000 MILES WHICH EVER OCCURS FIRST, UNLESS OTHERWISE SPECIFIED. A SERVICE CHARGE WILL BE APPLIED FOR ALL CARD PURCHASES.

Customer Signature: _____ **Date:** _____

TOTAL PARTS	$1,163.27
TOTAL LABOR	$1,260.40
SUBLET	$0.00
SHOP/HAZMAT	$121.18
SUBTOTAL	$2,544.85
OTHER FEES	$0.00
SALES TAX	$0.00
INVOICE TOTAL	**$2,544.85**
PAID	$0.00
DUE	$2,544.85

SECTION 30-20-1403, COLORADO REVISED STATUTES, REQUIRES RETAILERS TO COLLECT A WASTE TIRE FEE SET BY THE SOLID AND HAZARDOUS WASTE COMMISSION ON THE SALE OF EACH NEW MOTOR VEHICLE TIRE AND EACH NEW TRAILER TIRE:

Thank you for your business!