

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041389

9/1/2026
2:58 pm

2013 MERCEDES BENZ GLK350

V6-3498 3.5L DOHC
VIN : WDCGG8JB0DG008423

Mileage :

Trans : AUTO

License :

COLR : GRAY

DJPJ HOLDINGS

14635 HAGUS PL

PARKER, CO 80134

MOBILE:(734) 395-5097

WORK:(303)

Your Service Writer Today Is: SHOP OWNED

Center: SHOP OWNED VEHICLE

Service Requests:

Category Summary	Parts	Labor	Job Total
COMMENTS/NOTES	\$0.00	\$0.00	\$0.00
DRIVEABILITY	\$0.00	\$274.00	\$274.00
ELECTRICAL	\$0.00	\$137.00	\$137.00
ENGINE	\$1,665.16	\$3,836.00	\$5,501.16
INSPECTIONS	\$0.00	\$0.00	\$0.00
OIL CHANGE	\$321.34	\$137.00	\$458.34

Technician	Service Description	Parts	Labor	Job Total																									
TK	BASIC INSPECTION ROAD TEST VEHICLE, CHECK ALL LIGHTS, CHECK UNDER HOOD FLUIDS, INSPECT TIRES & ADJUST AIR PRESSURE. INSPECT BELTS & AIR FILTER SCAN ALL MODULES .		0.00																										
TK	EURO SYNTHETIC OIL CHANGE FILL WITH FACTORY SPECIFIED QUALITY AND AMOUNT OF OIL-EURO FULL SYNTHETIC OIL TYPE: EURO SYNTHETIC.	321.34	137.00	458.34																									
	<table> <tr> <th>Part Number</th><th>Part Description</th><th>Part Price Each</th><th>Quantity</th><th>Extended</th></tr> <tr> <td>WP-401759</td><td>OIL FILTER KIT INSER</td><td>62.00</td><td>1</td><td>62.00</td></tr> <tr> <td>15D934</td><td>MOTOR OIL EDGE FULL</td><td>150.66</td><td>1</td><td>150.66</td></tr> <tr> <td>15D932</td><td>MOTOR OIL EDGE FULL</td><td>31.68</td><td>2</td><td>63.36</td></tr> <tr> <td>109</td><td>COMPRESSION PERFORMANCE RESTORATION</td><td>22.66</td><td>2</td><td>45.32</td></tr> </table>	Part Number	Part Description	Part Price Each	Quantity	Extended	WP-401759	OIL FILTER KIT INSER	62.00	1	62.00	15D934	MOTOR OIL EDGE FULL	150.66	1	150.66	15D932	MOTOR OIL EDGE FULL	31.68	2	63.36	109	COMPRESSION PERFORMANCE RESTORATION	22.66	2	45.32			
Part Number	Part Description	Part Price Each	Quantity	Extended																									
WP-401759	OIL FILTER KIT INSER	62.00	1	62.00																									
15D934	MOTOR OIL EDGE FULL	150.66	1	150.66																									
15D932	MOTOR OIL EDGE FULL	31.68	2	63.36																									
109	COMPRESSION PERFORMANCE RESTORATION	22.66	2	45.32																									
TK	CHECK ENGINE LIGHT TESTING & ANALYSIS: CUSTOMER STATES THAT CHECK ENGINE LIGHT IS ON; INCLUDES MONITOR ENGINE COMPUTER FOR FAULT CODES AND INSPECT FOR APPLICABLE TECHNICAL SERVICE BULLETINS OR RECALLS. DOCUMENT MODULE SOFTWARE VERSION. IDENTIFY SOFTWARE UPDATES ADVISED. PERFORM PINPOINT ANALYSIS AND CIRCUIT TESTING.		274.00	274.00																									
TK	TECHNICIAN NOTES: Inspected vehicle for check engine light/engine performance concern. Performed complete vehicle scan and found faults P001177 for Bank 1 intake camshaft position unable to reach commanded position and P002177 for Bank 2 intake camshaft position unable to reach commanded position. Cleared faults and operated vehicle to verify concern. Both Bank 1 and Bank 2 intake camshaft timing faults returned. During testing, also noted that after the vehicle sits approximately 30 minutes or longer, engine produces a severe timing-chain/camshaft rattle during initial startup. Inspected operation of the camshaft adjustment system. Swapped intake camshaft adjustment magnet/solenoids to determine whether the fault would follow a control solenoid. Faults remained with the intake camshafts on both banks, indicating the adjustment magnets are not the cause of the concern. Using scan tool, commanded the intake camshaft adjusters through their operating range while monitoring commanded versus actual camshaft position. Found intake camshaft adjusters operate intermittently; at times the camshafts respond to commands, while at other times they fail to reach the requested position. This verifies an intermittent mechanical/hydraulic failure within the intake camshaft adjustment system. Due to possible oil contamination/sludge affecting camshaft adjuster operation, performed engine oil and filter change and treated engine oil system with BG EPR cleaner. Retested camshaft adjustment operation after service. No improvement was found; both intake camshafts continue to intermittently fail to reach commanded position. Based on repeated intake camshaft timing faults on both banks, failure to follow commanded position, faults remaining on the intake cams after swapping adjustment solenoids, no improvement following oil system service, and significant startup timing rattle after sitting, recommend replacement of both Bank 1 and Bank 2 intake camshaft sprocket/adjuster assemblies. Recommend		0.00																										



Thank you for your business!

HotShots Automotive

15035 E Hinsdale Dr. Unit B
Centennial, CO 80112
(303) 617-1125
FAST · HONEST · DONE RIGHT

Invoice #0041389**9/1/2026
2:58 pm****2013 MERCEDES BENZ GLK350**V6-3498 3.5L DOHC
VIN : WDCGG8JB0DG008423

Mileage :

Trans : AUTO

License :

COLR : GRAY

DJPJ HOLDINGS

14635 HAGUS PL

PARKER, CO 80134

MOBILE:(734) 395-5097

WORK:(303)

Your Service Writer Today Is: SHOP OWNED

Center: SHOP OWNED VEHICLE

Technician	Service Description	Parts	Labor	Job Total
	installing updated timing-chain tensioner check valves at the same time to help maintain oil pressure in the timing system during engine-off periods and address the startup rattle.After repairs, clear faults, perform camshaft adaptation/initialization as required, verify commanded versus actual camshaft positions, and perform cold-start verification after an extended soak.			
TK	ENGINE LABOR - REMOVE AND REPLACE BOTH INTAKE SPROCKETS ALONG WITH ADDING CHECK VALVES TO HYDRAULIC TIMING CHAIN TENSIONER	1665.16	3836.00	5501.16
	SPROCKET KIT	870.00	1	870.00
N	WP-648197 CYLINDER HEAD OIL CH	77.00	2	154.00
N	HT200C GASKET MAKER	77.16	1	77.16
N	WP-555657 INTAKE MANIFOLD GASK	34.00	6	204.00
N	276 050 38 00 SPROCKET OUTLET, LEFT	0.00	1	0.00
N	276 050 39 00 SPROCKET OUTLET, RIGHT	0.00	1	0.00
N	276 050 36 00 SPROCKET INTAKE, LEFT	0.00	1	0.00
N	276 050 37 00 SPROCKET INTAKE, RIGHT	0.00	1	0.00
N	WP-498680 TIMING CHAIN GUIDE R	28.00	2	56.00
N	WP-2382945 TIMING CHAIN TENSION	304.00	1	304.00
TK	ELECTRICAL LABOR: Replace Faceplate on Radio and replace driver door lock button		137.00	137.00

Repair Order Notes

I hereby authorize the repair work to be done along with the necessary parts and materials and hereby grant you and/or your employees permission to operate the vehicle herein described on streets, highways or elsewhere, at your discretion, for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. Not responsible for damage or articles left in vehicle theft or any other cause beyond our control.

WARRANTY IS 12 MONTHS OR 12,000 MILES WHICH EVER OCCURS FIRST, UNLESS OTHERWISE SPECIFIED. A SERVICE CHARGE WILL BE APPLIED FOR ALL CARD PURCHASES.

Customer Signature: _____ Date: _____

TOTAL PARTS	\$1,986.50
TOTAL LABOR	\$4,384.00
SUBLET	\$0.00
SHOP SUPPLY	\$201.25
SUBTOTAL	\$6,571.75
OTHER FEES	\$0.00
SALES TAX	\$147.67

INVOICE TOTAL \$6,719.42

PAID	\$0.00
DUE	\$6,719.42

SECTION 30-20-1403, COLORADO REVISED STATUTES, REQUIRES RETAILERS TO COLLECT A WASTE TIRE FEE SET BY THE SOLID AND HAZARDOUS WASTE COMMISSION ON THE SALE OF EACH NEW MOTOR VEHICLE TIRE AND EACH NEW TRAILER TIRE:

**Thank you for your business!**