

Main page Recent changes Server admin log (Prod) Server admin log (RelEng) **Deployments** SRE/Operations Help Incident status

Cloud VPS & Toolforge

Cloud VPS documentation **Toolforge** documentation

Request Cloud VPS

Server admin log (Cloud VPS)

Tools

What links here Related changes Special pages Permanent link Page information Cite this page

Print/export

Create a book Download as PDF Printable version

Page Discussion View source

View history

Search Wikitech

Q

Toolforge webservices are in the final stages of migrating to the toolforge.org domain. Please help us clean up older documentation referring to tools.wmflabs.org!

Incident documentation/20150324-Eqiad-Rack-C4

< Incident documentation

Contents [hide]

- 1 Summary
- 2 Timeline
- 3 Conclusions
- 4 Actionables

Summary

At around 09:30 UTC on March 24, the network switch for Rack 4 in Row C in our egiad datacenter went offline. This immediately stopped network traffic to all machines in this rack. None of the affected services were set up for paging ops as critical services, so no pages went out. The switch came back online and the affected machines were connected to the network again at about 09:50 UTC, for a total outage time window of about 20 minutes. Notable affected higher-level services included Phabricator and Graphite.

Timeline

- 09:30 UTC eqiad asw-c4 switch goes offline; Icinga alerts for hosts down. Immediately ets noticed by staff (Filippo, Giuseppe, Gage)
- 09:33 UTC Cause determined to be asw-c4
- 09:43 UTC Filippo calls Faidon
- 09:47 UTC Faidon logs in, connects to serial console of asw-c4-eqiad via the scs service and presses enter. The switch emits "Rebooting...", reboots itself and ultimately comes back up online.
- 09:50 UTC Icinga host UP alerts.

Conclusions

- 1. Not all opsens are familiar with layouts & processes regarding out of band console access and how to connect to otherwise unreachable equipment. While the switch stack (sans C4) was accessed and there was sufficient networking awareness to identify the issue, there was confusion on how to connect to the crashed switch via its console.
- 2. This is the second time the same symptoms are encountered on the exact same switch (but no others), see November 30th's incident. This is likely a hardware fault and will need to be addressed by a hardware swap.

Actionables

Being tracked in Phabricator at https://phabricator.wikimedia.org/T93730

Category: Incident documentation

This page was last edited on 24 March 2015, at 12:44.

Text is available under the Creative Commons Attribution-ShareAlike License; additional terms may apply. SeeTerms of Use for details.

Privacy policy About

Disclaimers Code of Conduct Developers Statistics Cookie statement Mobile view

MediaWiki

Wikitech

