

INSPECTION REPORT

Document Ref: IR-556 | Rotating Equipment Inspection

Inspection Date	01 Jul 2024
Asset	Centrifugal Pump P-204 (Boiler Feed Water Service)
Location	Unit 2, Pump House Bay 4
Inspector	R. Krishnan (Cert. Vibration Analyst, ISO 18436-2 Cat II)
Related Procedure	M-118 (Rotating Equipment Condition Monitoring)

Findings

Routine condition-monitoring inspection of Pump P-204 completed. Drive-end (DE) bearing vibration measured at 4.6 mm/s RMS, up from 2.1 mm/s RMS at the previous quarter reading. This is within the ISO 10816-3 Zone C band (elevated) but below the Zone D alarm threshold of 7.1 mm/s. Bearing housing temperature nominal at 62 C. Lubrication level low.

The rising vibration trend on the DE bearing is consistent with early-stage bearing wear. This is a leading indicator and warrants tracking. No immediate shutdown required.

Recommendation

1. Flag P-204 DE bearing for enhanced monitoring (weekly, not quarterly). 2. Schedule bearing replacement at next maintenance window per Procedure M-118. 3. Top up lubrication in the interim. Recommendation status: ELEVATED - MONITOR. Escalate if amplitude exceeds 7.1 mm/s.