

MAINTENANCE WORK ORDER / LOG

Document Ref: ML-1183 | Corrective Maintenance

Work Date	08 Jul 2024
Asset	Pump P-204
Triggered By	Inspection Report IR-556
Technician	S. Prakash (Mech. Maint. Team B)
Supervisor Sign-off	V. Menon
Procedure Referenced	M-118

Work Performed

Attended P-204 following IR-556 recommendation. Lubrication topped up on DE bearing housing with grade ISO VG 68. Vibration re-checked at 4.9 mm/s RMS (marginally higher than IR-556 reading). Bearing replacement was NOT carried out during this visit.

Deferral Note

DE bearing replacement deferred to next planned shutdown due to spare bearing (SKF 6316 C3) not being in stores at time of work order. Lube top-up applied as interim measure. Deferral approved by V. Menon. Next planned shutdown scheduled 6 weeks out.

NOTE: Procedure M-118 clause 4.3 states elevated-vibration bearings flagged in inspection should be replaced within 14 days, not deferred to next shutdown. Deferral logged as a temporary deviation pending spare availability.