# MAINTENANCE TECHNICAL SUPPORT CENTER HEADQUARTERS MAINTENANCE OPERATIONS UNITED STATES POSTAL SERVICE



## **Maintenance Management Order**

**SUBJECT**: Preventive Maintenance (PM) Guidelines

for the Computer Forwarding System II

(CFS-II)

**TO:** Maintenance Managers, CFS-II Offices

**DATE:** November 30, 2012

**NO:** MMO-124-12

FILE CODE: 13

gmar:mm08056ad

This Maintenance Management Order (MMO) provides PM guidelines for the CFS-II and supersedes MMO-072-00. The acronym is CFS. The class codes are DA, FA, and GA.

Attached maintenance checklists for the CFS-II, include the Non-Mechanized (NMT) and Flats Forwarding Terminals (FFT) as well as the Forwarding Control System (FCS).

The minimum maintenance skill level to perform each task on the various checklists is included in the Minimum Skill Level column. This does not preclude higher level employees from performing any of this work.

The workhours represented in this MMO reflect the maximum workhours required to maintain the equipment. Given local conditions, management may modify task frequencies.

## WARNING

Various products requiring Material Safety Data Sheets (MSDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current MSDS for each product used is on file and available to all employees. When reordering such a product, it is suggested that current MSDS be requested.

## WARNING

The use of compressed or blown air is prohibited. When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used only on optical equipment when other cleaning methods cannot be used.

Web Access: http://mtsc.usps.gov

## WARNING

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

The attached master checklists provide tasks to be performed at periodic intervals (daily, weekly, monthly, quarterly, and semi-annually), time required per task, and the minimum skill level for each task.

Maintenance Managers are to use these preventive maintenance guidelines when preparing the route sheets for local maintenance personnel. It is the responsibility of each Maintenance Manager to ensure all WARNINGS, CAUTIONS, and NOTES are included with each applicable task as part of the preparation of any local route sheets.

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at MTSC>HELPDESK>Create/Update Tickets or call (800) 366-4123.

Robert E. Albert

Manager

Maintenance Technical Support Center

**HQ** Maintenance Operations

- 1. Summary Workload Estimate
- 2. CFS II Master Checklist NMT: 03-CFS-DA-001-M: Monthly
- 3. CFS II Master Checklist NMT: 03-CFS-DA-002-M: Semi-Annual
- 4. CFS II Master Checklist FFT: 03-CFS-FA-003-M: Daily
- 5. CFS II Master Checklist FFT: 03-CFS-FA-004-M: Monthly
- 6. CFS II Master Checklist FFT: 03-CFS-FA-005-M: Quarterly
- 7. CFS II Master Checklist FFT: 03-CFS-FA-006-M: Semi-Annual
- 8. CFS II Master Checklist FCS: 03-CFS-GA-007-M: Daily
- 9. CFS II Master Checklist FCS: 03-CFS-GA-008-M: Weekly
- 10. CFS II Master Checklist FCS: 03-CFS-GA-009-M: Monthly
- 11. CFS II Master Checklist FCS: 03-CFS-GA-010-M: Quarterly

SUMMARY

WORKLOAD ESTIMATE

FOR

COMPUTER FORWARDING SYSTEM II

## **NON-MECHANIZED TERMINAL**

Operation	Routine	Repair*	Total Servicing	Nonproductive	Total
	Servicing	(Hrs/Yr)	& Repair Time	Time **	Servicing Per
	(Hrs/Yr)		(Hrs/Yr)	(Hrs/Yr)	Machine
					(Hrs/Yr)
5 day	3.867	1.160	5.027	0.503	5.529
6 day	3.867	1.160	5.027	0.503	5.529
7 day	3.867	1.160	5.027	0.503	5.529

### FLATS FORWARDING TERMINAL

Operation	Routine	Repair*	Total Servicing	Nonproductive	Total
	Servicing	(Hrs/Yr)	& Repair Time	Time **	Servicing Per
	(Hrs/Yr)		(Hrs/Yr)	(Hrs/Yr)	Machine
					(Hrs/Yr)
5 day	90.867	27.260	118.127	11.813	129.939
6 day	107.333	32.200	139.533	13.953	153.487
7 day	123.800	37.140	160.940	16.094	177.034

### FORWARDING CONTROL SYSTEM

Operation	Routine	Repair*	Total Servicing	Nonproductive	Total
	Servicing	(Hrs/Yr)	& Repair Time	Time **	Servicing Per
	(Hrs/Yr)		(Hrs/Yr)	(Hrs/Yr)	Machine
					(Hrs/Yr)
5 day	59.466	17.839	77.305	7.73	85.635
6 day	69	20.7	89.7	8.97	98.67
7 day	78.53	23.56	102.09	10.21	112.3

<sup>\*</sup>Repair estimates based on 30% of servicing. \*\*Based on 10% of total servicing and repair.

## **COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST**

Non-Mechanized Terminal

03-CFS-DA-001-M

MONTHLY

#### NOTE

Time in the estimated time column is given in minutes.

Time Total: 15 Minutes

Reference: MS-120, Volume A-C

ΑII

ΑII

2

ΑII

U.S. Postal Service								IDE	NTIF	CAT	ON					
Maintenance Checklist		RK DE			_		MENT NYM	•				ASS DE	N	UMBI	ĒR	TYPE
	0 3 C F S										D	Α	0	0	1	М
Equipment Nomenclature	Equipment Model							В	ulletin	tin Filename Occurre				ence		
Computer Forwarding System				CFS	SII				M	M080	056AD	)		Mc	nthl	y

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	NO	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### SAFETY STATEMENT

 COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found, notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### WARNING FOR EWP/PPE.

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

NON -MECHANIZED TERMINAL (NMT) 2. **Power down.** Power down the NMT. Lock out its electrical power as prescribed by the current local procedure providing lockout/restore procedures.

#### CAUTION

Use non-metallic ends on vacuum while cleaning the NMT Computer system keyboard.

NMT KEYBOARD Clean NMT keyboard. Vacuum keyboard to 2 All remove dust build-up.

NMT MONITOR

 Clean NMT monitor. Clean computer system monitor by using a soft lint free cloth and appropriate cleaner.

#### WARNING

Be cautious when working around or on equipment when power has been applied.

7

U.S. Postal Service								IDE	NTIF	ICATI	ON					
Maintenance Checklist	_	RK DE					MENT NYM	•			CLA CO		N	JMBI	≣R	TYPE
Waintenance Officerist	0 3 C F S										D	A	0	0	1	М
Equipment Nomenclature	Equipment Model							В	ulletir	Filer	name Occurrence				I	
Computer Forwarding System	mputer Forwarding System			CFSII MM08056AD N						Mc	onthl	y				

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	140	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

NMT

Restore equipment to service. Restore 7
 equipment (NMT) to service as prescribed by the
 current local procedure providing lockout/restore
 procedures.

CLEAN UP

6. **Clean up.** Remove maintenance materials and 2 All equipment from the work area. Report all deficiencies to supervisor.

Maintenance Technical Support Center

U.S. Postal Service								IDE	NTIF	CAT	ON					
Maintenance Checklist		RK DE			_		MENT NYM	•				ASS DE	N	UMBI	ĒR	TYPE
	0 3 C F S										D	Α	0	0	1	М
Equipment Nomenclature	Equipment Model							В	ulletin	tin Filename Occurre				ence		
Computer Forwarding System				CFS	SII				M	M080	056AD	)		Mc	nthl	y

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Gomponent	140	(Comply with all current salety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

## THIS PAGE BLANK

## **COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST**

Non-Mechanized Terminal
03-CFS-DA-002-M
SEMI-ANNUAL

Time Total: 26 Minutes

### **NOTE**

Time in the estimated time column is given in minutes.

Reference: MS-120, Volume A-C

ΑII

1

ΑII

U.S. Postal Service								IDE	NTIF	ICAT	ION					
<b>1</b>	WC	RK			Е	QUIP	MENT				CLA	SS	N	UMBI	ΞR	TYPE
Maintenance Checklist	CODE A						MYM				CO	CODE				1
	0 3 C F S										D	Α	0	0	2	M
Equipment Nomenclature	Equipment Model							В	ulletir	Filer	name	ame Occurrence				
Computer Forwarding System	CFSII MM08056AD Semi-Annu									ıual						

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	s
Component	NO	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

SAFETY STATEMENT  COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### WARNING FOR EWP/PPE.

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

NON -MECHANIZED TERMINAL 2. **Power down.** Power down the NMT.

CAUTION

Use non-metallic ends on vacuum while cleaning the NMT computer system interior.

CAUTION

Extreme care should be taken that rules regarding electro-static-discharge (ESD) are strictly followed when handling all printed circuit boards, including those in logic racks, system computers, etc. This includes the use of wrist straps and ESD pads.

U.S. Postal Service								IDEN	ITIFI	CATI	ON					
Maintenance Checklist		RK DE			_		MENT NYM					ASS DE	N	ĒR	TYPE	
	0 3 C F S										D	Α	0	0	2	М
Equipment Nomenclature	Equipment Model							Bu	Bulletin Filename C				Occurrence			
Computer Forwarding System				CFS	SII				ΜN	<i>1</i> 080	056AD	)	S	Semi	-Ann	ıual

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	S
Component	No	(Comply with all current safety precautions)	Time Req (min)	Skill Lev	Run Hours	Pieces Fed (000)	Freq.

NMT COMPUTER SYSTEM 3. Vacuum computer interior. Remove computer 15 system cover. Vacuum interior of computer avoiding damage to wiring and electrical components. Replace computer system cover.

5

7

7

#### WARNING

Be cautious when working around or on equipment when power has been applied.

**NMT** 

4. Restore equipment to service. Restore 7 equipment (NMT) to service as prescribed by the current local procedure providing lockout/restore procedures. Verify computer is communicating with FCS server and operating properly by printing test labels.

**CLEAN UP** 

 Clean up. Remove maintenance materials and 2 All equipment from the work area. Report all deficiencies to supervisor.

Maintenance Technical Support Center

U.S. Postal Service							IDE	NTIF	CATI	ON					
Maintenance Checklist		RK DE			_	 MENT NYM	•				ASS DE	N	UMBI	ΞR	TYPE
	0	3	С	F	S					D	Α	0	0	2	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del			В	ulletin	Filer	name	(	Occurr	ence		
Computer Forwarding System				CFS	SII			M	M080	)56AD	)	S	Semi	-Ann	iual

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Gomponent	140	(Comply with all current salety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

## THIS PAGE BLANK

### **COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST**

Flats Forwarding Terminal
03-CFS-FA-003-M
DAILY

Time Total: 19 Minutes

### **NOTE**

Time in the estimated time column is given in minutes.

Reference: MS-120, Volume D

ΑII

ΑII

U.S. Postal Service							IDE	NTIF	CAT	ON					
Maintenance Checklist	_	RK DE				 MENT NYM	•			_	ASS DE	N	JMBI	ΞR	TYPE
	0	3	С	F	S					F	A	0	0	3	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del			В	ulletin	Filer	name	(	Occurr	ence		
Computer Forwarding System				CFS	SII			M	M08	056AD	)			aily	

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	S
Component	No	(Comply with all current safety precautions)	Time Req (min)	Skill Lev	Run Hours	Pieces Fed (000)	Freq.

#### SAFETY STATEMENT

 COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

## THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### WARNING FOR EWP/PPE.

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

FLATS FORWARDING TERMINAL (FFT)

Power down and lock out power. Power down
 FFT. Lock out its electrical power as prescribed by
 the current local procedure providing
 lockout/restore procedures.

## WARNING

Before opening P/LA, ensure tamper assembly is in home position, under cutter assembly, or personnel injury or equipment damage may occur. Verify by looking through the Photo Array Label Port opening.

U.S. Postal Service							IDE	NTIF	ICAT	ION					
Maintenance Checklist		RK DE			_	 MENT NYM	•			_	ASS DE	N	UMBI	ΞR	TYPE
	0	3	С	F	S					F	Α	0	0	3	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del			В	ulletin	File	name	(	Occurr	ence		
Computer Forwarding System				CFS	SII			M	M08	056AD	)			aily	

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all content safety presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### NOTE

The following preventive maintenance procedures are found in the Flats Forwarding Terminal Maintenance and Troubleshooting Guide with supporting figures.

#### FFT 3. Cleaning FFT.

10 7

- Open P/LA to gain access.
- Manually rotate the cutter magnet until it is pointed toward the hall-effect sensor to raise the blade to its highest position.
- 3. Lower the print head carriage by rotating the head lift lever counterclockwise.
- 4. Remove the label stock from cutter area.
- 5. Remove ribbon stock from print head.
- Remove two screws securing blade guard to cutter.

#### WARNING

Discard solvent soaked materials according to local procedures to prevent spontaneous combustion.

- Use cotton swab dampened with site approved solvent to remove glue build-up from blade and anvil.
- 8. Use cotton swab dipped in alcohol to remove build-up on print head.
- Lubricate cutter by applying 1-2 drops of light machine oil to the cutter arm pivot screw.
- Install the blade guard and secure with two screws.
- 11. Re-load ribbon and label stock.
- 12. Secure print head lever.
- 13. Rotate cutter blade to trim label stock.
- 14. Close P/LA and close latch.

Maintenance Technical Support Center

U.S. Postal Service								IDE	NTIF	ICAT	ION					
Maintenance Checklist	WC	RK DE					MENT NYM	•			_	ASS DE	N	JMBI	ER	TYPE
Wantenance Oneckinst	0	3	С	F	s	ACRO	ואו ז אוכ				F	A	0	0	3	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del				В	Bulletir	File	name	(	Occurr	ence	ı	ı
Computer Forwarding System				CFS	SII				M	M08	056AD	)			aily	

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	140	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

## WARNING

Be cautious when working around or on equipment when power has been applied.

FFT 4. Restore equipment to service. Restore 2 7 equipment to service as prescribed by the current local procedure providing lockout/restore procedures.

CLEAN UP 5. Clean up. Remove maintenance materials and 2 All

equipment from the work area. Report all deficiencies to supervisor.

### **COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST**

Flats Forwarding Terminal
03-CFS-FA-004-M
MONTHLY

Time Total: 29 Minutes

### **NOTE**

Time in the estimated time column is given in minutes.

Reference: MS-120, Volume D

ΑII

ΑII

Attachment 5

U.S. Postal Service							IDE	NTIF	ICAT	ION					
Maintenance Checklist	_	DRK DDE			_	 MENT NYM	•				ASS DE	N	JMBI	ĒR	TYPE
	0	3	С	F	S					F	Α	0	0	4	М
Equipment Nomenclature	Equipmen		nt Mo	del			В	ulletin	File	name	(	Occurr	ence		
Computer Forwarding System				CFS	SII			M	M08	056AD	)		Mc	nthl	y

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all content safety presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### SAFETY STATEMENT

 COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

## THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### WARNING FOR EWP/PPE.

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

FLATS FORWARDING TERMINAL (FFT)

2

Power down and lock out power. Power down
 FFT. Lock out its electrical power as prescribed by
 the current local procedure providing
 lockout/restore procedures.

#### WARNING

Before opening P/LA, ensure tamper assembly is in home position, under cutter assembly, or personnel injury or equipment damage may occur. Verify by looking through the photo array labeling port.

U.S. Postal Service								IDE	NTIF	ICAT	ON					
Maintanana Chaolalat	_	RK					MENT	•			_	ASS	N	JMBE	₽R	TYPE
Maintenance Checklist	CO	DE				ACRO	MYM				CO	DE				
	0	3	С	F	S						F	Α	0	0	4	M
Equipment Nomenclature	Equ	ipmer	nt Mo	del				В	ulletir	Filer	name		Occurr	ence		
Computer Forwarding System				CFS	SII				M	M08	056AD	)		Mc	nthly	/

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all content safety presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### **NOTE**

The following preventive maintenance procedures are found in the Flats Forwarding Terminal Maintenance and Troubleshooting Guide with supporting figures.

TAMPER ASSEMBLY RECOMMEND LEVEL 9

#### 3. Lubricate tamper assembly.

5 7

- I. Open P/LA to gain access.
- 2. Remove two screws and lock washers from mounting block under tamper.

#### WARNING

Discard solvent soaked materials according to local procedures to prevent spontaneous combustion.

#### **NOTE**

If grease is dirty, wipe off all grease and apply clean silicon grease.

- Redistribute silicon grease around contact edges of mounting block.
- 4. Add additional silicon grease as needed.
- Reinstall mounting block, two screws, and lock washers.
- 6. Close P/LA and secure latch.
- Test the tamper by running maintenance option 4. Excessive silicone grease may cause tamper to drag resulting in poor performance or fault condition.

#### VALVE ASSEMBLY 4. Lubricate valve assembly.

13 7

- Remove motor and valve diverter securing hardware.
- 2. Remove motor and valve diverter as one unit from valve body.
- 3. Redistribute silicon grease around outside edges of valve diverter.

U.S. Postal Service								IDE	NTIF	ICAT	ION					
Maintenance Checklist	_	DRK DDE			_		MENT NYM	•				ASS DE	NUMBER			TYPE
	0 3 C F S									F	Α	0	0	4	М	
Equipment Nomenclature	Equipment Model							Bulletin Filename					Occurrence			
Computer Forwarding System	CFSII						MM08056AD				)		y			

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all content safety presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### WARNING

Discard solvent soaked materials according to local procedures to prevent spontaneous combustion.

#### NOTE

If grease is dirty, wipe off all grease and apply clean silicon grease.

- 4. Add additional silicon grease as needed.
- 5. Remove filter and vacuum clean.
- 6. Install filter.
- 7. Install motor and valve diverter as a unit onto the valve body.
- 8. Install motor and valve diverter securing hardware.
- 9. Close PLA Latch.

## WORK-STATION PC MONITOR

- 5. Clean the workstation PC monitor. Use a soft lint free cloth and appropriate cleaner if necessary.
- All

ΑII

7

## WORK-STATION PC KEYBOARD

Vacuum keyboard. Vacuum keyboard to remove 1 dust build-up.

#### WARNING

Be cautious when working around or on equipment when power has been applied.

FFT

Restore equipment to service. Restore 2
 equipment (FFT) to service as prescribed by the
 current local procedure providing lockout/restore
 procedures.

#### **CLEAN UP**

8. Clean up. Remove maintenance materials and 2 All equipment from the work area. Report all deficiencies to supervisor.

### **COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST**

Flats Forwarding Terminal
03-CFS-FA-005-M
QUARTERLY

Time Total: 29 Minutes

### **NOTE**

Time in the estimated time column is given in minutes.

Reference: MS-120, Volume D

												• • • • • • •				
U.S. Postal Service								IDEN	ITIFI	CAT	ION					
	WC	RK			Е	QUIF	MENT				CLA	ASS	N	UMB	ER	TYPE
Maintenance Checklist	CC	DE				ACRO	MYM				CO	DE				
	0 3 C F S									F	Α	0	0	5	М	
Equipment Nomenclature	Equipment Model						Bulletin Filename				C	Occurr				
Computer Forwarding System		CFSII MM08056AD Quarte						arter	ly							

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	S
Component	No	(Comply with all current safety precautions)	Time	Skill	Run	Pieces	Freq.
			Req	Lev	Hours	Fed	
			(min)			(000)	

#### SAFETY STATEMENT

1. COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### **WARNING FOR EWP/PPE:**

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

FLATS FORWARDING TERMINAL (FFT)  Power down and lock out power. Power down FFT. Lock out its electrical power as prescribed by the current local procedure providing lockout/restore procedures.

#### WARNING

Before opening P/LA, ensure tamper assembly is in home position, under cutter assembly, or personnel injury or equipment damage may occur. Verify by looking through the Photo Array port opening.

#### CAUTION

Extreme care should be taken regarding Electrostatic Discharge (ESD) during this procedure

All

ΑII

7

2

U.S. Postal Service								IDENT	IFICAT	ION					
Maintenance Checklist		RK DE			_		MENT NYM				ASS DDE	N	UMBI	≣R	TYPE
		0 3 C F S								F	Α	0	0	5	М
Equipment Nomenclature	Equipment Model							Bulletin Filename				Occurrence			
Computer Forwarding System	CFSII						MM08056AD					arter	ly		

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	S
Component	No	(Comply with all current safety precautions)	Time	Skill	Run	Pieces	Freq.
			Req	Lev	Hours	Fed	
			(min)			(000)	

#### **NOTE**

The following preventive maintenance procedures are found in the Flats Forwarding Terminal Maintenance and Troubleshooting Guide with supporting figures.

TAMPER ASSEMBLY CHECK RECOMMEND LEVEL 9

#### 3. Check tamper assembly.

- I. Unlock latch and open P/LA door to gain access to tamper assembly.
- 2. Check tamper assembly for visible damage.
- 3. Manually move tamper from home position to extended position to check for looseness, binding, or grinding noises.
- 4. Check tamper piston for looseness, binding, cracks, and obstructions that would inhibit air flow on the top of the piston.
- Check condition of wiring and mounting hardware. Inspect wiring for cracks in the sheath, exposed wires, and frayed wiring. Inspect mounting hardware for looseness and stripped threads.
- Return tamper to home position.

## WARNING

Use caution when near cutter blade to prevent injury.

CUTTER	Cutter assembly check.	5	7		
ASSEMBLY CHECK	Check cutter assembly for visible damage.     Turn magnet holder to manually rotate cutter stepper motor one full revolution.				
	2. Check cutter blade for looseness and binding.				
	<ol><li>Check cutter assembly mounting hardware for looseness, binding, and stripped threads.</li></ol>				
	<ol> <li>Check label guide for build-up of paper dust or adhesive from labels.</li> </ol>				
	<ol><li>If tamper was moved, return tamper to the home position.</li></ol>				

U.S. Postal Service								IDE	NTIF	ICAT	ON					
	WC	RK			Е	QUIF	MENT	•			CLA	ASS	N	UMBI	ER	TYPE
Maintenance Checklist	CO	CODE				ACRO	MYNC				CODE					
	0 3 C F S								FA		0	0	5	М		
Equipment Nomenclature	Equipment Model							Bulletin Filename				C	Occurr			
Computer Forwarding System	mputer Forwarding System CFSII								M	M08	3056AD Quar				arter	ly

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	S
Component	No	(Comply with all current safety precautions)	Time Req	Skill Lev	Run Hours	Pieces Fed	Freq.
			(min)			(000)	

#### PRINTER ASSEMBLY CHECK

#### 5. Check printer.

5

7

- Check the printer's print head cable and ensure it is securely fastened. Check for cracks or fraying in the printer's drive belt. Check for bends in head cam shaft, guide post, ribbon take-up hub, and roller drive.
- 2. Check printer's mounting hardware for looseness and stripped threads.
- If tamper was moved, return tamper to the home position.

#### VALVE/ BLOWER ASSEMBLY CHECK

#### 6. Check valve and blower assembly.

2 7

- Check valve and blower assembly for visible damage.
- Check hoses for tears, holes, crimping, or loose mounting hardware.
- 3. Check mounting hardware for looseness.
- 4. Check wiring for cracked sheaths, frayed wires, and exposed wires.
- 5. If tamper was moved, return tamper to the home position.
- 6. Close P/LA and secure latch.

#### FFT WORK-STATION CHECK

#### 7. Check workstation.

5

7

- 1. Check general condition of desk, including stability of legs.
- Check cables and power cords for fraying or other defects.
- 3. Check chair for stability.

## WARNING

Be cautious when working around or on equipment when power has been applied.

#### **FFT**

#### 8. Restore equipment to service.

2 7

Restore equipment to service as prescribed by the current local procedure providing lockout/restore procedures.

7

U.S. Postal Service								IDE	NTIF	CAT	ION					
Maintenance Checklist	_	RK DE					MENT NYM	•			CLA CO		N	UMBI	≣R	TYPE
Waintenance Officerist	0	3	С	F	S	HURC	IN T IVI				F	A	0	0	5	М
Equipment Nomenclature	Equipment Model Bu							Bulletin Filename				Occurrence				
Computer Forwarding System		CFSII					M	M080	056AD			ly				

Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	S
Component	No	(Comply with all current safety precautions)	Time	Skill	Run	Pieces	Freq.
			Req	Lev	Hours	Fed	
			(min)			(000)	

FFT WORK-STATION CHECK Check primary power box LED. With power 1 applied, check primary power box for LED indicating active surge suppressors.

CLEAN UP

10. **Clean up.** Remove maintenance materials and 2 All equipment from work area. Report all deficiencies to supervisor.

Maintenance Technical Support Center

U.S. Postal Service								IDE	NTIF	ICAT	ON					
<b>1</b>	WC	RK			Е	QUIP	MENT				CLA	SS	N	UMBI	ER	TYPE
Maintenance Checklist	CO	DE				ACRO	MYM				CO	DE				
	0	3	С	F	S						F	Α	0	0	5	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del				В	ulletir	Filer	name	(	Occurr	ence		
Computer Forwarding System	CFSII						M	M08	056AD			Qu	arter	ly		

	Part or	Item	Task Statement and Instruction	Est.	Min.		Threshold	S
	Component	No	(Comply with all current safety precautions)	Time Rea	Skill	Run	Pieces	Freq.
ı				(min)	Lev	Hours	Fed (000)	

## THIS PAGE BLANK

### COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST

Flats Forwarding Terminal
03-CFS-FA-006-M
SEMI-ANNUAL

Time Total: 24 Minutes

#### NOTE

Time in the estimated time column is given in minutes.

Reference: MS-120, Volume D

ΑII

ΑII

U.S. Postal Service							IDE	ENTIFI	CAT	ION					
Maintenance Checklist	_	RK DE			_	 MEN <sup>-</sup> NYM	-				ASS DE	N	UMBI	ER	TYPE
	0	3	С	F	S					F	Α	0	0	6	М
Equipment Nomenclature Computer Forwarding System	Equipment Model CFSII					E	Bulletin MN		name 056AD		Occurr		-Anr	nual	

Part or	Item No	Task Statement and Instruction	Est. Time	Min. Skill		Threshold	S
Component	NO	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### SAFETY STATEMENT

 COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### **WARNING FOR EWP/PPE:**

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

FLATS FORWARDING TERMINAL (FFT)  Power down and lock out power. Power down 4
 FFT. Lock out its electrical power as prescribed by
 the current local procedure providing lockout/restore procedures.

#### **CAUTION**

Use non-metallic ends on vacuum while cleaning the interior surfaces of the FFT Workstation PC. Avoid damaging the wiring and electrical components.

#### NOTE

The following preventive maintenance procedures are found in the Flats Forwarding Terminal Maintenance and Troubleshooting Guide with supporting figures

U.S. Postal Service								IDENT	FICAT	ION					
Maintenance Checklist		RK DE			_		MENT NYM				ASS DE	NI	UMBI	ĒR	TYPE
	0	3	С	F	S					F	Α	0	0	6	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del				Bulle	in File	name	(	Occurr	ence		
Computer Forwarding System		CFSII						N	1M08	056AD	)	S	Semi	-Anr	nual

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all content safety presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

## WORK-STATION PC

#### 3. Clean workstation PC.

15 9

7

- 1. Remove workstation PC support bracket.
- Disconnect cabling from the back of the workstation PC.
- 3. Remove the workstation PC from the FFT shelf and place on the floor.
- 4. Remove the workstation PC cover.
- Carefully vacuum the interior of the workstation PC.
- 6. Replace the workstation PC cover.
- 7. Replace workstation PC on FFT shelf.
- 8. Re-connect all cabling to workstation PC.
- 9. Install workstation PC support bracket.

## WARNING

Be cautious when working around or on equipment when power has been applied.

FFT

4. Restore equipment to service. Restore 2 equipment to service as prescribed by the current local procedure providing lockout/restore procedures. Verify PC communicates with FCS server and operates properly by printing test labels.

**CLEAN UP** 

 Clean up. Remove maintenance materials and 2 All equipment from the work area. Report all deficiencies to supervisor.

Maintenance Technical Support Center

U.S. Postal Service								IDENT	FICAT	ION					
Maintenance Checklist		RK DE			_		MENT NYM				ASS DE	N	UMBI	≣R	TYPE
	0	3	C	F	S					F	Α	0	0	6	М
Equipment Nomenclature	Equ	Equipment		del				Bulle	tin File	name	(	Occurr	ence		
Computer Forwarding System		CFSII							/M08	056AD	)	S	Semi	-Anr	nual

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Gomponent	140	(Comply with all current salety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

## THIS PAGE BLANK

### COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST

Forwarding Control System
03-CFS-GA-007-M
DAILY

Time Total: 11 Minutes

#### NOTE

Time in the estimated time column is given in minutes.

Reference: MS-120, Volume A-C

U.S. Postal Service								IDEN	NTIF	CAT	ON					
Maintenance Checklist		RK DE			_		MENT NYM					ASS DE	N	UMBI	ĒR	TYPE
	0	3	C	F	S						G	Α	0	0	7	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del				Bu	lletin	Filer	name	(	Occurr	ence		
Computer Forwarding System		CFSII							M	M080	056AD	)			aily	

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	NO	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### SAFETY STATEMENT

 COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

## THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### **WARNING FOR EWP/PPE:**

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

#### WARNING

Be cautious when working around or on equipment when power has been applied.

#### FORWARDING CONTROL SYSTEM (FCS)

2. Verify backup.

Use the Data Express Backup Utility log to verify successful tape backup of the FCS server.

- From FCS Server, login with the Supervisor account.
- 2. Select Launch Data Express Backup Utility.
- 3. At the Data Protector Express Login, press
- 4. Under favorites, select Recent Logs.
- Sort the list by the Start Time in descending order.

All

5

9

U.S. Postal Service								IDE	NTIF	ICAT	ON					
Maintenance Checklist		RK DE			_		MENT NYM	•				ASS DE	N	UMBI	≣R	TYPE
	0	3	С	F	S						G	Α	0	0	7	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del				В	ulletin	Filer	name	(	Occurr	ence		
Computer Forwarding System		CFSII							M	M08	056AD	)			aily	

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	NO	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

- 6. Verify backup took place at scheduled time.
- 7. Close Data Express Backup Utility.

FCS 3. Verifying drive status.

5 9

- 1. Select Launch Array Configuration Utility from the FCS Server Tray.
- 2. Next to Configuration View, left-click once on Show Physical View.
- 3. Verify that there are two drives listed under SAS Array A.
- 4. Under Controller State clear all status messages.

Status message accompanied by a red X should be reported to MTSC.

5. Exit the Array Configuration Utility by selecting Exit ACU.

Maintenance Technical Support Center

													_		
U.S. Postal Service							IDE	NTIF	ICATI	ON					
Maintenance Checklist	_	RK DE				 MENT NYM	•				ASS DE	N	UMBI	ΞR	TYPE
	0	3	С	F	S					G	Α	0	0	7	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del			В	ulletin	Filer	name	(	Occurr	ence		
Computer Forwarding System		quipment Model CFSII						M	M080	056AD	)			aily	

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

## THIS PAGE BLANK

## **COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST**

Forwarding Control System
03-CFS-GA-008-M
WEEKLY

Time Total: 11 Minutes

### **NOTE**

Time in the estimated time column is given in minutes.

ΑII

8

9

U.S. Postal Service							IDE	NTIF	CAT	ON					
Maintenance Checklist		RK DE			_	 MENT NYM	•				ASS DE	NI	JMBI	₽R	TYPE
	0	3	С	F	S					G	Α	0	0	8	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del			В	ulletin	Filer	name	(	Occurr	ence		
Computer Forwarding System				CFS	SII			M	M080	056AD	)		W	eekly	/

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	NO	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### SAFETY STATEMENT

 COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shutdown and lockout this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the

## THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### WARNING FOR EWP/PPE.

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

#### WARNING

Be cautious when working around or on equipment when power has been applied.

#### FORWARDING CONTROL SYSTEM (FCS)

2. FCS shutdown.

equipment.

#### NOTE

Performing this shutdown will re-initialize parameters and memory, promoting better system performance.

#### FCS shutdown:

- 1. Select server using Raritan CompuSwitch.
- 2. Login using Supervisor Account.
- 3. From the FCS Server Tray select Shutdown.
- 4. At the Server Tray popup, select Yes.

U.S. Postal Service							IDE	NTIF	ICATI	ON					
Maintenance Checklist	_	RK DE				 MENT NYM	•				ASS DE	NI	UMBI	ΞR	TYPE
	0	3	C	F	S					G	Α	0	0	8	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del			В	ulletir	Filer	name	(	Occurr	ence		
Computer Forwarding System		CFSII						M	M080	056AD	)		W	eekly	/

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all content safety presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### Observe the following message:

"Notifying clients of Shutdown, please wait 90 sec."

5. When the system powers off, wait 30 seconds and power on the FCS Server.

FORWARDING CONTROL SYSTEM (FCS)

#### 3. Cleaning tape drive

1. Insert the HP DDS cleaning cartridge into the tape drive.

2

9

#### **NOTE**

The tape will load automatically and start the cleaning process. The cleaning process takes 60 seconds to complete.

2. Remove the tape and place an X in the next available box on the tape.

Maintenance Technical Support Center

U.S. Postal Service							IDE	NTIF	ICATI	ON					
Maintenance Checklist	_	RK DE			_	 MENT NYM	•			CL/ CO	ASS DE	N	JMBE	ĒR	TYPE
	0	3	С	F	S					G	Α	0	0	8	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del			В	ulletin	Filer	name	(	Occurr	ence		
Computer Forwarding System				CFS	SII			M	M080	056AD	)		We	eekly	/

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Gomponent	140	(Comply with all current salety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

## THIS PAGE BLANK

### **COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST**

Forwarding Control System 03-CFS-GA-009-M

Monthly

Time Total: 5 Minutes

### **NOTE**

Time in the estimated time column is given in minutes.

Attachment 10 1

ΑII

3

9

U.S. Postal Service								IDE	NTIF	CAT	ION					
Maintenance Checklist		RK DE			_		MENT NYM				_	ASS DE	N	JMBI	ĒR	TYPE
Maintenance Checkinst	0	3	С	F	S	ACRO	INI Y IVI				G	A	0	0	9	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del				В	Bulletin	File	name	(	Occurr	ence		ı
Computer Forwarding System				CFS	SII				MN	M08	056AD	)		Mc	nthl	y

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all content safety presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

SAFETY STATEMENT  COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### WARNING FOR EWP/PPE.

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

#### WARNING

Be cautious when working around or on equipment when power has been applied.

FCS UN-INTERRUPTIBLE POWER SUPPLY 2. APC UPS battery check.

- 1. Log in to the FCS Server using the supervisor account.
- 2. Select Launch APC UPS PowerChute Console from the FCS Server Tray.
- 3. Login using the supervisor account and select Connect.
- 4. From the APC PowerChute Business Edition Basic, select VIEW.
- 5. Select Device Properties.

MMO-124-12

U.S. Postal Service								IDE	NTIF	ICAT	ION					
Maintenance Checklist	_	RK DE					MENT NYM	•			_	ASS DE	N	JMBI	ĒR	TYPE
Mantenance Checkinst	0	3	С	F	S	TORC	714 1 101				G	A	0	0	9	М
Equipment Nomenclature	Equ	ipmer	nt Mo	del				В	ulletir	Filer	name		Occurr	ence		
Computer Forwarding System				CFS	SII				M	M08	056AD	)		Mc	nthl	y

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	s
Component	110	(Comply with all content safety presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

- 6. In Device Properties select Diagnostics.
- 7. Click on Self Test.
- 8. After the test has completed, select Close.
- 9. Select Console then Exit.

CLEAN UP

3. Clean up. Remove maintenance materials and 1 All equipment from the work area. Report all deficiencies to supervisor.

Attachment 10 3

Maintenance Technical Support Center

		IDENTIFICATION.														
U.S. Postal Service		IDENTIFICATION														
Maintenance Checklist	WORK EQUIPI									CLASS CODE		NUMBER			TYPE	
	0	3	С	F	S						G	Α	0	0	9	М
Equipment Nomenclature	Equipment Model						В	Bulletin Filename				Occurrence				
Computer Forwarding System	CFSII					MM08056AD						y				

Part or Component	Item No			Min. Skill		S	
Component	110	(Comply with all current safety precautions)	Time Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

## THIS PAGE BLANK

#### COMPUTER FORWARDING SYSTEM II MASTER CHECKLIST

Forwarding Control System
03-CFS-GA-010-M
QUARTERLY

Time Total: 19 Minutes

### **NOTE**

Time in the estimated time column is given in minutes.

Attachment 11 1

ΑII

U.S. Postal Service		IDENTIFICATION														
Maintenance Checklist		RK DE	EQUIPMENT ACRONYM								CLASS CODE		NUMBER		TYPE	
	0	3	С	F	S	lorte					G	A	0	1	0	М
Equipment Nomenclature	Equipment Model					В	Bulletin Filename				Occurrence					
Computer Forwarding System	CFSII					MM08056AD					ly					

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	NO	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

#### SAFETY STATEMENT

 COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found notify supervisor prior to proceeding with any further action on the equipment.

## THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

#### WARNING FOR EWP/PPE.

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

#### WARNING

Be cautious when working around or on equipment when power has been applied.

FCS MONITOR 2. **Clean monitor.** Use a clean lint free cloth and 1 All approved cleaner to remove dust from monitor.

FCS KEYBOARD 3.

 Vacuum keyboard. Vacuum keyboard to remove 1 All dust build-up.

DOOR FILTERS

4. Clean filters.

15 All

- 1. Remove front and rear door filters.
- 2. Vacuum filters.
- 3. Replace filters.

U.S. Postal Service		IDENTIFICATION													
Martin Commence Of the United		WORK EQUIPMENT							CLASS				UMBI	TYPE	
Maintenance Checklist	CODE					ACRO	MYNC			CODE					
	0	3	С	F	S					G	Α	0	1	0	M
Equipment Nomenclature	Equipment Model					Bulletin Filename				Occurrence					
Computer Forwarding System	CFSII				MM08056AD					ly					

Ī	Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
	Component	140	(Gomply with all current salety presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Freq.

CLEAN UP

 Clean up. Remove maintenance materials and 1 All equipment from the work area. Report all deficiencies to supervisor.

Attachment 11 3