MAINTENANCE TECHNICAL SUPPORT CENTER HEADQUARTERS MAINTENANCE OPERATIONS LINITED STATES POSTAL SERVICE

UNITED STATES POSTAL SERVICE Maintenance Management Order UNITED STATES POSTAL SERVICETM

SUBJECT: Preventive Maintenance Guidelines for the Mail

Processing Infrastructure (MPI)

DATE: May 31, 2013

NO: MMO-056-13

TO: All MPI (LAN) Offices FILE CODE: Z2

dgue:mm13016aa

		Online Change Record											
Change #	Change # Date Description of Change												
1	3/7/22	Attachment 2, quarterly, item 4, deleted redundant Step 3e.											

This Maintenance Management Order (MMO) provides Preventive Maintenance (PM) guidelines for the Mail Processing Infrastructure. This MMO supersedes MMO-026-10.

The workhours indicated in the workload estimate (Attachment 1) reflect the maximum annual workhours required to maintain each system. Management may modify task frequencies to address local conditions.

The minimum maintenance skill level required to perform each task is included in the Minimum Skill Level column of each checklist. This does not preclude higher level employees from performing any of this work.

WARNING

Various products requiring Material Safety Data Sheets (MSDS) may be utilized during the performance of the procedures in this bulletin. Ensure the current MSDS for each product used is on file and available to all employees. When reordering such a product, it is suggested that current MSDS be requested. Refer to MSDS for appropriate personal protective equipment.

WARNING

The use of compressed or blown air is prohibited. An alternative cleaning method such as a HEPA filtered vacuum cleaner, a damp rag, lint-free cloth, or brush must be used in place of compressed or blown air.

Web Access: http://mtsc.usps.gov

WARNING

Steps contained in this bulletin may require the use of Personal Protective Equipment (PPE). Refer to the current Electrical Work Plan (EWP) MMO for appropriate PPE requirements.

Maintenance Managers are to use these preventive maintenance guidelines when preparing the route sheets for local maintenance personnel. It is the responsibility of each Maintenance Manager to ensure all WARNINGS, CAUTIONS, and NOTES are included with each applicable task as part of the preparation of any local route sheets.

For questions or comments concerning this bulletin contact the MTSC HelpDesk, either online at MTSC>HELPDESK>Create/Update Tickets or call (800) 366-4123.

Robert E. Albert

Manager

Maintenance Technical Support Center

HQ Maintenance Operations

Attachments: 1. Summary Workload Estimate

2. Master Checklist: 03-LAN-AA-001-M: Weekly

3. Master Checklist: 03-LAN-AA-002-M: Quarterly

4. Master Checklist: 03-LAN-AA-003-M: Annual

SUMMARY
WORKLOAD ESTIMATE
FOR MPI

SUMMARY WORKLOAD ESTIMATE FOR MPI

Weekly Hours Per Site

			Routine	Non-	Total
	Routine		Servicing +	productive	Servicing
Operation	Servicing	Repair*	Repair Time	Time**	Per System
	(Hrs/Yr)		(Hrs/Yr)	(Hrs/Yr)	(Hrs/Yr)
7	40	12.0	52.0	5.2	57.2

Quarterly and Annual Hours Per MPI MDF/IDF

			Routine	Non-	Total
	Routine		Servicing +	productive	Servicing
Operation	Servicing	Repair*	Repair Time	Time**	Per System
	(Hrs/Yr)	(Hrs/Yr)	(Hrs/Yr)	(Hrs/Yr)	(Hrs/Yr)
7	4.8	1.44	6.24	0.62	6.86

Total time equals the total number of Intermediate Distribution Frames (IDF) and Main Distribution Frames (MDF) per site times multiplied by 6.86 plus 57.2 hours.

Example:

6 IDFs + 1 MDF = 7 Distribution Frames X 6.86 Hrs per Distribution Frame = 48.02 Hrs Total Time = 48.02 Hrs + 57.2 Hrs = 105.22 Hrs

NOTES

*Repair estimates based on 30% of servicing.

**Based on 10% of total servicing and repair.

MASTER CHECKLIST

03-LAN-AA-001-M

WEEKLY

Time Total: 46 Minutes

U.S. Postal Service								IDI	ENTIF	ICAT	ION					
Maintenance Checklist	WORK EQUIPMENT CODE ACRONYM											ASS DE	N	JMBE	ER	TYPE
	0 3 L A N										Α	Α	0	0	1	М
Equipment Nomenclature MPI Cabinet		ipmer	nt Mo	del				E	Bulletin Filename mm13016aa				Frequency WEEKLY			Υ

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all carrent salety productions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Weeks

SAFETY STATEMENT

1. COMPLY WITH ALL SAFETY PRECAUTIONS.

Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found, notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

MAIL PROCESSING INFRASTRUCTURE (MPIW)

- 2. Verify all installed switches are live and responding to Watch It.
 - 1. Log into MPIW.
 - 2. Verify all installed switches are live and responding to Watch It.

For any status light not in a green condition, access that device and investigate.

- 3. Review Kiwi Log Viewer.
 - a. Open Kiwi Log Viewer and verify that Kiwi is logging messages.
 - Inspect Kiwi log and note warning messages, report relevant error to local management, create 05 work order and then take appropriate action as required to resolve problems.
- 3. Log off. Log off MPIW. Keep MPIW powered 3 All on.

3 All

40

PS

10

MASTER CHECKLIST

03-LAN-AA-002-M

QUARTERLY

Time Total: 52 Minutes

3

ΑII

													-			
U.S. Postal Service								IDE	NTIF	ICAT	ION					
Maintenance Checklist	WORK CODE					EQUIPMENT ACRONYM					CLASS CODE		N	JMBI	ER	TYPE
	0 3 L A N								Α	Α	0	0	2	М		
Equipment Nomenclature MPI Cabinet	•							В	ulletir m		name 016aa		Freque Q	,	RTER	RLY

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component	110	(Comply with all carrent salety productions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Weeks

SAFETY STATEMENT 1. COMPLY WITH ALL SAFETY PRECAUTIONS. Disconnect power and apply lockouts when required by this instruction. Refer to current local lockout procedures to properly shut down and lock out this machine. Open equipment and inspect dust conditions. Check for suspicious dust or unusual debris. If any unusual substance is found, notify supervisor prior to proceeding with any further action on the equipment.

THE USE OF COMPRESSED OR BLOWN AIR IS PROHIBITED.

When cleaning is required, an alternative cleaning method such as a HEPA filtered vacuum cleaner or a damp rag must be used in place of compressed or blown air. A lint-free cloth or brush may be used on optical equipment only when other cleaning methods cannot be used. Report safety deficiencies to your supervisor immediately upon detection.

CABINET

2. Remove MPI IDF or MDF cabinet filter.

15 PS

10

NOTE

Structured wiring IDF or MDF cabinets and also MPI Phase 3 Lite may be of a different design. Clean the cabinet filter that filters the air drawn into the cabinet.

Remove the MPI IDF or MDF cabinet filter in back of the cabinet and in front of the fan, clean both sides with HEPA filtered vacuum cleaner and replace. On the gray Rittal cabinets deployed in most offices, the filter cover is held in place by 2 tabs on each side. On the black Damac cabinets deployed in Earthquake Zones 3 and 4, the filter can simply be lifted out.

UPS

3. Check UPS.

1 PS 10

CAUTION

Do not test battery by unplugging UPS. This removes equipment ground and may cause damaging surges when the UPS is reconnected.

U.S. Postal Service								IDE	NTIF	ICAT	ION					
Maintenance Checklist	_	RK DE					MENT NYM					ASS DE	N	UMBI	ΞR	TYPE
	0 3 L A N									Α	Α	0	0	2	М	
Equipment Nomenclature MPI Cabinet	Equ	ipmer	nt Mo	del				В	ulletir m		name 016aa		reque Q	,	RTER	RLY

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	s
Component	110	(Comply war an our out carety productions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Weeks

If the UPS is not a Tripp Lite SmartPro, follow the manufacturer's instructions provided with the UPS. The MDF cabinet may or may not have an UPS.

NOTE

Consult the Owner's Manual provided with UPS to determine location of indicators and switches since this will vary with model.

- Ensure the UPS battery is fully charged. On the Tripp Lite SmartPro UPS, at the bottom of the MPI cabinet, press the Mute/Test switch, hold it down for 5 seconds and then release. The UPS will momentarily switch to battery to test its charge. If the Red battery fail indicator turns on, the battery is low or the UPS is defective.
- 2. Close cabinet doors securely when finished.
- 3. Open work order to investigate and correct problems with UPS.

MAIL PROCESSING INFRASTRUCTURE (MPI)

4. Verify operations of all MPI Cisco switches.

- 30
- PS 10

- 1. Log on to the MPIW computer.
- 2. Open a telnet session to each MPI switch.
- 3. Perform following commands on each switch:
 - a. Show env all.
 - Display status of the Fan/Power Supply and Temp of the switch.
 - The following information should be displayed. Report any and all discrepancies. Take appropriate corrective actions.
 - a) #sh env all.
 - b) FAN is OK.
 - c) TEMPERATURE is OK.
 - d) POWER is OK.
 - e) RPS is NOT PRESENT.

U.S. Postal Service							IDE	NTIF	ICATI	ON					
Malutanana Okaalillat	WORK			Е	QUIF	MENT	•			CL/	ASS	N	UMBI	ΞR	TYPE
Maintenance Checklist	CODE	CODE ACRONYM									DE				
	0 3	3 L A N								Α	A	0	0	2	М
Equipment Nomenclature	Equipment Model						Bı	ulletir	Filer	name		Frequency			
MPI Cabinet								mı	m13	016aa	ı	C	(UÁF	RTEF	RLY

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill		Threshold	S
Component		(comply man an earliest earliest production)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Weeks

- b. Show interface status.
 - Verify defined/connected ports match local MPI documentation spreadsheet.
 - Ensure all defined ports are connected in the proper speed/duplex/trunking modes.
 - Generate work order to investigate and correct any differences between the switches and the documentation spreadsheet.
- c. Show interface.
 - 1) Check all interfaces for input/output errors.
 - Review the command results for excessive number errors. Report excessive error conditions. Take appropriate corrective actions.
- d. Show cdp neighbor.
 - Ensure the switch can see the MPI switches directly connected to it.
 - Review the output of the command to ensure that all trunks are connected. Report any and all faulty trunks. Take appropriate corrective actions.
- 4. Back up MPI switch configuration to MPIW.
 - a. Start tftp server on MPIW.
 - b. Copy startup config to MPIW.

CLEAN UP

5. **Clean up.** Ensure all tools, lubricants, rags, etc., are removed from the work area. Report all deficiencies to your supervisor.

MASTER CHECKLIST

03-LAN-AA-003-M

ANNUAL

Time Total: 80 Minutes

WIWIO-030-13		ı					1410			UTITION		oai			<u> </u>	
U.S. Postal S	Service	-	WORK	1		EC	QUIPME		DEN	NTIFICA		_ASS	L NII	JMBI	-D	TYPE
Maintenance (Checkl	ist	CODE				CRON					ODE	'''	JIVIDI	_1\	IIFE
ĺ			0 3	L	Α	N					Α	Α	0	0	3	М
Equipment Nomenclature			Equipme	nt Mo	odel		-		Bu	ılletin Fi			Freque			
MPI Cab	inet									mm1	3016a	а		AN	NUA	L
			- .	01.1							I E i	l s a:		-		
Part or Component	Item No	(C	ı ask Comply wi				struction tv preca		ns)		Est. Time	Min. Skill			esholo	IS
·		,							,		Req	Lev	Run Hours		eces	Weeks
											(min)		Tiouis		000)	
SAFETY STATEMENT	1.	COMPL' Disconn required local lo down a equipme Check f If any supervise further a THE US	nect point by this ockout and locent are for suspenses or praction of the contraction of	wer is in pro ck od picio al s ior on th	and nstruction out inspous of substruction to ne eq	app ction ires this ect lust ance proc	oly loo . Ref to pr mach dust or und is for eeding	cko er t rope ine cusu usu our	uts erly onc al al, wit	whereurren y shu Oper ditions debris notif h an	n t t n s. s. y	All				
		IS PROPULATION IN THE OST IS PROPULATION IN CLEANING VACUUM IN PLACE IN THE OST IS PROPULATION I	HIBITED Cleaning method cleaned cleaned color by the or being the color by the colo	D. g is lod er ol mpro orus y wh	s red such r a da essed hen d hen d	quire amp d or ay boother t saf	ed, ar a H rag m blowr e use clean	n a EP/ nus n ai d c ing	ilte A f t b ir. on mien	rnative filtered e used A lint optica ethod cies t	e d d :- il s					
CABINET	2.	Vacuum	cabine	et.							31	PS				
		Using Hareas of Open re all reac displacin cables in carefully touch covacuum.	dust ac ar door hable ng elec nside. vacuu ommunic	ccum of of surfa trica Ope m recation	nulation cabin aces. It cores from the cores from t	on or et an Ads a ont d able ables	n outsind care void and color of surfact or co	de (efull dan omr f ca ces.	of of only when the office of	cabine vacuur ging c nicatio net an Do no	t. n or n d	10				
SWITCHES	3.		Check fans. Visually check that all fans on switches are running.													
CABLES	4.	Inspect labeled required	and dre									PS 10				
MAIL	5.	Verify o	peratio	ns c	of all	MPI	Cisco	sw	/itc	hes.	30	PS				
PROCESSING		-	-						10							
INFRASTRUCTURE	•	J I														
(MPI)		2. Ope	n a tein	et se	ession	1 to e	acn IV	ı۲ı	SW	IICN.						

2 Attachment 4

3. Perform following commands on each switch:

a. Show env all.

MMO-056-13

U.S. Postal Service	IDENTIFICATION															
Matatanasa Obsalatist		PK	EQUIPMENT						CLASS			SS	NUMBER			TYPE
Maintenance Checklist	CC	DE	ACRONYM								CODE					
	0	3	L	Α	Ν						Α	A	0	0	3	М
Equipment Nomenclature	Equipment Model						В	Bulletin Filename					Frequency			
MPI Cabinet								mm13016aa					\L			

Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill	Thresholds			
Component	110	(Comply with all current safety precautions)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Weeks	

- Display status of the Fan/Power Supply and Temp of the switch.
- Review the command results for excessive number errors. Report excessive error conditions and take appropriate corrective actions.
- b. Show interface status.
 - Verify defined/connected ports match local MPI documentation spreadsheet.
 - Ensure all defined ports are connected in the proper speed/duplex/trunking modes.
 - Generate work order to investigate and correct any differences between the switches and the documentation spreadsheet.
- c. Show interface.
 - Check all interfaces for input/output errors.
 - Review the command results for excessive number errors. Report excessive error conditions and take appropriate corrective actions.
- d. Show cdp neighbor.
 - Ensure the switch can see the MPI switches directly connected to it.
 - Review the output of the command to ensure that all trunks are connected. Report any and all faulty trunks and take appropriate corrective actions.
- e. Show interface status.
 - Verify defined/connected ports match local MPI documentation spreadsheet.
 - Open work order to correct any differences between the switches and the documentation spreadsheet.
- 4. Back up MPI switch configuration to MPIW.
 - Start tftp server on MPIW.

													-			
U.S. Postal Service	IDENTIFICATION															
Maintenance Checklist							QUIPMENT ACRONYM				CLASS CODE		NUMBER		TYPE	
	0	3	L	Α	N						Α	Α	0	0	3	М
Equipment Nomenclature MPI Cabinet	Equipment Model						E	Bulletin Filename mm13016aa				Frequency ANNUAL				
WII I Gabinet						IIIIIIIIIII				ANNOAL			· L			

Ī	Part or Component	Item No	Task Statement and Instruction (Comply with all current safety precautions)	Est. Time	Min. Skill	Thresholds		
	Сотрологи		(Somply man an surront surely presidential)	Req (min)	Lev	Run Hours	Pieces Fed (000)	Weeks

b. Copy startup config to MPIW.

CLEAN UP

6. **Clean up.** Ensure all tools, lubricants, rags, etc., are removed from the work area. Report all deficiencies to your supervisor.