DDCS V4.1 · SEA OTTER

User manual

Replacement controller software for the DDCS V4.1 — daily use at the machine



github.com/JSFrouws/ddcs-4.1-Sea-Otter · docs/user-manual.md

For the person at the machine. Sea Otter is the replacement controller software for the DDCS V4.1 (`app/`). This manual covers daily use. Design background is in operator-procedures.md, the network API in api-reference.md.


> **Status (2026-10-18):** tested on the real controller with no motors connected: step-exact positions, real CAM programs up to 64 000 lines. **Not yet** run with motors, real limit switches or homing switches. Do the first real tests with the motors unpowered or able to move freely.

---

0. Installing

From a USB stick, no PC tools needed on the controller: usb-install.md. In short: copy the `ddcsv4` install folder to a FAT32 stick, set the IP address in `network.conf`, plug it in, switch on, then take the stick out. The browser panel and the API answer at `http://<that IP>:8080/`. To go back to the vendor software, see the same page. Remote access with a password: ssh-setup.md.

1. The screen



- **Top right**: active work offset (G54…), `Homed ✓/–`, and the machine **state** (READY, RUN, HOLD, E-STOP, LIMIT, DRIVES OFF, SIMULATE…).
- **Soft keys F1–F7** along the bottom: their labels change per screen. **F7 is always Page R** (next screen); **Shift then F7** goes back.
- **Right strip**: what **Tab**, **Shift** and **Mode** do right now.
- **Toasts** (white box near the bottom): the result of what you just did, or why a key was refused. Nothing is refused silently.

2. Keys

Key	Does
Mode	Run ↔ Jog. Jog is locked while a program runs or holds.
F7 Page R	Run → Files → Work → Tools → Macros → Settings → Run
Tab	Next pane on the screen (e.g. Toolpath ↔ Program)
Shift	ALT layer for the next key (lit while active): touch-off, Page R back, …
Y± / X±	Move in lists and tables; jog in Jog
Enter / Select / Modify	Open / accept / edit the focused item
Cancel	Back / discard
F1 Start	Start or resume the program
F2 Pause	Feed hold on **every** screen while something moves
F3 Reset	Stop on **every** screen. Also switches the drives on after DRIVES OFF

3. Daily procedure

3.1 Power up

1. Switch on. If the E-stop is pressed, release it. The banner tells you what's needed.
2. **Mode** → Jog. **F1 Home** if you want soft limits (not required). Reset stops homing.

3.2 Load a program

1. **Page R** → Files. **F3** switches Local / USB. **Y±** picks a file.
2. **F1 Load** (or Select). The whole file is checked first; an unsupported code is reported with its line number and the file is not loaded. Supported: G0–G3 (also in the G17/G18/G19 planes), G4, G10 L2/L20, G20/G21, G28, G53, G54–G59, drilling cycles G73/G81/G82/G83/G85/G89 with G80 and G98/G99, G90/G91, G94, M0/M1, M3/M4/M5, M6 (pause for a tool change), M7/M8/M9, M10/M11, M30. G40/G49/G61/G64 are accepted. G43 is accepted but ignored (no tool length compensation). G41/G42 (cutter compensation) and G84 (tapping) are refused.

3.3 Zero the workpiece

1. Jog to the part's edge (Jog: arrow keys; **F4 Step** picks 0.01 / 0.1 / 1 / 10 mm or continuous).
2. **Shift + the axis key towards the part** sets that axis: with an edge Ø set (Jog setup, or Tools › F3) it accounts for the radius (X+ edge → X = −Ø/2). Press the same key again to set 0 instead.
3. Z: touch the top, **Shift + Z−** → Z = 0.
4. Check with **Goto 0** (Jog F2): Z up to safe height, then XY to 0.
5. Several parts: **Jog F5 WCS** picks G55, G56…; on **Work** mark them **F4 In job** and Start runs the program on each one in turn.

3.4 Check, then run

F5 TryCut on Run cycles what Start will do:

Armed	What happens
Run	The real job
TryCut	Spindle off; Z goes once to the **clearance level** (work Z0 + Safe Z) and stays there. The machine flies the whole path in the air
Simulate	Nothing moves. The position readout turns **orange**: those coordinates are fictitious. Afterwards the real position is shown again. M0/M1/M6 pauses still stop it, just like a real run

F1 Start. A program started over the network counts down on the panel first (default 5 s); **Reset cancels**.

3.5 During the run

- **Overrides**: pendant switch OFF + hold the dead-man + turn the wheel: **X1 = feed**, **X10 = spindle** (2 % per click), **X100 = feed in 10 % steps**. Feed and spindle go up to **300 %**. The bars stop at 200 % and the number shows the rest in amber. **Rapid follows the feed down** and never goes above 100 %. Its bar is half width, so 100 % lines up on all three bars.
- **The speed is capped** at what the controller can actually deliver (960 mm/min per axis at 2000 steps/mm). A higher F or override runs at the cap.
- **F4 View** cycles **2D → ISO → CPU saver**. CPU saver hides the toolpath and redraws once a second, leaving more time for motion. After an E-stop or limit the view switches to ISO by itself.
- **M6 / M0**: the machine holds with a message ("change to T3, then Start"). Do the change, **F1 Start** continues.
- **F2 Pause** = feed hold (F1 resumes). **F3 Reset** stops; the lines done so far are remembered.

3.6 Resume after a stop

Run → **Tab** → Program. Pick the line (**Y±** one line, **X±** ten), **Select**. The bar shows what Start will restore (WCS, F, S, tool, coolant) and how it approaches: Z up, XY across, then down. **F1 Start**.

4. When the machine stops on its own

4.1 Controlled stop (no lost steps)

Settings › Homing & limits › Controlled stop on Reset, E-stop, limit — **on by default**. Reset, the E-stop and a limit switch all **brake along the path** at the axes' maximum deceleration, so the motors don't lose steps and the position stays valid: no re-homing, no re-zeroing. The machine runs on by the **braking distance**: about **1 mm** at full speed (measured). **Mount limit switches with at least that much room before the hard stop.** Switch it off and the stop is abrupt (≈ 0.3–0.5 mm), but a fast-moving motor may then lose steps.

4.2 E-stop

The E-stop is for **unexpected or unwanted movement**. It stops motion, spindle and outputs. **The drives stay on**, so the axes keep their position and holding torque. Release the button and the machine is ready again. Jog, or resume from a line. **To remove power, switch the machine off.**

4.3 Limit switch

The banner shows e.g. `X+ LIMIT`. Only that direction is blocked. **Mode** → Jog and:

- **back off** the switch (X− here): the limit clears by itself when the switch releases;
- or move **sideways** (Y) or **up/down** (Z): never blocked.

A program that was running has stopped with its progress remembered: resume as in 3.6.

4.4 DRIVES OFF

Only when someone switched the drives off (Jog F3, or over the network). The banner says who. **F3 Reset** on any screen switches them on again.

5. Macros

Page R → Macros. **Y±** pick, **Select / Enter / F1** run. **Reset** stops any macro.

Macro	Does
Safe Z	Z up to work Z0 + Safe Z (only ever up)
Go to work zero	Z up, then X Y to the active work zero
Park	Z up, X Y to the park position, Z to its height *(homed machine only)*
Tool change position	Same, to the tool-change position *(homed machine only)*
Spindle warm-up	Spindle at the warm-up speed for the warm-up time, then off
Zero all	X Y Z of the active work offset = the current position

Positions, speed and time: *Settings › Macros* (machine coordinates).

6. Settings

Page R → Settings. Left: groups, right: values. Quick press / Modify / Enter starts editing. On/off, lists and small numbers change in place with Y± (or hold + wheel); larger numbers open the digit editor. **Enter accepts, Cancel discards.** Moving past the first or last value goes back to the groups, so the pendant alone can do everything.

- **Grey values don't apply** right now, and the reason is shown (e.g. "API is off"). They can't be edited until the setting they depend on is changed.
- Values marked **idle only** (machine settings) can't change while anything moves.
- **F2** restores this machine's original values. **F4** exports the settings to USB.

Useful ones: *Display › Default toolpath view* (2D / ISO / CPU saver) · *Jog & touch-off › Safe Z* · *Homing & limits › Controlled stop* · *Network & API › Allow remote START* (on by default; switch off if you don't want a network client to start programs) · *Pendant › Reverse wheel direction*.

7. The pendant (optional)

Input	Does
Wheel, dead-man released	**Moves the focus**: list items, settings, digit cursor, view
Wheel, dead-man held, switch OFF	**Changes** the focused value; while running: overrides
Wheel, dead-man held, switch X/Y/Z/4	**Jogs** that axis 0.001 / 0.01 / 0.1 mm per count (refused while running)
Quick press of the dead-man (switch OFF)	**Enter** on the focused item
Pendant E-stop	Same as the panel E-stop (§ 4.2)

8. Network

The controller serves a browser panel and the API on port 8080 (`http://<controller-ip>:8080/`). Every panel action is also an API call; see api-reference.md. Programs can be uploaded and started remotely. A remote start always counts down on the panel first, and Reset cancels it.

9. Known limits (2026-10-18)

- Not yet tested with motors, real limit/home switches or a probe (probing is not configured).
- Loading a very large file (64 000 lines) takes ~4 s, and the panel freezes for that time.
- G84 tapping and tool length compensation (G43) are not supported.
- `G28` without axis words sends all axes to machine zero **together**, not Z first, as written in the program. Check CAM output before the first real run.