**Invoice #2450** 

Name: Jamie Florence

Address: 310 S 16th ST

Selah WA 98942

Year: 1998

**Model:** 355 F1

Page 1 of 3

**Telephone:** 415-297-9958

 Date:
 3/10/2024

 Make:
 Ferrari

 Miles in:
 41,912

 Miles out:
 41,938

SEVEN/LAKES

166221 10th Avenue NW Arlington WA 98223 360-202-5220

Parts and Labor required		Labor Cost		Part Number	Part Description	Parts Cost	<b>Total Cost</b>		
Email: jamie@microforensics.com									
VIN: ZFFXR41A2W0111503 LIC: CAK8137	\$	1					\$ -		
Assembly #	\$	-					\$ -		
	\$	1					\$ -		
	\$	-	1	355 timing belt	30k svc kit	\$ 3,450.00	\$ 3,450.0		
	\$	1	2	184986	Timing belts	kit			
Perform Major service and timing belt replacement.	\$	7,800.00	2	167464	Belt tensioner bearings	kit			
Perform vehicle inspection and document needs.	\$	ı	1	163620	S/P cover gasket	kit			
Pre service emissions test	\$	1	1	163621	S/P cover gasket	kit			
Pre service scan of engine control units.	\$	1	4	114808	Cam bolt o-ring	kit			
Pre service scan of suspension control unit.	\$	-	1	176156	Cam cover gasket	kit			
Pressure test cooling system and inspect for leaks.	\$	-	1	176157	Cam cover gasket	kit			
Pre service compression and leak down test.	\$	-	8	149554	S/P o-ring	kit			
Replace front crank seals	\$	-	4	163987	Cam seal	kit			
Document cam timing prior to teardown.	\$	-	4	158349	Cam o-ring	kit			
Replace all camshaft gaskets, camshaft seals	\$	-	2	117275	Cam end o-ring	kit			
Replace timing belts and tensioner bearings.	\$	-	2	140787	Cam end gasket	kit			
Retime camshafts to factory specs.	\$	-	1	199830	A/C belt	kit			
Replace all accessory belts	\$	-	1	199833	Alternator belt	kit			
Change engine oil and filter,	\$	_	1	199832	P/S belt	kit			
Change gearbox oil	\$	-	1	172537	Tensioner pulley	\$ 102.23	\$ 102.2		
Inspect clutch and squib seals,	\$	-	1	163985	Front crank seal	\$ 64.00	\$ 64.0		
Reinstall engine and make throttle balance and idle speed and	\$	-	2	186922	Fuel filter	kit			
mixture adjustments.	\$	-	2	10280060	Fuel filter gasket	kit			
Perform four wheel alignment due to chassis removal	\$	-	3	113910	Fuel filter gasket	kit			
Siginficant oil leaks from the rear main seal, front main seal, both	\$	-	6		gearbox 75-90	\$ 55.23	\$ 331.3		
timing belt drive pulley shafts, oil pan.	\$	-	4	127816	Fuel line o-ring	\$ 3.30	\$ 13.2		
	\$	-	1	197654	Oil filter	kit			
Replace timing belt driven shaft seals and reseal front cover and waterpump	\$	2,450.00	1	10263460	Oil drain gasket	kit			
Housing to engine block.	\$	-	1	10257060	Oil drain gasket	kit			
Rebuild waterpump assembly.	\$	200.00	10	5w40	engine oil, QS Euro blend	\$ 18.50	\$ 185.0		

Replace thermastat		\$	-	2	159923	Coolant drain plug	\$ 8.41	\$ 16.82
Replace all coolant hoses. With silicon hoses and clamps	!	\$ 75	0.00	2	144810	Gearbox drain/fill ring	\$ 20.31	\$ 40.62
				1	5355000	silicone hose kit	\$ 630.00	\$ 630.00
		\$	-	4		Engine degreaser	\$ 30.44	\$ 121.76
		\$	-	1	gray	sealant	\$ 45.75	\$ 45.75
		\$	-	12	parts wash	solvents	\$ 9.99	\$ 119.88
		\$	-	2	104919	locknut	\$ 42.00	\$ 84.00
		\$	-	2	170787	front bearing drive	\$ 204.12	\$ 408.24
		\$	-	2	136140	oring	\$ 4.20	\$ 8.40
		\$	-	1	142472	oring rear	\$ 45.63	\$ 45.63
		\$	-	4	162769	motor/gearbox mount	\$ 348.23	\$ 1,392.92
		\$	-	1	153921	front cover gasket	\$ 36.65	\$ 36.65
				2	154984	Exhasut gaskets	\$ 36.00	\$ 72.00
		\$	-	1	183581	rear crankshaft seal	\$ 208.23	\$ 208.23
		\$	-	1	164556	Air injection tube	\$ 640.00	\$ 640.00
		\$	-	2	171177	inner bearing timing control	\$ 36.55	\$ 73.10
		\$	-					\$ -
		\$	-	3	Motule	Brake fluid	\$ 38.76	\$ 116.28
		\$	-	8		Parts wash	\$ 6.50	\$ 52.00
		\$	-	2	shell cool zone	Coolant	\$ 28.00	\$ 56.00
		\$	-	2	10280060	Radiator drain gasket	\$ 1.86	\$ 3.72
		\$	-	2	4902	Power steering fluid	\$ 11.00	\$ 22.00
		\$	-	8	169483	spark plugs	\$ 23.50	\$ 188.00
		\$	-	1	183759	Water pump seal	\$ 380.00	\$ 380.00
Car arrived with dead battery. Charge overnight and test. Battery		\$	-	1	143742	Water pump bearing	\$ 116.00	\$ 116.00
fails test. Installed new battery.	,	\$ 20	0.00	1	AGM platimun	Group 34	\$ 337.04	\$ 337.04
		\$	-	1	137868	oring	\$ 26.00	\$ 26.00
		\$	-	1	131736	oring	\$ 18.45	\$ 18.45
		\$	-	2	67546800/64610100	wiper blades	\$ 110.00	\$ 220.00
		\$	-					\$ -
		\$	-					\$ -
		\$	-					\$ -
Replace oil lines from block to the engine dry sump.		\$ 60	0.00	1	145040	oil line	\$ 912.47	\$ 912.47
		\$	-	1	145039	oil line	\$ 1,839.00	\$ 1,839.00
Repalce CV boots due to torn boots on RH axle.			0.00	2	dowty washers			\$ -
Replace Axle seals at the same time as CV boots			0.00		-			\$ _
-		\$	-	4	7006021	cv boot kit	\$ 124.45	\$ 497.80
				4	Moly grease	CV joint grease	\$ 18.23	72.92

				1	133628	axle seals RH	\$	81.47	\$	81.47
				1	141509	Axle seal LH	\$	81.47	\$	81.47
		\$	-	2	139453	Oring	\$	18.51	\$	37.02
		\$	-	1	177720	gearbox gasket	\$	34.83	\$	34.83
Replace gearbox and engine mounts, colapsed.		\$	450.00	1	177719	Gearbox gasket	\$	12.23	\$	12.23
		\$	-	1		set triple seals sf	\$	89.00	\$	89.00
		\$	-	1	170894	input shaft seal	\$	89.23	\$	89.23
				1	165539	bearing	\$	186.00	\$	186.00
		\$	-	1	104984	input shaft oring	\$	128.00	\$	128.00
Gear oil leak into bellhousing area has contaminated clutch.		\$	1,850.00	2	166432	clutch hydraulic oring	\$	16.00	\$	32.00
appears triple seals have failed between the inner and ourter shafts.		\$	-	1	143178	clutch support oring	\$	23.00	\$	23.00
Pull bellhousing, inspect clutch level.		\$	-	1		dual mass flywheel rebuild kit	\$	489.00	\$	489.00
Reseal throw out bearing, triple seals, input shaft seal.		\$	-	1	157754	clutch	\$	3,450.00	\$	3,450.00
Replace input shaft seal behind throw out bearing flange.		\$	-	1	103877	pilot bearing	\$	89.00	\$	89.00
Rebuild dual mass flywheel. Replace clutch as needed.		\$	-	1	CRB355f1s	Throw out bearing.	\$	1,320.00	\$	1,320.00
Self learn all F1 parameters.		\$	-	1	171307	F1 sensor	\$	1,189.00	\$	1,189.00
shipping aqnd customs		\$	-	1	anticipated	shipping and customs	\$	250.00	\$	250.00
				1	159507	Clutch friction surface	\$	1,589.00	\$	1,589.00
		\$	-	3	166595	clutch stop bolt	\$	26.32	\$	78.96
Desposit received via wire transfere 3/18/2024 \$21,000		\$	-	9	14305674	Clutch cover bolts	\$	9.85	\$	88.65
		\$	-	10	142202	vibration dampner	\$	33.17	\$	331.70
		\$	-	1	171074	Foglamp switch	\$	320.00	\$	320.00
Refinish cam covers in factory red Wrinkle		\$	1,250.00	1	171076	unlock button	\$	320.00	\$	320.00
		\$	=						\$	-
Labor Total		,	17,350.00				F	Parts Total	\$	23,257.05
You are hereby authorized the above repair work to be done along with the necessary labor and materials. You grant us permission to operate your vehicle for the purposes of testing, inspection, or delivery at your					Parts Total	\$ 23,257.05				
own risk. An express mechanic's lien is acknowledged on above vehicle to secure the amount of repairs					Labor Total	\$ 17,350.00				
thereto. We will not be held responsible for loss or damage to the vehicle or articles left in the vehicle in				Haz \	Waste, Supplies	\$ 250.00				
This estimate is valid for 30 days. This is only an estimate. Occasionally, upon commencement of the repair additional worn or damaged parts may be discovered. All additional parts and labor that exceed 10% of this estimate will require further customer					Subtotal	\$ 40,857.05	Denosit		d	S21,000.00
approval.				Subtotal Tax 9.1%		\$ 3,717.99	Deposit		,	21,000.00
					Total	\$ 44,575.04	Balance	÷	9	23,575.04
Customer Signature:	Date:			_ 7	Γhank you!					