

Field Engineering Case Study

Root-Cause Diagnosis of a 14CM15 Continuous Miner Tram Failure

Jason Duran Dutton

Overview

This case study describes a field troubleshooting event that occurred while working as an underground electrician in a coal mine. The event demonstrates systematic root-cause analysis, diagnostic test design, and technical decision-making under production pressure.

Situation

A 14CM15 continuous miner experienced a tram failure that brought production to a halt. The machine would no longer tram correctly, preventing the section from producing coal.

Initial troubleshooting performed by the section electrician suggested a possible fault within the pivot-head circuitry of the miner. Multiple continuity checks had already been performed, but no conclusive fault could be identified.

At this point, the operation faced increasing downtime costs while personnel continued searching for the source of the failure.

Challenge

The primary challenge was determining whether the fault existed within:

- Control circuitry
- Pivot-head wiring
- Field wiring
- Variable Frequency Drives (VFDs)
- Operator control systems

Traditional troubleshooting methods had narrowed the possibilities but had not identified the root cause.

Approach

Rather than continue repeating continuity tests, I decided to isolate the control and drive systems from one another.

The strategy was straightforward:

1. Remove the tram VFD panel.
2. Construct temporary diagnostic jumpers.

3. Connect the left tram VFD to the right-side tram control circuitry.
4. Observe whether the failure stayed with the controls or followed the drive.

The objective was to create a controlled diagnostic test that would eliminate multiple possible failure points simultaneously.

Execution

After removing the tram VFD panel and installing the diagnostic jumpers, the left-side drive was operated using the right-side control mechanism.

The results were decisive.

The controls functioned correctly through the alternate path, and the fault followed the left-side VFD rather than the control circuitry.

This immediately proved:

- The control system was operational.
- The pivot-head circuitry was operational.
- The wiring was operational.
- The fault existed within the left tram VFD.

The troubleshooting effort changed from searching for an unknown fault to replacing a confirmed failed component.

Result

The failed VFD required replacement at an approximate cost of \$20,000.

While the replacement was expensive, the diagnostic process prevented significantly larger production losses.

The operation was returned to coal production much sooner than if personnel had continued searching for wiring faults or replacing components based on assumptions.

The value was not simply identifying a failed drive.

The value was rapidly identifying the *correct* failed drive and minimizing downtime.

Technical Lessons

This experience reinforced several principles that continue to guide my engineering, software, and research work:

- Isolate variables whenever possible.
- Avoid repeatedly testing the same assumptions.
- Design experiments that eliminate multiple possibilities at once.
- Let evidence determine the root cause.
- Understand the cost of downtime when making technical decisions.

Professional Reflection

What I am most proud of is not finding a bad VFD.

What I am proud of is the reasoning process.

When existing troubleshooting reached a dead end, I stepped back, examined the system as a whole, and designed a test capable of proving where the fault truly existed.

That approach has remained consistent throughout my career.

Whether troubleshooting mining equipment, developing software systems, or conducting research, the process is the same:

Reduce the problem.

Isolate the variables.

Test assumptions.

Follow the evidence.

Core Competencies Demonstrated

- Electrical Troubleshooting
- Root Cause Analysis
- VFD Diagnostics
- Industrial Controls
- Systems Thinking
- Production-Critical Decision Making
- Engineering Problem Solving
- Risk Assessment