

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service	¬ =					
Cervice	Report		RMA Number	8005	59	
Customer Information:						
Company	Pacific Marine Environmer	ntal Lab			Date	7/1/2014
Contact	Shaun Bell					
PO Number	TBD					
Serial Number	er 430910					
Model Number	er SBE 43					
Services Requested: 1. Evaluate/Repair Instrumentation.						
Problems Found:						
The spar glass was cracked. Slow dry tau response found. The resolution was lower than expected. The membrane was wrinkled.						
Services Performed:						
Performed initial diagnostic evaluation. *						
2. Replaced the SBE 43 SPAR sub assembly. *						
3. Replaced the lid and membrane assembly (0.5 mil). *						
4. Replaced the electrolyte with new fluid. *						
5. Installed NEW board mounted battery. *						
6. Performed internal inspection and O-ring replacement. *						
7. Performed hydrostatic pressure test. *						
8. Performed "Final" calibration of the oxygen sensor. *						
9. Performed full diagnostic evaluation. *						
Special Notes:						
* All services we	ere performed at no charge.					

Page 1 of 1 Tuesday, July 01, 2014