

13431 NE 20th Street Bellevue, WA 98005 United States

+1-425-643-9866 www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

1005520964 **Service Request Date** SERVICE REPORT 02-JUL-2024 **Sales Order** 321000969

**CUSTOMER INFORMATION** 

Name: NOAA - PMEL PACIFIC MARINE ENVIRO LAB

Account: 40279844 DAVID STRAUSZ

DAVID.STRAUSZ@NOAA.GOV

206-526-4510

**Bill To Address** 

NOAA - PMEL PACIFIC MARINE ENVIRO LAB

7600 SAND POINT WAY NE

SEATTLE,WA,98115-6349,US

PO Number:

Phone

EA-133M-15-CQ-0039/1333MJ24F0016

**Ship To Address** 

NOAA - PMEL PACIFIC MARINE ENVIRO LAB SUPPLY CENTER / RECEIVING 7600 SAND POINT WAY NE, BLDG 8 SEATTLE, WA, 98115, US

#### PRODUCT INFORMATION

Item: 16.LEGACY

Item Description: (LEGACY) SBE 16 CT(D)

Serial: 194208-0655

**Special Notes** 

Services Requested:

SBS-SVC-16

CUSTOMER NOTES: Clock failed during last deployment. Note that this instrument has a digiquartz pressure sensor.

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
SERVICE16	Confirm / recertify SBE 16/16plus/16plusV2. Complete External Inspection. Test All Functions and input channel responses. Calibrate C & T. C&P and recal if necessary. Replace O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	1
PCAL16	Charge to calibrate SBE 16/16plus/16plusV2 pressure channel	1

Item	Item Description	Qty
22009	Lithium back-up battery (BR-2/3A-T2SP)	2



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

Service Request Date Sales Order

Phone

**1005520964** 02-JUL-2024 321000969

+1-425-643-9866

www.seabird.com

## PRODUCT INFORMATION

Item: 16P.LEGACY

Item Description: (LEGACY) SBE 16Plus (V1/V2) CT(D)

Serial: 19P68701-6902

**Special Notes** Services Requested: SBS-SVC-16

CUSTOMER NOTES: Connector for pump/comms is broken and needs replacing

Problems Found:

Connector J3 was non-operational.

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation.

Replaced connector J3. Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed "POST" cruise calibration.

Cleaned and replatinized the conductivity cell.

Performed a "Final" Calibration.

Item	Item Description	Qty
SERVICE16	Confirm / recertify SBE 16/16plus/16plusV2. Complete External Inspection. Test All Functions and input channel responses. Calibrate C & T. C&P and recal if necessary. Replace O-rings and Hydrostatic pressure test if necessary. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares or antifoulant replacement.)	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	1
REPLACEAF	Extra charge to install one antifoulant device, includes one 801542.1.	1

Item	Item Description	Qty
17628	Bulkhead connector, 6-pin Standard, AG-306-HP-SS	1
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
22009	Lithium back-up battery (BR-2/3A-T2SP)	3



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

+1-425-643-9866

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

 Service Request
 1005520964

 Date
 02-JUL-2024

 Sales Order
 321000969

Phone

## PRODUCT INFORMATION

Item: 16P.LEGACY

Item Description: (LEGACY) SBE 16Plus (V1/V2) CT(D)

**Serial:** 163611-0521

**Special Notes** Services Requested: SBS-SVC-16

CUSTOMER NOTES: Instrument clock failed during the last deployment.

Problems Found:

Battery bulkhead is corroded.

We are no longer able to repair this make and model of SBE 16.

The instrument will be returned "AS IS".



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

Service Request Date Sales Order

Phone

1005520964 02-JUL-2024 321000969

+1-425-643-9866

www.seabird.com

### PRODUCT INFORMATION

Item: FAA-015257

Item Description: ECO-Triplet-BBFL2-WB (700,CHL,CDOM)(25,50,375)

Serial: BBFL2WB-7201

**Special Notes**Services Requested:
SBS-SVC-ECOTRIPLE

CUSTOMER NOTES: Instrument read really high on the last deployment, appears to be out of spec.

**ECO Calibration and Repairs** 

Diagnosis: Evaluated instrument (BBFL2WB-7201) and found it required a head replacement.

Repairs and Modifications: Replaced head, tuned, calibrated, and standard service performed.

Comments: New Device file and characterization sheets included.

#### ECO Standard Service:

The instrument bulkhead connector, pressure housing and window\optics are inspected for damage. Instrument is checked to determine proper functionality. Incoming settings and memory are collected if incoming condition allows.

If applicable, a pre-service characterization is performed. Data is analyzed and Instrument is rescaled.

The head is inspected for cracks in detector and motor bores. Case seals, shaft, shaft seal, faceplate, wiper, desiccant pack, and batteries (if equipped) are replaced. Noise, stability, and live pressure test performed.

Final calibration and characterization is completed. Including calibration of thermistor and pressure sensor (if equipped). A device file, repair sheet, and new characterization sheets are provided to customer via USB.

Item	Item Description	Qty
SRVECOTRIPLET	Standard service includes evaluation, minor repairs, firmware updates, board modifications, calibration, and testing. This pricing does not include major repairs or shipping costs. Any additional repairs that are not listed will be quoted on an individual basis and provided with a revised service order after the technician examines the instrument.	1

Item	Item Description	Qty
EXA-ZX0064	BATTERY, 9v, Lithium	6
MAA-230330	FACEPLATE, Triplet-S, ECO	1
BAA-537894	ASSY, motor, wiper, Triplet-W	1
BAA-537894	ASSY, motor, wiper, Triplet-W	1
AXA-BX0067	BRD. Processor G4. ECO	1



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

SERVICE REPORT Date
Sales Order

 Service Request
 1005520964

 Date
 02-JUL-2024

 Sales Order
 321000969

KAA-015250	BBFL2W(700,CHL,CDOM),OptHd	1
BAA-251671	ASSY, power plug mount, ECO Trip-W	1
BAA-251621	ASSY, WIPER, TRIP-W or ECO-V2	1



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

Service Request Date Sales Order

Phone

**1005520964** 02-JUL-2024 321000969

+1-425-643-9866

## PRODUCT INFORMATION

Item: 39.LEGACY

Item Description: (LEGACY) SBE 39 Temperature (Depth) Recorder

Serial: 3965436-5474

**Special Notes** Services Requested: SBS-SVC-39

CUSTOMER NOTES: These all have prety old cals

Problems Found:

The thermistor guard is damaged.

Services Performed: Perform initial diagnostic evaluation. Replaced the thermistor guard. Performed "POST" cruise calibration. Replaced battery.

Item	Item Description	Qty
SERVICE39	Complete External Inspection. Test All Functions. Calibrate temperature channel, 11 points (-1 to 31 deg C). Replace end cap O-rings and Hydrostatic pressure test. Install new batteries. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares.)	1

Item	Item Description	Qty
233062	SBE39 THERMISTOR GUARD, V2, DN 233062	1
22074	SBE 39 lithium battery, UltraLife U9VL, 9V (spare)	1



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

+1-425-643-9866

(Do Not Send Payments To This Physical Address – See Remit to Information)

SERVICE REPORT Date

 Service Request
 1005520964

 Date
 02-JUL-2024

 Sales Order
 321000969

Phone

## PRODUCT INFORMATION

Item: 39.LEGACY

Item Description: (LEGACY) SBE 39 Temperature (Depth) Recorder

Serial: 3935165-1423

**Special Notes** Services Requested: SBS-SVC-39

CUSTOMER NOTES: These all have prety old cals

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Replaced the battery.

Item	Item Description	Qty
SERVICE39	Complete External Inspection. Test All Functions. Calibrate temperature channel, 11 points (-1 to 31 deg C). Replace end cap O-rings and Hydrostatic pressure test. Install new batteries. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares.)	1

Item Description	Qty
SBE 39 lithium battery, UltraLife U9VL, 9V (spare)	1



**SERVICE REPORT** 

## Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

ess – See Remit to Information)
Service Request

Phone

Date Sales Order **1005520964** 02-JUL-2024

+1-425-643-9866

www.seabird.com

321000969

## PRODUCT INFORMATION

Item: 39.LEGACY

Item Description: (LEGACY) SBE 39 Temperature (Depth) Recorder

Serial: 3935165-1420

**Special Notes** Services Requested: SBS-SVC-39

CUSTOMER NOTES: These all have prety old cals

Problems Found:

The connector is missing a pin.

Services Performed: Perform initial diagnostic evaluation. Replaced the connector. Replaced the O-rings.

Performed a hydrostatic pressure test. Performed "POST" cruise calibration.

Replaced the battery.

Item	Item Description	Qty
SERVICE39	Complete External Inspection. Test All Functions. Calibrate temperature channel, 11 points (-1 to 31 deg C). Replace end cap O-rings and Hydrostatic pressure test. Install new batteries. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares.)	1

Item	Item Description	Qty
17654	Bulkhead connector, 4-pin Standard, XSG-4-BCL-HP-SS	1
22074	SBE 39 lithium battery, UltraLife U9VL, 9V (spare)	1



**SERVICE REPORT** 

## Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

W

Phone

www.seabird.com

+1-425-643-9866

(Do Not Send Payments To This Physical Address – See Remit to Information)

Service Request

Date
Sales Order

**1005520964** 02-JUL-2024 321000969

## **PRODUCT INFORMATION**

Item: 39.LEGACY

Item Description: (LEGACY) SBE 39 Temperature (Depth) Recorder

Serial: 3935165-1424

**Special Notes** Services Requested: SBS-SVC-39

CUSTOMER NOTES: These all have prety old cals

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Replaced the battery.

Item	Item Description	Qty
SERVICE39	Complete External Inspection. Test All Functions. Calibrate temperature channel, 11 points (-1 to 31 deg C). Replace end cap O-rings and Hydrostatic pressure test. Install new batteries. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares.)	1

Item	Item Description	Qty
22074	SBE 39 lithium battery, UltraLife U9VL, 9V (spare)	1



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

Service Request Date Sales Order

Phone

**1005520964** 02-JUL-2024 321000969

+1-425-643-9866

## PRODUCT INFORMATION

Item: 39.LEGACY

Item Description: (LEGACY) SBE 39 Temperature (Depth) Recorder

Serial: 3935165-1638

**Special Notes** Services Requested:

PCAL39 SBS-SVC-39

CUSTOMER NOTES: This is the only one with a pressure sensor

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration. Performed "POST" cruise calibration.

Replaced the battery.

Item	Item Description	Qty
SERVICE39	Complete External Inspection. Test All Functions. Calibrate temperature channel, 11 points (-1 to 31 deg C). Replace end cap O-rings and Hydrostatic pressure test. Install new batteries. Includes typical repairs. (Does not include: Major electronic board replacement. Instruments deemed "Damaged Beyond Repair". Missing/damaged mounts or cables. Upgrades or modifications. Spares.)	1
PCAL39	Extra charge for pressure calibration	1

Gilbilion Rollio		
Item	Item Description	Qty
22074	SBE 39 lithium battery, UltraLife U9VL, 9V (spare)	1