CONT ON SHEET FL TITLE STANDING INSTRUCTIONS . 3S7507RA103C2 ---FIRST MADE FOR SH NO. REVISIONS Test Equipment Required A. AC Source - 0 to 20 volts - 60 Hz - 2 ampere capacity. Digital multimeter - Data Precision Model 1450 or equivalent. C. Capacitance Bridge - Acc \pm 0.5% = 0 to 10 mfd. Resistor - .95K to 1.05K - 1 watt. E. Drawings Assembly 44B360101 Rev 0 Elementary 440303900 Resistance and Capacitance Check A. Adjust 3P and 4P fully clockwise. Ter. to Ter. Resistance (Ohms) Capacitance (mfd) В. 30 9.5K to 10.5K 35 30 33 4,465 to 4,935 Adjust 4P CCW 35 13K to 17K 30 30 7965 to 11,435 33 Adjust 3P CCW 35 30 16.5K to 23.5K 30 33 10,465 to 17,935 Return 3P and 4P fully clockwise 12 10 1160 to 1260 10 1.8 to 2.2 11 30 34 3.6 to 4.4 C. Connect a lK resistor acorss terminals 44 and 45. Apply 20 \pm 0.15 VAC to ter. 43 and 36. Ter. 44(+) to $45(-) = 16.5 \pm 0.3$ VDC. Remove the AC voltage ter. 43 to 36. E. Adjust IP fully counter clockwise. G. Apply 10 \pm 0.05 VAC to ter. 60 and 61. Ter. 15(+) to 17(-) = 8.0 to 8.95 VDC. Ter. 16(+) to 17(-) = 3.4 to 5.1 VDC. DL13 3ELI H. Remove all power from the PC Board. PRINTS TO MADE BYW LUNSFORD BOOKS IN DRIVE SYSTEMS DIY OR 2 7 8 A 4 5 7 3 mag E UE 1-22-80 FLSALEM, VA. LOCATION

PRINTED IN U.S.A