g		GE Energy Services	Functional Testing Specification
	Parts & Repair Services Louisville, KY		LOU-GED-DS3800NHVE

Test Procedure for a High Voltage Card

DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column						
REV.	DESCRIPTION	SIGNATURE	REV. DATE			
A	Separated DS3800NHVE information into its own test from	D. Laemmle	8/20/2008			
	parent document DS3800NHVx.	Glenn Chandler				
В						
C						
D						
E						
F						
G						
Н						
I						
J						
K						
L						

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

PREPARED BY R. Duvall	REVIEWED BY D. Laemmle	REVIEWED BY	QUALITY APPROVAL Charlie Wade
DATE 07/19/02	DATE 10/14/02	DATE	DATE 8/20/2008

g

LOU-GED-DS3800NHVE REV. A

GE Energy Parts & Repair Services Louisville, KY Page 2 of 5

Functional test procedure for High Voltage Card

1. SCOPE

1.1 This is a functional testing procedure for a High Voltage Card

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
 - 3.1.1 UUT documentation folder

4. ENGINEERING REQUIREMENTS

- **4.1** Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- **4.2** Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - **4.2.1.1** Wires broken or cracked
 - **4.2.1.2** Terminal strips / connectors broken or cracked
 - **4.2.1.3** Loose wires
 - **4.2.1.4** Components visually damaged
 - **4.2.1.5** Capacitors leaking
 - 4.2.1.6 Solder joints damaged or cold
 - **4.2.1.7** Circuit board burned or de-laminated
 - **4.2.1.8** Printed wire runs burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Fluke 85 DMM (or Equivalent)
1		O-Scope
1		28 VDC Power Supply
1		SCR Firing Box

6. TESTING PROCESS

6.1 Testing Procedure

6.1.1 Attenuator Resistor Test (Resistive)

DS3800NHVE	Point A	Point B	Value	Point B
Circuit # 1	JA-5	JA-2	20K +/2%	Bergs:BJ1-BJ5 to H Pos
Circuit # 2	JA-3	JA-2		
Circuit # 3	JA-6	JA-2		
Circuit # 4	JA-7	JA-2		
Circuit # 5	JA-4	JA-2		
Circuit # 1	JA-5	JA-2	10K +/1%	Bergs:BJ1-BJ5 to L Pos
Circuit # 2	JA-3	JA-2		
Circuit # 3	JA-6	JA-2		
Circuit # 4	JA-7	JA-2		
Circuit # 5	JA-4	JA-2		
Circuit # 1	JM1	JA4	996K +/4%	Jumper J1 to JH1
Circuit # 2	JN1	JA5		Jumper J2 to JH2
Circuit # 3	JP1	JA6		Jumper J3 to JH3
Circuit # 4	JQ1	JA3		Jumper J4 to JH4
Circuit # 5	JR1	JA7		Jumper J5 to JH5
Circuit # 1	JM1	JA4	498K +/2%	Jumper J1 to JL1
Circuit # 2	JN1	JA5		Jumper J2 to JL2
Circuit # 3	JP1	JA6		Jumper J3 to JL3
Circuit # 4	JQ1	JA3		Jumper J4 to JL4
Circuit # 5	JR1	JA7		Jumper J5 to JL5

6.1.1.1 Using the DMM verify the resistor values in table 1.

g

LOU-GED-DS3800NHVE REV. A

GE Energy Parts & Repair Services Louisville, KY

Page 4 of 5

6.1.2 Firing Circuit & LED Test

6.1.2.1 For the specific model being tested, use the information in table 3 to apply a non-isolated negative pulse from the SCR Firing box to each circuit and verify with the scope a controllable pulse train output on each circuit. (Reference Figure 1). See notes 1&2 for amplitude.

6.1.2.2 Using the information in table 3, probe each of the circuits positive input with the power supply common and verify that the LED for each circuit illuminates to full brightness.

6.1.2.3 TABLE 3

DS3800NHVE	SCR Box	SCR	Scope +	Scope	28 VDC +	Notes
	СОМ	Box		-		
		NEG				
Circuit # 1	JA-11	JA-12	JC-1	JC-2	JA-9	1,2
Circuit # 2	JA-13	JA-14	JD-1	JD-3	JA-9	1,2
Circuit # 3	JA-15	JA-16	JE-3	JE-4	JA-9	1,2
Circuit # 4	JA-17	JA-18	JF-3	JF-5	JA-9	1,2
Circuit # 5	JA-19	JA-20	JG-2	JG-5	JA-9	1,2
Circuit # 6	JA-21	JA-22	JJ-4	JJ-5	JA-9	1,2

TABLE

Note 1: NHVE amplitude is 17 volts. Note 2: 28 VDC COM to SCR Box COM

6.2 ***TEST COMPLETE *** SEAL POTS ON TEMP SENSOR **CARDS**

7. **NOTES**


Output voltages (Waveforms) of gate circuits are measured with output unloaded.

g

GE Energy Parts & Repair Services Louisville, KY Page 5 of 5

Oscilloscope Verification Examples:





17V Peak 5V/Div .5ms/Div