g		GE Energy	Functio	nal Testing Spe	cification
	Parts & Repair Services Louisville, KY		Lo	OU-GED-DS3800DG	BRA
	Test Procedure for a DS3800DGRA				
DOCU	MENT REVISION STATUS: Determined	by the last entry in the "REV" a	nd "DATE" colu	mn	
RFV	DES	SCRIPTION		SIGNATURE	REV DATE

DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column			
REV.	DESCRIPTION	SIGNATURE	REV. DATE
Α	Initial release	Steve Pharris	1/22/2010
В	Corrected Typographic Errors	Steve Pharris	12/11/2012
С			

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

PREPARED BY Steve Pharris	REVIEWED BY	REVIEWED BY	Charlie Wade
DATE 1/22/10	DATE	DATE	DATE 1/22/2010

LOU-GED-DS3800DGRA	g GE Energy	Page 2 of 8
REV. B	Parts & Repair Services Louisville, KY	

1. SCOPE

1.1 This is a functional testing procedure for a DS3800DGRA.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
 - **3.1.1** Check board's electronic folder for more information

4. **ENGINEERING REQUIREMENTS**

- 4.1 Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.
- **4.2** Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - 4.2.1.1 Wires broken, cracked, or loosely connected
 - 4.2.1.2 Terminal strips / connectors broken or cracked
 - 4.2.1.3 Components visually damaged
 - **4.2.1.4** Capacitors bloated or leaking
 - 4.2.1.5 Solder joints damaged or cold
 - 4.2.1.6 Circuit board burned or de-laminated
 - 4.2.1.7 Printed wire runs / Traces burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Fluke 87 DMM (or Equivalent)
1		Tenma Dual Power Supply

6. TESTING PROCESS

- 6.1 Setup
 - 6.1.1 See Notes

6.2 Testing Procedure

- 6.2.1 Install Jumper J4R
- **6.2.2** Verify DA9-TP1 = 27.4K ohms
- **6.2.3** Verify DA11-DA9 = 82.5K ohms
- **6.2.4** Verify DA2-DA9 = 18.2K ohms

LOU-GED-DS3800DGRA REV. B

GE EnergyParts & Repair Services Louisville, KY

Page 3 of 8

- **6.2.5** Verify DA9-TP3 = 18.2K ohms
- 6.2.6 Install Jumper J38R
- **6.2.7** Verify DA2-DA21 = Short
- **6.2.8** Verify DA28-DA29 = 100K-150K ohms as R11 is adjusted
- **6.2.9** Verify DA28-TP1 = 50K ohms
- **6.2.10** Verify DB19-DA6 = 22.1K ohms
- **6.2.11** Verify DA6-DA5 = 22.1K ohms
- **6.2.12** Verify DA5-DA11 = 100K ohms
- 6.2.13 Install Jumper J1R
- **6.2.14** Verify DA7-DA11 = 100K ohms
- 6.2.15 Install Jumper J2R
- **6.2.16** Verify DA7-DB23 = 221K ohms
- 6.2.17 Install Jumper J41R
- **6.2.18** Verify DA3-DB11 = 297.5K ohms
- **6.2.19** Verify DB27-TP22 = Short
- 6.2.20 Install jumper in saddle clamps C5 and C5A
- **6.2.21** Verify DA13-TP6 = Short
- **6.2.22** Verify DA13-DA29 = Short
- 6.2.23 Install Jumper J39R
- **6.2.24** Verify DA21-DB37 = 2.41M ohms
- **6.2.25** Verify DA10-TP5 = Short
- **6.2.26** Verify DA19-TP2 = Short
- 6.2.27 Install Jumper J43R
- **6.2.28** Verify DB29-DA31 = Short
- 6.2.29 Install Jumper J46R
- **6.2.30** Verify DB39-DB20 = Short
- 6.2.31 Install Jumper J45R
- **6.2.32** Verify DB20-DB17 = Short
- 6.2.33 Install Jumper J9R
- **6.2.34** Verify DA34-DA31 = Short
- 6.2.35 Install Jumper J47R
- **6.2.36** Verify DA33-DA31 = Short
- 6.2.37 Install Jumper J42R
- **6.2.38** Verify DA33-DB17 = Short

LOU-GED-DS3800DGRA REV. B

GE EnergyParts & Repair Services Louisville, KY

Page 4 of 8

- **6.2.39** Install Jumper J44R
- **6.2.40** Verify DB29-DB17 = Short
- 6.2.41 Install Jumper J8R
- **6.2.42** Verify DB7-DB21 = 0-10K ohms as R22 is adjusted
- 6.2.43 Install Jumper J7R
- **6.2.44** Verify DB2-TP1 = 3.27K ohms (must remove J14/J15)
- **6.2.45** Verify DB6-DA14 = 109.7K ohms
- **6.2.46** Verify DB32-DA14 = 82.5K ohms
- **6.2.47** Verify DB32-TP1 = 79.9K ohms
- 6.2.48 Install Jumper in R74 (Saddle Clamp)
- **6.2.49** Verify DB5-DB13 = 0-5K ohms as R21 is adjusted
- **6.2.50** Verify DA15-TP14 = 100K ohms
- 6.2.51 Install Jumper in C18 (Saddle Clamp)
- **6.2.52** Verify DA23-DB13 = 10K ohms
- **6.2.53** Install Jumper in R70 (Saddle Clamp)
- **6.2.54** Install Jumper in R73 (Saddle Clamp)
- 6.2.55 Install Jumper J11R
- **6.2.56** Verify DB18-R71 (Saddle Clamp) = Short
- **6.2.57** Verify DB18-R72 (Saddle Clamp) = Short.
- 6.2.58 Verify DB18-R68 (Saddle Clamp) = Short
- **6.2.59** Verify DB18-R69 (Saddle Clamp) = Short
- **6.2.60** Verify DB18-TP1 = Short
- 6.2.61 Install Jumper J12R
- 6.2.62 Verify DB13-R73 (Saddle Clamp) = Short
- 6.2.63 Install Jumper J13R
- **6.2.64** Verify DB16-DB13 = Short
- 6.2.65 Install Jumper J24R
- **6.2.66** Verify DB37-DB38 = 0-100K ohms as R8 is adjusted
- **6.2.67** Verify DB38-DB36 = 100K ohms
- 6.2.68 Install Jumper J6R
- **6.2.69** Verify DA17-DA25 = Short
- **6.2.70** Verify DA17-TP8 = Short
- 6.2.71 Install Jumper J3R
- **6.2.72** Verify TP6-DA25 = 1.221M ohms

LOU-GED-DS3800DGRA REV. B

GE Energy Parts & Repair Services Louisville, KY

Page 5 of 8

- 6.2.73 Remove anything installed at R112 and C28A
- **6.2.74** Verify DB15-DA25 = 1.15M ohms
- **6.2.75** Install Jumper in R112 (Saddle Clamp)
- **6.2.76** Install Jumper in C28A (Saddle Clamp)
- **6.2.77** Verify DB15-DA25 = 1M ohms
- 6.2.78 Install Jumper J18R
- **6.2.79** Verify DB26-TP1 = Short
- 6.2.80 Install Jumper J40R
- **6.2.81** Verify DB23-DB11 = 321K ohms
- 6.2.82 Install Jumper J34R
- **6.2.83** Verify DB11-TP1 = 110K ohms
- **6.2.84** Verify DB9-DA31 = Open
- **6.2.85** Verify DB9-DA31 = Short when SW2 is toggled in either direction
- 6.2.86 Install Jumper J25R
- **6.2.87** Verify DA12-DB4 = Short
- 6.2.88 Install Jumper J27R
- **6.2.89** Verify TP12-TP13 = Short
- 6.2.90 Install Jumper J23R
- **6.2.91** Verify DA30-TP9 = Short
- 6.2.92 Remove Jumper J23R
- **6.2.93** Verify DA30-DB12 = 1M ohms
- **6.2.94** Verify DA30-TP19 = 2M ohms
- 6.2.95 Install Jumper in R111 (Saddle Clamp)
- **6.2.96** Install Jumper in C29 (Saddle Clamp)
- **6.2.97** Verify DB12-TP12 = Short
- **6.2.98** Move Jumper at C29 to C29A (Saddle Clamp)
- **6.2.99** Verify DB12-TP12 = Short
- **6.2.100** Verify DA22-DA24 = 0-10K ohms as R23 is adjusted
- **6.2.101** Verify DA26-DA24 = 0-10K ohms as R23 is adjusted
- **6.2.102** Verify DA26-TP1 = 0-10K ohms as R13 is adjusted
- **6.2.103** Verify DB24-TP16 = Short
- 6.2.104 Install Jumper J33R
- 6.2.105 Verify DB38-TP24 = Short
- **6.2.106** Verify TP24-DB35 = 8.25K ohms

LOU-GED-DS3800DGRA REV. B

GE Energy Parts & Repair Services Louisville, KY

Page 6 of 8

- 6.2.107 Install Jumper J31R
- **6.2.108** Verify DB31-DB35 = 8.25K ohms
- **6.2.109** Install Jumper in R157 (Saddle Clamp)
- **6.2.110** Install Jumper in C42 (Saddle Clamp)
- **6.2.111** Install Jumper in C40 (Saddle Clamp)
- 6.2.112 Install Jumper in R158 (Saddle Clamp)
- **6.2.113** Verify TP1-TP24 = 0-1K ohms as R29 is adjusted
- **6.2.114** Verify Right side of C41-TP24 = 0-1K ohms as R29 is adjusted
- 6.2.115 Install Jumper J35R
- **6.2.116** Verify DB40-TP1 = 835 ohms
- 6.2.117 Verify DB40-TP20 = Short
- **6.2.118** Install Jumper in C40A (Saddle Clamp)
- **6.2.119** Remove Jumper in C40 (Saddle Clamp)
- 6.2.120 Remove Jumper J35R
- **6.2.121** Verify TP24-DB40 = 8K-9K ohms as R29 is adjusted
- **6.2.122** Verify TP24-DB8 = Short
- 6.2.123 Install Jumper J37R
- **6.2.124** Verify TP20-TP21 = 200K ohms
- **6.2.125** Verify TP21-DB14 = 100K ohms
- **6.2.126** Verify TP17-DB30 = Short
- **6.2.127** Verify TP11-DA32 = Short
- 6.2.128 Install Jumper J36R
- **6.2.129** Verify TP12-TP21 = 200K ohms
- 6.2.130 Install Jumper J26R
- **6.2.131** Verify DA18-TP13 = Short
- **6.2.132** Verify DA4-TP4 = Short
- **6.2.133** Verify DA27-TP7 = Short
- 6.2.134 Install Jumper J5R
- **6.2.135** Verify DA9-DA11 = 20K ohms
- 6.2.136 Set power supplies for +15VDC and -15VDC
- 6.2.137 Connect +15VDC to DB1
- 6.2.138 Connect -15VDC to DB2
- 6.2.139 Connect Com to DB3
- **6.2.140** Apply Power

LOU-GED-DS3800DGRA REV. B

GE Energy Parts & Repair Services Louisville, KY

Page 7 of 8

- **6.2.141** Verify DA16 = 0-15VDC as R20 is adjusted
- **6.2.142** Verify DA23 = -14-14VDC as R10is adjusted
- **6.2.143** Verify DB24 = .6-15VDC as R27 is adjusted
- **6.2.144** Verify DB22 = 0-15VDC as R17 is adjusted
- 6.2.145 Install Jumper J14R
- **6.2.146** Verify DB28 = 0- (-)15VDC as R9 is adjusted
- 6.2.147 Install Jumper J15R
- **6.2.148** Verify DB28 = 0-15VDC as R9 is adjusted
- 6.2.149 Install Jumper J16R
- **6.2.150** Verify DB10 = 0-15VDC as R7 is adjusted
- 6.2.151 Install Jumper J17R
- **6.2.152** Verify DB10 = 0- (-)15VDC as R7 is adjusted
- **6.2.153** Verify TP9-DA24 = Short
- **6.2.154** Verify TP4 = -10VDC
- 6.2.155 Set R15 to 0
- **6.2.156** Verify TP18 = -15-15VDC as R6 is adjusted
- 6.2.157 Push SW1 and verify no change at TP18
- 6.2.158 Set R15 to 100
- **6.2.159** Verify TP18 = -15-15VDC as R6 is adjusted
- 6.2.160 Push SW1 and verify .1VDC change at TP18
- **6.2.161** Verify DA4 = -10.75VDC
- **6.2.162** Verify DA1 = 0- (-)10.75VDC as R1 is adjusted
- **6.2.163** Verify DA8 = 0- (-)12VDC as R2 is adjusted
- **6.2.164** Apply 5VDC to DA11
- **6.2.165** Verify DA10 = 0-4VDC as R12 is adjusted
- 6.2.166 Apply -5VDC to DA11
- **6.2.167** Verify DA10 = 0- (-)4VDC as R3 is adjusted
- 6.2.168 Remove Jumper R158
- **6.2.169** Apply 5VDC to DB8
- **6.2.170** Verify TP20 = 0-4VDC as R19 is adjusted
- 6.2.171 Apply -5VDC to DB8
- **6.2.172** Verify TP20 = 0- (-)4VDC as R18 is adjusted
- 6.2.173 Apply 5VDC to DB12
- **6.2.174** Verify DB4 = 0-4VDC as R26 is adjusted

GE Energy
Parts & Repair Services
Louisville, KY

LOU-GED-DS3800DGRA REV. B

- 6.2.175 Apply -5VDC to DB12
- **6.2.176** Verify DB4 = 0- (-)4VDC as R16 is adjusted
- 6.2.177 Install Jumper J28R
- 6.2.178 Remove Jumper J27R
- 6.2.179 Remove Jumper J26R
- 6.2.180 Disconnect + and -15VDC from DB1 and DB2
- 6.2.181 Apply 5VDC to DB4
- **6.2.182** Verify DA32 = .4 .55VDC as R5 is adjusted
- 6.2.183 Install Jumper J29R
- 6.2.184 Apply -5VDC to DB4
- **6.2.185** Verify DA32 = -.4- (-).55VDC as R14 is adjusted
- 6.2.186 Reconnect +15VDC to DB1 and -15VDC to DB2
- **6.2.187** Apply 5VDC to DB14
- **6.2.188** Verify DB30 = 0-4VDC as R24 is adjusted
- 6.2.189 Apply -5VDC to DB14
- **6.2.190** Verify DB30 = 0- (-)4VDC as R25 is adjusted
- 6.2.191 Remove Jumper J31R
- 6.2.192 Remove Jumper J33R
- 6.2.193 Remove Jumper R157
- 6.2.194 Apply 5VDC to DB35
- **6.2.195** Verify TP24 = 5VDC
- 6.2.196 Apply -5VDC to DB35
- **6.2.197** Verify TP24 = -5VDC
- 6.3 ***TEST COMPLETE ***

7. NOTES

7.1 When adjusting pots, verify a smooth linear movement.

8. ATTACHMENTS

8.1 None at this time.