g		GE Industr	ial Systems	Functional	Testing Spe	ecification
Chapter 2 Renewal Services			LOU-GED-DS3800XDCD			
	Louisville,KY	Test P	rocedure for a	Lard Card		
DOCIII	MENT REVISION STATUS:	Determined by the last o	ntm: in the "BEV" o	nd "DATE" column		
REV.	WENT REVISION STATUS.	DESCRIPTION	nuy in the KEV a		SIGNATURE	REV. DATE
Α	Initial release				M. Starling	10/30/2002
В						
С						
© COP	YRIGHT GENERAL ELECTRI	C COMPANY				
	PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.					
	ARED BY e Starling	REVIEWED BY	REVIEWI	ED BY	Rober .	
DATE 10/30	/2002	DATE	DATE		DATE 11/04/02	TO AUROSO

g

LOU-GED-DS3800XDCD REV. A

GE Industrial Systems Renewal Services Louisville, KY

Page 2 of 5

Functional test procedure for a IGTO Load Firing Card

1. SCOPE

1.1 This is a functional testing procedure for a DS3800XDCD IGTO Load Firing Card.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
 - 3.1.1 DS3800XDCD Schematics
 - 3.1.2 This Document

4. ENGINEERING REQUIREMENTS

- 4.1 Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.2 Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - **4.2.1.1** Wires broken or cracked
 - 4.2.1.2 Terminal strips / connectors broken or cracked
 - **4.2.1.3** Loose wires
 - 4.2.1.4 Components visually damaged
 - 4.2.1.5 Capacitors leaking
 - 4.2.1.6 Solder joints damaged or cold
 - 4.2.1.7 Circuit board burned or de-laminated
 - 4.2.1.8 Printed wire runs burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Fluke 85 DMM (or Equivalent)
1		Oscilloscope
1		Function Generator
1		Bench Power Supply
1		12 Output Fiber Optic Module

LOU-GED-DS3800XDCD REV. A

GE Industrial Systems Renewal Services

Louisville, KY

Page 3 of 5

TEST SETUP

6.1 Connect power supply plug connector to JB on XDCD card.

g

- 6.2 Connect RED lead to +5V, YELLOW lead to +15V and BLACK lead to COM on power
- **6.3** Do not make any connections to JA, JC and JDC until instructed to do so.

TESTING PROCESS7.1 Apply power to supply, verify IMOK LED on XDCD card comes on. Verify listed voltages at the following locations with respect to COM.

POSITIVE 5 VOLTS	POSITIVE 15 VOLTS	
JDA13	JDA17	
JDB13	JDB17	
JDC13	JDC17	

7.2 Turn off power and check for continuity at the following locations.

FROM	ТО	
СОМ	JDA16, JDB16, JDC16	
СОМ	JDA16, JDB16, JDC16	
СОМ	JZ1, JZ3, JZ5, JZ7	
СОМ	JZ9, JZ11, JZ13	
JA9	JZ14	
JA12	JZ24	
JA11	JZ23	
JA14	JZ19	
JA13	JZ22	
JA16	JZ16	
JA15	JZ15	
JA18	JZ18	
JA17	JZ17	
JA20	JZ26	
JC5	JDA2, JDB2, JDC2	
JC1	JDA1, JDB1, JDC1	
JC3	JZ4	
JC8	JDA8, JDB8, JDC8	
JC10	JDA7, JDB7, JDC7	
JC30	JDA10, JDB10, JDC10	
JC32	JDA9, JDB9, JDC9	
JC34	JZ10	
JC27	JDA4, JDB4, JDC4	
JC23	JDA3, JDB3, JDC3	

[©] COPYRIGHT GENERAL ELECTRIC COMPANY

LOU-GED-DS3800XDCD REV. A GE Industrial Systems Renewal Services

Louisville, KY

Page 4 of 5

JC25	JZ8	
JC18	JDA6, JDB6, JDC6	
JC14	JDA5, JDB5, JDC5	
JC16	JZ6	
JC17	JDA12, JDB12, JDC12	
JC19	JDA11, JDB11, JDC11	
JC21	JZ12	
TP1	JA19, JZ25	
TP1	JDA20, JDB20, JDC20	

7.3 Turn power on and set DVM for DC volts, make the following checks.

g

FROM	то	VOLTAGE
COM	JA3, JDA15, JDB15, JDC15	APPROX. 1.62 VDC
COM	JDA14, JDB14, JDC14	APPROX. 0 VDC

7.4 Apply a LOW to JA7 and check following.

FROM	то	VOLTAGE
СОМ	JDA14, JDB14, JDC14	APPROX. 3.34 VDC
COM	JDA18, JDB18, JDC18	APPROX. 5 VDC

7.5 Remove LOW from JA7 and apply a LOW to JA5. Check the following.

FROM	то	VOLTAGE
COM	JDA18, JDB18, JDC18	APPROX. 0.2 VDC

- 7.6 Install test plug marked DS3800XDCD JC and JDC into their respective connectors.
- 7.7 Verify all gray transmit laser LED's are illuminated and equal in intensity.
- **7.8** Apply a LOW to JA5 and JA7.
- **7.9** Using one Fiber Optic cable insert the gray end into any one of the gray transmitters.
- 7.10 Insert the blue end of Fiber Optic cable one by one into each of the blue receivers; verify that it's respective LED on front edge of XDCD card illuminates. The LED should remain on when Fiber Optic cable is removed. This will verify that the SCR's hold after being triggered. Note: Only pull cable out of receivers and transmitters by the end connectors, or they may be damaged.
- 7.11 After all front edge LED's are illuminated, remove low at JA7. All LED's should go out.
- **7.12** Setup spare output on bench power supply for 12 VDC and turn off power supply.
- **7.13** Connect red and black power leads of the 12 Output Fiber Optic Module to the spare output you just setup.
- 7.14 Setup a Function Generator to output a 5 VDC TTL square wave at 25 kHz.
- 7.15 Connect the common of the spare power supply channel to the common of the Function Generator. Connect the positive output of the Function Generator to the + post of the 12 Output Fiber Optic Module.
- 7.16 Connect JA plug to JA connector and turn on power supply.

LOU-GED-DS3800XDCD REV. A GE Industrial Systems Renewal Services Louisville, KY

Page 5 of 5

- 7.17 Verify light is being emitted through the Fiber Optic cables.
- **7.18** Connect the 12 Fiber Optic cables to 12 of the receivers on the XDCD card. <u>Note:</u>
 Since there are 18 circuits and only 12 fiber optic outputs, 6 of the outputs will need to be moved to the other locations to complete tests.
- **7.19** Verify that the appropriate LED's on front edge of card are illuminated with respect to respective inputs on the front edge of card.
- **7.20** Setup an O-scope for 5 VOLT/DIV and 20µS TIME/DIV. Verify waveform in Section 8 Fig. 1 while monitoring JDA19, JDB19 and JDC19 respectfully.
- **7.21** Verify that when a cable is removed from a receiver it's respective LED will extinguish.
- 7.22 Move cables to other 6 locations and repeat step 7.20.
- 7.23 Allow unit to warm up and verify no failures occur.
- 7.24 END OF TEST

8. Oscilloscope Verification Examples:

