g	G	E Energy	Functional Testing Specification
	Parts & Repair Services Louisville, KY		LOU-GED-DS3800NFOA

Test Procedure for a Multi-purpose Option Card

REV.	DESCRIPTION	SIGNATURE	REV. DATE
Α	Initial release	Steve Pharris	4/22/2010
В	Simplified Procedure	Steve Pharris	4/27/2010
С			

© COPYRIGHT GENERAL ELECTRIC COMPANY

Hard copies are uncontrolled and are for reference only.

PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.

PREPARED BY Steve Pharris	REVIEWED BY	REVIEWED BY	QUALITY APPROVAL Charlie Wade
DATE 4/22/2010	DATE	DATE	DATE 4/28/2010

	g	
LOU-GED-DS3800NFOA	GE Energy	Page 2 of 9
REV. B	Parts & Repair Services	
	Louisville, KY	

1. SCOPE

1.1 This is a functional testing procedure for a DS3800NFOA.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
 - **3.1.1** Check board's electronic folder for more information

4. **ENGINEERING REQUIREMENTS**

- 4.1 Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.
- **4.2** Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - 4.2.1.1 Wires broken, cracked, or loosely connected
 - 4.2.1.2 Terminal strips / connectors broken or cracked
 - 4.2.1.3 Components visually damaged
 - **4.2.1.4** Capacitors bloated or leaking
 - 4.2.1.5 Solder joints damaged or cold
 - 4.2.1.6 Circuit board burned or de-laminated
 - 4.2.1.7 Printed wire runs / Traces burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
2		Fluke 87 DMM (or Equivalent)
2		Rainbow Box
1		DS3800 Power Supply
1		DS3800 Dual Connector Box
1		Fluke 5500A Calibrator
1		O-Scope
1		Daughter Board Emulator
1		10K Ohm Resistor
1		270 Ohm Resistor

LOU-GED-DS3800NFOA
REV. B

GE Energy
Parts & Repair Services
Louisville, KY

Page 3 of 9

6. <u>TESTING PROCESS</u>

6.1 Setup

- **6.1.1** Connect Dual DS3800 Connector box to rainbow boxes
- **6.1.2** Connect DS3800 Power Supply to either rainbow box (the dual connector box applies the proper voltages to all points on the card.)
- **6.1.3** Attach daughter card emulator to UUT
- 6.1.4 Connect PA1-PA9 and PB1-PB9

6.2 Testing Procedure

- **6.2.1** Apply power to UUT
- **6.2.2** Verify the following tables. (The following tables are read vertically. Meaning, once you meet the input requirements of the first vertical column the outputs of that column should match.)

INPUTS										
PA78	8		8	8		44.5	44.5	40.5	10.5	
(VDC)	8	8	8	8	8	11.5	11.5	13.5	13.5	8
PA32	1	0	0	1	1	1	0	0	1	1
PA28	0	0	1	1	1	1	1	0	0	1
PA26	0	0	1	1	1	1	0	0	0	1
PA70	1	1	1	1	1	1	1	1	1	1
PB28	0	1	1	0	1	1	1	0	0	0
OUTPUTS										
TA2	0	0	0	0	0	0	0	1	1	0
PA24	0	0	1	0	0	0	1	0	1	0
PA21	0	0	1	0	0	1	0	0	1	0
TA1	0	0	0	0	0	1	1	1	1	0
PA14	0	0	23	0	0	23	23	0	23	0
(VDC)	U	0	23	0	0	23	23	0	23	0

LOU-GED-DS3800NFOA REV. B

GE Energy Parts & Repair Services Louisville, KY

Page 4 of 9

6.2.3	Remove Power and all previous connections
6.2.4	Connect TB1-H
6.2.5	Connect PB46-H
6.2.6	Connect PB28-H
6.2.7	Connect PB18-L
6.2.8	Connect PB70-H
6.2.9	Apply Power
6.2.10	Verify PB16=L (if not toggle SW1)
6.2.11	Momentarily remove then reconnect PB18
6.2.12	Verify PB16=H
6.2.13	CR65=Off
6.2.14	Momentarily connect PB28 to L then tie H
6.2.15	Verify PB16=L
6.2.16	Connect TB1-L
6.2.17	Connect PB46-L
6.2.18	Connect TB1-H
6.2.19	Connect PB46-H (this sets the flip flop to "last state")
6.2.20	Connect PB46-L
6.2.21	Momentarily remove then reconnect PB18
6.2.22	Verify PB16=H
6.2.23	Toggle SW1
6.2.24	Verify PB16=L
6.2.25	Verify PB26=H
6.2.26	Connect PB28-L
6.2.27	Verify PB26=L
6.2.28	Connect PB28=H
6.2.29	Verify PB30=H
6.2.30	Connect PA30-L
6.2.31	Connect PA42-L
6.2.32	Verify PB30=L
6.2.33	Connect TB1-L

6.2.34 Connect PB46-L 6.2.35 Connect TB1-H

LOU-GED-DS3800NFOA
REV. B

GE Energy
Parts & Repair Services
Louisville, KY

Page 5 of 9

6.2.36 Momentarily connect PB46-H then reconnect to L **6.2.37** Momentarily remove then reconnect PB18 **6.2.38** Verify PB30=H 6.2.39 Toggle SW1 6.2.40 Verify PB30=L 6.2.41 Using the fluke 5500A Calibrator apply a 5V RMS sine wave to JA01 at 60Hz **6.2.42** Verify JA04 = 14V p-p sine wave in phase with input **6.2.43** Using the fluke 5500A Calibrator apply a 5V RMS sine wave to JA06 at 60Hz **6.2.44** Verify JA07 = 14V p-p sine wave in phase with input **6.2.45** Using the fluke 5500A Calibrator apply a 5V RMS sine wave to JA17 at 60Hz **6.2.46** Verify JA18 = 14V p-p sine wave in phase with input **6.2.47** Using the fluke 5500A Calibrator apply a 5V RMS sine wave to JA10 at 60Hz **6.2.48** Verify JA11 = 14V p-p sine wave in phase with input **6.2.49** Using the fluke 5500A Calibrator apply a 5V RMS sine wave to JA13 at 60Hz **6.2.50** Verify JA12 = 14V p-p sine wave in phase with input **6.2.51** Verify JA23 = H**6.2.52** Verify PB24 = L 6.2.53 Verify LED CR71 (tst) is off 6.2.54 Connect JA23 to JA21 **6.2.55** Verify PB24 = H 6.2.56 Verify LED CR71 (tst) is on **6.2.57** Verify JA24 is a 6V p-p sine wave +/- 1.5V **6.2.58** Verify JA25 is a 6V p-p sine wave +/- 1.5V **6.2.59** Verify JA26 is a 7V p-p sine wave +/- 1.5V **6.2.60** Verify that adjusting R290 varies the frequency at JA24 from 61Hz to 56Hz **6.2.61** Set R290 so JA24 = 60Hz +/- 2Hz 6.2.62 Verify JA25 is also 60Hz sine wave and lags JA24 by 120 degrees **6.2.63** Verify JA26 is also 60Hz sine wave and lags JA24 by 240 degrees **6.2.64** Connect JA01, JA06, JA10, JA13 to Common **6.2.65** Apply 10.5V to JA17 6.2.66 Verify CR69 (imok) is on **6.2.67** Increase voltage at JA17 to 12.5

6.2.68 Verify CR69 (imok) is off

6.2.69 Remove ground connections at JA01 and JA06

LOU-GED-DS3800NFOA
REV. B

GE Energy
Parts & Repair Services
Louisville, KY

Page 6 of 9

- **6.2.70** Connect JA24 to JA1
- **6.2.71** Connect JA25 to JA6
- **6.2.72** Verify TB25 is a 13V p-p 60Hz sine wave
- 6.2.73 Verify TB24 is an 8V p-p 60Hz sine wave and leads TB25 by 90 degrees
- 6.2.74 Verify TB1 is a 60Hz signal switching from L to H
- 6.2.75 Connect PA72 to Common
- **6.2.76** Apply a 151mV 60Hz sine wave to PB2
- **6.2.77** Toggle SW1
- **6.2.78** Verify TA27 = -15VDC
- **6.2.79** Verify TA6 = 0V
- **6.2.80** Verify TA21 = 0V
- **6.2.81** Verify PB25 = L
- **6.2.82** Verify TA19 = H
- **6.2.83** Verify CR66 (puls) is on
- 6.2.84 Increase voltage at PB2 to 604mV
- 6.2.85 Verify CR66 (puls) is off
- **6.2.86** Verify TA27 is oscillating from +4V to -15V at 60Hz (DC coupling on scope)
- **6.2.87** Verify TA6 is a 20V p-p 60Hz sine wave
- **6.2.88** Verify TA19 = L
- **6.2.89** Verify PB25 = H
- 6.2.90 Remove connection from PA72 to Common
- **6.2.91** Repeat steps **6.2.37** to **6.2.48** using a 50Hz frequency and verify all 60Hz signals are now 50Hz.
- **6.2.92** Apply .4VDC to JA01, JA06, and JA17
- 6.2.93 Connect JA11 and JA12 to Common
- **6.2.94** Verify TB12 = 4.8VDC
- **6.2.95** Verify TB17 = -4.8VDC
- **6.2.96** Verify TB20 = 4.8VDC
- **6.2.97** Verify TB23 = -4.8VDC
- **6.2.98** Verify TB14 = 4.8VDC
- **6.2.99** Verify TB13 = -4.8VDC
- **6.2.100** Verify TB6 = -.5VDC
- **6.2.101** Verify TB10 = -.5VDC
- **6.2.102** Verify TB5 = -.5VDC

LOU-GED-DS3800NFOA REV. B

GE Energy Parts & Repair Services Louisville, KY

Page 7 of 9

- **6.2.103** Verify TB3 = -.5VDC
- **6.2.104** Verify TB2 = -.5VDC
- **6.2.105** Verify PB23 = -.5VDC
- **6.2.106** Verify PA34 = H
- **6.2.107** Verify PA36 = H
- **6.2.108** Verify PA38 = L
- 6.2.109 Increase the input voltage to .5VDC
- **6.2.110** Verify outputs at **6.2.55 6.2.60** = 6VDC
- **6.2.111** Verify outputs at **6.2.61 6.2.66** = H
- **6.2.112** Verify PA34 = L
- **6.2.113** Verify PA36 = L
- **6.2.114** Verify PA38 = H
- 6.2.115 Apply 165mV RMS 60Hz sine wave to JA01, JA06, and JA17
- **6.2.116** Verify outputs at **6.2.55 6.2.60** = 6V p-p sine wave at 60Hz
- **6.2.117** Verify outputs at **6.2.61 6.2.66** = L
- **6.2.118** Verify PA34 = H
- **6.2.119** Verify PA36 = H
- **6.2.120** Verify PA38 = L
- 6.2.121 Increase the voltage at 6.2.76 to 530mV RMS
- **6.2.122** Verify outputs at **6.2.55 6.2.60** = 18V p-p sine wave at 60Hz
- **6.2.123** Verify outputs at **6.2.61 6.2.66** are switching from -.4V to +5V
- 6.2.124 Verify PA34 and PA36 are switching from L H
- 6.2.125 Verify PA38 is also switching from L H but inversely of PA34 and PA36
- 6.2.126 Toggle SW1
- **6.2.127** Connect 270 Ohm resistor between PB72 and Common
- 6.2.128 Connect a 10K ohm resistor between PB6 and PB36
- 6.2.129 Connect PA78 to Common
- 6.2.130 Connect PA76 to +15V
- **6.2.131** Apply 1VDC to PA80
- **6.2.132** Verify TA20 = H
- **6.2.133** Verify PB72 = 23VDC
- **6.2.134** Verify PB4 to PB34 = 0VDC
- 6.2.135 Verify CR70 (dcf) is on
- 6.2.136 Increase voltage at PA80 to 3.5VDC

LOU-GED-DS3800NFOA REV. B

GE Energy Parts & Repair Services Louisville, KY

Page 8 of 9

- **6.2.137** Verify TA20 = -15VDC
- **6.2.138** Verify PB72 = 0
- **6.2.139** Verify CR70 (dcf) is off
- **6.2.140** Verify PB4 to PB34 = 32VDC
- 6.2.141 Decrease voltage at PA80 to 1VDC
- 6.2.142 Toggle SW1
- 6.2.143 CR70 (dcf) is on
- **6.2.144** Verify PB72 = 23VDC
- **6.2.145** Verify PB4 to PB34 = 0VDC
- 6.2.146 Connect DMM to PA61
- **6.2.147** Connect DMM to TA15
- **6.2.148** Verify PA61 = 3.5VDC
- **6.2.149** Verify TP6 = -5.9VDC
- 6.2.150 (READ FIRST) Apply -18VDC to PA20 and -15VDC to PA44 simultaneously
- 6.2.151 Verify PA61 increases to -9.5VDC +/- 2VDC
- 6.2.152 Verify TA15 increases to 13VDC +/- 2VDC
- **6.2.153** Verify PA40 = -1.7VDC
- **6.2.154** Verify TA4 = -13VDC
- **6.2.155** Verify TP11 = 7VDC
- 6.2.156 Verify CR67 (tof)= off
- 6.2.157 Change -18VDC at PA20 to +15VDC
- 6.2.158 Verify TP11 = 0VDC
- **6.2.159** Verify PA61 = -6.3VDC
- 6.2.160 Reduce voltages at PA20 and PA44 to 0VDC and allow one minute reset time
- 6.2.161 Toggle SW1
- **6.2.162** Verify PA74 = 3.5VDC
- **6.2.163** Verify TA24 = -5.9VDC
- 6.2.164 (READ FIRST) Apply 10VDC to PA20 and -15VDC to PA44 simultaneously
- 6.2.165 Verify PA74 increases to -9.5VDC +/- 2VDC
- 6.2.166 Verify TP1 increases to 13VDC +/- 2VDC
- **6.2.167** Verify PB78 = 7VDC
- **6.2.168** Verify PA67 = -1.7VDC
- 6.2.169 Verify TA22 = -13VDC
- **6.2.170** Verify CR68 (tor) = Off

LOU-GED-DS3800NFOA REV. B

GE Energy Parts & Repair Services Louisville, KY Page 9 of 9

- 6.2.171 Change 10VDC at PA20 to -15VDC
- **6.2.172** Verify PB78 = L
- **6.2.173** Verify PA74 = -6.34VDC
- **6.2.174** Verify PA67 = 0VDC
- 6.2.175 Remove connection at PA20
- **6.2.176** Apply .5VDC to PA54
- **6.2.177** Verify PA55 = -11VDC
- 6.2.178 Change voltage at PA54 to -.5VDC
- **6.2.179** Verify PA55 = 11VDC
- 6.2.180 Move -.5VDC from PA54 to PA52
- **6.2.181** Verify PA55 = 11VDC
- 6.2.182 Remove voltage at PA52
- 6.2.183 Toggle SW1
- 6.2.184 Verify all LED's are on except IMOK and TST
- 6.3 ***TEST COMPLETE ***

7. NOTES

7.1 None at this time.

8. ATTACHMENTS

8.1 None at this time.