244A8610

2 sh no. 1

REVISIONS

Note

5/18/72

 $\omega$ 

CONT ON SHEET TITLE TEST INSTRUCTIONS \$1ip Guard Relay Module - With Meter 244A8610 SH NO. 1 FIRST MADE FOR CONT ON SHEET

For ease of test, card extender may be used. Allen wrench to position knobs is required.

Verify the following: C50 is 100 volt, 360MFD capacitor CR1 is securely fastened to heat sink Mechanically zero power factor meter Check with ohmeter on RX10,000 that CR1 is isolated from heat sink.


Set Trip PF and time delay full CCW. Jumper S (TB1) to T (TB1). Connect input transformer for 115 volt connection and apply 115 volts 60CPS to H1, H4. Momentarily, jumper R (TB1) to D (TB1). Relay RR should pick up and stay up. Check with ohmeter between X1 (TB2) and Z1 (TB2) that this is true

3. Measure voltage from SPFA pin 26 to pin 22. It should be +27 volts  $\pm 2V$ with less than .1V P.P. ripple. Power factor meter should read 1.0 power factor and voltage N (34) to COM (22) should be +5 volts DC. Adjust R65 on SPFA card if necessary to obtain unity power factor and 4.7 to 5.3 volts. Record this voltage as  $V_{\rm N}$ . Connect jumper from R to D.

Slowly turn TPF CW until relay drops out. This should occur when (6) to COM (22) is  $V_N$ .  $\pm \cdot 1$  volt. Position TPF knob on shaft so that pointer is opposite 1.0 PF when (6) to COM (22) reads the trip voltage. To reset remove AC for 10 sec. Repeat step 4 to see that relay now trips when TPF knob points to 1.0 PF and power factor meter reads 1.0 PF. Verify that power supply is still +27 volts  $\pm 2V$  with less than .1 volt PP ripple. Remove AC power. Remove R (TB2) to D (TB2) jumper.

5. Reapply AC power. Turn TPF full CCW and TD full CW. Push white button on RR and check that relay picks up and light lights. Wait 15 sec. then quickly snap TPF full CW and verify that RR drop out after roughly 1 sec. delay. Turn TD full CCW and repeat. Delay should now be almost instantaneous (.1 to .2 sec.) (times are not critical). Remove all power. Set TPF to max. CCW. Remove all jumpers.

6. Connect circuit per Fig. 1. Jumper R (TB1) to D (TB1). Reapply power.



MADE BY APPROVALS DIV OR 244A8610 Industry Control 13/2 ISSUED Salem, Virginia LOCATION CONT ON SHEET

FF-803-WF (2-71) PRINTED IN U.S.A

+

+

+

CODE IDENT NO.

1E A9

PRINTS TO

PR-1

244A8610

CONT ON SHEET FL SH NO. 2

REVISIONS

DELETED NOTE 8

244A8610

TITLE

TEST INSTRUCTIONS

Slip Guard Relay Module - With Meter

CONT ON SHEET FL SH NO. 2

FIRST MADE FOR

Use variable time and amplitude on scope to make channel 2 cover 10 divisions and both channel 1 and channel 2 to have same zero level (DC) and same peak to peak amplitude. Vary rheostat to obtain figure 2. Channel 1 should cross zero 3 divisions before channel 2. Verify that power factor meter reads .8 leading power factor  $\pm 5\%$ .

SAME HEIGHT




FIGURE 2

- 7. Switch to log position and obtain Figure 2 except channel 1 now reversed. Power factor meter should read .8 lagging  $\pm 5\%$ . Relay should be picked up. Slowly increase TPF CW and verify that relay drops when reach .8 +5%.
- 8. Set "TPF" to .8 lagging and "time delay" to .6 sec. and lock knobs with screwdriver. This completes test.

RICINA P6A <del>61</del> IEA9

PRINTS TO MADE BY 244A8510 D.C. Finch DIV OR Industry Control ISSUED Salem, Virginia FL LOCATION CONT ON SHEET SH NO.

FF-803-WF (2-71) PRINTED IN U.S.A

+

+

CODE IDENT NO.