g		GE Industrial Syste	ms Func	tional Testing Sp	ecification	
	Renewal Services Louisville,KY			LOU-GED-44C372602		
		Test Procedure for a G	round Detector o	eard		
DOCU REV.	MENT REVISION STATUS: Deter	mined by the last entry in the DESCRIPTION	e "REV" and "DATE"	SIGNATURE	REV. DATE	
A	Initial release	DECOME FIOR		P. Kelley	7/17/02	
В	Moved procedure to new f	ormat		R. Duvall	10/25/02	
2						
 [©] COP	YRIGHT GENERAL ELECTRIC COM	MPANY				
PROPR MAY N	RIETARY INFORMATION – THIS DO NOT BE USED OR DISCLOSED TO C	OCUMENT CONTAINS PROPRI OTHERS, EXCEPT WITH THE V	WRITTEN PERMISSION	OF GENERAL ELECTRIC	COMPANY.	
PROPR MAY N	RIETARY INFORMATION – THIS DO NOT BE USED OR DISCLOSED TO C ARED BY REVI	OCUMENT CONTAINS PROPRI OTHERS, EXCEPT WITH THE V		OF GENERAL ELECTRIC	COMPANY.	

LOU-GED-44C372602
REV. B

GE Industrial Systems
Renewal Services
Louisville, KY

Page 2 of 5

Functional test procedure for a Card

1. SCOPE

1.1 This is a functional testing procedure for a Card.

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
 - 3.1.1 277A3907
 - 3.1.2 GEK-36553

4. **ENGINEERING REQUIREMENTS**

- 4.1 Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.2 Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - 4.2.1.1 Wires broken or cracked
 - 4.2.1.2 Terminal strips / connectors broken or cracked
 - **4.2.1.3** Loose wires
 - 4.2.1.4 Components visually damaged
 - 4.2.1.5 Capacitors leaking
 - 4.2.1.6 Solder joints damaged or cold
 - 4.2.1.7 Circuit board burned or de-laminated
 - 4.2.1.8 Printed wire runs burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Reference #	Description
	Fluke 85 DMM (or Equivalent)
	Reference #

LOU-GED-44C372602
REV. B

GE Industrial Systems
Renewal Services
Louisville, KY

Page 3 of 5

6. <u>TESTING PROCESS</u>

6.1 Setup

6.1.1

Note:

6.2 Testing Procedure

6.2.1 See Attached Sheets

6.3 ***TEST COMPLETE ***

7. NOTES

g

LOU-GED-44C372602 REV. B

GE Industrial Systems Renewal Services Louisville, KY

Page 4 of 5

Oct-25-02 12:30

From-GE IS LOUISVILLE (502) 493-9189

5024930640

T-693 P.01

F-152

 $\widetilde{}$

Test for 44C372602-G01

- Connect the board as shown in the test drawing.
- Apply power.
- Meter readings below are with the neg lead from the volt meter to pin ? (used as common).
- Position NEG ALO and POS ALO switches down (on front panel).
- Press RESET button (on front panel).
- Verify that LEDs marked NEG and POS on the front panel of the UUT are both on.
- Verify that the LED marked MCA on the front panel is blinking at a 1HZ rate.
- Verify that the LED between pin 23 and com is blinking at approx a 2 HZ rate.
- Verify < .5 volt on pin 21.
- Verify < 2 volts on pin 24 (you may see a 2 HZ signal but it should stay < 2 volts).
- Verify < .5 volt on pin 29.
- Verify < 2 volts on pin 19 (you may see a 2 HZ signal but it should stay < 2 volts).
- Connect the side of the 4.7 K resistor not connected to pin 3 to pin 9 for one second and release.
- Verify that the NEG LED on the front panel is blinking at approx a 2HZ rate.
- Verify that pin 21 reads 24 volts.
- Verify that pin 24 is going from < 2 volts to 24 volts at a 2HZ rate.
- Position the NEG ALO switch on the front panel to the up position.
- Verify < .5 volts on pin 21.
- Verify < 2 volts on pin 24 (you may see a 2 HZ signal but it should stay < 2 volts).
- Verify 24 volts on pin 29.
- Verify that pin 19 is going from < 2 volts to 24 volts at a 2HZ rate.
- Position the NEG ALO switch on the front panel to the down position.
- Press the reset button on the front panel.
- Verify that the NEG LED on the front panel is on (not blinking).
- Connect the side of the 4.7 K resistor not connected to pin 3 to pin 7 for one second and
- Verify that the POS LED on the front panel is blinking at approx a 2 HZ rate.
- Verify that pin 21 reads 24 volts.
- Verify that pin 24 is going from < 2 volts to 24 volts at a 2HZ rate....
- Position the POS ALO switch on the front panel to the up position.
- Verify < .5 volts on pin 21.
- Verify < 2 volts on pin 24 (you may see a 2 HZ signal but it should stay < 2 volts).
- Verify 24 volts on pin 29.
- Verify that pin 19 is going from < 2 volts to 24 volts at a 2HZ rate.
- Position the POS ALO switch on the front panel to the down position.
- Press the reset button on the front panel.
- Verify that the POS LED on the front panel is on (not blinking).
- Done.

LOU-GED-44C372602 REV. B GE Industrial Systems Renewal Services Louisville, KY

Page 5 of 5

Oct-25-02 12:31

From-GE IS LOUISVILLE (502) 493-9189

g

5024930640

T-693 P.02

F-152

44 (372602 - GOI Tes

