	0314-A01	•			FOR THE REH	EAT PRE	SSURE S	ENSOR		
CONT ON SHEET	<u> 5 ян на</u>	o. 5 F	IRST MADE FO	R EHC	MARK II	· · · · · · · · · · · · · · · · · · ·	·			Tana.
					BOARD ASS Sch. 115D		L15D2230)		REVISIO
.*					Patchboar		M1_	•		
v •	TEST PR	OCEDURE :			PCR					-
•									on en entre reseau per en er er	
	Method	1	•	•						
•	A. Equ	ipment ne	eded:					***************************************		
• • • • • • • • • • • • • • • • • • •	- 1	_								
		DVM SD70	05A milliammet	er HP 12	8 8				y .	
•			Source 4-2		OD	•	•	•		
",·		Scope TE								THE TABLE OF THE T
			or HP 3300 p Harr. 6			: .	•		*	
			-		· · · · · · · · · · · · · · · · · · ·					
•	NOTE:				ents are <u>+</u> 1	L MVDC	unless			
•		ebecrir	ed otherwi	se.						
	B. Pat	ched prog	ram is as	shown in	Fig. A.					
	C CFN	ERAL PROC	म्या राज्य							-
	O. CIM	INALI INCO	EDONE							
	Bef	ore plugg	ing board	in:						
	1.	Adj. VRl	CCW.					:		
	• •						•			
	2.	ALL SWIT	CHES DOWN.		د اد موسود از با المحاود از از ادارات مدارات		بلية و الموا			
	Plu	g in Boar	d:							
			•	_		-			•	
	3•	Check te	st supply	voltages						1
i en	4.				ages at TPl	and TP	2 for	· .		
	•	+15.7 an	d -15.7 VD	C (Tol.	+ 1.0 VDC).				* .	
	5.	SW 11 up	- Grd.	TP5.			* · ·	· · ·	***	
					• • • •		e şi	•		
•	6,	Adj. off	set (VR 50) of IC	l for 0 VDC	at TP4	• 1			
	7.	SW 11 do	wn.						Africa di distance della constance di la const	
	,			•						
	8.	Adj. off	set (VR 51) of IC	2 for 0 VDC	at TP3	•			
	9.	\$10 up	- Sll up	- Adj.	current so	irce fo	r -5.00	MA.		
									e was e	
						· .				
. •		•				•	•		·· ·	-
		•			•			**	• .	PRINTS

••		GENERAL (%) ELECTRIC P3K-AL-0314-A01	
REV O		1 TITLE	н но. 6
P3K-AL-C	314-A01	TEST INSTRUCTIONS FOR THE REHEAT PRESSURE SENSOR	
CONT ON SHEET	7 . sh no.	FIRST MADE FOR EHC MARK II	
	\.		REVISION
	10.	Check TP6 volts for -1.505 to 1.535 VDC.	
	11.	Adj. current source for -1.500 VDC at TP6.	
	12.	Check range of VR2 at TP4. (Also at BP3, BP5 and BP6)	
	•	<u>cw</u> <u>ccw</u>	
	•	+3.830/4.262 +2.490/2.592	
	13.	Adj. current source for -5.00 MA.	
	14.	Adj. VR2 at TP4 for -3.125 VDC. (FINAL SETTING)	
	15.	Adj. current source for -4.00 MA	
	16.	Unground TP5.	
	17.	Check range of VR3 at TP5.	
		CW CCW	
		0/+4 MVDC +2,360/+2.720	
	18.	Adj. VR3 for O VDC at TP4.	
	19.	Check linearity of pressure amp.	
		Current TP4 Source Volts	The state of the s
	:	- 4.00 MA 0 - 8.00 + 2.500 VDC + 2 MV - 12.00 + 5.000 5 - 16.00 + 7.500 7 - 20.00 + 10.000 10	
	20.	With -20.00 MA applied, adj. VRl for 1.0 MA deflection of MA meter.	
	21.	Check saturation levels (>+12.5 VDC) of IC 1(TP4) and IC 2 (TP3) by applying +25.00 MA and then -25.00 MA.	
	•		PRINTS
R.S. Gor	don Mar.	20, 1973 Steam Turbine DIV OR P3K-AL-0314-A01	
	2.7 2.0 197		SH NO. 6

FF-803-WA (1-72) PRINTED IN U.S.A.

CODE IDENT

R.Gordon Mar. 20, 1973

FF-803-WA (1-72) Printed in U.S.A. APPROVALS

Steam Turbine DEPT.
Schenectady, N.Y. LOCATION

P3K-AL-0314-A01

CONT ON SHEET

sh NO. 7

PRINTS TO

CODE IDENT NO

PRINTS TO PRINTS