g		GE Energy Service	Functio	onal Testing Specification					
	Inspection an Louisville, KY	d Repair Services		LOU-GED-68A993xxx					
		Test Procedure for a S	CR gate	and filter ca	rd				
DOCUM	MENT REVISION STATUS:	Determined by the last entry in th	ne "RFV" a	nd "DATF" coli	umn				
REV.		SIGNATURE	REV. DATE						
Α	Initial release	D. Laemmle	6/19/02						
В	Added info pertaining to Notes section	J. Madden	3/18/04						
С	Added test setup pic	s per Matt Trull			L. Groves	12/6/2017			
© COPY	YRIGHT GENERAL ELECTF	RIC COMPANY							
		THIS DOCUMENT CONTAINS PROPE ED TO OTHERS, EXCEPT WITH THE							
	RED BY emmle	REVIEWED BY J. Madden	REVIEWE	D BY	QUALITY API				
D. Lac	J	DATE	DATE		Motor a	Dunll			
07/09/	/02	3/18/04	DATE		07/09/02				

LOU-GED-68A993xxx
REV. A

GE Industrial Systems
Renewal Services
Louisville, KY

Page 2 of 8

#### Functional test procedure for a SCR gate and filter card.

### 1. SCOPE

**1.1** This is a functional testing procedure for a SCR gate and filter card.

# 2. STANDARDS OF QUALITY

**2.1** Refer to the current revision of the IPC-A-610 standard for workmanship standards.

# 3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
  - 3.1.1 Alteration Notice BU11604GR

# 4. ENGINEERING REQUIREMENTS

- 4.1 Equipment Cleaning
  - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.2 Equipment Inspection
  - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
    - 4.2.1.1 Wires broken or cracked
    - 4.2.1.2 Terminal strips / connectors broken or cracked
    - **4.2.1.3** Loose wires
    - 4.2.1.4 Components visually damaged
    - 4.2.1.5 Capacitors leaking
    - 4.2.1.6 Solder joints damaged or cold
    - 4.2.1.7 Circuit board burned or de-laminated
    - 4.2.1.8 Printed wire runs burned or damaged

# 5. EQUIPMENT REQUIRED

**5.1** The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1	H033787	SCR GATE AND FILTER CARD TEST FIXTURE
		SCR FIRING BOX
		LAMP LOAD- 230v OR 460v PER CARD VOLTAGE RATING
		120//230 OR 12/460 TRANSFORMER PER CARD VOLTAGE RATING.

LOU-GED-68A993xxx
REV. A

GE Industrial Systems
Renewal Services
Louisville, KY

Page 3 of 8
Renewal Services

### 6. TESTING PROCESS

- 6.1 Setup
  - **6.1.1** See notes on fixture before hooking up card.
  - 6.1.2 Be sure that Alteration Notice BU11604GR has been performed before testing.
    See <u>Notes</u> section below and attached documents for more information on this alteration.
- 6.2 Testing Procedure
  - 6.2.1 Hook up equipment per diagram on test fixture. Pay close attention to voltage ratings on bulbs and how to connect them (series or parallel), so as not to apply more than the specified voltage to any individual bulb, creating a failure of the bulb(s) or a physical danger to the you or any personnel in the immediate vicinity.
  - 6.2.1 With firing box switch in boost position and firing control knob full CCW, apply power to transformer. Lamp load should not be lit. However, indicator lamp(s) on unit under test should be at full illumination.
  - 6.2.2 Turn firing control knob on firing box slowly CW and load lamps should slowly brighten up. Indicator lamp(s) should gradually go out, and should be completely out at approximately 50% power on firing box control (maybe a little higher if using the orange replacement lamps we keep in stock for these units). The fixture can get hot and possibly suffer damage if left at full power for too long, especially with dual firing circuit cards, so observe the temperature of the fixture if running units for extended periods of time. Apply some method of cooling if you are "burning a unit in". Return control knob to full CCW and lamps should go out.
  - **6.2.3** Switch off firing box and remove power from transformer.
- 6.3 \*\*\*TEST COMPLETE \*\*\*

#### 7. NOTES

If card has two firing circuits, tie them together at the firing circuit input as shown on the fixture. Removing one or the other will cut output to load lamps approximately in half.

2000


g

LOU-GED-68A993xxx REV. A

# GE Industrial Systems Renewal Services Louisville, KY


Page 4 of 8

# **Connections for testing:**




g

LOU-GED-68A993xxx REV. A GE Industrial Systems Renewal Services Louisville, KY Page 5 of 8



LOU-GED-68A993xxx REV. A g

GE Industrial Systems Renewal Services Louisville, KY Page 6 of 8



LOU-GED-68A993xxx
REV. A

GE Industrial Systems
Renewal Services
Louisville, KY

Page 7 of 8

Renewal Services

Our firing boxes will, on occasion, be loaded to the point of cutting out or "sputtering" at high levels of output (near 100% on control knob). This is why we use the Boost setting on the firing box. Using Boost helps, but does not eliminate this altogether on some cards, dual firing circuit cards in particular. On some dual circuit cards simply firing only one circuit at a time will alleviate the symptoms. This problem is not necessarily an indication of a problem with the unit under test. Be sure to have replaced the UJT/bilateral switch transistors (2n4987) and any glass bead diodes to be sure to eliminate them as a cause of the "sputtering". If problem is affecting test too severely to ensure proper operation, try using another firing box to see if symptoms change from box to box or if they stay with the card.

When performing the alteration BU11604GR to the firing signal input circuit, on certain boards you must take care not to install the diode after a resistor that present on certain cards right next to R15. It must connect between tab 13 and the rest of the input circuit. Watch for these!

Phasing: Our benches are not always in phase with each other or with wall outlets, and running the firing box from one outlet and 230/460 power transformer from another can put these two devices out of phase, causing erratic test results. Be sure to use the same outlet cluster or power strip for both units to eliminate this problem.

g

LOU-GED-68A993xxx REV. A

### GE Industrial Systems Renewal Services Louisville, KY

Page 8 of 8

	Apperatus Pub LBA 99 3 12 3  ALTERATION NOTICE  T.S. for Dwg. No.  A.N. No. Buil 600  DEPT. Short No. J. Courts on Dept. Short No. J													
3	EQ. or D.A Drafting Required							'	P.O. or S.O					
	MA	TERIAL AF	BY CH	ANGE			Sh.		Tool o	r Patt.	COST IN	CREASE	(Dece	
rr.					promine no. N			No.	No. No.				SAL	LABOR
1	DISPOSITA		aus					-						
2	mod, in	sT.						<del>                                     </del>	-					
3								-	-					
4	STAT		·	· .	BPORTICE TO SERVICE TO			1	cetion	Cher	-			
IT.	Rough-Unassemi-A		aStock				took -Se	PP M	of eteria	Chg. Rese. Byrnb.	Resp. No.	1. Eng.	4. C	NTA.
1			··· • ··· · ···	<u> </u>								2. DRs. 3. Factor		trer é utaide
2												7	YPE OF L	
3												Spolings	Extra Cost	Obs
4														
•	MANUFACT	TURING	INFO	RMAT	TON (	OR EN	GINE	ERIN	GIN	STRU	JCTIC	ONS		
	tem HSPOSITION:	SCP	MOD	USE	PLR	C/0	SPE					MENTS		
.*						_		۲۵۷ هم	A 1 0 E			FAB	150	
İ	FAB	. 🗆		Ø	Ш			5110	ρ T.	MA	KE X	20 Mi	DRE F	AAS
	PCBG/UNTST		$\boxtimes$					MAJ	سخدا	AT	twol	K K	UA) L.	
	PCBG/TESTED		$\boxtimes$							··				
	STOCK		X											
	ESA/PL		П				X	Cof	3BU	16	Bras	eos F	A.L.	
		_					IXI □			LE T				
i	FINAL/ASH			_	_		_				(03)		···	
	RPO		$\boxtimes$					·				·		
	RER		$\boxtimes$						-					
	FIELD			$\boxtimes$										
	MOD INST.			-						1 R15				
	1. A DD D100	e 68	A722	.s f 3	IN	7,	of Vier	n C	2	1 4				
	FEED THRU									F=0				
	Z. CUT RUN				42 Z	4οωλ)	۵.			] O.	٧			
	- · <del>-</del> ·		_				CI	JT _	Q	·71-16,				
	2000		0 12	-	<u> </u>			F		(L)2	7 00			
	MUD, R	EV. (						•	>r\	CRIO	PROX	LOSS I	io I 6 -	IC
	tanned Operation									POU				
K 2	tenned Operation		2) (22.6)	(د يع)		Dube	6/2	5/84	<del></del>	Ma		<del></del>	Estimate	
K 2 0	tanned Operation	тэн)(р	Stici Con	(w 5) NER	-	Date Date Date	6/25				terial bor		Estimate	
K ZOO	tanned Operation  lotice Issued By Change Approved By Drawing Changed By	тэн)(р	001 001	NER		Date Date				La	sterial bor	rheed.	Estimate	
2 0	tanned Operation  lotice Issued By Change Approved By Drawing Changed By	тэн)(р	DE COM	<u>νεν</u> —Pen	ming	Date Date				Fa Sh	terial bor	rheed et	Estimate	
K 200	tanned Operation  totice issued By thange Approved By traveling Changed By Cant. Prod.	тэн)(р	a) fraci Con	Plan DN.	ning	Date Date				Fa Sh Sc	sterial bor ic. Ove iop Co	rheed st	Estimate  Dept. No	