g		GE Energy		Functional T	esting Spe	ecification			
	Parts & Repa Louisville, KY	LOU-GED-DS3800DCMB							
	Test Procedure for a DS3800DCMB card								
DOCIII	MENT REVISION STATUS	Determined by the last er	ntry in the "REV" a	nd "DATE" column					
REV.	WENT REVISION STATUS	DESCRIPTION	indy in the INEV a		GNATURE	REV. DATE			
Α	Transferred from pa	per to electronic format	t	J.	Wychulis	7/15/2011			
_									
В									
С									
© COPYRIGHT GENERAL ELECTRIC COMPANY Hard copies are uncontrolled and are for reference only.									
PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.									
	ARED BY	REVIEWED BY	REVIEWE		QUALITY APF				
J. Wy		INTAILANTO DI	KEVIEWE	.0 01	Charlie Wa				
DATE		DATE	DATE		DATE	u .			
7/15/2	2011				7/15/2011				

	g	
LOU-GED-DS3800DCMB	GE Energy	Page 2 of 4
REV. A	Parts & Repair Services	
	Louisville, KY	

### 1. SCOPE

**1.1** This is a functional testing procedure for a DS3800DCMB.

# 2. STANDARDS OF QUALITY

**2.1** Refer to the current revision of the IPC-A-610 standard for workmanship standards.

# 3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
  - **3.1.1** Check board's electronic folder for more information

# 4. **ENGINEERING REQUIREMENTS**

- 4.1 Equipment Cleaning
  - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to site specific SRA's for cleaning guidelines.
- 4.2 Equipment Inspection
  - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
    - 4.2.1.1 Wires broken, cracked, or loosely connected
    - 4.2.1.2 Terminal strips / connectors broken or cracked
    - 4.2.1.3 Components visually damaged
    - 4.2.1.4 Capacitors bloated or leaking
    - 4.2.1.5 Solder joints damaged or cold
    - 4.2.1.6 Circuit board burned or de-laminated
    - 4.2.1.7 Printed wire runs / Traces burned or damaged

## 5. EQUIPMENT REQUIRED

**5.1** The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description	
1		FVE Module	
1		See equipment section in the following page scanned test	

٤

# LOU-GED-DS3800DCMB REV. A

### GE Energy Parts & Repair Services Louisville, KY

Page 3 of 4

### 6. <u>Testing Process</u>

### 6.1 Page 1 of scanned DMCB instruction

```
DCMB1D1B.FUN
         PREFACE
         Functional verification for the DS3800DCMB.
         EQUIPMENT
         Test Module "FVE".
         Extender card DS3800XEXA1A1B (or equiv).
         FVE switch box and ribbon cable (10 pin).
         Power supply DS3820PLSA1A1A (or equiv). Mother board DS3800HCMB.
         Test prom "PSG304A9936AACE".
         Test connectors:
          #1. 218A4638P2 with pins 3-P5 4-DCOM 5-10 6-9 7-18 8-20 #2. 218A4801P1 with pins 2-3 4-5 8-20 17-24
         SETUP
         Connect FVE switch box JD to module backplane JD. Plug test prom into HCMB U32 socket.
         Set HCMB berg jumpers as follows:
                  J2,J3
                                      "PROM"
                                     "F"
                  J4-J6
                  J7-J15
                                     Toward daughter board posts
                  J16
                                      HINT
                  J17-J19,J21,J22 "F"
J20,J23,J24 "T"
        J20,J23,J24 "T"

Set DCMB berg jumper J1,J2,J3,J4,J5,J6,J7="IN"

Mount DCMB on HCMB.
        Plug HCMB/DCMB into module slot 1A (using extender card).
        Close HCMB PA06 to DCOM (on FVE switch box). Plug test connector #1 into DCMB JA socket. Plug test connector #2 into DCMB JB socket.
        TEST PROCEDURE
        Turn power on.
        Momentarily open PA06 from DCOM, and then reconnect.
              (This applies a reset to HCMB.)
        Verify the following LED conditions:
                  DCMB LED's
                                               HCMB LED's
                  CR3 all on
                                           CR2 LED's (all) flashing on/off
            CR4 TXDB on
                                           all others off
                  CR4 RXDB on
                  all others off
        Change HCMB berg jumper J17 from "F" to "T" position.
        Verify the following LED conditions:
                  DCMB LED's
                                              HCMB LED's
                  CR3 all on
                                               CR2 LED segments 1-3 flashing on/off
                  CR4 TXDB on
                                              all others off
                  CR4 RXDB on
                  CR4 CTSB on
                  all others off
        END OF TEST
```

### 6.2 \*\*\*TEST COMPLETE \*\*\*

#### 7. Attachments

LOUICED DesagonCMB	g CE Engreus	Dogo 4 of 4
LOU-GED-DS3800DCMB	GE Energy	Page 4 of 4
REV. A	Parts & Repair Services	
	Louisville, KY	

**7.1** None at this time.