g		GE Industri	al Systems	Function	al Testing Spe	ecification	
Renewal Services Louisville,KY				LOU-GED-531X207LCS			
Test Procedure for a LAN power Supply Card							
DOCUMENT REVISION STATUS: Determined by the last entry in the "REV" and "DATE" column							
REV.		DESCRIPTION			SIGNATURE	REV. DATE	
Α	Initial release				K. Greenwell	7/1/02	
В							
С							
© COPY	(RIGHT GENERAL ELECT	TRIC COMPANY					
		THIS DOCUMENT CONTAIN SED TO OTHERS, EXCEPT W					
	RED BY eenwell	REVIEWED BY	REVIEWE	D BY	Rober a	PROVAL	
DATE 07/01/	/02	DATE	DATE		DATE 08/09/02		

LOU-GED-531X207LCS REV. A GE Industrial Systems Renewal Services Louisville, KY

Page 2 of 3

Functional test procedure for

1. SCOPE

1.1 This is a functional testing procedure for a LAN power supply card.

g

2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

3. APPLICABLE DOCUMENTS

- **3.1** The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.
 - 3.1.1 531X207LCSx Documentation Folder

4. ENGINEERING REQUIREMENTS

- 4.1 Equipment Cleaning
 - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.2 Equipment Inspection
 - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
 - 4.2.1.1 Wires broken or cracked
 - 4.2.1.2 Terminal strips / connectors broken or cracked
 - **4.2.1.3** Loose wires
 - 4.2.1.4 Components visually damaged
 - 4.2.1.5 Capacitors leaking
 - 4.2.1.6 Solder joints damaged or cold
 - 4.2.1.7 Circuit board burned or de-laminated
 - 4.2.1.8 Printed wire runs burned or damaged

5. EQUIPMENT REQUIRED

5.1 The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		Fluke 85 DMM (or Equivalent)
1		50 Ohm resistor
1		115VAC Line Cord

g

LOU-GED-531X207LCS REV. A

GE Industrial Systems Renewal Services Louisville, KY

Page 3 of 3

6. <u>TESTING PROCESS</u>

- 6.1 Setup
 - **6.1.1** Set JP1 to position 2-3 for +15VDC setting.



- **6.2** Testing Procedure
 - **6.2.1** Apply 115VAC to TB1 pins 1 & 3.
 - **6.2.2** Verify +15VDC at TB1 pins 7 (Neg.) & 8 (Pos.).
 - **6.2.3** Remove 115VAC power.
 - **6.2.4** Change JP1 from 2-3 to 1-2 for +5VDC operation.
 - **6.2.5** Apply 115VAC power.
 - **6.2.6** Verify +5VDC at TB1 pins 7 (Neg.) & 8 (Pos.).
 - 6.2.6.1 Adjust +5VDC at P1 if necessary.
 - **6.2.7** Remove 115VAC power.
 - **6.2.8** Return JP1 to the 2-3 position.
 - **6.2.9** Install a 50 ohm resistor in series with an ammeter across TB1 pins 11 & 12.
 - **6.2.10** Apply 115VAC power.
 - **6.2.11** Verify Ammeter reading of 0.255 Amps.
- 6.3 ***TEST COMPLETE ***

7. NOTES