g	GE Industrial Systems		Functional Testing Specification							
	Renewal Serv Louisville,KY		LOU-GED-IC3622GSDE							
	Test Procedure for a Solenoid Driver Card IC3622GSDEx									
	MENT REVISION STATUS	Determined by the last e	ntry in the "REV" a			1				
REV.		DESCRIPTION			SIGNATURE	REV. DATE				
Α	Initial release				P. Kelley	10/13/94				
В	Total re-write of pro-	Total re-write of procedure. GPTC test is now inoperable.			. Laemmle	11/19/02				
С										
© COPYRIGHT GENERAL ELECTRIC COMPANY  PROPRIETARY INFORMATION – THIS DOCUMENT CONTAINS PROPRIETARY INFORMATION OF GENERAL ELECTRIC COMPANY AND MAY NOT BE USED OR DISCLOSED TO OTHERS, EXCEPT WITH THE WRITTEN PERMISSION OF GENERAL ELECTRIC COMPANY.										
PREPARED BY D. Laemmle		REVIEWED BY	REVIEWE	D BY	Rober Dunll					
<b>DATE</b> 11/19	/02	DATE	DATE		DATE 11/20/02	·				

LOU-GED-IC3622GSDE
REV. A

GE Industrial Systems
Renewal Services
Louisville, KY

Page 2 of 3

- 1. Functional test procedure for IC3622GSDE1,2
  - 1.1 This is a functional testing procedure for a IC3622GSDE1,2 Solenoid Driver Card

## 2. STANDARDS OF QUALITY

2.1 Refer to the current revision of the IPC-A-610 standard for workmanship standards.

# 3. APPLICABLE DOCUMENTS

3.1 The following document(s) shall form part of this specification to the extent specified herein. Unless otherwise indicated, the latest issue shall apply.2.1.1

#### 4. ENGINEERING REQUIREMENTS

- 4.1 Equipment Cleaning
  - **4.1.1** Equipment should be clean and free of debris prior to applying power unless performing an initial check. Refer to the local documented procedures for cleaning guidelines.
- 4.2 Equipment Inspection
  - **4.2.1** Equipment should be visually inspected for any defects prior to applying power. This inspection should include the following as a minimum:
    - 4.2.1.1 Wires broken or cracked
    - 4.2.1.2 Terminal strips / connectors broken or cracked
    - **4.2.1.3** Loose wires
    - 4.2.1.4 Components visually damaged
    - 4.2.1.5 Capacitors leaking
    - 4.2.1.6 Solder joints damaged or cold
    - 4.2.1.7 Circuit board burned or de-laminated
    - 4.2.1.8 Printed wire runs burned or damaged

# 5. EQUIPMENT REQUIRED

**5.1** The following equipment is required to perform the process requirements. Equipment may be substituted provided that all accuracy's and test ratios are equivalent or better.

Qty	Reference #	Description
1		100 watt 120v lamp
1		15VDC supply

g

## LOU-GED-IC3622GSDE REV. A

#### GE Industrial Systems Renewal Services Louisville, KY

Page 3 of 3

# 6. <u>TESTING PROCESS</u>

- 6.1 Setup
  - 6.1.1
- 6.2 Testing Procedure
  - 6.2.1 Circuit #1. Connect a 100 watt light bulb load from AC2 Pin 42 to Com, Pin 1. Connect a 15v DC supply (+) to Pin 27, (-) to Pin 1. Connect ISOLATED 115VAC line to AC1 Pin 34 and neutral to Pin 1. Apply power. The load lamp should not light nor any of the neons. Connect Circuit #1 IN ( Pin 2) to Com.(Pin 1). The light bulb load should light and DS1 neon lamp on card should light also. Remove and reconnect the com connection to Pin 2 several times to test relay operation.
  - **6.2.2** Circuit #2. Move 100 watt lamp, ISOLATED AC and IN connector to corresponding Pins of Circuit #2 per chart and test the same as Circuit #1.
  - **6.2.3** Circuit #3. Same as Circuit #2 per chart.
  - **6.2.4** Circuit #4. Same as Circuit #2 per Chart.

Circuit #	IN	AC1	AC2	Neon
1	2	34	42	DS1
2	4	36	44	DS2
3	6	38	46	DS3
4	8	40	48	DS4

### 6.3 \*\*\*TEST COMPLETE \*\*\*

### 7. NOTES