REV O	TITI		-	CONT	ON SHEET 2	SH
P3K-AL-0	T	EST PROCEDURE - OSEMOUNT TRANSD		Ĭ.		
CONT ON SHEET 2	sh No. 1 FIRS	T MADE FOR MARK	I			
I. PURPOSE						
1	pose of this spe to test the Powe O.		•			
II. DOCUMENT	TS PERTAINING TO	THIS SPECIFICA	TION			
A. Pow	er Supply - U602	8AF Pt. 2				
B. Pre	ssure Transducer	- U5151 Pt. 1	*		E E	
c.			*			
			12 0440	· · · · · · · · · · · · · · · · · · ·		-
III. EQUIPMEN	NT NEEDED TO TES	T				
A. 1 -	DC Ohmmeter - 5	% (M7)				
в. 3-	DC Voltmeter -	30 VDC 1% (M1,	M2, M6)			
C. 1 -	Variac - 0-120	VAC 1 ampere (V	1)			-
D. 2 -	DC Ammeter - 0-	100 ma 1% (M3,	M4)		4	
E. 1-	AC Voltmeter -	0-150 VAC 5% (M	5) (68A.	7020 P3	(50 D)	
F. 2 -	Resistors - 350	1/2% 5 watts	(R_1, R_2)			5
IV. CIRCUIT	DESCRIPTION	*				
				• •		
the b oa r filtered	rcuit board cons rd. The 120 VAC I to 28 VDC and I plies can be used	power is fed i 30 ma current.	nto these sup By connectin	oplies, is r ng various j	rectified, jumpers	ned.
8 57 11 6			121	-	- 0	_
V. TEST INS	TRUCTIONS					
AG001	Tests		Marianto			
<i>y</i> ^ 1.	Using M7, measu	e 0 ohms between	en:			
	Pins 30 and 28;		d 36: and gre	ater than o	ne megohm	7)
1	between pins 6	and 23.				4
2.	Connect the circ	uit board as p	er Figure la.			
COPYRIGHT 1983	GORNA BACIBIC CO.					
MADE BY J.Polacek Dec	8 1977	PROVALS Steam T	ırbine	DIV OR P	3K-AL-0257	
ISSUED	1977	Schenect	ady, N.Y.	DEPT.	on SHEET 2	SH A
FF-803-WA (2-76)			1	O	TO	C

Schenectady, N.Y.

FF-803-WA (2-76) PRINTED IN U.S.A.

DEC

1977

CODE IDE

GENERAL (%) ELECTRIC P3K-AL-0257 CONT ON SHEET 4 sh NO. 3 TITLE TEST PROCEDURE - POWER SUPPLY P3K-AL-0257 ROSEMOUNT TRANSDUCER FIRST MADE FOR MARK I sh NO. 3 CONT ON SHEET 4 **REVISI** V. TEST INSTRUCTIONS C. -G003 Tests Using M7, measure 0 ohms between pins 6 and 23; greater than one megohm between pins 30 and 28, and pins 34 and 36. Connect the circuit card per Figure la. Set variac until M5 reads 120 + 1 VAC. 4. M1 shall read 28 + 0.1 VDC. 5. M3 shall read 80 + 1 ma DC. M2 and M4 shall read 0 VDC and 0 ma DC. 6. 7. Set variac until M5 reads 0 VAC. Connect the circuit board per Figure 1b. Set variac until M5 reads 120 + 1 VAC. M2 shall read 28 ± 0.1 VDC. 10. 11. M4 shall read 80 + 1 ma DC. 12. M1 and M3 shall read 0 VDC and 0 ma DC. 13. Set variac until M5 reads 0 VDC. 14. Disconnect all test equipment, test over. D. -G004 Tests Using M7, measure one megohm between pins 30 and 28; pins 34 and 36, and pins 6 and 23. 2. Connect the circuit board as per Figure la. 3. Set variac until M5 reads 120 + 1 VAC. 4. Ml shall read 28 ± 0.1 VDC. M3 shall read 80 + 1 ma VDC.

MADE BY

+

+

APPROVALS

1977

Set variac until M5 reads 0 VAC.

M2 and M4 shall read 0 VDC and 0 ma DC.

Steam Turbine

Schenectady, N.Y.

DIV OR

P3K-AL-0257


LOCATION CONT ON SHEET

SHEET 4 SH NO. 3

PRINTS

GENERAL (%) ELECTRIC

REV O		TITLE			CONT ON SHEET	SH NO
P3K-AL-025	7	TEST PF ROSEMOU	ROCEDURE - POWER INT TRANSDUCER	SUPPLY		
CONT ON SHEET 5	sh no. 4	FIRST MADE	FOR MARK I	 		1
v. Test I	NSTRUCTIONS	Ą.,				R
D.	-					
= 8.	Connect ci	rcuit board	d as per Figure l	Lb.		
9.	Set variac	until M5 1	reads 120 <u>+</u> 1 VA0	C .		
10.	M2 shall r	ead 28 ± 0.	.1 VDC.			
11.	M4 shall r	ead 80 <u>+</u> 1	ma DC.			. 12.460
12.	Ml and M3	shall read	O VDC and O ma I	DC.		
13.	Set variac	until M5 1	reads 0 VAC.			-
14.	Disconnect	all test e	equipment, test (over.		
			V			1.0g.2m03.05====
NOIE.			not meet the cal atrol Engineering		ue, scop	20
NOIB.					ue, stop	
NOIB.					ue, stop	
ROID.					ue, stop	
NOIB.					ue, stop	
NOID.					ue, stop	
NO.1B.					ue, stop	
NO.1B.	testing and				ue, stop	
NO.1B.	testing and				ue, stop	
AO I B	testing and				ue, stop	
NO.15	testing and				ue, stop	
NO.1B.	testing and				ue, stop	
NO.15.	testing and				ue, stop	
NO.L.	testing and				ue, stop	
	testing and	notify Con			ue, stop	
ADE BY J Polacek Decision of the same of t	testing and				DR P3K_AT	



CODE IDENT

REV NO.	TITLE	CONT ON SHEET _ SH NO.	. 6
P3K-AL-0257	TEST PROCEDURE - POWER SUPPLY ROSEMOUNT TRANSDUCER		
CONT ON SHEET - SH NO. 6	FIRST MADE FOR MARK I		
		Į.	REV
		<u> </u>	
		£(
		(a) =	
	$\alpha \circ \alpha \circ \alpha$		
	1 Sugar land	DATE 1//29/77	
PREPARED BY:	J. Barngher	DATE ///	
	arrigher SIGN ENGINEERING	er og som året til er og som er og e	
	10 10 10 10		
		FI 9	
		6 5	
	* *		
		e ³¹	
		6 FO	
		4	
		¥	
k. Tarlettin neimen attimatera atti arasista anno a mara arasista paragi e arasigi e arasigi e)	Control of the Control of the State of the Control	
REVIEWED BY:	(Clean	DATE 11-29-77	
P.C. C	allan - Manager		
	SIGN ENGINEERING		
a conservation of the second	A		
To T. Prod & Pt. 37 Still Sec. To.			PRII
J. Polacek Dec. 8, 1977	APPROVALS Steam Turbine	DIV OR P3K-AL-0257	
SUED DEC 8 1977	Schenectady, New York		

FF-803-WA (2-76) PRINTED IN U.S.A.

Data Sheet

Job# 9/	200 7	789	1					
Serial #	R5088	6	-		Burn-in Start	3-	6-12	8:30
Date _ 3 -	6-12							
Data Sheet 1	for 142	D7210G	5000		Burn-in Stop	<u> </u>	13-12	-
Test Proced	ure <u>P</u> Z	K-AL-C	757		Technician		GC	
Test Procedure					:2		/alues	
Step	Nominal	Lower Limit	Pre-Burn in Results	Post Burn in Results	Upper Limit	CW	licable CCW	Pass/Fail
1A	02		05	00				
1R	71meg	Imag D	open	open:				
H m1	+28V	+27.7	+27.750	+27.752	+28.3			
4m2	+28V	+27.7	127.746	+27.753	128.3			
5m3	80ma	79mg	79.4 mg	79,4 mg	81mg			
5m4	20 me	79 ma	79.4 ma	79,4 mg	81mg			
6	01		0.0 V	O:OV				
	01		0.0 V	0.0V				
		С						
4m	t28V	+27.7	+27,750	+27,750	+28.3			
4m2	t28V	+27.7	427.751	127.749	+28.3	- <u>-</u>		
5m3	80ma	79 ma	79.4ma	79.4 mg	81mg			
5m4	80ma	79ma	79.4mg	79.4mg	81 mg			<u></u>
6	OV	6V	0.01	O.OV.	5 5			
7	oV	OV	0.01	0.0	~ '			
122								
*								
	::							
								