

NO.4 E/R VENT. FAN (REV) — Confirmed Trip: EOCR Overcurrent (o.C)

HI-2536-ME-SD1/SD2 · Hyundai HiMP-D06 · CT-OC(R) 100/5A · Updated after confirmed abnormal stop

START → RUN → STOP

1 PRE-START

52 ON · SOURCE ON · Amp ≈ 0

2 PRESS SUPPLY/EXHAUST

4F/4R ON · heater out if was on

3 REDUCED-V START

6-1/6-2 + ATr

4 TIMER 19 ≈ 30 s

Transfer to full voltage

5 FULL-VOLTAGE RUN

88F/88R · 4FX/4RX feedback

6 MONITOR

Door A · EOCR · lamps

CONFIRMED FAULT STOP

SMC: ABNORMAL = ON (red)

EOCR HiMP-D06 display: o.C

Phase LED: R lit (S/T off)

CT-OC(R) = 100/5A

Ammeter after stop = 0 A

HEATER switch OFF → HEATING OFF

(Earlier HEATING ON was only because heater switch was ON — not the cause)

ROOT CAUSE: EOCR OVERCURRENT TRIP (o.C) ON R-PHASE

While running (earlier)

Door amp ~63 A (under FLA 65.4) · EOCR measured 3.7 A > SET 3.27 A

At this stop

ABNORMAL ON · EOCR = o.C · R phase LED ON · Amp 0

CT confirmed

CT-OC(R) RATIO 100/5A → secondary = primary ÷ 20

Expected at 63 A

$63 \div 20 = 3.15 \text{ A}$ (below SET 3.27 — should NOT trip)

EOCR saw 3.7 A

$3.7 \times 20 = 74 \text{ A}$ equivalent — above SET → INV trip after minutes

88F

Already renewed — not the trip device

DO THIS NEXT (before resetting)

1. Record EOCR o.C + R LED (photo done) — then reset EOCR / clear ABNORMAL only after checks.
2. Clamp-meter R, S, T at motor/contactor while running — compare to door A and EOCR.
3. If clamp R ≈ 63 A but EOCR still ~3.7: suspect CT-OC(R) wiring, CT burden, or HiMP-D06.
4. If clamp R high (~70A+): real overload — check fan load, damper, bearings, imbalance.
5. Check R-phase CT secondary K-L terminals tight; never open CT secondary while energized.
6. Do NOT raise SET'G from 3.27 only to "stop the trips."