

CT-OC(R) Check Checklist

NO.4 E/R VENT. FAN (REV) | HiMP-D06 | Keep at panel

SAFETY

- Prefer motor STOPPED before loosening anything.
- NEVER open / disconnect CT secondary (K-L) while motor is running.
- Open CT secondary = dangerous high voltage. Keep K-L closed.
- If only looking while running: look only - do not unscrew terminals.

YOUR LAST READINGS (reference)

Door ammeter ~ 65 A | rc SET = 3.40 A | Expected EOCR at 65 A ~ 3.25 A (CT 100/5)

R = 3.65 A (HIGH) S ~ 3.4 A T = 3.54 A

R is highest -> check CT-OC(R) first. Do not raise rc to hide trip.

CHECK 1 - Visual (motor STOPPED)

- ☐ Find brown ring CT-OC(R) - thick black cable through center, wires K and L
- ☐ Confirm ratio marking used: 100/5A
- ☐ Count cable passes through CT hole: must be ONE pass only
- ☐ If 2 passes -> reading ~ double (can cause false high / o.C)
- ☐ Cable not pinched; insulation OK; CT body not cracked/burnt
- ☐ K and L screws tight; no corrosion; ferrules OK
- ☐ K-L wires go to HiMP CT input (not loose / not open)

CHECK 2 - Compare phases (motor RUNNING - no disconnect)

- ☐ On HiMP: SELECT Down -> read R, then S, then T
- ☐ Write values: R ____ S ____ T ____ Door A ____
- ☐ If only R clearly highest -> CT-OC(R) / R-phase suspect
- ☐ If R~S~T and all high -> load issue or EOCR/common CT problem

CHECK 3 - Swap test (best proof - STOPPED / authorized only)

- ☐ Stop & isolate as required. Mark all wires before touching.
- ☐ Swap CT-OC(R) with CT-OC(S) (keep secondary closed - never open live CT)
- ☐ Run again -> read R/S/T
- ☐ High reading MOVES with CT -> bad CT (or its wiring)
- ☐ High reading STAYS on electrical R -> real R load/cable issue

PASS (good)

- Cable through CT once
- K-L tight & clean
- EOCR ~ 3.2-3.3 A at door 65 A
- R ~ S ~ T
- No more delayed o.C

FAIL / FIX

- 2 turns through CT -> make 1 turn
- Loose K-L -> tighten
- Bad CT -> replace 100/5A
- Do NOT raise rc only
- After fix: retest R/S/T + door A

Path: R/S/T -> 52 -> 88F -> 6-1 -> CT-OC -> Motor | CT secondary -> HiMP-D06 (51)

NO.4 E/R VENT. FAN (REV) | HI-2536-ME-SD1 | CT-OC(R) checklist Rev.1

Related: HiMP setting card | Schematic current-path overlay