

23/07/2025

DIVING SERVICE REPORT UNIT 2A UNDERWATER STOP LOG & SEAL PLATE INSPECTION.



Table of Contents

1. Introduction
2. Scope
3. Methodology
4. Photographic Section
5. Observations
6. Challenges
7. Recommendations
8. Conclusion

INTRODUCTION.

On **23RD July, 2025**, our diving team conducted a follow-up underwater operation at the top dam of **Bujagali HPP Top Dam Unit 2A** after the initial inspection revealed foreign materials preventing the stop logs from sealing. During this operation, all foreign materials (pieces of logs and a stone) were successfully removed from beneath the stop logs. The stop logs were then carefully re-seated and further inspected. A final inspection confirmed that the stop logs are now seated properly with no gaps, forming a complete watertight seal with zero water leakage observed.

The initial inspection identified foreign materials lodged beneath the stop logs, causing leakage. A corrective diving operation was therefore scheduled to remove all debris and confirm proper sealing. This report documents the procedures, findings, and outcome of the cleaning and re-seating operation.

SCOPE OF WORK

- i. Remove all foreign materials beneath the stop logs or at the bottom seal plate.
- ii. Clean the seating area thoroughly.
- iii. Re-seat and align the stop logs.
- iv. Inspect and confirm full sealing with no leakage.

METHODOLOGY

The operation was carried out by certified commercial divers following approved safety protocols:

- Equipment checks, safety briefings, and lock-out procedures confirmed prior to dive.
- Divers manually removed pieces of wood and the lodged stone using hand tools.
- The base area was brushed to ensure no remaining particles.
- Stop logs were gently and slowly lowered to ensure even seating on the seal.
- Final inspection included visual checks and manual probing

PHOTOGRAPHIC SECTION



Attach photos showing the debris removal process, final seating and indicating the cleaned areas.

OBSERVATIONS

1. Multiple pieces of small wooden debris and a stone identified during the initial inspection were successfully removed.
2. The seating area was left clean, smooth, and free of obstructions.
3. After re-seating, no gaps were observed on the edges or along the length of the stop logs.
4. Water leakage previously noted (approximately 2 cm gap) is now completely eliminated.
5. The stop logs are in good structural condition and firmly sealed.

CHALLENGES

- Visibility improved compared to previous inspection but still limited to 1 meter.
- A mild but noticeable current required divers to maintain firm positioning during inspection.

RECOMMENDATION

- Continue routine underwater inspections before and after stop log installation to ensure a clean seating surface.
- Once the dive is completed, first initiate the lowering of the bottom stop logs on both sections.

CONCLUSION

The follow-up diving operation successfully achieved its objectives. All foreign materials beneath the stop logs were removed, and the stop logs were re-seated properly. A thorough inspection confirmed a perfect watertight seal with no leakage. The stop logs are now functioning as intended, ensuring safe and efficient operation of the top dam.