

Renault Traffic — persistent electrical / infotainment faults

Diagnostic request for the service department. Please read the highlighted note and carry out the listed tests.

Registration: YO24 PBF

Owner: _____

Date: _____

VIN: _____

Mileage: _____

Renault UK case ref: _____

IMPORTANT — please read first. A new head unit and a new telematics module have already been fitted, and the faults below remain. Two new modules behaving identically indicates the fault is **not in the modules**. Please stop replacing modules and diagnose **what feeds them**: the antennas, coax, connectors, earth/ground points and the 12V supply. Several faults appeared or worsened after that work — please confirm no antenna or battery-sensor connections were disturbed.

Reported symptoms (grouped by likely common cause)

Group	Symptom
A — Reception (antenna / coax / earth)	• GPS: permanent '<i>Searching for GPS signal</i>'. • DAB radio: loses signal on strong stations (Radio 2 / Radio 5) on main roads & motorways (Derby, Doncaster, Kettering). • Traffic-sign recognition: intermittent and shows the wrong speed limit.
B — 12V power (charging / drain / earth)	• Keyless: '<i>place key fob in zone</i>' — will not start (new fault; fob always carried in pocket, previously fine). • Low-battery warning previously appeared roughly every 2 weeks; has stopped since the dealer work — no warning now.
C — Infotainment (possibly not sleeping)	• Radio freezes regularly — needs rebooting at least once a day. • After engine off then on: radio shows ON, volume 20–22, but no sound until rebooted. • Was previously 'fixed' then returned.

Diagnostics requested (please carry out and record the result of each)

1. Physically verify **every antenna connector (GPS + DAB)** is correctly seated at the new modules and at the aerial — confirm none were left disconnected or pinched during the module replacements. []
2. **Antenna / coax continuity & signal test** for GPS and DAB. []
3. Check and clean the **common earth / ground points** for the infotainment and telematics. []
4. **Parasitic draw (quiescent current) test** after the vehicle sleeps 30–60 min — identify any module not shutting down. []
5. **Charging-system / alternator output test** and a **battery load test**. []
6. Confirm the **Intelligent Battery Sensor (IBS)** is connected and functioning; confirm any replacement battery was **coded to the BMS**. []
7. Confirm head-unit & telematics **software is latest level** and correctly configured / coded to the VIN. []
8. Test / replace the **key-fob battery** (rule out the simple cause of the keyless fault). []

Escalation

The fault has survived replacement of **two major modules**. Please open a case with **Renault Technical (RTECH)** for factory support. The owner has opened / will open a case with Renault UK (reference above) and is keeping a dated log of all visits.

Dealer findings / actions / advisor / date: