# 1.0 경보 배치도

r	1	2	3	4	5
A	OVERPOWER	OVERTEMP	LOOP 1 RC	LOOP 2 RC	LOOP 3 RC
	DT (C4)	DT (C3)	T AVG	T AVG	T AVG
	ALERT	ALERT	HIGH	HIGH	HIGH
	1/33	2/33	3/33	4/33	5/33
В	RPS RC	RPS RC	LOOP 1 RC	LOOP 2 RC	LOOP 3 RC
	OVERPOWER DT	OVERTEMP DT	T AVG/AUCT	T AVG/AUCT	T AVG/AUCT
	ALERT	ALERT	T AVG HIGH	T AVG HIGH	T AVG HIGH
	6/33	7/33	8/33	9/33	10/33
С	T REF/AUCT	SSPS	LOOP 1 RC	LOOP 2 RC	LOOP 3 RC
	T AVG	T AVG	T AVG/AUCT	T AVG/AUCT	T AVG/AUCT
	HIGH	LOW-LOW	T AVG LOW	T AVG LOW	T AVG LOW
	11/33	12/33	13/33	14/33	15/33
D	T REF/AUCT		LOOP 1 RC	LOOP 2 RC	LOOP 3 RC
	T AVG		DT/AUCT DT	DT/AUCT DT	DT/AUCT DT
	LOW		TEMP HIGH	TEMP HIGH	TEMP HIGH
	16/33		17/33	18/33	19/33
Е	LTOP		LOOP 1 RC	LOOP 2 RC	LOOP 3 RC
	ARMING		DT/AUCT DT	DT/AUCT DT	DT/AUCT DT
	TEMP		TEMP LOW	TEMP LOW	TEMP LOW
	20/33		21/33	22/33	23/33
F	RCS PRESS				
	HIGH AT				
	COLD				
	24/33				
ŀ	•	DCD DUC			,
G		RCP BUS UNDER FREQ			
		ALERT			
ŀ		25/33			
Н		RCP	RCP A	RCP B	RCP C
		UNDER VOLT	VIBRATION	VIBRATION	VIBRATION
		ALERT	HI/HI-HI	HI/HI-HI	HI/HI-HI
-		26/33	27/33	28/33	29/33
I		LOW TEMP			
		T AVG OR			
		T ERROR			
		30/33			
J		'	RC LOOP 1	RC LOOP 2	RC LOOP 3
			LO FLOW	LO FLOW	LO FLOW
			ALERT	ALERT	ALERT
L			31/33	32/33	33/33

고리원자력본부

제2발전소

제 목 : 원자로 보조기기 제어반

(RK-UA-908)

절차서 번호	경보-08	
개정번호	10	
페 이 지	3 / 33	

LOOP 1 RC T AVG HIGH 경보창 위치: RK-UA-908-A-3

설 정 치 : 310.0 ℃

발 생 원 : BB-TB-412D 컴퓨터 I·D : T0400, T0401

# 1.0 원인

- 1.1 고출력 운전상태에서 터빈출력 급감발시
- 1.2 제어봉의 비정상적인 인출 또는 붕소희석으로 인한 중성자속 증가시
- 1.3 계기 고장

### 2.0 자동동작사항

2.1 제어봉의 자동 삽입 발생(Tavg-Tref 편차에 의해)

#### 3.0 결과

3.1 OPDT, OTDT 설정치 강하

#### 4.0 긴급조치

- 4.1 터빈출력 급감발에 의해 경보 발생시 제어봉이 자동으로 삽입되는지 확인한다.
- 4.2 제어봉의 비정상 인출 또는 붕소희석으로 인해 경보 발생시 제어봉을 수동으로 조절하여 Tavg를 정상상태로 복구한다.
- 4.3 Loop 1, 2, 3의 Tavg를 비교한다.

#### 5.0 후속조치

- 5.1 봉소희석으로 인해 중성자속 증가시 봉소열재생계통 및 원자로보충수계통의 밸브 배열을 확인하여 조치한다.
- 5.2 계기 고장이면 정비 의뢰한다.

#### 6.0 관련 신호

6.1 TB 62-10 (9460,S0,NO)

#### 7.0 참조

- 7.1 3-J-BB-208, 3-J-SB-222
- 7.2 3-J-PCD-F002
- 7.3 3-M-BB-F001, F003
- 7.4 고리 3,4호기 설정치 종합목록

# RK-UA-908-A-3(JP005)

고리원자력본부

제2발전소

제 목 : 원자로 보조기기 제어반

(RK-UA-908)

절차서 번호 경보-08 개 정 번 호 10 페 이 지 4 / 33

LOOP 2 RC T AVG HIGH 경보창 위치: RK-UA-908-A-4

설 정 치 : 310.0 ℃

발 생 원 : BB-TB-422D 컴퓨터 I·D : T0420, T0421

#### 1.0 원인

- 1.1 고출력 운전상태에서 터빈출력 급감발시
- 1.2 제어봉의 비정상적인 인출 또는 붕소희석으로 인한 중성자속 증가시
- 1.3 계기 고장

### 2.0 자동동작사항

2.1 제어봉의 자동 삽입 발생(Tavg-Tref 편차에 의해)

#### 3.0 결과

3.1 OPDT, OTDT 설정치 강하

#### 4.0 긴급조치

- 4.1 터빈출력 급감발에 의해 경보 발생시 제어봉이 자동으로 삽입되는지 확인한다.
- 4.2 제어봉의 비정상 인출 또는 붕소희석으로 인해 경보 발생시 제어봉을 수동으로 조절하여 Tavg를 정상상태로 복구한다.
- 4.3 Loop 1, 2, 3의 Tavg를 비교한다.

#### 5.0 후속조치

- 5.1 봉소희석으로 인해 중성자속 증가시 봉소열재생계통 및 원자로보충수계통의 밸브 배열을 확인하여 조치한다.
- 5.2 계기 고장이면 정비 의뢰한다.

#### 6.0 관련 신호

6.1 TB 67-10 (3B40,S0,NO)

#### 7.0 참조

- 7.1 3-J-BB-208, 3-J-SB-222
- 7.2 3-J-PCD-F003
- 7.3 3-M-BB-F001, F003
- 7.4 고리 3,4호기 설정치 종합목록

# RK-UA-908-A-4(JP005)

고리원자력본부

제2발전소

제 목 : 원자로 보조기기 제어반

(RK-UA-908)

절차서 번호 경보-08 개 정 번 호 10 페 이 지 5 / 33

LOOP 3 RC T AVG HIGH 경보창 위치: RK-UA-908-A-5

설 정 치 : 310.0 ℃

발 생 원 : BB-TB-432D 컴퓨터 I·D : T0440, T0441

# 1.0 원인

- 1.1 고출력 운전상태에서 터빈출력 급감발시
- 1.2 제어봉의 비정상적인 인출 또는 붕소희석으로 인한 중성자속 증가시
- 1.3 계기 고장

### 2.0 자동동작사항

2.1 제어봉의 자동 삽입 발생(Tavg-Tref 편차에 의해)

#### 3.0 결과

3.1 OPDT, OTDT 설정치 강하

#### 4.0 긴급조치

- 4.1 터빈출력 급감발에 의해 경보 발생시 제어봉이 자동으로 삽입되는지 확인한다.
- 4.2 제어봉의 비정상 인출 또는 붕소희석으로 인해 경보 발생시 제어봉을 수동으로 조절하여 Tavg를 정상상태로 복구한다.
- 4.3 Loop 1, 2, 3의 Tavg를 비교한다.

#### 5.0 후속조치

- 5.1 봉소희석으로 인해 중성자속 증가시 봉소열재생계통 및 원자로보충수계통의 밸브 배열을 확인하여 조치한다.
- 5.2 계기 고장이면 정비 의뢰한다.

#### 6.0 관련 신호

6.1 TB 62-17 (3B50,S0,NO)

#### 7.0 참조

- 7.1 3-J-BB-208, 3-J-SB-222
- 7.2 3-J-PCD-F004
- 7.3 3-M-BB-F001, F003
- 7.4 고리 3,4호기 설정치 종합목록

# RK-UA-908-A-5(JP005)