



THE COMPANY

Home Inspection Group



1634 Benedict Canyon Drive, Beverly Hills, CA 90210

Inspection prepared for: Mike Cheringal

Date of Inspection: 3/16/2021 Time: 9:00 AM

Age of Home: 1936 Size: 3921

Weather: cold, clear

Order ID: 354

Inspector: Rodrigo Gomez

InterNACHI CPI

Phone: (909)771-3521

Email: Thecompanyrod@gmail.com



213-393-3670



DISCLOSURES – PLEASE READ THE ENTIRE REPORT.

In order for you to receive the full value of this inspection, please read all of the information we have provided.

RED PRINT – Indicates items of **IMMEDIATE CONCERN** to this structure. These items should be further evaluated and addressed before closing escrow. However, the entire report must be read for full disclosure, as other items written in this report may also require further evaluation as deemed necessary by those parties reading the report. If further evaluation is not performed and additional defects are found after the contingency period has expired, disputes or claims against this inspection will be denied. Failing to read this report and follow the advice contained here is not cause for holding the inspector, the inspection report, or The Company Home Inspection Group Inc. liable.

This is a limited inspection: A home inspection is meant to reflect, as accurately as possible, the visible condition of the home during the time of the inspection only, it doesn't reflect, anticipate or predict future conditions. Conditions at a property for sale can change drastically over night. So a home inspection is not meant to guarantee what condition the home will be after the transaction finalizes. During the inspection your inspector didn't dismantle equipment, dismantle any structural items, or destructive testing. Any areas that are hidden, painted over, or aren't readily visible are not covered in this report. This report is not a guarantee or warranty on the condition of your property or it's contents. This report provides an unbiased visual inspection only. Defects will be indicated and marked as such, even though the condition may be considered normal for the age, and should be inspected by the appropriate licensed contractor. The inspector doesn't determine the age or remaining life of any system or building material during this inspection. Cosmetic issues are considered obvious and are often not included in the report. Your report doesn't include all items covered in the Real Estate Transfer Disclosure Form. We recommend that you read the full disclaimers page in complete detail to understand the limitation of a Home Inspection.

An Attorney, and/or Real Estate Broker should be consulted on additional items not included in this report.

ENVIRONMENTAL DISCLAIMER: Mold spores, asbestos, formaldehyde, lead paint, radon, poria, Chinese drywall and all other toxic items/materials or concern cannot be identified as dangerous/toxic with this inspection report. Your inspector is not certified to identify these dangerous or toxic items/materials and will not include any information about them in this report. It is recommended the client have the property tested by certified professionals on these areas, on all cases.

Buildings constructed between 1965 and 1974 have the possibility of having aluminum wiring throughout the structure. It's recommended to have a licensed electrician further evaluate houses built in this era for aluminum wiring. Houses with galvanized or cast iron plumbing present are recommended to be further evaluated by a plumbing contractor regardless of the age or condition of the plumbing.

Buildings constructed prior to 1978 may contain asbestos materials. It's recommended to have a licensed asbestos contractor further evaluated houses built in this era for asbestos material.

Buildings constructed prior to 1978 may contain lead paint. It's recommended that a licensed lead paint specialist further evaluate houses built in this era for lead paint material.

The Company Home Inspection Group will not engage in any claims regarding lead paint, asbestos, or aluminum wiring.

Please carefully read your entire inspection report. Call the inspector after you've reviewed your report, so we can go over any questions or concerns you may have, throughout the entire closing process.

The inspection report is based on the inspection of the visible areas of the structure. The inspection may be limited by height restrictions, vegetation, weather, and possessions. Depending on the age of the property some items like GFCI outlets may not be installed. This report/inspection focuses on safety and function, not current building codes. This report identifies specific non-building code, non-cosmetic concerns that the inspector may feel needs further investigation or repair. It's not a requirement that a home being sold be brought up to today's building code standards.

A home inspector is not a code inspector. We advise you to check all building permits for all areas of the structures present. If the property building permits have not been obtained or don't have final building inspection signatures, then you shouldn't assume that these areas were installed to applicable building codes. Further investigation/evaluation beyond the scope of the home inspection may be needed.

"Needing service" or "needs to be serviced" will be a common phrase/comment used throughout this inspection report, it means in the inspectors opinion, maintenance, repair, or upgrade may be needed and the item should be further evaluated by the proper professional. Often items discovered by the inspector or only small clues to a potentially bigger issue, further evaluating may uncover items the inspector didn't see or disclose during the inspection.

For your safety and liability purposes, we always recommend that licensed contractors further evaluate and repair any and all concerns or defects noted in the report.

Sewer scope/Lateral Sewer Line Camera Inspection: Any underground drain cannot be viewed by the inspector. They can often have internal issues that cannot be viewed or detected during the home inspection. We always advise to have a sewer camera inspection before the end of your

inspection contingency's.

Every home or structure is different/unique, therefore may be inspected in different formats. Inspections usually can take anywhere from 1 to 5 hrs depending on the size, age, and condition of the structure being inspected. Inspection methods are generally the same among all inspectors, however experience and personal preference may differ between inspectors. The same goes for report writing, inspectors are given the freedom to narrate or edit comments they see fit for each inspection. An inspector cannot predict or find every defect in the property being inspected. The time frame of an inspection only allows the inspector to examine areas in a location by location order. If a defect arises in another area of the property (this includes the exterior) for which this defect was not visible or present during the inspection, then the inspector cannot be liable for notifying of the defect.

There is no set time frame for how long each water fixture should be operated. Water will be turned on at all accessible/visible water fixtures in the property. Leaks can only be documented if they're visible at the time of operating the designated fixture during the inspection. Future leaks cannot be detected. The inspector cannot determine if they're plumbing leaks inside a wall or ceiling unless visible moisture or evidence of moisture are present and visible during the inspection. The inspection does not give confirmation of water conservation devices at any fixture.

This report is meant to reflect the defects found in a home at the time of the inspection. It doesn't predict future conditions. We always recommend that you or your representation conduct a final walk through inspection before closing to check the condition of the property. Conditions may change at any time during the escrow period. You're responsible for verifying all conditions before the close of escrow.

This inspection report is non-transferable to another party.

Thank you for using The Company Home Inspection Group.

INSPECTION AGREEMENT

By acceptance of this inspection report, you agree to the terms of this agreement and the terms & conditions of the contract. You further agree that you understand the limitations of a home inspection and have read the disclaimer page of this report.

SCOPE OF THE INSPECTION / REPORT

We will perform a non-invasive visual examination designed to identify material defects in the systems, structures, and components of buildings located on the property to be inspected, as they exist at the time of the inspection. Our inspection will be limited to those specific systems, structures and components that are present and visually accessible. We will only operate components and systems with normal user controls and as conditions permit. Unless we agree otherwise, we will only inspect the primary building, and its associated primary parking structure on the property. Out structures are not included in our inspection: this exclusion encompasses exterior barbecues, appliances, fire pits, fire places, play equipment, ponds or fountains, sheds, workshops, lean-to structures, barns, etc.. We will also provide you with a written report that describes and identifies the inspected systems, structures and components and any visible material defects observed at the time of the inspection. We may amend the report within twenty-four (24) hours after completing the inspection.

RE-INSPECTION: A re-inspection may be scheduled with our office as needed to re-evaluate specific items that may have been repaired since our original inspection or that may have been obstructed and not visible or accessible during the original inspection. The fee for a re-inspection varies upon how many items are to be re-inspected and/or the length of time required to perform the re-inspection. A re-inspection is completed only for the items specified in writing by the buyer or buyer's Agent at the time of the re-inspection. A re-inspection does not include a complete inspection of the entire home or property, however the Inspector may update the inspection report with additional defects observed at the re-inspection that may not have been visible or accessible during the original inspection. It is recommended that you obtain all the necessary building permits, contractor receipts and any warranties provided by the manufacturer/installer/contractor for the repaired or replaced items. Unless we agree otherwise, we will perform the inspection, and issue the report, in accordance with the mandatory parts of the current Standards of Practice (Residential Standards - Four or Less Units) of the International Association of Certified Home Inspectors ("the InterNACHI Standards") and subject to the Definitions, Scope, Limitations, Exceptions and Exclusions in the InterNACHI Standards. Terms in this Agreement have the same meaning as the defined terms in the InterNACHI Standards. The InterNACHI Standards are available from InterNACHI's website: <http://www.nachi.org/>

IF YOU DISCOVER A DEFECT FOR WHICH YOU THINK WE MAY BE LIABLE TO YOU, YOU MUST NOTIFY US AND GIVE US A REASONABLE OPPORTUNITY TO RE-INSPECT THE PROPERTY BEFORE YOU REPAIR THE DEFECT. FAILURE TO FOLLOW THIS PROCESS WILL RESULT IN VOIDING THIS AGREEMENT AND CONTRACT. YOUR NOTICE MUST BE IN WRITING, INCLUDE A SIGNED COPY OF THIS AGREEMENT, AND BE MAILED TO OUR CORPORATE OFFICE:

The Company Home Inspection Group, Attn: Inspector Supervisor, 9668 Milliken Avenue, Suite 104-181, Rancho Cucamonga, CA 91730

OUR LIABILITY TO YOU FOR CLAIMS ARISING FROM OUR INSPECTION OR OUR REPORT, WHETHER SOUNDING IN TORT OR CONTRACT, WILL NOT BE MORE THAN THE LESSER OF ACTUAL DAMAGES OR THREE (3) TIMES THE INSPECTION FEE. TCHIP (The Company Home Inspection Group, Inc.) AND CLIENT AGREE THAT CLIENT CANNOT FILE A LEGAL ACTION AGAINST TCHIP OR ITS EMPLOYEES, WHETHER SOUNDING IN TORT OR CONTRACT, MORE THAN ONE YEAR AFTER THE CLIENT DISCOVERS, OR WITH THE EXERCISE OF REASONABLE DILIGENCE SHOULD HAVE DISCOVERED THE BREACH OR MATERIAL DEFECT.

Our report is NOT a warranty of the items inspected. However, The Company Home Inspection Group, Inc. may offer you additional warranties through a third party service provider. In all cases, you must contact your home warranty company first for any issues that arise after the date of the original home inspection. Failure to do so may result in voiding your home warranty.

Additional questions or concerns can be addressed through our customer service phone: 213-393-3670

Please read the "About Your Inspection" and "Disclaimers" pages prior to filing any online claims as this will help you to determine if your claim is valid and within the scope of the home inspection.

CONFLICT OF INTEREST DISCLOSURE AND STATEMENT OF COMMITMENT

Our goal is to provide valuable and unbiased information that helps consumers make informed decisions. A portion of our business may be based on relationships with other professions- real estate sales professionals, lawyers, lenders, vendors, etc., and our reports sometimes conflict with the business interests of these parties. We do not allow these relationships to compromise the integrity of our service. However, they do enable us to deliver more value to our clients. Our reports are intended to accurately reflect our impartial professional opinion, without exception.

YOU MUST PAY THE INSPECTION FEE AND SIGN THE CONTRACT BEFORE WE CAN DELIVER THE REPORT TO YOU.

Summary Page

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expenses to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all of the pages of the report as the summary alone does not explain all the issues. Further evaluation is recommended for any item written in red text or marked "Service recommended" on this report -- further evaluation often times will allow a contractor to find additional items needing repair beyond the scope of the home inspection. Failure to further evaluate any item as recommended releases us of any liability.

Interior		
Page 11 Item: 1	Wall Conditions	• Microbial growth/irregular staining present – further evaluation is recommended - wine cellar
Page 12 Item: 2	Ceiling Conditions	• Stains/blistered areas present – moisture present when tested with moisture meter – recommend further evaluation
Page 14 Item: 8	Fireplaces	• No damper stop clamp – required for cosmetic gas logs, fire-glass or other cosmetic fire system that uses gas at the primary fuel • Missing spark screen – service recommended • Moisture damage – service recommended- pool house
Page 16 Item: 14	Smoke Detectors	• Missing at hall – needs to be installed - West hall & pool house
Page 16 Item: 15	Carbon Monoxide Detectors	• Missing at hall – needs to be installed in West hall - Main hall - North hall & pool house
Bedrooms		
Page 19 Item: 5	Window Conditions	• Missing crank handle(s) or stripped crank(s) – window(s) not tested – service recommended - multiple windows • Inner seals at double pane windows are bulging/moving due to heat – service recommended
Page 20 Item: 6	Doors	• Missing lock - multiple doors - service recommended
Page 21 Item: 7	Sliding Glass Doors	• Did not open properly – service recommended - Master bedroom - right side
Bathrooms		
Page 23 Item: 2	Wall Conditions	• Cracked tiles - West bathroom - service recommended
Page 23 Item: 3	Ceiling Conditions	• Cracking observed throughout structure - recommend patching and painting
Page 25 Item: 6	Doors	• Missing lock - multiple doors - service recommended
Page 26 Item: 9	Sinks	• Drain operated slowly – service recommended - Master bathroom - left sink - Half Bath
Page 28 Item: 11	Bath Tubs	• Tub fixture not operating properly – needs to be further evaluated by a Licensed Plumber - Master bathroom • Hot water above 120 degrees, recommend adjusting the temperature at the water heater or upgrading fixture to anti-scald device - throughout property
Page 28 Item: 12	Showers	• Hot water does not operate properly – service recommended - Northwest bathroom • Drain operated slowly – service recommended – West bathroom

Page 29 Item: 13	Shower Walls	Cracked/loose/missing grout in areas – recommend grout and sealer
Page 29 Item: 14	Enclosures / Shower doors	Evidence of past leaking – recommend resealing the enclosure to prevent further leaking - Master bathroom
Page 30 Item: 15	Toilets	Toilet did not flush properly – service recommended - West bathroom
Page 31 Item: 18	Electrical	Some bulbs defective/missing/light(s) did not function – check bulbs/consult electrician to further evaluate - throughout entire property

Kitchen

Page 37 Item: 10	Spray Wands	Sprayer not operational – service recommended
Page 37 Item: 12	Dishwashers	Leaking at door – service recommended
Page 39 Item: 17	Microwaves	Not operating properly – service recommended - needs to be replaced

Laundry Area

Page 44 Item: 11	Gas Valve	Gas smell present – recommend Gas Company to evaluate
------------------	------------------	---

Heating/Air Conditioning

Page 46 Item: 5	Gas Supply Valves and Pipes	- No sediment trap at gas supply – may have not been required at time of original installation, but is recommended - Gas supply pipe not properly supported & significant rusting present– service recommended- roof
Page 49 Item: 14	Air Conditioning Compressors	Split unit in pool house not tested - remote not present – service recommended

Water Heater(s)

Page 50 Item: 1	Water Heaters Condition	Unit old and appears to be nearing end of useful life – we recommend that you budget for a replacement- pool house
Page 50 Item: 2	Venting	- Missing screws at vent connections – service recommended, three screws are recommended at all vent connections- both - Draft hood is loose and not properly secured over the water heater exhaust area – service recommended- pool house
Page 51 Item: 3	Plumbing	- Corrosion present – service recommended - Expansion tank at the water is not properly secure- recommend further evaluation
Page 52 Item: 11	Enclosures	Microbial growth/irregular staining present – further evaluation is recommended- main house

Electrical/Gas Service

Page 54 Item: 2	Sub Panels	- Sharp-pointed metal screws hold panel cover in place. These are a potential hazard as they may puncture wire insulation and electrify panel box, becoming a shock or electrocution hazard. These screws should be replaced with approved, flat-tipped screws. Throughout - Modifications present at old Zinsco panel – further evaluation is recommended - front closet - Manufacture of panel a brand (Zinsco/Sylvania/Federal Pacific/Stab-Lok) known for frequent issues – recommend further evaluation by a Licensed Electrician
Page 56 Item: 4	Breakers	- Loose breakers present – service recommended-garage - Manufacture of breakers/panel is a brand (Zinsco/Sylvania/Federal Pacific/Stab-Lok) known for frequent issues – recommend further

		evaluation by a Licensed Electrician- pool house
Page 57 Item: 6	Main Gas Valve	Gas smell present at the main valve – recommend contacting the gas utility company to repair

Attic Area

Page 58 Item: 2	Structure	Evidence of past or present leaks, dry at time of the inspection – recommend Licensed Roofing Contractor to evaluate
Page 59 Item: 3	Insulation	Attic insulation is in contact with recessed light. These older recessed ceiling cans trap heat, degrading the in-contact surrounding insulation, thereby increasing its combustion potential. This is a fire hazard. A minimum of 3" clearance is required from insulation material. Recommend a qualified contractor review these recessed lights and repair as needed.

Garage and/or Carport

Page 61 Item: 3	Main Automotive Doors	Missing and or damaged bottom seal – service recommended
Page 63 Item: 11	Slab	Evidence of past moisture intrusion– needs to be further evaluated
Page 64 Item: 15	Ventilation	None – recommend installing ventilation for garage

Exterior Areas

Page 65 Item: 1	Stucco	- Cracking/chipping/holes more than typical – service recommended - Condensation/moisture present – appears to be seeping through from roof gutter areas - recommend further evaluation
-----------------	---------------	--

Foundation

Page 68 Item: 3	Access Panels	Solid access cover present, recommend installing a cover with a screen to assist in ventilating the space
Page 68 Item: 4	Foundation Walls	Concrete deterioration present– service recommended
Page 70 Item: 10	Ventilation	Inadequate venting observed in crawlspace – recommend installing additional vents for proper moisture control
Page 71 Item: 12	Electrical	Conduit or metal wire sheathing in contact with soil – service recommended
Page 71 Item: 13	Plumbing	Visibly leaking plumbing – recommend immediate evaluation by a Licensed Plumber to prevent unwanted moisture in crawl space • Water supply pipes not properly fastened/supported – service recommended

Grounds

Page 73 Item: 1	Driveways and Walkways	Cracking/blistering materials– service recommended
Page 73 Item: 3	Stairs & Handrails	Wood deterioration present on steps – service recommended
Page 74 Item: 4	Exterior Electrical	Electrical fixtures(lights) need to be caulked/sealed to wall attachments to help prevent moisture entry • Non – energized (dead) outlet(s) – service recommended- outside pool house
Page 76 Item: 8	Water Pressure	Pressure is higher than 120 psi, we recommend that a plumber further evaluate this high pressure as soon as possible
Page 76 Item: 9	Pressure Regulator	Installed but pressure is above 80 PSI – service recommended by a plumbing contractor

Page 76 Item: 11	Fencing and Walls	• Wood retaining walls deteriorated/loose – limited service life remaining
Page 77 Item: 12	Gates	• Gate(s) not self closing or latching properly – needs to be further evaluated by a Licensed Pool Contractor for safety • Blistering paint /rusting present – service recommended
Page 78 Item: 13	Planters	• No drain(s) visible for planter, recommend confirm or installation – service recommended • Planter walls are being affected by plant/tree roots – service recommended
Page 78 Item: 14	Grading	• Underground drains visible from inlet openings filled with soil/debris - drained slowly– service recommended/cleaned

Roof

Page 80 Item: 1	Condition	• Roof material not properly fastened – service recommended- see picture for location
Page 82 Item: 4	Vents and Vent Caps	• Mastic at vent(s) is weathered and cracked – service recommended and resealed at all penetration points

Pool and/or Spa

Page 85 Item: 9	Timers	• Missing interior shock cover – service recommended- light timer located on garage wall
Page 86 Item: 12	Heater	• Not functional/not operating – service recommended
Page 86 Item: 13	Tile	• Missing in sections – service recommended • Heavy mineral build-up – service recommended
Page 88 Item: 17	Structure	• Plaster finish rough – service recommended

The Company Inspection

1. Additional Items Added

Observations:

- Sprinklers were tested during this inspection – see the Grounds page of the report in the sprinkler section for additional details
- A thermal imaging infrared apparatus was used in areas of the home to help look for moisture leaks, take temperatures as needed, look for air leaks in the HVAC system and to look for hot or overheating parts of the electrical system. Photos will be included in the inspection report and labeled if defects exist.
- **Visible Microbial growth/irregular staining was detected today during this inspection; further evaluation is recommended**

Overview

1. Inspection Details

Inspection type: The Company Premier Home Inspection

Single Family Residence

Front door faces West (approximate)

All Utilities are ON for this inspection

Vacant structure – some areas contain staging materials or personal items left behind – these items are not moved and will prevent a complete inspection and limit visible access to some areas (this applies to all areas inside and outside of the structure being inspected).

Evidence of remodeling in areas – check all building permits to ensure that all remodeled areas were completed properly to city/county code

2. Main Utilities Location

- Main water valve shut off location: West side of structure
- Main gas valve shut off location: West side of structure
- Main electrical panel location: West side of structure

3. Who is present at the inspection?

- Buyer present during inspection
- Buyer's agent present during inspection
- Seller's agent present during inspection
- Roofing/Geologist/Contractor/Specialist present during inspection (see any additional reports/notes from these contractors)
- Termite Inspector present during the inspection (see additional report/notes from this contractor regarding this structure)
- Sewer Scope Inspector present during inspection

4. Wall materials throughout the structure

Drywall

5. Ceiling materials throughout the structure

Drywall

6. Floor materials throughout the structure

Tile • Wood (cannot determine type: might be hardwood, engineered or laminate)

7. Window materials/type throughout the structure

Double pane • Aluminum framed • Fixed frame or stationary type (does not open or close) • Crank style