| Step<br>Number | Step Title         |          | Parts list         | To       | ools list     | Remarks   |
|----------------|--------------------|----------|--------------------|----------|---------------|---|
|                | Stop mus           | Quantity | Part name          | Quantity | Tool name     |   |
| 01             | Bottom Panel       | 1        | Bottom Panel       | 1        | Allen Key 5.0 | Do not tighten the screws yet for further alignment.  |
|                |                    | 8        | B-screw M8-10      | 1        | Allen Key 4.0 | On the right profile, insert T-nuts M6 and attach it to the Bottom Panel, with the cable duct on top. |
|                |                    | 4        | B-screw M6-12      | 1        | Ruler         | Position the cable duct starting about 70 mm from the front of the machine.                           |
|                |                    | 3        | Profile 30-1100    |          |               |   |
|                |                    | 1        | Cable Duct         |          |               |   |
|                |                    | 8        | T-nut M8           |          |               |   |
|                |                    | 4        | T-nut M6           |          |               |   |
| 02             | Attach Electronics | 2        | Motor Driver       | 1        | Allen Key 2.5 | All motor drivers should have the switches pointing outwards.   |
|                |                    | 1        | Small Motor Driver | 1        | Allen Key 3.0 |   |
|                |                    | 1        | Logic Power Supply |          |               |   |
|                |                    | 1        | Laser Power Supply |          |               |   |
|                |                    | 1        | Controller PCB     |          |               |   |
|                |                    | 4        | Plastic Screw M3-8 |          |               |   |
|                |                    | 4        | Standoff M3 MF     |          |               |   |
|                |                    | 6        | C-screw M3-10      |          |               |   |
|                |                    | 3        | C-screw M3-6       |          |               |   |
|                |                    | 4        | C-screw M4-6       |          |               |   |
| 03.1           | Inner Right Panel  | 1        | Inner Right Panel  | 1        | Allen Key 3.0 | Attach the parts before inserting the panel in the Bottom Panel.                                      |
|                |                    | 1        | Motor Power Supply |          |               |   |
|                |                    | 3        | C-screw M4-6       |          |               |   |
| 03.2           | Y-motor            | 1        | Cable Duct         | 1        | Allen Key 3.0 | Fix the pulley on the motor shaft aligning it to the edge, with the setscrews towards the motor side. |

| Step<br>Number | Step Title                        |          | Parts list          | To       | ools list     | Remarks  |
|----------------|-----------------------------------|----------|---------------------|----------|---------------|--|
|                | Stop mis                          | Quantity | Part name           | Quantity | Tool name     |  |
|                |                                   | 5        | C-screw M4-6        | 1        | Wrench 5.5    | Tighten the set screws of the pulley to the flat part of the motor shaft.                            |
|                |                                   | 4        | Lock Nut M4         |          |               | Insert the belt before fixing the motor on the Inner Right Panel.                                    |
|                |                                   | 1        | Y-motor Belt        |          |               | Fix the cable duct after attaching the motor. They should not be touching each other.                |
|                |                                   | 1        | Y-motor Pulley      |          |               |  |
|                |                                   | 1        | Y-motor             |          |               |  |
|                |                                   | 1        | Y-motor Holder      |          |               |  |
|                |                                   | 4        | Washer M4           |          |               |  |
|                |                                   | 4        | C-screw M4-45       |          |               |  |
| 04             | Inner Left Panel and Middle Panel | 1        | Inner Left Panel    | 1        | Allen Key 5.0 | The side indent of the Middle Panel needs to point to the left of the machine (from the front view). |
|                |                                   | 1        | Middle Panel        |          |               |  |
|                |                                   | 3        | Hinge Support       |          |               |  |
|                |                                   | 6        | B-screw M8-35       |          |               |  |
|                |                                   | 6        | Lock Nut M8         |          |               |  |
| 05             | Laser Panel                       | 1        | Laser Panel         | 1        | Allen Key 3.0 | The base of the First Mirror Holder should be fixed upside-down on the bottom of the Laser Panel     |
|                |                                   | 1        | First Mirror Holder | 1        | Allen Key 4.0 |  |
|                |                                   | 2        | Laser Tube Holder   |          |               |  |
|                |                                   | 8        | C-screw M5-16       |          |               |  |
|                |                                   | 2        | C-screw M4-10       |          |               |  |

| Step<br>Number | Step Title     |          | Parts list              | To       | ools list     | Remarks  |
|----------------|----------------|----------|-------------------------|----------|---------------|--|
|                | Stop Halo      | Quantity | Part name               | Quantity | Tool name     | Remarks  |
| 06             | Pistons        |          |                         |          |               |  |
|                |                | 2        | Piston                  |          |               |  |
|                |                |          |                         | 1        | Wrench 13     |  |
|                |                | 2        | Piston Support          |          |               |  |
|                |                |          |                         | 1        | Allen Key 5.0 |  |
|                |                | 9        | Lock Nut M8             |          | -             |  |
|                |                | 2        | Washer M8               |          |               |  |
|                |                | 5        | B-screw M8-35           |          |               |  |
|                |                | 1        | B-screw M8-25           |          |               |  |
|                |                | 1        | Thin Nut M8             |          |               |  |
|                |                | 2        | B-screw M8-60           |          |               |  |
| 07             | Sensor Holders | 1        | Window Sensor           | 1        | Allen Key 2.5 |  |
|                |                | 1        | Window Sensor Holder    | 1        | Wrench 5.5    |  |
|                |                | 4        | C-screw M3-10           |          |               |  |
|                |                | 2        | C-screw M3-12           |          |               |  |
|                |                | 2        | Lock Nut M3             |          |               |  |
|                |                | 1        | Y-endstop Sensor Holder |          |               |  |
|                |                | 1        | Y-endstop Sensor        |          |               |  |
| 08             | Back Panel     | 1        | Back Panel              | 1        | Allen Key 3.0 | To fit the panel, move the machine slightly out of the table. Use a rubber hammner if necessary. |
|                |                | 2        | Water Connector         | 1        | Allen Key 5.0 | Fix the Air connector in the left hole and the Chiller Sensor Connector in the right hole.       |
|                |                | 1        | Air Connector           | 1        | Wrench 13     |  |

| Step<br>Number | Step Title        | Parts list |                          | Tools list |                             | Remarks  |
|----------------|-------------------|------------|--------------------------|------------|-----------------------------|--|
|                | Step Hile         | Quantity   | Part name                | Quantity   | Tool name                   | Remarks  |
|                |                   | 1          | Chiller Sensor Connector | 1          | Rubber Hammer               |  |
|                |                   | 1          | Power Socket             | 1          | Wrench 19                   |  |
|                |                   | 2          | C-screw M4-6             |            |                             |  |
|                |                   | 7          | B-screw M8-20            |            |                             |  |
|                |                   | 1          | Exhaust Adaptor          |            |                             |  |
|                |                   | 4          | Lock Nut M8              |            |                             |  |
| 09.1           | Bed Frame         | 2          | Angle Profile            | 1          | Allen Key 5.0               |  |
|                |                   | 2          | Profile 40-700           |            |                             |  |
|                |                   | 4          | T-nut M8                 |            |                             |  |
|                |                   | 4          | B-screw M8-16            |            |                             |  |
|                |                   | 4          | B-screw M8-10            |            |                             |  |
| 09.2           | Bed Legs          | 4          | Bed Leg                  | 1          | Wrench 13                   |  |
|                |                   | 4          | Lock Nut M8              |            |                             |  |
|                |                   | 4          | Bed Adjuster             |            |                             |  |
| 09.3           | Bed Lamella       | 27         | Bed Lamella              | 1          | Paper Cutter or<br>Scissors | The Angle Profiles should be placed with the larger side down.     |
|                |                   | 1          | Double-sided Tape        |            |                             | For the last Angle Profile, place it pointing backwards.           |
| 09.4           | Inserting the Bed | 4          | Washer M8 Large          |            |                             |  |
| 10             | Front Panel       | 1          | Front Panel              | 1          | Allen Key 5.0               | After fixing the Front Panel, tighten all the Bottom Panel screws. |
|                |                   | 6          | T-nut M8                 |            |                             | Insert the T-nut in the side of the profiles.                      |
|                |                   | 3          | B-screw M8-20            |            |                             |  |

| Step<br>Number | Step Title           |          | Parts list            | To       | ools list     | Remarks   |
|----------------|----------------------|----------|-----------------------|----------|---------------|---|
|                |                      | Quantity | Part name             | Quantity | Tool name     |   |
| 11             | Y-axis Guide         | 2        | Y-linear Shaft        | 1        | Allen Key 6.0 | Insert the Y-guide Blocks in the guide before fixing it.  |
|                |                      | 1        | Y-bearing Block Left  | 1        | Wrench 10     | Work with 2 people.   |
|                |                      | 1        | Y-bearing Block Right |          |               | Insert the Hex Screw in the Y-bearing Block Right.  |
|                |                      | 4        | B-screw M12-20        |          |               |   |
|                |                      | 1        | Hex Screw M6-12       |          |               |   |
| 12.1           | Y-axis Motion Back 1 | 5        | Bearing Unit          | 1        | Allen Key 6.0 | The Bearing units need to be fixed with the setscrews pointing left (right side of the machine looking from the front).                 |
|                |                      | 10       | B-screw M10-12        |          |               |   |
| 12.2           | Y-axis Motion Back 2 | 1        | Y-shaft 1400          | 1        | Lubricant     | For inserting the shaft, the bearings of the Bearing Units can tilt. Use some force and lubricant.                                      |
|                |                      | 2        | Y-pulley 26-5M-15     | 1        | Rubber Hammer | Pulleys need to be inserted while inserting the shaft, with setscrews pointing left (right side of the machine looking from the front). |
|                |                      | 4        | Setscrew              |          |               | Y Pulley 26-5M-15   |
|                |                      | 1        | Y-pulley 26-5M-09     |          |               | Start inserting the shaft from the left side of the machine.  |
| 12.3           | Y-axis Motion Front  | 4        | Bearing Unit          | 1        | Allen Key 6.0 |   |
|                |                      | 2        | Y Pulley 26-5M-15     |          |               |   |
|                |                      | 2        | Setscrew              |          |               |   |
|                |                      | 1        | Y-shaft Left 100      |          |               |   |
|                |                      | 1        | Y-shaft Right 150     |          |               |   |
|                |                      | 8        | B-screw M10-12        |          |               |   |

| Step<br>Number | Step Title             |          | Parts list                   | Tools list |                           | Remarks  |
|----------------|------------------------|----------|------------------------------|------------|---------------------------|--|
|                | Otep Title             | Quantity | Part name                    | Quantity   | Tool name                 | Remarks  |
| 13.1           | Wiring DC              | 1        | Controller Power Cable       | 1          | Screwdriver slotted small |  |
|                |                        | 1        | Motor Driver Power Cable     | 1          | Screwdriver<br>Phillips   |  |
|                |                        | 1        | Expansion Driver Power Cable |            |                           |  |
|                |                        | 2        | Driver Logic Cable           |            |                           |  |
| 13.2           | Wiring AC              | 3        | Connector 3 slots            | 1          | Screwdriver<br>Phillips   |  |
|                |                        | 1        | Connector 2 slots            |            |                           |  |
|                |                        | 1        | Emergency Button Cable       |            |                           |  |
| 14.1           | Preparing the X-axis 1 | 1        | X-plate                      | 1          | Allen Key 4.0             | Push the Linear Guide to the outside to align and tighten the screws all at the same time. |
|                |                        | 1        | Linear Guide                 |            |                           |  |
|                |                        | 20       | C-screw M5-14                |            |                           |  |
| 14.2           | Preparing the X-axis 2 | 2        | C-screw M3-10                | 1          | Allen Key 2.5             | Hammer the shaft inside the X-axis Support.  |
|                |                        | 1        | X-shaft                      | 1          | Allen Key 5.0             | Fix the X-endstop Sensor Holder in the correct position.                                   |
|                |                        | 1        | X-shaft Pulley               | 1          | Hammer                    | Do not tighten the Belt attachers yet.   |
|                |                        | 2        | Setscrew                     | 1          | Lubricant                 |  |
|                |                        | 4        | Belt Attacher                |            |                           |  |
|                |                        | 8        | C-screw M6-16                |            |                           |  |
|                |                        | 8        | Washer M6                    |            |                           |  |
|                |                        | 1        | X-endstop Sensor Holder      |            |                           |  |
| 14.3           | Preparing the X-axis 3 | 1        | Second Mirror Holder         | 1          | Allen Key 4.0             |  |
|                |                        | 1        | Mirror Spacer                |            |                           |  |

| Step<br>Number | Step Title            |          | Parts list            | To       | ools list     | Remarks  |
|----------------|-----------------------|----------|-----------------------|----------|---------------|--|
|                | 33,                   | Quantity | Part name             | Quantity | Tool name     |  |
|                |                       | 2        | C-screw M4-25         |          |               |  |
| 15             | Attaching the X-axis  | 1        | Linear Guide Carriage | 1        | Allen Key 5.0 | Insert the Linear Guide carefully, removing the plastic linear guide.  |
|                |                       | 8        | B-screw M8-20         |          |               | Insert the carriage after passing the X-axis through the bottom slot of the Inner left Panel.  |
|                |                       | 1        | X-endstop Sensor      |          |               | Tighten the cable of the X-endstop sensor on the body of the sensor  |
|                |                       | 1        | Cable Tie             |          |               |  |
| 16             | Attaching the X-motor | 1        | X-motor               | 1        | Allen Key 3.0 |  |
|                |                       | 4        | B-screw M5-20         | 1        | Wrench 8      |  |
|                |                       | 4        | Lock Nut M5           |          |               |  |
|                |                       | 1        | X-motor Pulley        |          |               |  |
|                |                       | 2        | Setscrew              |          |               |  |
| 17             | Install LEDs          | 2        | LED Strip             | 1        | Allen Key 3.0 | The cables of the LED strip should point to the holes in the Inner side panels.  |
|                |                       | 2        | C-wire Fixer          |          | -             |  |
|                |                       | 4        | C-screw M4-10         |          |               |  |
|                |                       | 2        | U-wire Fixer          |          |               |  |
| 18             | Top Profiles          | 2        | Profile 3060-1100     | 1        | Allen Key 6.0 |  |
|                |                       | 6        | B-screw M10-20        |          |               |  |
|                |                       | 6        | T-nut M8              |          |               | Insert the T-nuts in the profiles  |
| 19             | Y-belts               | 2        | Y-belt 230 cm         | 1        | Large Pliers  | To tighten the Y-belts, loosen the front Bearing Units. Then fix one end of the belt with the Belt attacher gripping the belt teeth. Pass the belt around the pulley and fix the other end of the belt. Then tighten the Bearing units again to tension the belts. |

| Step<br>Number | Step Title             |          | Parts list                  | Tools list |                                   | Remarks   |
|----------------|------------------------|----------|-----------------------------|------------|-----------------------------------|---|
|                | Stop Title             | Quantity | Part name                   | Quantity   | Tool name                         | Remarks   |
| 20             | Install Air Pipes      | 1        | Merging Air Pipe            |            |                                   |   |
|                |                        | 1        | Pipe Splitter               |            |                                   |   |
|                |                        | 1        | Laser Pointer Air Connector |            |                                   |   |
|                |                        | 1        | Laser Pointer Air Tube      |            |                                   |   |
|                |                        | 1        | Head Air tube               |            |                                   |   |
| 21             | Install Laser Head     | 1        | Laser Head Support          | 1          | Allen Key 2.5                     | Pass the Head Air Tube through the X-chain before fixing it.  |
|                |                        | 1        | Laser Head                  |            |                                   | Fix the chain in the right position. If needed, invert the ending piece.  |
|                |                        | 8        | C-screw M4-12               |            |                                   | Fix the chain to the X-axis with cable ties, together with the X-endstop Sensor. Position it under the X-axis.                              |
|                |                        | 1        | X-chain                     |            |                                   |   |
|                |                        | 3        | Countersink Screw M4-40     |            |                                   |   |
|                |                        | 1        | Chain Spacer                |            |                                   |   |
|                |                        | 3        | Cable Tie                   |            |                                   |   |
| 22             | Align X-axis           |          |                             | 2          | Template or two identical objects | Align the X-axis using the templates as reference to set an equal distance from the Front Panel. Then tighten all the pulley of the Y-axis. |
| 23             | Insert X-belt          | 1        | X-belt                      | 1          | Allen Key 3.0                     | After inserting the belt around the pulleys, tighten it by unscrewing the Hex-screw in the Y-bearing Block Right.                           |
|                |                        | 1        | X-belt Fixer                |            |                                   |   |
|                |                        | 2        | C-screw M4-16               |            |                                   |   |
|                |                        | 2        | Washer M4                   |            |                                   |   |
| 24             | Installing the Y-chain | 1        | Y-chain                     | 1          | Allen Key 3.0                     | Make sure the chain has the correct length.   |

| Step<br>Number | Step Title                  |          | Parts list               | То       | ols list                  | Remarks   |
|----------------|-----------------------------|----------|--------------------------|----------|---------------------------|---|
|                |                             | Quantity | Part name                | Quantity | Tool name                 |   |
|                |                             | 5        | B-screw M5-10            | 1        | Drill with 5 mm bit       | Insert the Head Air Tube, the X-endstop Sensor Cable and the X-motor cables in the Y-chain. The segments can be opened with a flat screwdriver.             |
|                |                             | 2        | Lock Nut M5              | 1        | Wrench 8                  | Drill two holes on top of the cable duct cover to fix the bottom end of the Y-chain.  |
| 25             | Water Pipes                 | 1        | Water Tube Inlet Inside  |          |                           |   |
|                |                             | 1        | Water Tube Outlet Inside |          |                           |   |
|                |                             | 2        | Water Tube Outside       |          |                           |   |
| 26             | Laser Tube                  | 1        | Laser Tube               | 1        | Cutter                    | Remove the top part of the laser tube holder to insert the laser tube.  |
|                |                             | 1        | Cable Tie                |          |                           | Connect the Water Tube Inlet Inside to the Laser Tube Inlet and the Water Tube Outlet Inside to the Laser Tube Outlet. Fix the connections with Cable Ties. |
| 27.1           | Wiring                      |          |                          | 1        | Screwdriver slotted small |   |
| 27.2           | Cable Management            |          | Cable Tie                |          |                           |   |
| 28.1           | Sub and Spacer Sides Panels | 1        | Subpanel Right           |          |                           |   |
|                |                             | 1        | Subpanel Left            |          |                           |   |
|                |                             | 1        | Spacer Panel Right       |          |                           |   |
|                |                             | 1        | Spacer Panel Left        |          |                           |   |
| 28.2           | Top Panel                   | 1        | Top Panel                | 1        | Screwdriver<br>Phillips   | Insert the T-nuts before placing the Top Panel.   |
|                |                             | 8        | B-screw M8-10            |          |                           |   |
|                |                             | 8        | T-nut M8                 |          |                           |   |
|                |                             | 1        | Emergency Button         |          |                           |   |
| 28.3           | Sub and Spacer Back Panels  | 1        | Subpanel Back            | 1        | Allen Key 5.0             | Fit the Subpanel back and the Spacer Panel Back under the Top Panel with the holes aligned.   |

| Step<br>Number | Step Title     |          | Parts list              | To       | ools list     | Remarks   |
|----------------|----------------|----------|-------------------------|----------|---------------|---|
|                |                | Quantity | Part name               | Quantity | Tool name     |   |
|                |                | 1        | Spacer Panel Back       | 1        | Wrench 13     |   |
|                |                | 3        | Hinges                  |          |               |   |
|                |                | 6        | Countersink Screw M8-40 |          |               |   |
|                |                | 6        | Lock Nut M8             |          |               |   |
| 28.4           | Subpanel Front | 1        | Subpanel Front          | 1        | Allen Key 5.0 |   |
|                |                | 8        | B-screw M8-20           | 1        | Wrench 13     |   |
|                |                | 8        | Lock Nut M8             |          |               |   |
| 29             | Fillet Profile | 1        | Fillet Profile          | 1        | Wrench 13     | Fix the Front Panel Holder and the Front Subpanel Holder to the Fillet Profile before fixing it to the Front Panel. |
|                |                | 1        | Front Panel Holder      | 1        | Allen Key 5.0 | Do not tighten the screws yet for further alignment.  |
|                |                | 2        | Lock Nut M8             | 1        | Allen Key 2.5 |   |
|                |                | 2        | T-nut M8                |          |               |   |
|                |                | 2        | B-screw M8-10           |          |               |   |
|                |                | 2        | B-screw M8-20           |          |               |   |
|                |                | 2        | Front Subpanel Holder   |          |               |   |

| Step<br>Number | Step Title     |          | Parts list              | То       | ols list      | Remarks   |
|----------------|----------------|----------|-------------------------|----------|---------------|---|
|                | Otep Title     | Quantity | Part name               | Quantity | Tool name     | Kemarks   |
|                |                | 4        | C-screw M3-10           |          |               |   |
|                |                | 4        | Washer M3               |          |               |   |
|                |                | 4        | T-nut M3                |          |               |   |
| 30             | Prepare Window | 1        | Window                  | 1        | Allen Key 4.0 | Window holes are not symmetric. The profiles holes should be matched before inserting the corner connectors |
|                |                | 1        | Window Profile Front    | 1        | Wrench 10     |   |
|                |                | 1        | Window Profile Back     | 1        |               |   |
|                |                | 1        | Window Profile Left     | 1        | Allen Key 3.0 |   |
|                |                | 1        | Window Profile Right    |          | -             |   |
|                |                | 11       | B-screw M6-30           | 1        | Allen Key 2.5 |   |
|                |                | 11       | Lock Nut M6             |          |               |   |
|                |                | 4        | Corner Connector        |          |               |   |
|                |                | 2        | C-screw M4-35           |          |               |   |
|                |                | 1        | Handle                  |          |               |   |
|                |                | 1        | Window Magnet           |          |               |   |
|                |                | 2        | C-screw M3-10           |          |               |   |
| 31             | Install Window | 1        | Prepared Window         | 1        | Allen Key 5.0 |   |
|                |                | 6        | Countersink Screw M8-25 | 1        | Allen Key 6.0 |   |
|                |                | 2        | Standoff M8 M-F         | 1        | Wrench 13     |   |
|                |                | 2        | B-screw M8-35           |          |               |   |

| Step<br>Number | Step Title              |          | Parts list              | То       | ols list            | Remarks   |
|----------------|-------------------------|----------|-------------------------|----------|---------------------|---|
|                | 5.5p5                   | Quantity | Part name               | Quantity | Tool name           |   |
|                |                         | 6        | Washer M8               |          |                     |   |
|                |                         | 2        | Lock Nut M8             |          |                     |   |
| 32             | Prepare for Calibration | 1        | Air Compressor          | 1        | Digital Level meter | Semi-tighten the screws of the laser tube holder and first mirror.          |
|                |                         | 1        | Chiller                 |          |                     | Test the water.   |
|                |                         | 1        | Water Flow Sensor Cable |          |                     | Make sure the tube is parallel to the frame and horizontally levelled.      |
|                |                         | 1        | Air Tube Outside        |          |                     | Pre-align visually first mirror, second mirror and laser tube.              |
|                |                         | 1        | Air Compressor Adapter  |          |                     |   |
| 33             | Insert Mirrors          | 3        | Mirror                  |          |                     | Do not touch the surface of the mirrors.                                    |
| 34             | Insert Lens             | 1        | Lens                    |          |                     | Place it with the flat surface down.  |
|                |                         | 2        | Rubber Ring             |          |                     | Do not touch the surface of the lens.                                       |
| 35             | Fix Top Back Panel      | 1        | Laser Pointer Switch    | 1        | Allen Key 2.5       |   |
|                |                         | 1        | Laser Pointer Cable     |          |                     |   |
|                |                         | 1        | Top Back Panel          |          |                     |   |
|                |                         | 8        | B-screw M4-10           |          |                     |   |
| 36             | Insert Side Panels      | 1        | Left Panel              | 1        | Allen Key 5.0       | Tighten the screws of the Front Panel Holder and the Front Subpanel Holder. |
|                |                         | 1        | Right Panel             |          |                     | To fix the Side Panels, insert them in the slot of the Front Panel first.   |

| Step<br>Number | Step Title | Parts list |                    | Tools list |           | Remarks |
|----------------|------------|------------|--------------------|------------|-----------|---------|
|                |            | Quantity   | Part name          | Quantity   | Tool name |         |
|                |            | 12         | B-screw M8-10      |            |           |         |
|                |            | 2          | B-screw M8-20      |            |           |         |
|                |            | 1          | USB Cable Inside   |            |           |         |
|                |            | 2          | Plastic Screw M3-8 |            |           |         |