| | OLSK Small 3D Printer V2 Workbook | | | | | |
|--------|------------------------------------|----------|----------------------------|--|--|--|
| Step | O | | Parts list | D | | |
| Number | Step Title | Quantity | Part name | Remarks | | |
| 1 | Prepare Side Frames | 2 | Side Frame | The side frames and window stoppers are not symetrical | | |
| | | 2 | Top Side Window Stopper | | | |
| | | 2 | Bottom Side Window Stopper | | | |
| | | 4 | B-screw M3-6 | | | |
| | | 16 | C-screw M6-12 | | | |
| | | 8 | Shaft Holder | | | |
| | | 6 | C-screw M4-16 | | | |
| 2 | Prepare the Bed Frame | 1 | Bed Frame | Separate the parts of the coupler and fix one of the sides on the Bed Frame | | |
| | | 2 | Oldham Coupler | | | |
| | | 4 | C-screw M3-10 | | | |
| | | 4 | Linear Bearing Z | | | |
| | | 8 | B-screw M5-12 | | | |
| 3 | Assemble the Sides and Floor Frame | 1 | Floor Frame | | | |
| | | 1 | Rubber Grommet | | | |
| | | 1 | Prepared Right Frame | | | |
| | | 1 | Prepared Left Frame | | | |
| 4.1 | Insert the Bed Frame | 1 | Prepared Bed Frame | | | |
| | | 4 | Z Linear Shaft | | | |
| 4.2 | Prepare the Z Motors | 2 | Z Motor | | | |
| | | 2 | Leadscrew Nut | | | |
| | | 4 | C-screw M3-10 | | | |
| | | 4 | Lock Nut M3 | | | |
| 4.3 | Attach the coupler parts | | | Position the screw nut of the motor screw in the end of the screw | | |
| | | | | Assemble the parts of the coupler by sliding the them: top (fixed at the Bed Frame), middle part (loose) and bottom (fixed at the Screw Nut) | | |

| | | OLSK Sr | mall 3D Printer V2 Workbook | |
|--------|-------------------------|----------|-----------------------------|---|
| Step | Step Title | | Parts list | Remarks |
| Number | | Quantity | Part name | Remarks |
| 4.4 | Fix the Z motors | 8 | B-screw M3-6 | |
| 5 | Prepare the Tensioner | 2 | Tensioner Frame | |
| | | 2 | Tensioner | |
| | | 2 | C-screw M4-16 | |
| | | 4 | Flange Bearing | |
| | | 4 | Nylon Washer M3 | |
| | | 1 | Tensioner Top | |
| | | 2 | B-screw M3-20 | |
| | | 2 | Nut M3 | |
| 6.1 | Prepare the Top Frame 1 | 1 | Top Frame | Pay attention to the position of the flanges of the bearings. |
| | | 1 | Sub-top Frame | |
| | | 6 | B-screw M3-25 | |
| | | 2 | Spacer M3-10 | |
| | | 2 | Spacer M3-20 | |
| | | 12 | Flange Bearing | |
| | | 12 | Nylon Washer M3 | |
| 6.2 | Prepare the Top Frame 2 | 8 | B-screw M3-30 | |
| | | 8 | Spacer M3-20 | |
| | | 2 | X Motor | |
| | | 2 | Pulley | |
| | | 4 | Setscrew M3-6 | |
| | | 1 | Top Frame Wire Holder | |
| | | 2 | C-screw M4-6 | |
| 6.3 | Prepare the Top Frame 3 | 2 | Prepared Tensioners | |

| OLSK Small 3D Printer V2 Workbook | | | | | |
|-----------------------------------|-------------------------|-------------|----------------------------|--|--|
| Step Number | Step Title | Our matitus | Parts list | Remarks | |
| Number | | Quantity | Part name | | |
| | | 8 | B-screw M3-20 | | |
| | | 4 | Spacer M3-8 | | |
| 6.4 | Prepare the Top Frame 4 | 1 | Camera Holder | | |
| | | 1 | Camera Module | | |
| | | 2 | C-screw M2-6 | | |
| | | 2 | C-screw M3-8 | | |
| 6.5 | Prepare the Top Frame 5 | 2 | Belt | Pass the belts through the bearing and pulleys, leaving the ends loose in the center | |
| 7 | Install Top Frame | 4 | B-screw M6-12 | | |
| | | 1 | Prepared Top Frame | | |
| 8.1 | Attach Electronics 1 | 1 | Power Supply | Carefully lay the machine on its side to make sure the side frames won't open. | |
| | | 4 | B-screw M4-8 | | |
| | | 1 | DC-DC Converter | | |
| | | 2 | C-screw M5-8 | | |
| | | 1 | CPU | | |
| | | 4 | B-screw M3-6 | | |
| | | 4 | Standoff M-F M3-6+6 | | |
| | | 4 | Nylon Nut M3 | | |
| 8.2 | Attach Electronics 2 | 1 | Buck Converter | Fix the spacers and nuts on the boards before fixing them on the frame. | |
| | | 1 | Main Board Octopus Pro | Attach the stepper drivers on the Main Board | |
| | | 3 | Stepper driver tmc2130 | Fix the heat sink in their respective stepper drivers | |
| | | 2 | Stepper driver tmc5160 pro | | |
| | | 6 | B-screw M3-6 | | |
| | | 6 | Standoff M-F M3-6+6 | | |
| | | 6 | Nylon Nut M3 | | |

| | OLSK Small 3D Printer V2 Workbook | | | | | |
|--------|-----------------------------------|----------|-----------------------------|--|--|--|
| Step | Cton Title | | Parts list | Bounda | | |
| Number | Step Title | Quantity | Part name | Remarks | | |
| 8.3 | Attach Electronics 3 | 2 | Driver Fan | Fix the fans and USB Hub with double-sided tape | | |
| | | 1 | USB Hub | | | |
| 9 | Install Bottom Frame | 1 | Bottom Frame | | | |
| | | 4 | Feet | | | |
| | | 4 | B-screw M6-12 | | | |
| | | 3 | Bottom Bracket | | | |
| | | 1 | Bottom Bracket Power Supply | | | |
| | | 8 | B-screw M3-6 | | | |
| 10 | Fix Fillet Profiles | 4 | Fillet Profile | Insert 2x T-nuts in the front slot of each back fillet profile | | |
| | | 8 | T-nut M3 | | | |
| | | 4 | Uniblock w/ Nut | | | |
| | | 8 | B-screw M6-12 | | | |
| 11.1 | Prepare X-axis 1 | 1 | Gantry Bridge | Tighten the screws of the linear guide while pushing it front wall of the slot in the gantry bridge to align it. | | |
| | | 1 | Linear Guide w/ Carriage | | | |
| | | 2 | C-screw M3-12 | | | |
| | | 7 | C-screw M3-8 | | | |
| 11.2 | Prepare X-axis 2 | 1 | Gantry Bracket Right | Align well the Linear Bearing, Gantry Brackets and Gantry bridge | | |
| | | 1 | Gantry Bracket Left | | | |
| | | 2 | Linear Bearing Y | | | |
| | | 4 | C-screw M5-16 | | | |
| 11.3 | Prepare X-axis 3 | 1 | Top Extruder Plate | The flange bearings should be inserted mirrored in each screw | | |
| | | 4 | Counter Sunk Screw M3-6 | | | |
| | | 1 | Belt Bracket Right | | | |
| | | 1 | Belt Bracket Left | | | |

| | OLSK Small 3D Printer V2 Workbook | | | | | |
|--------|-----------------------------------|----------|----------------------|---|--|--|
| Step | Otors Title | | Parts list | Remarks | | |
| Number | Step Title | Quantity | Part name | Remarks | | |
| | | 6 | Spacer M3-10 | | | |
| | | 2 | Spacer M3-18 | | | |
| | | 8 | Flange Bearing | | | |
| | | 8 | B-screw M3-25 | | | |
| 12 | Prepare Back Frame | 1 | Back Frame | | | |
| | | 1 | Power Plug | | | |
| | | 2 | B-screw M3-6 | | | |
| | | 1 | Fuse | | | |
| | | 2 | Nylon Screw M3-12 | | | |
| | | 1 | USB Cable Inside | | | |
| 13 | Install Back Frame | 1 | Prepared Back Frame | | | |
| | | 2 | B-screw M6-12 | | | |
| | | 2 | B-screw M5-16 | | | |
| 14 | Prepare the Hinges | 4 | Hinge Part A | | | |
| | | 4 | Hinge Part B | | | |
| | | 4 | B-screw M3-16 | | | |
| | | 4 | Lock Nut M3 | | | |
| 15 | Prepare Front Frame | 1 | Front Frame | | | |
| | | 1 | Top Door Stopper | | | |
| | | 1 | B-screw M3-6 | | | |
| | | 1 | Neopixel strip | | | |
| | | 4 | Prepared Hinge | | | |
| | | 4 | C-screw M3-10 | | | |
| 16 | Install Front Frame & Gantry | 1 | Prepared Front Frame | Fix the camera holder attached to the top frame on the front frame. | | |
| | | 4 | B-screw M6-12 | | | |
| | | 2 | Y Linear Shaft | | | |
| | | 1 | Prepared X-axis | | | |

| | OLSK Small 3D Printer V2 Workbook | | | | | |
|--------|-----------------------------------|----------|-------------------------|---|--|--|
| Step | Step Title | | Parts list | | | |
| Number | | Quantity | Part name | Remarks | | |
| | | 2 | B-screw M5-16 | | | |
| | | 2 | C-screw M3-8 | | | |
| 17 | Attach the Fillament Fan | 1 | Filament Fan | | | |
| | | 1 | Fillament Fan Adapter | | | |
| | | 2 | C-screw M4-40 | | | |
| | | 1 | Fan Cover | | | |
| | | 4 | O-ring | | | |
| | | 2 | Washer M4 | | | |
| | | 1 | Fit Connector | | | |
| | | 1 | Filament Sensor | | | |
| | | 2 | C-screw M3-16 | | | |
| 18 | Attach 3D Touch Sensor | 1 | 3D Touch Sensor | | | |
| | | 1 | 3D Touch Sensor Spacer | | | |
| | | 2 | C-screw M3-35 | | | |
| 19 | Attach Extruder Heat Sink | 1 | Extruder Heat Sink | | | |
| | | 1 | Extruder Fan | | | |
| | | 2 | B-screw M3-14 | | | |
| | | 2 | Counter Sunk Screw M3-6 | | | |
| | | 1 | Heat Break | | | |
| 20 | Prepare the Extruder | 1 | Extruder | Substitute the screws of the motor for the B-screw M3-20 to attach the extruder motor wire holder | | |
| | | 1 | Extruder Wire Holder | | | |
| | | 2 | B-screw M3-20 | | | |
| 21 | Attach the Extruder | 1 | Prepared Extruder | | | |
| | | 1 | Bottom Extruder Plate | | | |
| | | 1 | Accelerometer | | | |
| | | 2 | B-screw M3-6 | | | |
| | | 2 | C-screw M4-25 | | | |
| | | 2 | Spacer M3-20 | | | |

| | OLSK Small 3D Printer V2 Workbook | | | | | |
|--------|-----------------------------------|----------|-------------------|---|--|--|
| Step | Step Title | | Parts list | Damania | | |
| Number | | Quantity | Part name | Remarks | | |
| | | 2 | C-screw M3-35 | | | |
| | | 2 | Nut M4 | | | |
| 22 | Tighten the Belts | 4 | Belt Clip | Insert one Belt Clip in each end of the belt before passing it around the head screw. Slide the Belt Clip closing the end of the belt, when its teeth are gripping. Pull the other end of the belt slightly tightening it and close it with the clip. Repeat with the other belt. | | |
| | | | | To tighten the belt, screw the belt tightener | | |
| | | | | Tighen both belts while checking the alignement of the X-axis against the front of the machine. | | |
| 23 | Attach the Heat Block | 1 | Heat Block | Screw the Heat Block in the Heat Break and align it to the Heat Sink. | | |
| | | 1 | Nozzle | Nozzle needs to be tightened again once the heat block is heated. | | |
| | | 1 | B-screw M3-14 | | | |
| | | 1 | Thermistor | | | |
| | | 1 | Heating cartridge | | | |
| | | 1 | Setscrew M3-6 | | | |
| 24 | Attach the Cooling Duct | 1 | Cooling Duct | | | |
| | | 2 | B-screw M3-6 | | | |
| 25 | Prepare the Bed | 1 | Flexible Sheet | Tape the magnetic bad to the bed with double-sided tape | | |
| | | 1 | Magnetic Bed | | | |
| | | 1 | Bed | | | |
| | | 1 | Heat Pad | | | |
| | | 4 | M8 to M5 Insert | | | |
| | | 4 | Flat Nut M8 | | | |
| 26 | Attach the Bed | 4 | Thumb Screw | | | |
| | | 4 | Silicon Spacer | | | |

| | OLSK Small 3D Printer V2 Workbook | | | | | |
|--------|-----------------------------------|----------|----------------------|--|--|--|
| Step | Oten Title | | Parts list | D | | |
| Number | Step Title | Quantity | Part name | Remarks | | |
| 27 | Cable Management 1 | 2 | Cable Mesh | Cover the Extruder Fan wire with a small shrinking tube. | | |
| | | 4 | Shrinking Tube Big | Pass the Thermistor and Heating Cartrigde wires through the Extruder Wire Holder and pass them through a cable mesh, closing both ends with a big shrinking tube and a cable tie | | |
| | | 2 | Shrinking Tube Small | Cover the Bed wires also with a mesh. | | |
| | | 2 | Cable Tie | Insert the Camera and the Neopixel strip cables in the fillet profiles and pass them through the holes in the floor frame | | |
| 28 | Attach Screen Holder | 1 | Screen | Connect the USB cable that is included with the screen | | |
| | | 1 | HDMI Cable | | | |
| | | 1 | Screen Holder | | | |
| | | 4 | C-screw | | | |
| | | 2 | Magnet | | | |
| | | 2 | B-screw M3-8 | | | |
| 29 | Wiring 1 | | | | | |
| | | 1 | Power Cable 48V | | | |
| | | 1 | Power Cable 24V | | | |
| | | 1 | Power Cable 19V | | | |
| | | 1 | 24V Jumper Cable | | | |
| | | 1 | Earth Cable | | | |
| | | 1 | Camera USB | | | |
| | | 1 | Wifi adapter | | | |
| | | 1 | HDMI to DP adapter | | | |
| 30 | Cable Management 2 | | Cable Tie | | | |
| | | 2 | Wire Holder Profile | | | |
| | | 4 | B-screw M3-6 | | | |

| | OLSK Small 3D Printer V2 Workbook | | | | | |
|--------|-----------------------------------|----------|------------------|---------|--|--|
| Step | Chair Title | | Parts list | Remarks | | |
| Number | Step Title | Quantity | Part name | Remarks | | |
| 31 | Fix Bottom Cover | 1 | Bottom Cap | | | |
| | | 4 | B-screw M3-6 | | | |
| 32 | Fix Air and Filament Tubes | 1 | Air Tube | | | |
| | | 1 | Filament Tube | | | |
| | | 3 | Velcro Cable Tie | | | |
| 33 | Install Spool Holder | 4 | B-screw M4-6 | | | |
| | | 1 | Spool Holder | | | |
| | | 1 | Spool Stopper | | | |
| 34 | Install Windows | 4 | Window | | | |
| | | 16 | B-screw M3-6 | | | |
| 35 | Prepare the Doors | 2 | Door | | | |
| | | 2 | Handle | | | |
| | | 4 | B-screw M4-10 | | | |
| | | 2 | B-screw M3-6 | | | |
| | | 2 | Nut M3 | | | |
| | | 2 | Nylon Washer M3 | | | |
| 36 | Install the Doors | 2 | Prepared Door | | | |
| | | 4 | B-screw M3-12 | | | |
| | | 4 | Lock Nut M3 | | | |
| 37 | Calibrating the machine | | | | | |