



Entegris Alarms Document

*Generated at Fri Nov 8 12:52:40 2024
For firmware version V1011.1536*

DESCRIPTION:

This document describes the Alarm Event codes for the IntelliGen RULV, ULV, LV, MV, HMT, and HV20 generation dispense systems.

This document is auto generated directly from the source code of MMI/FIRMWARE.

Entegris Confidential Not For Commercial Use

Entegris Alarms Document	1
Alarms Index	3
Alarm Descriptions	10

Alarms Index

Alarm	Code
Power On Event	20
Internal Testing Event (shorts)	21
Internal Testing Event (ushorts)	22
Internal Testing Event (Pressure)	23
Internal Testing Event (ml)	24
Internal Testing Event (bytes)	25
Internal Testing Event (time)	26
Internal Testing Event (long)	27
Clock Set Event	28
System Reset Event - Serial	29
Firmware Download Event	30
Alarms Cleared Event (re-init)	31
Alarms Cleared Event	32
User Requested Re-init Event	34
Unknown Module Detected	35
Maintenance Mode Started (With Timeout)	36
Maintenance Mode Started (Without Timeout)	37
Maintenance Mode Ended (By Timeout)	38
Maintenance Mode Ended	39
Maintenance Mode Ended (By Error)	40
New Major Version Detected	41
New Minor Version Detected	42
New Product ID Detected	43
Invalid Product ID Detected	44
New Interface Module ID Detected	45
Clock Mismatch Event	46
Watchdog Reset Event	47
Task Watchdog Reset Event	48
PLL Limp Error Event	49
PLL Wrong Error Event	50
Passwords Set Event	52
Bad Password Event	53
Module Errors Detected	60
Module Remote Errors Detected	61
Module Syncs Detected	62
Module Communications Detected	63
System Reset Event - IO	64
User Note Saved Event	65
User EMO Event	66
User Offline Event	67
User Online Event	68

Offline State Detected	69
Initialize System Parameters	200
Initialize System Names	201
Initialize Recipes	202
Initialize Firmware information	203
Initialize Calibration	204
Initialize Version	205
Initialize Recharge	206
Initialize Cycle Counters	207
Initialize Priming	209
Initialize Serial Numbers	210
Initialize Confirmation Limits	211
Initialize Dispense Info	212
Initialize Confirmation Profile	213
Initialize Passwords	214
Initialize RDS-01 Saved	215
Initialize Volume Counters	216
Initialize Pre-Filtration Pressure Control	217
Initialize Fill Ready Pressure Control	218
Fixing System Parameters	300
Fixing System Names	301
Fixing Recipes	302
Fixing Firmware information	303
Fixing Calibration	304
Fixing Version	305
Fixing Recharge	306
Fixing Cycle Counters	307
Fixing Alarms	308
Fixing Priming	309
Fixing Serial Numbers	310
Fixing Confirmation Limits	311
Fixing Dispense Info	312
Fixing Confirmation Profile	313
Fixing Passwords	314
Fixing RDS-01 Saved	315
Fixing Volume Counters	316
Fixing Pre-Filtration Pressure Control	317
Fixing Fill Ready Pressure Control	318
Priming Started Event	500
Priming Stopped Event	501
Total Priming Time	502
Trigger Held Detected	503
Ready Pressure Lower Limit	504
Ready Pressure Upper Limit	505
Reserved	506

Trigger When Busy	507
Trigger When Busy (T-100)	508
Pre-Filtration Timeout	509
Pre-Filtration Motor Limit	510
Fill Motor Stall (Filtration)	511
Fill Motor Stall (Fill)	512
Fill Motor Home Not Detected	513
Fill Motor Home Not Detected (Power-up)	514
Fill Motor Home Always On (Power-up)	515
Dispense Volume Too Large	516
Pre-Dis Re-trigger Timeout	517
Over Temperature Detected	518
Over Pressure Detected (Dispense)	519
Over Pressure Detected (Fill)	520
Over Current Detected (Dispense)	521
Dispense Motor Home Failure	522
Dispense Motor Unstable (Power-up A)	523
Dispense Motor Unstable (Power-up B)	524
Dispense Motor Position Error	525
Dispense Motor Driver Fault	526
Filtration Timeout Detected	527
Over Pressure During Filtration (Fill Stage)	528
Under Pressure During Filtration (Fill Stage)	529
Over Pressure During Filtration (Dis Stage)	530
Under Pressure During Filtration (Dis Stage)	531
Confirmation Reference Save Event	532
Dispense Motor Encoder Reset Event	533
Low Vacuum Supply Detected	534
Low N2 Supply Detected	535
High N2 Supply Detected	536
Priming Paused Event	537
Priming Resumed Event	538
Counters Reset Event	539
Fill Motor Timeout Detected	540
Dispense Motor Timeout Detected	541
Filtration Set-up Timeout	542
filter Counter Cycle Limit	543
Error During Pre-dispense	544
Pressure Sensor Error Detected	545
Fill Pressure Sensor Malfunction	546
Dispense Pressure Sensor Malfunction	547
Pre-filtration Ended In Negative Pressure	548
RDS-01 Recipe Mismatch	549
RDS-01 Maximum Dispense Volume	550
Motor Calculation Error Detected	551

Flow Sensor Not Responding	552
RDS01 Step Size Error	553
RDS01 Enable Timeout Error	554
RDS01 Over Range Error	555
Confirmation Temporarily Disabled	556
24 VDC Fill Motor Fault	557
24 VDC Dispense Motor Fault	558
Suckback Greater Than Dispense	559
Trigger Error Detected	560
Trigger When Busy State	561
Recharge timeout (T-100)	562
Confirmation Reference Delete Event	563
Trigger When Busy (SHV)	564
Consecutive auto-vents	565
N2 Supply Buffer Inadequate	566
No reference	567
Flow sensor unexpected command	568
Flow sensor reset at startup	569
Volume Counters Reset Event	570
Vent Performed	571
Auto-vent Consecutive Performed	572
Self-Test Started (Dispense Backlash)	900
Self-Test Started (Dispense Backlash)	901
Self-Test Started (Dispense Backlash)	902
Confirmation Profile Failure	1000
Confirmation Recipe Not Detected	1001
Confirmation Failure (Ready Pressure)	1020
Confirmation Failure (Ready Correction)	1021
Confirmation Failure (Profile Compare)	1022
Confirmation Failure (Flow Compare)	1023
Confirmation Failure (Max Pressure)	1024
Confirmation Failure (Average Pressure)	1025
Confirmation Failure (Cut-off Pressure)	1026
Confirmation Failure (Average Rate)	1027
Confirmation Failure (Total Volume)	1028
Confirmation Failure (Average Current)	1029
Confirmation Failure (Predicted Current)	1030
Confirmation Failure (Dispense Temperature)	1031
Confirmation Failure (Air Detect)	1032
Confirmation Failure (Flow Volume)	1033
Confirmation Failure (Delta Pressure)	1034
Confirmation Failure (Filtration Upstrm Pressure)	1035
Confirmation Failure (Filtration Average Rate)	1036
Confirmation Failure (Filtration Time)	1037
Confirmation Failure (Vent Time)	1038

Confirmation Failure (Fill Minimum Pressure)	1039
Confirmation Failure (Fill Average Rate)	1040
Confirmation Failure (Fill Time)	1041
Confirmation Failure (Max Pressure Time)	1042
Confirmation Failure (Fill Motor Mismatch)	1043
Confirmation Failure (Total Cycle Time)	1044
Confirmation Failure (Reserved Test 5)	1045
Confirmation Failure (Profile Compare IGMINI style)	1046
Self-Test Started (Dispense Backlash)	1100
Self-Test Passed (Dispense Backlash)	1101
Self-Test Failed (Dispense Backlash)	1102
Self-Test Incomplete (Dispense Backlash)	1103
Self-Test Results A (Dispense Backlash)	1104
Self-Test Results B (Dispense Backlash)	1105
Self-Test Started (Fill Strength)	1120
Self-Test Passed (Fill Strength)	1121
Self-Test Failed (Fill Strength)	1122
Self-Test Incomplete (Fill Strength)	1123
Self-Test Results A (Fill Strength)	1124
Self-Test Results B (Fill Strength)	1125
Self-Test Results C (Fill Strength)	1126
Self-Test Results D (Fill Strength)	1127
Self-Test Started (Dispense Strength)	1140
Self-Test Passed (Dispense Strength)	1141
Self-Test Failed (Dispense Strength)	1142
Self-Test Incomplete (Dispense Strength)	1143
Self-Test Results A (Dispense Strength)	1144
Self-Test Results B (Dispense Strength)	1145
Self-Test Results C (Dispense Strength)	1146
Self-Test Results D (Dispense Strength)	1147
Self-Test Results E (Dispense Strength)	1148
Self-Test Started (Sensor Accuracy)	1160
Self-Test Passed (Sensor Accuracy)	1161
Self-Test Failed (Sensor Accuracy - Dispense)	1162
Self-Test Failed (Sensor Accuracy - Fill)	1163
Self-Test Incomplete (Sensor Accuracy)	1164
Self-Test Results A (Sensor Accuracy)	1165
Self-Test Results B (Sensor Accuracy)	1166
Self-Test Results C (Sensor Accuracy)	1167
Self-Test Results D (Sensor Accuracy)	1168
Self-Test Results E (Sensor Accuracy)	1169
Self-Test Started (System Leak)	1180
Self-Test Passed (System Leak)	1181
Self-Test Failed (System Leak)	1182
Self-Test Incomplete (System Leak)	1183

Self-Test Results A (System Leak)	1184
Self-Test Results B (System Leak)	1185
Self-Test Results C (System Leak)	1186
Self-Test Results D (System Leak)	1187
Self-Test Started (Air Detect)	1200
Self-Test Passed (Air Detect)	1201
Self-Test Failed (Air Detect)	1202
Self-Test Incomplete (Air Detect)	1203
Self-Test Results A (Air Detect)	1204
Self-Test Results B (Air Detect)	1205
Self-Test Results C (Air Detect)	1206
Self-Test Results D (Air Detect)	1207
Self-Test Started (Sensor Re-zero)	1250
Self-Test Passed (Sensor Re-zero)	1251
Self-Test Failed (Sensor Re-zero - NV Save)	1252
Self-Test Failed (Sensor Re-zero - Dispense)	1253
Self-Test Failed (Sensor Re-zero - Fill)	1254
Self-Test Incomplete (Sensor Re-zero)	1255
Self-Test Results A (Sensor Re-zero)	1256
Self-Test Results B (Sensor Re-zero)	1257
Self-Test Results C (Sensor Re-zero)	1258
Self-Test Results D (Sensor Re-zero)	1259
Self-Test Results E (Sensor Re-zero)	1260
Self-Test Results F (Sensor Re-zero)	1261
Self-Test Results G (Sensor Re-zero)	1262
Self-Test Results H (Sensor Re-zero)	1263
Self-Test Started (System Valve Test)	1301
Self-Test Started (System Valve Test - Inlet)	1302
Self-Test Started (System Valve Test - Isolate)	1303
Self-Test Started (System Valve Test - Vent)	1304
Self-Test Started (System Valve Test - Barrier)	1305
Self-Test Started (System Valve Test - Purge)	1306
Self-Test Passed (System Valve Test)	1307
Self-Test Failed (System Valve Test)	1308
Self-Test Incomplete (System Valve Test)	1309
Self-Test Results A (System Valve Test)	1310
Self-Test Results B (System Valve Test)	1311
Self-Test Results C (System Valve Test)	1312
Self-Test Started (Valve Timing Test)	1351
Self-Test Started (Valve Timing Test)	1352
Self-Test Started (Valve Timing Test)	1353
Self-Test Started (Valve Timing Test)	1354
Self-Test Started (Valve Timing Test)	1355
Self-Test Started (Valve Timing Test)	1356
Self-Test Passed (Valve Timing Test)	1357

Self-Test Failed (Valve Timing Test)	1358
Self-Test Incomplete (Valve Timing Test)	1359
Self-Test Results A (Valve Timing Test)	1360
Self-Test Results B (Valve Timing Test)	1361
Self-Test Results C (Valve Timing Test)	1362

Alarm Descriptions

Code 20	Power On Event	Info
Message:	System power on. Total power ons: \$LONG	
Description:	The dispense system was powered on or reset (#) times.	
Possible Solutions:	This alarm will happen at every power up. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 21	Internal Testing Event (shorts)	Info
Message:	short0 = \$SHORT0 short1 = \$SHORT1	
Description:	Used for internal testing only.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 22	Internal Testing Event (ushorts)	Info
Message:	short0 = \$USHORT0 short1 = \$USHORT1	
Description:	Used for internal testing only.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 23	Internal Testing Event (Pressure)	Info
Message:	pressure0 = \$PRESSURE0 pressure1 = \$PRESSURE1	
Description:	Used for internal testing only.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 24	Internal Testing Event (ml)	Info
Message:	ml0 = \$ML_0 ml1 = \$ML_1	
Description:	Used for internal testing only.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 25	Internal Testing Event (bytes)	Info
Message:	byte0=\$BYTE0 byte1=\$BYTE1 byte2=\$BYTE2 byte3=\$BYTE3	
Description:	Used for internal testing only.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 26	Internal Testing Event (time)	Info
Message:	time = \$TIME	
Description:	Used for internal testing only.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 27	Internal Testing Event (long)	Info
Message:	long = \$LONG	
Description:	Used for internal testing only.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 28	Clock Set Event	Info
Message:	Clock time set (was \$TIME)	
Description:	The time was set in the real time clock. The previous value is shown for reference.	
Possible Solutions:	The real time clock should only need to be set infrequently. If this is a frequent event, please contact an Entegris customer representative for more information.	

Code 29	System Reset Event - Serial	Info
Message:	Software reset - command	
Description:	A software reset was performed by a serial command.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 30	Firmware Download Event	Info
Message:	Flashing firmware: Past Firmware Version: \$USHORT1	
Description:	New firmware was installed.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 31	Alarms Cleared Event (re-init)	Info
Message:	\$USHORT1 alarms were cleared by the user - Re init was required	
Description:	(#) alarms were cleared and system required a re-initialization.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 32	Alarms Cleared Event	Info
Message:	\$USHORT1 alarms were cleared by the user	
Description:	(#) alarms were cleared and system did not require a re-initialization.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 34	User Requested Re-init Event	Info
Message:	The re-init hardware line was activated	
Description:	A signal from the track to reinitialize was received.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 35	Unknown Module Detected	Info
Message:	New unknown module type: \$ULONG	
Description:	The dispense system does not recognize the module type.	
Possible Solutions:	Confirm the external interface module type is correct. Possible outdated firmware or communication problem may be present. If problem continues, please contact an Entegris customer representative for more information.	

Code 36	Maintenance Mode Started (With Timeout)	Info
Message:	Maintenance mode was started with a timeout of \$LONG minutes	
Description:	Maintenance mode was started with a timeout value set.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 37	Maintenance Mode Started (Without Timeout)	Info
Message:	Maintenance mode was started with a no timeout	
Description:	Maintenance mode started without a set timeout value set.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 38	Maintenance Mode Ended (By Timeout)	Info
Message:	Maintenance mode was ended by timeout	
Description:	Maintenance mode ended by a timeout expiring.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 39	Maintenance Mode Ended	Info
Message:	Maintenance mode ended by the user	
Description:	Maintenance mode function was canceled by user.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 40	Maintenance Mode Ended (By Error)	Info
Message:	Maintenance mode ended by a system error	
Description:	A critical error was triggered which caused the end of maintenance mode.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 41	New Major Version Detected	Info
Message:	New Major Version (\$SHORT1->\$SHORT0)	
Description:	Displays the major version of the system after an upgrade.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 42	New Minor Version Detected	Info
Message:	New Minor Version (\$SHORT1->\$SHORT0)	
Description:	Displays the minor version of the system after an upgrade.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 43	New Product ID Detected	Error
Message:	New Product ID detected. Old ID: \$SHORT1 -> New ID: \$SHORT0	
Description:	The Product ID is set by a dip switch setting on the Internal PCB. This alarm will typically happen on the first power-up. It could mean that the hardware switches were set incorrectly for the hardware. It could also mean that the Internal or Main PCB has failed.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 44	Invalid Product ID Detected	Critical
Message:	Product ID is invalid. Invalid Product ID: \$LONG	
Description:	The Product ID that was set by the hardware is invalid. The product ID was default to 0, however the system can not operate in this state.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 45	New Interface Module ID Detected	Info
Message:	New Module: \$MODULE	
Description:	The system detected a new interface module type.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 46	Clock Mismatch Event	Warning
Message:	The RTC time is off by \$LONG seconds	
Description:	The software RTC and the hardware RTC are out of sync.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 47	Watchdog Reset Event	Warning
Message:	The system was reset by the watchdog.	
Description:	A critical error was detected and the system restarted.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 48	Task Watchdog Reset Event	Warning
Message:	The system was reset by the watchdog for task \$LONG.	
Description:	A critical error was detected and the system restarted.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 49	PLL Limp Error Event	Error
Message:	PLL Limp Mode: DIV=\$USHORT1 DIVSEL=\$USHORT0	
Description:	PLL Limp Mode - OSCCLK is removed or absent from the system	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 50	PLL Wrong Error Event	Warning
Message:	PLL changed: DIV=\$USHORT1 DIVSEL=\$USHORT0	
Description:	PLL Corrected	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 52	Passwords Set Event	Warning
Message:	Passwords was set by the user.	
Description:	An Information alarm is triggered when the Owner-Admin sets passwords. A Warning alarm is triggered when passwords are set by someone other than the Owner-Admin.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 53	Bad Password Event	Warning
Message:	The wrong password given for command: \$USHORT1	
Description:	The wrong password given for command.	
Possible Solutions:	Check password that was entered into the system. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 60	Module Errors Detected	Error
Message:	Too many errors with interface module: \$ULONG	
Description:	The connection to the interface module has errors.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 61	Module Remote Errors Detected	Error
Message:	Too many errors reported by interface module: \$ULONG	
Description:	The connection to the interface module has errors.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 62	Module Syncs Detected	Error
Message:	Synchronization Error with interface module (Syncs=\$ULONG)	
Description:	The connection to the interface module has errors.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 63	Module Communications Detected	Error
Message:	Lost communication with the interface module (Syncs=\$ULONG)	
Description:	The connection to the interface module has errors.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 64	System Reset Event - IO	Info
Message:	Software reset - IO	
Description:	A software reset was performed by an IO line.	
Possible Solutions:	The user issued a software reset command via an input line. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 65	User Note Saved Event	Info
Message:	User note saved at record: \$ULONG	
Description:	A user created note was saved to the log.	
Possible Solutions:	Alarm indication that a note was saved to the log.	

Code 66	User EM0 Event	Critical
Message:	User issued an emergency system stop command	
Description:	The user issued an emergency stop command via serial input.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 67	User Offline Event	Info
Message:	User issued a go to offline state command	
Description:	The user issued a go to offline state command. This puts the pump in an offline state. It will allow a hardware trigger but no other operations will be allowed.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 68	User Online Event	Info
Message:	User issued a go to online state command	
Description:	The user issued a go to online state command. This returns the pump to normal operation from an offline state.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 69	Offline State Detected	Info
Message:	System went into an offline state	
Description:	The system has completed the previous operation and has entered the offline state. Only hardware triggers will be allowed until the system goes back online.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 200	Initialize System Parameters	Warning
Message:	Writing system parameters: On flash memory page \$SHORT1	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 201	Initialize System Names	Warning
Message:	Writing system names: On flash memory page \$SHORT1	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 202	Initialize Recipes	Warning
Message:	Writing recipe \$SHORT0: On flash memory page \$SHORT1	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 203	Initialize Firmware information	Warning
Message:	Writing firmware info: On flash memory page \$SHORT1	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 204	Initialize Calibration	Warning
Message:	Writing calibration: (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 205	Initialize Version	Warning
Message:	Writing version: (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 206	Initialize Recharge	Warning
Message:	Writing recharge parameters (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 207	Initialize Cycle Counters	Warning
Message:	Cycle counters fail (lb=\$USHORT0, ptr=\$USHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 209	Initialize Priming	Warning
Message:	Writing priming (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 210	Initialize Serial Numbers	Warning
Message:	Writing Serial Numbers (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 211	Initialize Confirmation Limits	Warning
Message:	Writing DC Limits (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 212	Initialize Dispense Info	Warning
Message:	Writing Dispense Info Reference (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 213	Initialize Confirmation Profile	Warning
Message:	Initializing DC Profile (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 214	Initialize Passwords	Warning
Message:	Initializing Passwords	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 215	Initialize RDS-01 Saved	Warning
Message:	Initializing R02 Persistent Settings	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 216	Initialize Volume Counters	Warning
Message:	Initializing Volume Counters	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 217	Initialize Pre-Filtration Pressure Control	Warning
Message:	Writing pre-filtration pressure control parameters (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 218	Initialize Fill Ready Pressure Control	Warning
Message:	Writing fill ready pressure control parameters (\$SHORT1)	
Description:	Saved structure in memory is corrupted.	
Possible Solutions:	This may indicate a NV memory failure. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 300	Fixing System Parameters	Warning
Message:	Fixing System Parameters field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 301	Fixing System Names	Warning
Message:	Fixing system names field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 302	Fixing Recipes	Warning
Message:	Fixing recipe \$SHORT0 field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 303	Fixing Firmware information	Warning
Message:	Fixing firmware info field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 304	Fixing Calibration	Warning
Message:	Fixing calibration field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 305	Fixing Version	Warning
Message:	Fixing version field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 306	Fixing Recharge	Warning
Message:	Fixing recharge parameters field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 307	Fixing Cycle Counters	Warning
Message:	Fixing Cycle Counters field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 308	Fixing Alarms	Warning
Message:	Fixing alarm parameters field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 309	Fixing Priming	Warning
Message:	Fixing priming field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 310	Fixing Serial Numbers	Warning
Message:	Fixing Serial Numbers field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 311	Fixing Confirmation Limits	Warning
Message:	Fixing DC Limits field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 312	Fixing Dispense Info	Warning
Message:	Fixing Dispense Info Reference field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 313	Fixing Confirmation Profile	Warning
Message:	Fixing DC Profile field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 314	Fixing Passwords	Warning
Message:	Fixing Passwords field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 315	Fixing RDS-01 Saved	Warning
Message:	Fixing R02 Persistent Settings	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 316	Fixing Volume Counters	Warning
Message:	Fixing Volume Counters \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 317	Fixing Pre-Filtration Pressure Control	Warning
Message:	Fixing pre-filtration pressure control parameters field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 318	Fixing Fill Ready Pressure Control	Warning
Message:	Fixing fill ready pressure control parameters field \$SHORT1	
Description:	A field was initialized to be in bounds.	
Possible Solutions:	Verify all settings for accuracy. This was most likely the result of a firmware upgrade and is most likely normal. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 500	Priming Started Event	Info
Message:	System priming started. Priming Sequence: \$USHORT1	
Description:	A priming sequence was started by the user. The prime sequence number is also displayed.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 501	Priming Stopped Event	Info
Message:	User stopped priming. Priming Sequence: \$USHORT1	
Description:	The user sent a command to stop the priming sequence. The prime sequence number is also displayed.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 502	Total Priming Time	Info
Message:	Priming completed. Total time: \$LONG mins	
Description:	The total time required to complete the priming sequence in minutes.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 503	Trigger Held Detected	Error
Message:	Trigger held active	
Description:	Trigger was already active when system reached ready state.	
Possible Solutions:	Possible trigger line broken, bad cable connection or interface module issue. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 504	Ready Pressure Lower Limit	User
Message:	Ready pressure below the lower control limit of \$PRESSURE0: \$PRESSURE1	
Description:	The system is unable to maintain ready pressure setpoint during the ready state. The pressure in the dispense chamber fell below the lower limit.	
Possible Solutions:	Check system; problems could include outlet valve operation, bad filter, air in system or leaks. Also check N2 supplied to the system and outlet valve. If problem continues, please contact an Entegris customer representative for more information.	

Code 505	Ready Pressure Upper Limit	User
Message:	Ready pressure above the upper control limit of \$PRESSURE0: \$PRESSURE1	
Description:	The system is unable to maintain ready pressure setpoint during the ready state. The pressure in the dispense chamber rose above the upper limit.	
Possible Solutions:	Check system; problems could include outlet valve operation, bad filter, air in system or leaks. Also check N2 supplied to the system and outlet valve. If problem continues, please contact an Entegris customer representative for more information.	

Code 506	Reserved	User
Message:	reserved for future use	
Description:	reserved for future use	
Possible Solutions:	reserved for future use	

Code 507	Trigger When Busy	Error
Message:	A dispense was triggered while system was busy. Original Trigger: \$SHORT0 -- Busy Trigger: \$SHORT1	
Description:	A dispense was triggered while system was busy.	
Possible Solutions:	Bad hardware line or the track attempted to trigger the system while it was busy. If problem continues, please contact an Entegris customer representative for more information.	

Code 508	Trigger When Busy (T-100)	Error
Message:	T-100 retrofit was asked to trigger while system was not ready	
Description:	A dispense was triggered while system was busy.	
Possible Solutions:	Bad hardware line or track attempted to trigger while system was busy. If problem continues, please contact an Entegris customer representative for more information.	

Code 509	Pre-Filtration Timeout	User
Message:	Pre filtration timeout: pressure setpoint was lowered to \$PRESSURE1	
Description:	Set pressure was not reached during filtration.	
Possible Solutions:	Check the system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 510	Pre-Filtration Motor Limit	User
Message:	Pre filtration motor limit: pressure setpoint was lowered to \$PRESSURE1	
Description:	Set pressure was not reached during filtration.	
Possible Solutions:	Check the system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 511	Fill Motor Stall (Filtration)	Error
Message:	Fill motor stalled during filtration or vent. Skip volume: \$SHORT1	
Description:	During the filtration or vent stage, the sensor could not find home position.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 512	Fill Motor Stall (Fill)	Error
Message:	Fill motor stalled during fill. Skip volume: \$SHORT1	
Description:	During the fill stage, the sensor could not find home position.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 513	Fill Motor Home Not Detected	Critical
Message:	Home sensor was not found	
Description:	During initialization, the sensor could not find home position.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 514	Fill Motor Home Not Detected (Power-up)	Critical
Message:	Home sensor was not found during power-up	
Description:	During initialization, the sensor could not find home position. The home sensor is always off.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 515	Fill Motor Home Always On (Power-up)	Critical
Message:	Home sensor is always on - power-up	
Description:	During initialization, the sensor could not find home position. The home sensor is always on.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 516	Dispense Volume Too Large	Error
Message:	Dispense volume in this recipe is too large to dispense	
Description:	Combined volumes for dispense segments, purge and vent exceed maximum dispense volume.	
Possible Solutions:	Check recipe settings. If problem continues, please contact an Entegris customer representative for more information.	

Code 517	Pre-Dis Re-trigger Timeout	Error
Message:	Pre-dispense re trigger timeout	
Description:	A main dispense was not executed before the 30 second timeout after a pre-dispense.	
Possible Solutions:	Clear alarm and try again. Execute a dispense within the 30 second period following the pre-dispense. If problem continues, please contact an Entegris customer representative for more information.	

Code 518	Over Temperature Detected	Critical
Message:	System temperature switch has tripped	
Description:	The temperature switch protecting the dispense motor from over temperature was tripped.	
Possible Solutions:	Monitor system; problems could include faulty main PCB, faulty dispense motor, or faulty switch. If problem continues, please contact an Entegris customer representative for more information.	

Code 519	Over Pressure Detected (Dispense)	Critical
Message:	Dispense pressure is over limit of \$PRESSURE0: \$PRESSURE1	
Description:	Pressure in the dispense stage has exceeded the absolute maximum pressure limit.	
Possible Solutions:	Decrease the dispense rate or increase "outlet valve open adjust" on the recipe page. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 520	Over Pressure Detected (Fill)	Critical
Message:	Fill pressure is over limit of \$PRESSURE0 : \$PRESSURE1	
Description:	Pressure in the fill stage has exceeded the absolute maximum pressure limit.	
Possible Solutions:	Decrease the dispense rate or increase "outlet valve open adjust" on the recipe page. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 521	Over Current Detected (Dispense)	Critical
Message:	Dispense motor over current. \$SHORT1 mAmps	
Description:	Motor current exceeded acceptable limitations.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 522	Dispense Motor Home Failure	Critical
Message:	Dispense motor failed to find hard stop at power-up	
Description:	During initialization, dispense motor could not find lower hard stop.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 523	Dispense Motor Unstable (Power-up A)	Critical
Message:	Dispense motor was unstable at power-up: possible binding	
Description:	Motor position at power-up is exceeding stability limitations.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 524	Dispense Motor Unstable (Power-up B)	Critical
Message:	Dispense motor was unstable at power-up: possible binding	
Description:	Motor position at power-up is exceeding stability limitations.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 525	Dispense Motor Position Error	Critical
Message:	Dispense motor was unable to maintain its position. Total error: \$MLS_1	
Description:	The dispense motor position is monitored in real time. If the dispense motor position error is greater then .1 mL for longer then 2 seconds this alarm will be set.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 526	Dispense Motor Driver Fault	Critical
Message:	Dispense motor driver fault. Current before fault: \$SHORT1 mAmps	
Description:	The dispense motor driver chip is in fault.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 527	Filtration Timeout Detected	User
Message:	The filtration step exceeded the timeout value	
Description:	Filtration took longer than time allowed under current settings.	
Possible Solutions:	Change error to warning to continue. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 528	Over Pressure During Filtration (Fill Stage)	User
Message:	Fill Stage pressure during filtration was too high: \$PRESSURE1	
Description:	During the filtration segment, fill stage pressure couldn't maintain upper limitations.	
Possible Solutions:	Change error to warning to continue. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 529	Under Pressure During Filtration (Fill Stage)	User
Message:	Fill Stage pressure during filtration was too low: \$PRESSURE1	
Description:	During the filtration segment, fill stage pressure couldn't maintain lower limitations.	
Possible Solutions:	Change error to warning to continue. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 530	Over Pressure During Filtration (Dis Stage)	User
Message:	Dispense Stage pressure during filtration was too high: \$PRESSURE1	
Description:	During the filtration segment, dispense stage pressure couldn't maintain upper limitations.	
Possible Solutions:	Change error to warning to continue. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 531	Under Pressure During Filtration (Dis Stage)	User
Message:	Dispense Stage pressure during filtration was too low: \$PRESSURE1	
Description:	During the filtration segment, dispense stage pressure couldn't maintain lower limitations.	
Possible Solutions:	Change error to warning to continue. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 532	Confirmation Reference Save Event	Info
Message:	Confirmation reference profile was saved for Recipe \$SHORT1	
Description:	A new reference profile was saved.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 533	Dispense Motor Encoder Reset Event	Info
Message:	Dispense motor encoder debug A. Counts: \$LONG	
Description:	Used for internal testing only.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 534	Low Vacuum Supply Detected	User
Message:	Vacuum supply to system is inadequate. Limit: \$PRESSURE0. Reading: \$PRESSURE1	
Description:	The vacuum level has dropped below -8.34 psi (-58 kPa) for greater than 2 seconds. This indicates the facility vacuum is inadequate during operation. This alarm may be due to a momentary drop in the vacuum supply or the lines may be disconnected. Note: It is recommended that the vacuum level be maintained greater than -9.86 psi (-68 kPa). This alarm will not be posted while the system is idle.	
Possible Solutions:	Check facility lines supplied to the system. Ensure that all facility lines are properly connected and no pneumatic lines are pinched or damaged. Check levels of both N2 and vacuum supplied to the system. Check the stability of those values over time. If problem continues, please contact an Entegris customer representative for more information.	

Code 535	Low N2 Supply Detected	User
Message:	N2 supply to system is inadequate. Limit: \$PRESSURE0. Reading: \$PRESSURE1	
Description:	This indicates that the facility N2 supplied to system is inadequate. This may have been a momentary drop in the N2 supply or the lines may be disconnected. The system can not function properly in this condition.	
Possible Solutions:	Check facility lines supplied to the system. Ensure that all facility lines are properly connected and no pneumatic lines are pinched or damaged. Check levels of both N2 and vacuum supplied to the system. Check the stability of those values over time. If problem continues, please contact an Entegris customer representative for more information.	

Code 536	High N2 Supply Detected	User
Message:	N2 supply to system exceeds maximum. Limit: \$PRESSURE0. Reading: \$PRESSURE1	
Description:	This indicates that the facility N2 supplied to system is above acceptable levels. This may have been a momentary rise in the N2 supply or an incorrect regulator setting. The system can not function properly in this condition.	
Possible Solutions:	Check facility lines supplied to the system. Ensure that all facility lines are properly connected and no pneumatic lines are pinched or damaged. Check levels of both N2 and vacuum supplied to the system. Check the stability of those values over time. If problem continues, please contact an Entegris customer representative for more information.	

Code 537	Priming Paused Event	Info
Message:	Priming was paused by the user. Priming Sequence: \$USHORT1	
Description:	The user paused the priming by serial command or the MMI.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 538	Priming Resumed Event	Info
Message:	Priming was resumed by the user. Priming Sequence: \$USHORT1	
Description:	The user resumed a paused priming by serial command or the MMI.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 539	Counters Reset Event	Info
Message:	Counter \$LONG was reset (0=A, 1=B)	
Description:	The resettable counter was reset.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 540	Fill Motor Timeout Detected	Critical
Message:	The fill motor has timed out before reaching the target position	
Description:	The dispense motor failed to reach the target position within the time out period. This could be caused by a faulty motor or home sensor.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 541	Dispense Motor Timeout Detected	Critical
Message:	The dispense motor has timed out before reaching the target position	
Description:	The dispense motor failed to reach the target position within the time out period. This could be caused by a faulty motor or position encoder.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 542	Filtration Set-up Timeout	Warning
Message:	The fill stage did not reach filtration set-up pressure: \$PRESSURE1	
Description:	The fill stage pressure is forced to raise above the filtration pressure during a step called filtration set-up. This warning means the fill stage pressure did not reach the setpoint within the timeout period. This could mean there is air in the fill stage or filter.	
Possible Solutions:	The system may have air which prevented it from reaching the desired pressure. Please check for air and perform priming if required. If problem continues, please contact an Entegris customer representative for more information.	

Code 543	filter Counter Cycle Limit	Warning
Message:	The cycle counter (A) on the filter has exceeded the limit of \$LONG cycles	
Description:	Cycle counter (A) is used to track the number of cycles on the filter. A cycle limit setting alerts the user of a filter replacement time. Resettable cycle counter (A) value is displayed on the filter and as well as in the Info tab. Reset this count by going to the Utility tab and pressing the reset A button.	
Possible Solutions:	It is recommended to change the filter, then reset the resettable cycle counter A in the Utility tab. Or the alarm limit can be increased by going to the System tab and increasing the Filter Cycle Alarm Limit. If problem continues, please contact an Entegris customer representative for more information.	

Code 544	Error During Pre-dispense	Critical
Message:	An error occurred during pre-dispense.	
Description:	This error will force the pump to initialization, which will be necessary to continue normal operation after an error during pre-dispense	
Possible Solutions:	This forces the system to initialization after any error during a pre-dispense. If problem continues, please contact an Entegris customer representative for more information.	

Code 545	Pressure Sensor Error Detected	Warning,
Message:	Pressure sensor. Dispense: \$USHORT1 Fill: \$USHORT0	
Description:	Errors were detected while communicating with a digital pressure sensor.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 546	Fill Pressure Sensor Malfunction	Critical
Message:	Fill pressure sensor malfunction	
Description:	The dispense chamber fluid pressure sensor has malfunctioned.	
Possible Solutions:	If problem does not clear by normal clear error operation then try a software reset operation. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 547	Dispense Pressure Sensor Malfunction	Critical
Message:	Dispense pressure sensor malfunction	
Description:	The fill chamber fluid pressure sensor has malfunctioned.	
Possible Solutions:	If problem does not clear by normal clear error operation then try a software reset operation. This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 548	Pre-filtration Ended In Negative Pressure	Critical
Message:	Pre-filtration ended in negative pressure. Pressure: \$PRESSURE1	
Description:	A negative pressure at the end of pre-filtration could indicate the system has air.	
Possible Solutions:	Problems could include bad filter, air in system or leaks. If problem continues, call an Entegris representative for more information.	

Code 549	RDS-01 Recipe Mismatch	Warning
Message:	Potential recipe time mismatch between pump recipe and track recipe (RDS - Track)	
Description:	When using the pump in an RDS-01 retrofit situation the user is required to adjust settings in the track recipe as well as in the pump recipe/recharge parameters. The reason for this is the pump runs in a partial emulation mode. Which means the dispense portion is controlled by the track recipe and the recharge portion is controlled by the pump parameters. This situation requires that the pump recipe finishes first so the pump will be in ready state when the track finishes it recipes.	
Possible Solutions:	The track recipe completed before the pump recipe completed, shorten the pump recipe or lengthen track recipe. If problem continues, please contact an Entegris customer representative for more information.	

Code 550	RDS-01 Maximum Dispense Volume	Error
Message:	Recipe dispense volume is too large for pump hold-up volume	
Description:	The pump was asked to dispense more then the current hold-up volume of the pump will allow	
Possible Solutions:	Check maximum dispense volume setting in the recharge tab of the pump. Check the recipe settings on the track to ensure the proper setting. If problem continues, please contact an Entegris customer representative for more information.	

Code 551	Motor Calculation Error Detected	Error
Message:	Dispense motor home position calculation debug error	
Description:	Used for internal testing only.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 552	Flow Sensor Not Responding	Error
Message:	The flow sensor is not responding	
Description:	The system is configured for a flow sensor. The flow sensor that is connected to the interface module is not responding.	
Possible Solutions:	Check flow sensor connection or the system configuration. If problem continues, please contact an Entegris customer representative for more information.	

Code 553	RDS01 Step Size Error	Error
Message:	RDS-01 specific alarm - Step Size Error. Status Code: \$SHORT1	
Description:	Step size signals coming from the track are invalid.	
Possible Solutions:	Check cable connections to the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 554	RDS01 Enable Timeout Error	Info
Message:	RDS-01 specific alarm - Enable Timeout Error. Status Code: \$SHORT1	
Description:	RDS-01 specific alarm - Enable Timeout Error.	
Possible Solutions:	Check cable connections to the system. This indicates a possible problem with the track equipment. If problem continues, please contact an Entegris customer representative for more information.	

Code 555	RDS01 Over Range Error	Info
Message:	RDS-01 specific alarm - Over Range Error. Status Code: \$SHORT1	
Description:	RDS-01 specific alarm - Over Range Error.	
Possible Solutions:	Check cable connections to the system. This indicates a possible problem with the track equipment. If problem continues, please contact an Entegris customer representative for more information.	

Code 556	Confirmation Temporarily Disabled	Info
Message:	System detected invalid dispense: dispense confirmation was disabled for this dispense	
Description:	Track sent a false dispense signal. The pump dispensed; however since this dispense was not on a wafer, the confirmation feature was disabled for this dispense only.	
Possible Solutions:	The operation of the track caused this condition. This operation could be normal, check operation of the track. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 557	24 VDC Fill Motor Fault	Critical
Message:	PWR 24 VDC to the fill motor driver circuit has been lost.	
Description:	PWR 24 VDC to the fill motor driver circuit has been lost. Mostly likely Fuse F6 has blown as a result of a circuit failure.	
Possible Solutions:	Monitor system; problems could include faulty main PCB, faulty fill motor, or faulty motor connections. Also for information, the main PCB is field replaceable without the loss of any important system calibration parameters. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 558	24 VDC Dispense Motor Fault	Critical
Message:	PWR 24 VDC to the dispense motor driver circuit has been lost.	
Description:	PWR 24 VDC to the dispense motor driver circuit has been lost. Mostly likely Fuse F5 has blown as a result of a circuit failure.	
Possible Solutions:	Monitor system; problems could include faulty main PCB, faulty fill motor, or faulty motor connections. Also for information, the main PCB is field replaceable without the loss of any important system calibration parameters. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 559	Suckback Greater Than Dispense	Error
Message:	The suckback volume is greater than the dispense volume. (Suckback: \$ML_0 > Dispense: \$ML_1)	
Description:	This recipe cannot be dispensed as set. The suckback volume is greater than the dispense volume.	
Possible Solutions:	The suckback volume needs to be lower than the dispense volume or the suckback mode needs to be changed to "Add Volume". The suckback mode is in the system parameters. If problem continues, please contact an Entegris customer representative for more information.	

Code 560	Trigger Error Detected	Error
Message:	A trigger line was asserted but then was found to be invalid after the debounce time. Code: \$ULONG	
Description:	A trigger line was asserted but then was found to be invalid after the debounce time. This alarm is not expected, this is for internal debug only. It is possible trigger line failure.	
Possible Solutions:	Check cable connections to the system. This indicates a possible problem with the track equipment. If problem continues, please contact an Entegris customer representative for more information.	

Code 561	Trigger When Busy State	Error
Message:	A dispense was triggered while system was busy. Busy Status Code: \$SHORT1	
Description:	A dispense was triggered while system was busy. Busy status code is included.	
Possible Solutions:	Bad hardware line or the track attempted to trigger the system while it was busy. If problem continues, please contact an Entegris customer representative for more information.	

Code 562	Recharge timeout (T-100)	Error
Message:	T-100 failed to recharge before the timeout	
Description:	T-100 failed to recharge before the timeout.	
Possible Solutions:	Bad hardware line or track failed to send recharge signals. If problem continues, please contact an Entegris customer representative for more information.	

Code 563	Confirmation Reference Delete Event	Info
Message:	Confirmation reference profile was deleted for Recipe \$SHORT1	
Description:	A reference profile was deleted.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 564	Trigger When Busy (SHV)	Error
Message:	SHV retrofit was asked to trigger while system was not ready	
Description:	A dispense was triggered while system was busy.	
Possible Solutions:	Bad hardware line or track attempted to trigger while system was busy. If problem continues, please contact an Entegris customer representative for more information.	

Code 565	Consecutive auto-vents	User
Message:	Too many consecutive auto-vent operations. Consecutive auto-vents: \$USHORT1	
Description:	Too many consecutive auto-vent operations. The user set a limit on the number of consecutive auto-vents. This limit has been exceeded. This is to prevent a large number unintended auto-vents from being preformed.	
Possible Solutions:	Check the system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 566	N2 Supply Buffer Inadequate	User
Message:	The N2 supply pressure is not high enough to support the dispense pressure. N2 Supply: \$PRESSURE0, Dispense pressure: \$PRESSURE1	
Description:	This indicates that the facility N2 supplied to system is lower than the detected dispense pressure. This could possibly cause some of the internal fluid valves to leak by. This may have been a momentary drop in the N2 supply or an incorrect regulator setting. The system can not function properly in this condition.	
Possible Solutions:	Check facility lines supplied to the system. Ensure that all facility lines are properly connected and no pneumatic lines are pinched or damaged. Check levels of both N2 and vacuum supplied to the system. Check the stability of those values over time. If problem continues, please contact an Entegris customer representative for more information.	

Code 567	No reference	Warning
Message:	No valid reference recipe was detected. The confirmation feature will not be calculated properly. Code: \$USHORT1	
Description:	The system was not able to determine the correct reference recipe or a valid reference does not exist. As a result the system will not be able to calculate the confirmation values correctly.	
Possible Solutions:	The reference recipe will need to be reset. If problem continues, please contact an Entegris customer representative for more information.	

Code 568	Flow sensor unexpected command	Warning
Message:	Flow sensor or module provided an unexpected sensor command	
Description:	The system is configured for a flow sensor. The flow sensor that is connected needed to be reset.	
Possible Solutions:	Check flow sensor connection or the system configuration. If problem continues, please contact an Entegris customer representative for more information.	

Code 569	Flow sensor reset at startup	Error
Message:	Flow sensor is communicating, but received no valid flow data	
Description:	The system is configured for a flow sensor. The flow sensor that is connected did not send any data.	
Possible Solutions:	Check flow sensor connection or the system configuration. If problem continues, please contact an Entegris customer representative for more information.	

Code 570	Volume Counters Reset Event	Info
Message:	Volume Counters were reset	
Description:	The volume counters were reset.	
Possible Solutions:	If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 571	Vent Performed	Info
Message:	Vent operation started based on vent frequency count \$SHORT1	
Description:	Vent operation started based on vent frequency count.	
Possible Solutions:	Informational message when vent is performed based on cycle count.	

Code 572	Auto-vent Consecutive Performed	Info
Message:	Auto-vent operation started because PreFiltration failed. Auto-vent consecutive count \$SHORT1	
Description:	Auto-vent operation started because PreFiltration failed. Auto-vent consecutive count \$SHORT1	
Possible Solutions:	Informational message informing that Auto-vent operation started because PreFiltration failed.	

Code 900	Self-Test Started (Dispense Backlash)	Info
Message:	AirDetect Rise = \$MPRESSURE1	
Description:	Air Detect Values	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 901	Self-Test Started (Dispense Backlash)	Info
Message:	AirDetect Corrected Rise = \$MPRESSURE1	
Description:	Air Detect Values	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 902	Self-Test Started (Dispense Backlash)	Info
Message:	AirDetect AirAmount = \$ML_1	
Description:	Air Detect Values	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1000	Confirmation Profile Failure	Error
Message:	Confirmation failure, reference profile load failure. code:\$SHORT1	
Description:	Internal error for firmware debug.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 1001	Confirmation Recipe Not Detected	Error
Message:	Confirmation failure, recipe not detected during confirmation	
Description:	Internal error for firmware debug.	
Possible Solutions:	This alarm should not occur in normal operation. Power down to re-initialize the system. If problem continues, please contact an Entegris customer representative for more information.	

Code 1020	Confirmation Failure (Ready Pressure)	User
Message:	Confirmation failure, average ready pressure limit \$PRESSURE0. Value: \$PRESSURE1	
Description:	The starting ready pressure is different than what was expected by the confirmation test limits.	
Possible Solutions:	The ready pressure at the start of the last dispense is different than the ready pressure at the start of the reference dispense. This could be an indication of air in the system and a motor drive issue. Check system; problems could include, air in system, bad motor drive or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 1021	Confirmation Failure (Ready Correction)	User
Message:	Confirmation failure, ready correction volume limit \$ML_0. Value: \$ML_1	
Description:	The starting ready correction volume is different than what was expected by the confirmation test limits.	
Possible Solutions:	The ready correction volume at the start of the last dispense is different than the ready correction volume at the start of the reference dispense. This could be an indication of air in the system and a motor drive issue. Check system; problems could include, air in system, bad motor drive or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 1022	Confirmation Failure (Profile Compare)	User
Message:	Confirmation failure, pressure profile comparison limit \$USHORT0. Value: \$USHORT1	
Description:	The dispense pressure profile compare is different than what was expected by the confirmation test limits.	
Possible Solutions:	The overall pressure profile of the last dispense is statistically different then the reference. Confirm the dispense variables have not changed since last confirmation save. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 1023	Confirmation Failure (Flow Compare)	User
Message:	Confirmation failure, flow profile comparison limit \$USHORT0. Value: \$USHORT1	
Description:	The dispense flow profile compare is different than what was expected by the confirmation test limits.	
Possible Solutions:	The overall flow profile of the last dispense is statistically different then the reference. Confirm the dispense variables have not changed since last confirmation save. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.	

Code 1024	Confirmation Failure (Max Pressure)	User
Message:	Confirmation failure, maximum dispense pressure limit \$PRESSURE0. Value: \$PRESSURE1	
Description:	The maximum dispense pressure is different than what was expected by the confirmation test limits.	
Possible Solutions:	The maximum dispense pressure can be affected by recipe changes, outlet valve issues or air in the system. Check recipe variables or the system outlet valve and line. If problem continues, please contact an Entegris customer representative for more information.	

Code 1025	Confirmation Failure (Average Pressure)	User
Message:	Confirmation failure, average dispense pressure limit \$PRESSURE0. Value: \$PRESSURE1	
Description:	The average dispense pressure is different than what was expected by the confirmation test limits.	
Possible Solutions:	The average dispense pressure can be affected by recipe changes, outlet valve issues, air in the system or fluid changes. Check recipe variables, the system outlet valve and line, and system fluid. If problem continues, please contact an Entegris customer representative for more information.	

Code 1026	Confirmation Failure (Cut-off Pressure)	User
Message:	Confirmation failure, dispense cut-off pressure limit \$PRESSURE0. Value: \$PRESSURE1	
Description:	The dispense cut-off pressure is different than what was expected by the confirmation test limits.	
Possible Solutions:	The cut-off pressure is the average dispense pressure when the outlet valve closes. It can be affected by recipe changes, outlet valve issues, air in the system, or fluid changes. Check recipe variables, the system outlet valve and line, and system fluid. If problem continues, please contact an Entegris customer representative for more information.	

Code 1027	Confirmation Failure (Average Rate)	User
Message:	Confirmation failure, average dispense rate limit \$MLS_0. Value: \$MLS_1	
Description:	The average dispense rate is different than what was expected by the confirmation test limits.	
Possible Solutions:	The average dispense rate can be affected by recipe changes or motor drive issues. Check recipe variables. If problem continues, please contact an Entegris customer representative for more information.	

Code 1028	Confirmation Failure (Total Volume)	User
Message:	Confirmation failure, total dispense volume limit \$ML_0. Value: \$ML_1	
Description:	The total dispense volume is different than what was expected by the confirmation test limits.	
Possible Solutions:	The total dispense volume can be affected by recipe changes or motor drive issues. Check recipe variables. If problem continues, please contact an Entegris customer representative for more information.	

Code 1029	Confirmation Failure (Average Current)	User
Message:	Confirmation failure, average dispense current limit \$SHORT0 mA. Value: \$SHORT1 mA	
Description:	The average dispense current is different than what was expected by the confirmation test limits.	
Possible Solutions:	The average dispense motor current can be affected by recipe changes, fluid changes, or motor drive issues. Check recipe variables. If problem continues, please contact an Entegris customer representative for more information.	

Code 1030	Confirmation Failure (Predicted Current)	User
Message:	Confirmation failure, predicted dispense current limit \$SHORT0 mA. Value: \$SHORT1 mA	
Description:	The average dispense current is different than what was expected by the confirmation test limits.	
Possible Solutions:	The predicted dispense motor current can be affected by motor rate changes or dispense pressure changes. Check recipe variables and system set-up. If problem continues, please contact an Entegris customer representative for more information.	

Code 1031	Confirmation Failure (Dispense Temperature)	User
Message:	Confirmation failure, dispense temperature limit \$SHORT0 mA. Value: \$SHORT1 mA	
Description:	The dispense temperature is greater than what was expected by the confirmation test limits.	
Possible Solutions:	The dispense temperature can be sign of motor drive issue or faulty dispense pressure sensor. If problem continues, please contact an Entegris customer representative for more information.	

Code 1032	Confirmation Failure (Air Detect)	User
Message:	Confirmation failure, dispense air detect limit \$ML_0. Value: \$ML_1	
Description:	The dispense air detect value is different than what was expected by the confirmation test limits.	
Possible Solutions:	The dispense air detect is a pressure rise test that is designed to measure air in the dispense stage of the system which includes the dispense line. It can be affected by recipe changes, outlet valve issues, air in the system, or fluid changes. Check recipe variables, the system outlet valve and line, and system fluid. If problem continues, please contact an Entegris customer representative for more information.	

Code 1033	Confirmation Failure (Flow Volume)	User
Message:	Confirmation failure, total flow volume limit \$ML_0. Value: \$ML_1	
Description:	The total flow volume is different than what was expected by the confirmation test limits.	
Possible Solutions:	The total flow volume can be affected by recipe changes, motor drive issues or air in the dispense line. Check recipe variables. If problem continues, please contact an Entegris customer representative for more information.	

Code 1034	Confirmation Failure (Delta Pressure)	User
Message:	Confirmation failure, average filtration delta pressure limit \$PRESSURE0. Value: \$PRESSURE1	
Description:	The average filtration delta pressure is different than what was expected by the confirmation test limits.	
Possible Solutions:	Filtration delta pressure failure could indicate a clogged filter, changes to the recharge values or a fluid viscosity change. Check recharge variables and the filter. If problem continues, please contact an Entegris customer representative for more information.	

Code 1035	Confirmation Failure (Filtration Upstrm Pressure)	User
Message:	Confirmation failure, filtration upstream pressure limit \$PRESSURE0. Value: \$PRESSURE1	
Description:	The maximum filtration upstream pressure is different than what was expected by the confirmation test limits.	
Possible Solutions:	Maximum filtration pressure is the maximum pressure in the fill stage of the system. High pressure here could cause a fill motor stall. Failure could indicate a clogged filter, changes to the recharge values or a fluid viscosity change. Check recharge variables and the filter. If problem continues, please contact an Entegris customer representative for more information.	

Code 1036	Confirmation Failure (Filtration Average Rate)	User
Message:	Confirmation failure, average filtration rate limit \$MLS_0. Value: \$MLS_1	
Description:	The average filtration motor rate is different than what was expected by the confirmation test limits.	
Possible Solutions:	The average filtration rate can be affected by recharge changes or motor drive issues. Check recharge variables. If problem continues, please contact an Entegris customer representative for more information.	

Code 1037	Confirmation Failure (Filtration Time)	User
Message:	Confirmation failure, filtration time limit \$CSECS0. Value: \$CSECS1	
Description:	The total filtration time is different than what was expected by the confirmation test limits.	
Possible Solutions:	Filtration time failure could indicate a clogged filter, changes to the recharge values or a fluid viscosity change. Check recharge variables and the filter. If problem continues, please contact an Entegris customer representative for more information.	

Code 1038	Confirmation Failure (Vent Time)	User
Message:	Confirmation failure, total vent time limit \$CSECS0. Value: \$CSECS1	
Description:	The total vent time is different than what was expected by the confirmation test limits.	
Possible Solutions:	Vent time failure could indicate changes to the recharge values or a fluid viscosity change. Check recharge variables. If problem continues, please contact an Entegris customer representative for more information.	

Code 1039	Confirmation Failure (Fill Minimum Pressure)	User
Message:	Confirmation failure, minimum fill pressure limit \$PRESSURE0. Value: \$PRESSURE1	
Description:	The average fill pressure is different than what was expected by the confirmation test limits.	
Possible Solutions:	Fill pressure failure could indicate a clogged/damaged inlet line, changes to the recharge values or a fluid viscosity change. Check recharge variables and the system inlet line. If problem continues, please contact an Entegris customer representative for more information.	

Code 1040	Confirmation Failure (Fill Average Rate)	User
Message:	Confirmation failure, average fill rate limit \$MLS_0. Value: \$MLS_1	
Description:	The average fill motor rate is different than what was expected by the confirmation test limits.	
Possible Solutions:	Fill rate failure could indicate a clogged/damaged inlet line, changes to the recharge values or a fluid viscosity change. Check recharge variables and the system inlet line. If problem continues, please contact an Entegris customer representative for more information.	

Code 1041	Confirmation Failure (Fill Time)	User
Message:	Confirmation failure, fill time limit \$CSECS0. Value: \$CSECS1	
Description:	The total fill time is different than what was expected by the confirmation test limits.	
Possible Solutions:	Fill time failure could indicate a clogged/damaged inlet line, changes to the recharge values or a fluid viscosity change. Check recharge variables and the system inlet line. If problem continues, please contact an Entegris customer representative for more information.	

Code 1042	Confirmation Failure (Max Pressure Time)	User
Message:	Confirmation failure, maximum dispense pressure time limit \$SHORT0. Value: \$SHORT1	
Description:	The maximum dispense pressure time is different than what was expected by the confirmation test limits.	
Possible Solutions:	The maximum dispense pressure time can be affected by recipe changes, outlet valve issues or air in the system. Check recipe variables or the system outlet valve and line. If problem continues, please contact an Entegris customer representative for more information.	

Code 1043	Confirmation Failure (Fill Motor Mismatch)	User
Message:	Confirmation failure, fill motor mismatch limit \$MLS_0. Value: \$MLS_1	
Description:	The fill motor mismatch is different than what was expected by the confirmation test limits.	
Possible Solutions:	Fill motor mismatch is a measure of skip steps on the fill motor. Failure could indicate a clogged filter, changes to the recharge values, fluid viscosity change or motor drive issues. Check recharge variables and the filter. If problem continues, please contact an Entegris customer representative for more information.	

Code 1044	Confirmation Failure (Total Cycle Time)	User
Message:	Confirmation failure, total cycle time limit \$CSECS0. Value: \$CSECS1	
Description:	The total cycle time is different than what was expected by the confirmation test limits.	
Possible Solutions:	Cycle time failure could indicate a clogged/damaged inlet line, changes to the recharge values or a fluid viscosity change. Check recharge variables and the system inlet line. If problem continues, please contact an Entegris customer representative for more information.	

Code 1045	Confirmation Failure (Reserved Test 5)	User
Message:	reserved for future use	
Description:	reserved for future use	
Possible Solutions:	reserved for future use	

Code 1046	Confirmation Failure (Profile Compare IGMINI style)
Message:	Confirmation failure, pressure profile comparison (IGMINI style) limit \$USHORT0. Value: \$USHORT1
Description:	The dispense pressure profile compare (IGMINI style) is different than what was expected by the confirmation test limits.
Possible Solutions:	The overall pressure profile (IGMINI style) of the last dispense is statistically different than the reference. Confirm the dispense variables have not changed since last confirmation save. Check system; problems could include bad filter, air in system or leaks. If problem continues, please contact an Entegris customer representative for more information.

Code 1100	Self-Test Started (Dispense Backlash)	Info
Message:	Self Test Started: Dispense backlash	
Description:	User started Self Test: Dispense backlash	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1101	Self-Test Passed (Dispense Backlash)	Info
Message:	Self Test Passed: Dispense backlash	
Description:	Self Test Passed: Dispense backlash	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1102	Self-Test Failed (Dispense Backlash)	Info
Message:	Self Test Failed: Dispense backlash	
Description:	Self Test Failed: Dispense backlash	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1103	Self-Test Incomplete (Dispense Backlash)	Info
Message:	Self Test Incomplete: Dispense backlash	
Description:	Self Test Incomplete: Dispense backlash	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1104	Self-Test Results A (Dispense Backlash)	Info
Message:	Self Test Results: Dispense backlash = \$USHORT1 um	
Description:	Self Test Results: Dispense backlash	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1105	Self-Test Results B (Dispense Backlash)	Info
Message:	Self Test Results: Dispense backlash pressure = \$PRESSURE1	
Description:	Self Test Results: Dispense backlash pressure	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1120	Self-Test Started (Fill Strength)	Info
Message:	Self Test Started: Dry Fill Motor Strength	
Description:	Self Test Started: Dry Fill Motor Strength	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1121	Self-Test Passed (Fill Strength)	Info
Message:	Self Test Passed: Dry Fill Motor Strength	
Description:	Self Test Passed: Dry Fill Motor Strength	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1122	Self-Test Failed (Fill Strength)	Info
Message:	Self Test Failed: Dry Fill Motor Strength	
Description:	Self Test Failed: Dry Fill Motor Strength	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1123	Self-Test Incomplete (Fill Strength)	Info
Message:	Self Test Incomplete: Dry Fill Motor Strength	
Description:	Self Test Incomplete: Dry Fill Motor Strength	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1124	Self-Test Results A (Fill Strength)	Info
Message:	Self Test Results: Fill Motor Current = \$SHORT1 mA	
Description:	Self Test Results: Fill Motor Current = \$SHORT1 mA	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1125	Self-Test Results B (Fill Strength)	Info
Message:	Self Test Results: Fill Motor Strength Pressure = \$PRESSURE1	
Description:	Self Test Results: Fill Motor Strength Pressure = \$PRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1126	Self-Test Results C (Fill Strength)	Info
Message:	Self Test Results: Starting Fill Motor Mismatch = \$ML_1	
Description:	Self Test Results: Starting Fill Motor Mismatch = \$ML_1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1127	Self-Test Results D (Fill Strength)	Info
Message:	Self Test Results: Final Fill Motor Mismatch = \$ML_1	
Description:	Self Test Results: Final Fill Motor Mismatch = \$ML_1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1140	Self-Test Started (Dispense Strength)	Info
Message:	Self Test Started: Dry Dispense Motor Strength	
Description:	Self Test Started: Dry Dis Motor Strength	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1141	Self-Test Passed (Dispense Strength)	Info
Message:	Self Test Passed: Dry Dispense Motor Strength	
Description:	Self Test Passed: Dry Dis Motor Strength	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1142	Self-Test Failed (Dispense Strength)	Info
Message:	Self Test Failed: Dry Dispense Motor Strength	
Description:	Self Test Failed: Dry Dis Motor Strength	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1143	Self-Test Incomplete (Dispense Strength)	Info
Message:	Self Test Incomplete: Dry Dispense Motor Strength	
Description:	Self Test Incomplete: Dry Dis Motor Strength	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1144	Self-Test Results A (Dispense Strength)	Info
Message:	Self Test Results: Dispense Motor Current = \$SHORT1 mA	
Description:	Self Test Results: Dispense Motor Current = \$SHORT1 mA	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1145	Self-Test Results B (Dispense Strength)	Info
Message:	Self Test Results: Dispense Motor Predicted Current = \$SHORT1 mA	
Description:	Self Test Results: Dispense Motor Predicted Current = \$SHORT1 mA	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1146	Self-Test Results C (Dispense Strength)	Info
Message:	Self Test Results: Dispense Motor Position Error = \$ML_1	
Description:	Self Test Results: Dispense Motor Position Error = \$ML_1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1147	Self-Test Results D (Dispense Strength)	Info
Message:	Self Test Results: Dispense Motor Strength Pressure = \$PRESSURE1	
Description:	Self Test Results: Dispense Motor Strength Pressure = \$PRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1148	Self-Test Results E (Dispense Strength)	Info
Message:	Self Test Results: Dispense Motor Avg rate = \$MLS_1	
Description:	Self Test Results: Dispense Motor Avg rate = \$MLS_1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1160	Self-Test Started (Sensor Accuracy)	Info
Message:	Self Test Started: Pressure Sensor Accuracy	
Description:	Self Test Started: Pressure Sensor Accuracy	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1161	Self-Test Passed (Sensor Accuracy)	Info
Message:	Self Test Passed: Pressure Sensor Accuracy	
Description:	Self Test Passed: Pressure Sensor Accuracy	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1162	Self-Test Failed (Sensor Accuracy - Dispense)	Info
Message:	Self Test Failed: Dis Pressure Sensor Accuracy	
Description:	Self Test Failed: Dis Pressure Sensor Accuracy	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1163	Self-Test Failed (Sensor Accuracy - Fill)	Info
Message:	Self Test Failed: Fill Pressure Sensor Accuracy	
Description:	Self Test Failed: Fill Pressure Sensor Accuracy	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1164	Self-Test Incomplete (Sensor Accuracy)	Info
Message:	Self Test Incomplete: Pressure Sensor Accuracy	
Description:	Self Test Incomplete: Pressure Sensor Accuracy	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1165	Self-Test Results A (Sensor Accuracy)	Info
Message:	Self Test Results: Setpoint Pressure = \$PRESSURE1	
Description:	Self Test Results: Setpoint Pressure = \$PRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1166	Self-Test Results B (Sensor Accuracy)	Info
Message:	Self Test Results: Dispense pressure = \$PRESSURE1	
Description:	Self Test Results: Dispense pressure = \$PRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1167	Self-Test Results C (Sensor Accuracy)	Info
Message:	Self Test Results: Dispense Full Scale Error % = \$CPERC1	
Description:	Self Test Results: Dispense Full Scale Error % = \$CPERC1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1168	Self-Test Results D (Sensor Accuracy)	Info
Message:	Self Test Results: Fill pressure = \$PRESSURE1	
Description:	Self Test Results: Fill pressure = \$PRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1169	Self-Test Results E (Sensor Accuracy)	Info
Message:	Self Test Results: Fill Full Scale Error % = \$CPERC1	
Description:	Self Test Results: Fill Full Scale Error % = \$CPERC1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1180	Self-Test Started (System Leak)	Info
Message:	Self Test Started: Pump Leak Test	
Description:	Self Test Started: Pump Leak Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1181	Self-Test Passed (System Leak)	Info
Message:	Self Test Passed: Pump Leak Test	
Description:	Self Test Passed: Pump Leak Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1182	Self-Test Failed (System Leak)	Info
Message:	Self Test Failed: Pump Leak Test	
Description:	Self Test Failed: Pump Leak Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1183	Self-Test Incomplete (System Leak)	Info
Message:	Self Test Incomplete: Pump Leak Test	
Description:	Self Test Incomplete: Pump Leak Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1184	Self-Test Results A (System Leak)	Info
Message:	Self Test Results: Starting Pressure = \$MPRESSURE1	
Description:	Self Test Results: Starting Pressure = \$MPRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1185	Self-Test Results B (System Leak)	Info
Message:	Self Test Results: Ending Pressure = \$MPRESSURE1	
Description:	Self Test Results: Ending Pressure = \$MPRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1186	Self-Test Results C (System Leak)	Info
Message:	Self Test Results: Delta Pressure = \$MPRESSURE1	
Description:	Self Test Results: Delta Pressure = \$MPRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1187	Self-Test Results D (System Leak)	Info
Message:	Self Test Results: Leak Rate = \$MPRESSURE1/min	
Description:	Self Test Results: Leak Rate = \$MPRESSURE1/min	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1200	Self-Test Started (Air Detect)	Info
Message:	Self Test Started: Air Detect Test	
Description:	Self Test Started: Air Detect Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1201	Self-Test Passed (Air Detect)	Info
Message:	Self Test Passed: Air Detect Test	
Description:	Self Test Passed: Air Detect Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1202	Self-Test Failed (Air Detect)	Info
Message:	Self Test Failed: Air Detect Test	
Description:	Self Test Failed: Air Detect Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1203	Self-Test Incomplete (Air Detect)	Info
Message:	Self Test Incomplete: Air Detect Test	
Description:	Self Test Incomplete: Air Detect Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1204	Self-Test Results A (Air Detect)	Info
Message:	Self Test Results:	
Description:	Self Test Results:	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1205	Self-Test Results B (Air Detect)	Info
Message:	Self Test Results:	
Description:	Self Test Results:	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1206	Self-Test Results C (Air Detect)	Info
Message:	Self Test Results:	
Description:	Self Test Results:	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1207	Self-Test Results D (Air Detect)	Info
Message:	Self Test Results:	
Description:	Self Test Results:	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1250	Self-Test Started (Sensor Re-zero)	Info
Message:	Self Test Started: Pressure Sensor Re-zero	
Description:	Self Test Started: Dispense Pressure Sensor Re-zero	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1251	Self-Test Passed (Sensor Re-zero)	Info
Message:	Self Test Passed: Pressure Sensor Re-zero	
Description:	Self Test Passed: Dispense Pressure Sensor Re-zero	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1252	Self-Test Failed (Sensor Re-zero - NV Save)	Info
Message:	Self Test Failed: Pressure Sensor Re-zero (NV save)	
Description:	Self Test Failed: Pressure Sensor Re-zero (NV save)	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1253	Self-Test Failed (Sensor Re-zero - Dispense)	Info
Message:	Self Test Failed: Dispense Pressure Sensor Re-zero	
Description:	Self Test Failed: Dispense Pressure Sensor Re-zero	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1254	Self-Test Failed (Sensor Re-zero - Fill)	Info
Message:	Self Test Failed: Fill Pressure Sensor Re-zero	
Description:	Self Test Failed: Fill Pressure Sensor Re-zero	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1255	Self-Test Incomplete (Sensor Re-zero)	Info
Message:	Self Test Incomplete: Pressure Sensor Re-zero - Out of range	
Description:	Self Test Incomplete: Dispense Pressure Sensor Re-zero	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1256	Self-Test Results A (Sensor Re-zero)	Info
Message:	Self Test Results: Pre Dispense pressure = \$PRESSURE1	
Description:	Self Test Results: Pre Dispense pressure = \$PRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1257	Self-Test Results B (Sensor Re-zero)	Info
Message:	Self Test Results: Pre Dispense Full Scale Error = \$CPERC1	
Description:	Self Test Results: Pre Dispense Full Scale Error % = \$CPERC1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1258	Self-Test Results C (Sensor Re-zero)	Info
Message:	Self Test Results: Pre Fill pressure = \$PRESSURE1	
Description:	Self Test Results: Pre Fill pressure = \$PRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1259	Self-Test Results D (Sensor Re-zero)	Info
Message:	Self Test Results: Pre Fill Full Scale Error = \$CPERC1	
Description:	Self Test Results: Pre Fill Full Scale Error % = \$CPERC1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1260	Self-Test Results E (Sensor Re-zero)	Info
Message:	Self Test Results: Post Dispense pressure = \$PRESSURE1	
Description:	Self Test Results: Post Dispense pressure = \$PRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1261	Self-Test Results F (Sensor Re-zero)	Info
Message:	Self Test Results: Post Dispense Full Scale Error = \$CPERC1	
Description:	Self Test Results: Post Dispense Full Scale Error % = \$CPERC1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1262	Self-Test Results G (Sensor Re-zero)	Info
Message:	Self Test Results: Post Fill pressure = \$PRESSURE1	
Description:	Self Test Results: Post Fill pressure = \$PRESSURE1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1263	Self-Test Results H (Sensor Re-zero)	Info
Message:	Self Test Results: Post Fill Full Scale Error = \$CPERC1	
Description:	Self Test Results: Post Fill Full Scale Error % = \$CPERC1	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1301	Self-Test Started (System Valve Test)	Info
Message:	Self Test Started: Pump Valve Funcion Test	
Description:	Self Test Started: Pump Valve Funcion Test	
Possibile Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1302	Self-Test Started (System Valve Test - Inlet)	Info
Message:	Self Test Started: Pump Valve Funcion Test - Inlet	
Description:	Self Test Started: Pump Valve Funcion Test - Inlet	
Possibile Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1303	Self-Test Started (System Valve Test - Isolate)	Info
Message:	Self Test Started: Pump Valve Funcion Test - Isolate	
Description:	Self Test Started: Pump Valve Funcion Test - Isolate	
Possibile Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1304	Self-Test Started (System Valve Test - Vent)	Info
Message:	Self Test Started: Pump Valve Funcion Test - Vent	
Description:	Self Test Started: Pump Valve Funcion Test - Vent	
Possibile Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1305	Self-Test Started (System Valve Test - Barrier)	Info
Message:	Self Test Started: Pump Valve Funcion Test - Barrier	
Description:	Self Test Started: Pump Valve Funcion Test - Barrier	
Possibile Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1306	Self-Test Started (System Valve Test - Purge)	Info
Message:	Self Test Started: Pump Valve Function Test - Purge	
Description:	Self Test Started: Pump Valve Function Test - Purge	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1307	Self-Test Passed (System Valve Test)	Info
Message:	Self Test Passed: Pump Valve Function Test	
Description:	Self Test Passed: Pump Valve Function Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1308	Self-Test Failed (System Valve Test)	Info
Message:	Self Test Failed: Pump Valve Function Test	
Description:	Self Test Failed: Pump Valve Function Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1309	Self-Test Incomplete (System Valve Test)	Info
Message:	Self Test Incomplete: Pump Valve Function Test	
Description:	Self Test Incomplete: Pump Valve Function Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1310	Self-Test Results A (System Valve Test)	Info
Message:	Self Test Results: Close Valve Pressure = \$MPRESSURE	
Description:	Self Test Results: Close Valve Pressure = \$MPRESSURE	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1311	Self-Test Results B (System Valve Test)	Info
Message:	Self Test Results: Open Valve Pressure = \$MPRESSURE	
Description:	Self Test Results: Open Valve Pressure = \$MPRESSURE	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1312	Self-Test Results C (System Valve Test)	Info
Message:	Self Test Results: Delta Pressure = \$MPRESSURE	
Description:	Self Test Results: Delta Pressure = \$MPRESSURE	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1351	Self-Test Started (Valve Timing Test)	Info
Message:	Self Test Started: Pump Valve Function Test	
Description:	Self Test Started: High Viscosity Valve Timing Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1352	Self-Test Started (Valve Timing Test)	Info
Message:	Self Test Started: Pump Valve Function Test - Inlet	
Description:	Self Test Started: High Viscosity Valve Timing Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1353	Self-Test Started (Valve Timing Test)	Info
Message:	Self Test Started: Pump Valve Function Test - Isolate	
Description:	Self Test Started: High Viscosity Valve Timing Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1354	Self-Test Started (Valve Timing Test)	Info
Message:	Self Test Started: Pump Valve Function Test - Vent	
Description:	Self Test Started: High Viscosity Valve Timing Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1355	Self-Test Started (Valve Timing Test)	Info
Message:	Self Test Started: Pump Valve Function Test - Barrier	
Description:	Self Test Started: High Viscosity Valve Timing Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1356	Self-Test Started (Valve Timing Test)	Info
Message:	Self Test Started: Pump Valve Function Test - Purge	
Description:	Self Test Started: High Viscosity Valve Timing Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1357	Self-Test Passed (Valve Timing Test)	Info
Message:	Self Test Passed: Pump Valve Function Test	
Description:	Self Test Passed: High Viscosity Valve Timing Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1358	Self-Test Failed (Valve Timing Test)	Info
Message:	Self Test Failed: Pump Valve Function Test	
Description:	Self Test Failed: High Viscosity Valve Timing Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1359	Self-Test Incomplete (Valve Timing Test)	Info
Message:	Self Test Incomplete: Pump Valve Function Test	
Description:	Self Test Incomplete: High Viscosity Valve Timing Test	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1360	Self-Test Results A (Valve Timing Test)	Info
Message:	Self Test Results: Starting Pressure = \$MPRESSURE	
Description:	Self Test Results: Starting Pressure = \$MPRESSURE	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1361	Self-Test Results B (Valve Timing Test)	Info
Message:	Self Test Results: Ending Pressure = \$MPRESSURE	
Description:	Self Test Results: Starting Pressure = \$MPRESSURE	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

Code 1362	Self-Test Results C (Valve Timing Test)	Info
Message:	Self Test Results: Test Time = \$MSECS	
Description:	Self Test Results: Starting Pressure = \$MSECS	
Possible Solutions:	Information regarding self test. If this was an intentional action by the user, no other action is required. If this alarm occurred outside of that condition, please contact an Entegris customer representative for more information.	

