

1. Facing Errors

This manual covers the Press-2000 hydraulic shop press.

The Press-2000 uses a different error code scheme from the RoboInject line.

Always confirm the machine model before applying a code.

E101 Low Hydraulic Pressure

Probable causes: hydraulic fluid below level, worn pump seal, relief valve leak.

Corrective action:

1. Check hydraulic fluid level and top up with ISO-VG68.

2. Inspect the pump seal for wear.

3. Bleed the relief valve.

4. Cycle the press empty to confirm pressure holds.

Source: Section 3.1, page 92.

E204 High Press Pressure

Preas exceeded the set limit. Check the pressure relief on the intensifier.

Source: Section 5.2, page 138.