

1. Error Code Reference

This manual covers the RoboInject-300 injection molding machine.

Error codes in this manual are specific to the RoboInject-300.

E101 Winding Overtemperature

Probable causes: blocked cooling fan, dirty air filter, failed NTC sensor.

Corrective action:

1. Power down safely and lock out the machine.

2. Clear debris from the fan intake.

3. Verify 24V DC reaching the fan motor.

4. Retest under load for 20 minutes.

Source: Section 4.2, page 214.

E204 Servo Stall

The injection arm servo exceeded its torque limit.

Check the arm rails for obstruction and the servo current draw.

6.1 Temperature Sensor

The NTC sensor should read 2.4k Ω at 25°C. Replace if out of tolerance.

Source: Section 6.1, page 247.