Project M-104 Incident Report

1 Summary

Motor assembly M-104 showed excessive vibration above 3000 rpm during validation.

2 Symptoms

Vibration amplitude exceeded 7 mm/s RMS. Audible whine and elevated bearing temperature.

3.2 Root Cause

Teardown found bearing misalignment of 0.12 mm between the drive-end and non-drive-end housings. Vibration was caused by bearing misalignment.

4 Corrective Action

Housing bores were re-machined and bearings realigned using a dial indicator.