

Workaround for CCS MSP430 installation error

1. Install CCS again but do NOT select MSP430 device support. Install for some other device family instead (ex: C2000 or C13xx, etc). Once the installation is complete, please download the following zip files:

- https://software-dl.ti.com/ccs/non-esd/misc/msp430pack/ti_msp430pack_support_files_setup_11.1.0.zip
- https://software-dl.ti.com/ccs/non-esd/misc/msp430pack/ti_msp430pack_header_files_setup_11.1.0.zip
- https://software-dl.ti.com/ccs/non-esd/misc/msp430pack/ti_msp430pack_header_files_gcc_setup_11.1.0.zip
- https://software-dl.ti.com/ccs/non-esd/misc/msp430pack/ti_msp430pack_setup64_windows_11.1.0.zip

NOTE: In the below instructions, replace <CCS INSTALL DIR> with the actual root CCS installation directory (ex. C:\ti\ccs1220)

2. Extract the contents of each zip into: <CCS INSTALL DIR>\ccs\

Note that you will get some warning about overwriting the existing **components.xlsx** file. You can choose to just have Windows give a new unique name to the file for each instance.

3. After the zip files have been extracted, browse to:

<CCS INSTALL DIR>\ccs\ccs_base\common\targetdb

and delete the **timestamp** file in the directory

4. Open a DOS command window and run the following three commands from the command line:

```
<CCS INSTALL
DIR>/ccs/ccs_base\emulation\drivers\msp430\DPInst\DPinst64.exe
/q /se /sa /lm /path "<CCS INSTALL
DIR>/ccs/ccs_base\emulation\drivers\msp430\USB_eZ-RF"
```

```
<CCS INSTALL
DIR>/ccs/ccs_base\emulation\drivers\msp430\DPInst\DPinst64.exe
/q /se /sa /lm /path "<CCS INSTALL
DIR>/ccs/ccs_base\emulation\drivers\msp430\USB_FET_Win7_8_10_64"
```

```
<CCS INSTALL
DIR>/ccs/ccs_base\emulation\drivers\msp430\DPInst\DPinst64.exe
/q /se /sa /lm /path "<CCS INSTALL
DIR>/ccs/ccs_base\emulation\drivers\msp430\USB_CDC"
```

5. Download and install **MSPDS-USB-DRIVER** for Windows:
<https://www.ti.com/tool/MSPDS#downloads>
6. Next is to install the MSP430 compiler. Please refer to the below link for more details on how to do this:
 - https://software-dl.ti.com/ccs/esd/documents/ccs_compiler-installation-selection.html

This should be it. You should now have MSP430 support added to your CCS installation.