

Cranes Daily Report

IoT Device Monitoring

● DRAFT TEMPLATE – SAMPLE DATA FOR LAYOUT REVIEW ONLY

MONITORED SITES	TOTAL DEVICES	CURRENT ACTIVE	ATTENTION NEEDED
6	42	33	9

SITES OVERVIEW

SITE	DEVICES	NO DATA HRS	ACTIVE %	CURRENT STATUS	REMARK
BSC East Wing HEALTHY	12	11.6	96.0%	10 Active / 1 Static / 1 Stalled	Repeated weak connection at Level 2. Check signal and consider adding a bridge.
Computime ATTENTION	10	19.9	91.7%	7 Active / 1 Static / 1 Stalled / 1 Inactive	RHT-04 and RTD CH1 require site inspection. Bridge may improve connection.
G Hotel HEALTHY	8	4.3	97.8%	7 Active / 1 Stalled	Monitor DPM CH1. Inspect wiring or network if status repeats.
KPJAP ATTENTION	6	8.5	94.1%	5 Active / 1 Inactive	Inspect UFM 01 power, MQTT configuration and signal coverage.
Sanmina HEALTHY	4	0.0	100%	4 Active	No action required. Continue daily monitoring.
Robert Bosch ATTENTION	2	48.0	0.0%	2 Inactive	Urgent gateway/network inspection. Replace gateway only after power and network checks.

* Click a site name above to jump directly to its detailed device report.

SITE

Computime

Factory · Penang, Malaysia

ATTENTION

Expected device reporting: 24 hours

SYSTEM TYPE

Chiller Optimization System (COpti)

Device Health · Daily Reporting

DEVICE HEALTH

SUMMARY

TOTAL DEVICES

10

CURRENT ACTIVE

7

DEVICE HEALTH

70%

ATTENTION NEEDED

3

DEVICE TYPE BREAKDOWN

RHT

4

2 attention

DPM

2

Healthy

FLOWMETER

1

Healthy

RTD

2

1 attention

GATEWAY

1

Healthy

DEVICE CONDITION AND RECOMMENDATION

DEVICE	TYPE	STATUS	ACTIVE HRS	AFFECTED HRS	ISSUE OCC.	SIGNAL HEALTH	ENGINEER RECOMMENDATION
CT_RHT_01	RHT	ACTIVE	24.0	0.0	0	RSSI -68 / PRR 100%	No action. Continue monitoring.
CT_RHT_02	RHT	STATIC	22.8	1.2	2	RSSI -70 / PRR 100%	Inspect sensor/probe. Replace if static condition repeats after validation.
CT_RHT_03	RHT	ACTIVE	24.0	0.0	0	RSSI -72 / PRR 100%	No action. Continue monitoring.
CT_RHT_04	RHT	INACTIVE	18.7	5.3	3	RSSI -91 / PRR 48%	Add or reposition bridge. Replace device if issue remains after coverage improves.
DPM Main	DPM	ACTIVE	24.0	0.0	0	LAN / Good	No action.
DPM West Wing	DPM	ACTIVE	24.0	0.0	0	LAN / Good	No action.
UFM 01	UFM	ACTIVE	24.0	0.0	0	RSSI -74 / PRR 99%	No action.
RTD CH1	RTD	STALLED	23.4	0.6	4	RSSI -87 / PRR 62%	Check bridge coverage and antenna position. Monitor after adjustment.
RTD CH2	RTD	ACTIVE	24.0	0.0	0	RSSI -71 / PRR 100%	No action.
Gateway 01	GW	ACTIVE	24.0	0.0	0	LAN / Good	No action.

Computime

PIC FOLLOW-UP

ISSUE	REMARK	ASSIGNED PIC	DATE ASSIGN
CT_RHT_04 Inactive	Offline since 18:42 (RSSI -91, PRR 48%). Likely bridge coverage gap after nearby rack relocation; needs on-site signal survey.	Facilities Eng. (Computime)	19 Aug 2026
RTD CH1 Stalled	4 stalled occurrences today; signal weak during peak hours (RSSI -87). Suspect antenna position after nearby equipment change.	IoT Vendor Team	20 Aug 2026
CT_RHT_02 Static	Reading unchanged since ~14:00; probe may be stuck or faulty. Needs physical inspection before replacement decision.	Facilities Eng. (Computime)	21 Aug 2026