

Industrial CNC — Maintenance Manual (Excerpt)

Version 0.9, 2025-09-07

Table of Contents

- 1. Introduction 2
- 2. Safety Requirements 3
 - 2.1. PPE (Personal Protective Equipment) 3
 - 2.2. Lockout/Tagout (LOTO) — Summary 3
- 3. Routine Maintenance Schedule. 4
- 4. Fault Codes 5
 - 4.1. After-Clear Checklist 5
 - 4.2. Escalate to OEM/Service When 5
- 5. Diagrams. 6
- 6. Recordkeeping. 7
 - 6.1. Maintenance Log Template 7
 - 6.2. Usage Rules. 7
 - 6.3. Retention. 7
- 7. References & Standards 8
- Appendix A: Controlled Document Info 9

This excerpt illustrates routine maintenance, safety procedures, and fault code handling for a fictional CNC machining center (Model CNC-5000). Prepared as a portfolio sample.

Chapter 1. Introduction

Intended audience: certified maintenance technicians and supervisors. **Scope:** routine service, selected fault codes, and recordkeeping templates.

Chapter 2. Safety Requirements



Maintenance must be performed only by trained personnel. Lockout/Tagout (LOTO) is **mandatory** before opening guards or working near moving parts. Failure to follow these instructions may result in serious injury.

2.1. PPE (Personal Protective Equipment)

- Safety helmet and ANSI Z87.1/EN 166 eye protection
- Cut-resistant gloves appropriate to task
- Hearing protection (≥ 25 dB SNR)
- Steel-toe safety footwear
- Protective clothing free of loose items (no jewelry, secure long hair)

2.2. Lockout/Tagout (LOTO) — Summary

1. Notify affected operators and stop the machine; press **E-Stop**.
2. Isolate **electrical energy**: set main disconnect to **OFF**; apply personal lock and tag.
3. Isolate **pneumatic/hydraulic energy**: close supply valves; bleed off stored pressure; apply locks/tags.
4. Isolate **mechanical/kinetic energy**: block or brace moving parts as required.
5. **Verify zero energy**:
 - a. Attempt a normal start to confirm isolation (machine must not power).
 - b. Use appropriate test devices: absence-of-voltage indicator; gauges at **0** pressure.
6. Perform maintenance.
7. Remove tools/fixtures, reinstall guards, clear work area.
8. Remove personal locks/tags; restore energy in reverse order; perform a controlled test run.



Follow facility-specific procedures in addition to this summary. Reference: OSHA 1910.147 (Control of Hazardous Energy), ISO 16090-1 (Machine tool safety), and applicable local regulations.

Chapter 3. Routine Maintenance Schedule



Intervals assume two-shift operation in clean, indoor conditions. Increase frequency for abrasive materials (cast iron, composites) or heavy coolant carryout. Record each task in the maintenance log.

Interval	Task	Area	Tools/Materials	Notes
Daily	Clean chips/swarf; empty conveyors & bins	Enclosure, conveyors	Scraper/brush; PPE	Power off; check for jams at discharge points.
Daily	Check coolant level & concentration (6–8%)	Coolant system	Refractometer; premix	Top up with premix; skim tramp oil if present.
Daily	Wipe/inspect way covers & wipers	Axes	Lint-free cloth	Replace if torn, dragging, or leaking.
Weekly	Lubricate spindle bearings	Spindle	Grease gun (NLGI-2)	2–3 pumps per fitting; do not over-pack.
Weekly	Verify auto-lube reservoir; inspect lines	Ways/balls crews	OEM way oil	Fill to mark; inspect for leaks or blocked metering units.
Weekly	Drain air line water separator; check pressure	Pneumatic s	Drain key; gauge	Maintain 6–8 bar; replace filter element if saturated.
Monthly	Replace hydraulic filter; check ΔP gauge	Hydraulics	Wrench set; new element	Depressurize first; log hours since last change.
Monthly	Inspect/tension belts	Spindle/axes	Tension gauge	Replace if frayed/glazed; set to spec.
Quarterly	Verify axis backlash & home repeatability	X/Y/Z	Dial indicator; test macro	Compare to spec; adjust or schedule service.
Quarterly	Test E-Stops, door interlocks, light curtain	Safety systems	Checklist	Document results; correct faults before production.
Annual	Coolant system deep clean	Coolant system	Cleaning additive; PPE	Drain, flush, disinfect, refill with fresh premix.



After any maintenance affecting motion, run a short test program and verify part accuracy on a gauge block or test coupon.

Chapter 4. Fault Codes

Code	Meaning	Corrective Action
E-101	Axis overtravel	Press RESET ; home the machine; check limit switches and soft limits.
E-102	Spindle overheating	Stop; verify coolant/fan operation; allow cooldown; inspect spindle load history.
E-204	Servo drive fault	Note drive LED code; power-cycle control only once; reseat connectors; check encoder cable; consult drive manual.
E-305	Low hydraulic pressure	Stop motion; verify pump runs; check reservoir level and filters; inspect for leaks.
E-410	Door interlock open	Verify doors fully closed; check interlock switch alignment and wiring.
E-512	Coolant flow low	Clean intake screen; check pump and lines for blockage; verify concentration 6–8%.
E-601	Pneumatic pressure low	Check main supply (6–8 bar); drain water separator; inspect regulator and leaks.

4.1. After-Clear Checklist

1. Clear alarms; **home all axes**.
2. Run a short warm-up cycle (spindle + axes); observe temperatures and loads.
3. Verify part accuracy on a test coupon before resuming production.




Do **not** clear and restart repeatedly without investigation. Recurrent or intermittent faults may indicate wiring damage, failing sensors, or drive issues.

4.2. Escalate to OEM/Service When

- Spindle temperature rises rapidly at idle or faults recur after cooldown.
- Servo faults persist after verifying cables, connectors, and supply voltages.
- Hydraulic pressure fluctuates under steady load or ΔP gauge spikes after filter change.

Chapter 5. Diagrams

CNC Exploded View (placeholder)



Callouts

1. Spindle assembly — lubrication points A/B; monitor temperature trend after service.
2. Way covers — inspect for tears/binding; verify smooth travel across full stroke.
3. Hydraulic unit — replace filter per schedule; verify pressure within spec at idle and load.
4. Coolant tank — clean intake screen; check return baffles; maintain 6–8% concentration.



Replace this placeholder with the OEM exploded view when available. Keep diagram revision/date in the controlled footer.

Chapter 6. Recordkeeping

6.1. Maintenance Log Template

Date	Technician	Task	Parts/Materials	Machine Hours	Signature

6.2. Usage Rules

- Complete entries in **permanent ink**; no erasures. Use single strike-through for corrections and add initials/date.
- Record **machine hours** at the start of each task.
- Note torque values, measurements, and test results (e.g., coolant 7.2% Brix, backlash 0.006 mm).
- Attach supporting checklists (E-Stop/door interlock tests) and reference their file IDs in the log.
- After any safety or motion-related maintenance, run a **controlled test program** and record results.

6.3. Retention

Maintain maintenance logs and checklists for **5 years** (or per facility policy). Provide on request to auditors or OEM service.

Chapter 7. References & Standards

- ISO 16090-1 — Machine tool safety
- OSHA 29 CFR 1910.147 — Control of hazardous energy (LOTO)
- IEC 60204-1 — Safety of machinery — Electrical equipment of machines
- ISO 4413 — Hydraulic fluid power — General rules and safety requirements
- ISO 8573-1 — Compressed air — Contaminants and purity classes
- NFPA 70 (NEC) — National Electrical Code

Appendix A: Controlled Document Info

Doc ID: CNC-5000-MNT-EX-01

Revision: 0.9 (Portfolio Sample)