

CNC-5000 Industrial Machining Center — Maintenance Manual

IronClad Machinery GmbH

Version 1.0, 2026-09-26

Table of Contents

- 1. Introduction 2
 - 1.1. Machine Overview 2
- 2. Safety Requirements 3
 - 2.1. PPE (Personal Protective Equipment) 3
 - 2.2. Lockout/Tagout (LOTO) — Summary 3
 - 2.3. Emergency Shutdown Procedures 4
 - 2.3.1. Electrical Emergency 4
 - 2.3.2. Mechanical Emergency (Collision, Jam, Broken Tool) 5
 - 2.3.3. Hydraulic/Coolant Leak 5
 - 2.4. Risk Assessment by Task 5
- 3. Routine Maintenance Schedule 6
 - 3.1. Service Points 8
- 4. Fault Codes 10
 - 4.1. After-Clear Checklist 12
 - 4.2. Escalate to OEM/Service When 12
- 5. Recordkeeping 13
 - 5.1. Maintenance Log Template 13
 - 5.2. Usage Rules 13
 - 5.3. Retention 13
- 6. References & Standards 14
- Appendix A: Controlled Document Info 15

This excerpt illustrates routine maintenance, safety procedures, and fault code handling for a fictional CNC machining center (Model CNC-5000) manufactured by IronClad Machinery GmbH. Prepared as a portfolio sample.

This is a portfolio sample

All company names, addresses, and contact details are fictional. This document is created for demonstration purposes only.

Chapter 1. Introduction

Manufacturer: IronClad Machinery GmbH, 2210 Werkstrasse, Düsseldorf, Germany

Support: support@ironclad-machinery.example · +49-211-555-0199

Intended audience: certified maintenance technicians and supervisors.

Scope: routine service, selected fault codes, and recordkeeping templates.

1.1. Machine Overview




Figure 1. CNC-5000 main components

1. Spindle assembly — lubrication points A/B (see [Service Points](#)); monitor temperature trend after service.
2. Way covers — inspect for tears/binding; verify smooth travel across full stroke.
3. Hydraulic unit — replace filter per schedule; verify pressure within spec at idle and load.
4. Coolant tank and chip conveyor — clean intake screen; check return baffles; maintain 6–8% concentration.
5. Emergency stop (E-Stop) — on the operator panel; see [Emergency Shutdown Procedures](#).

Chapter 2. Safety Requirements



Maintenance must be performed only by trained personnel. Lockout/Tagout (LOTO) is **mandatory** before opening guards or working near moving parts. Failure to follow these instructions may result in serious injury.

2.1. PPE (Personal Protective Equipment)

- Safety helmet and ANSI Z87.1/EN 166 eye protection
- Cut-resistant gloves appropriate to task
- Hearing protection (≥ 25 dB SNR)
- Steel-toe safety footwear
- Protective clothing free of loose items (no jewelry, secure long hair)

2.2. Lockout/Tagout (LOTO) — Summary

1. Notify affected employees that the machine will be shut down and locked out; stop the machine with a normal cycle stop, then press **E-Stop**.
2. Isolate **electrical energy**: set main disconnect to **OFF**; apply personal lock and tag.
3. Isolate **pneumatic/hydraulic energy**: close supply valves; bleed off stored pressure; apply locks/tags.
4. Isolate **mechanical/kinetic energy**: block or brace moving parts (for example, a vertical axis that can drop under gravity) as required.
5. **Discharge stored electrical energy**: wait at least **5 minutes** for the servo-drive DC-bus capacitors to discharge. Verify **< 50 V DC** at the DC-bus test points before touching any drive terminal.
6. **Verify zero energy**:
 - a. With isolation in place, attempt a normal start at the **operator panel** (cycle start, spindle start, axis jog). The machine must not respond.
 - b. Use appropriate test devices: absence-of-voltage tester on the load side of the disconnect; gauges at **0** pressure.
 - c. Return all operator controls to **OFF/neutral**.
7. Perform maintenance.
8. Remove tools/fixtures, reinstall guards, clear work area; confirm all personnel are clear of the machine.
9. Notify affected employees that locks are being removed and the machine is about to be re-energized.
10. Each person removes their own lock and tag; restore energy in reverse order; perform a controlled test run.




Figure 2. Energy isolation points, locked out

1. Main electrical disconnect — rotated to **OFF**.
2. Personal padlock and blank tag — write your name, date, and reason on the tag.
3. Pneumatic supply ball valve — closed, with valve lockout device and padlock.



Stored electrical energy. Servo-drive DC-bus capacitors stay charged at hazardous voltage after the main disconnect is OFF. Contact can cause electric shock, burns, or death. Wait at least 5 minutes, then verify < 50 V DC at the DC-bus test points before touching drive terminals.



Follow facility-specific procedures in addition to this summary. Reference: OSHA 1910.147 (Control of Hazardous Energy), ISO 16090-1 (Machine tool safety), and applicable local regulations.

2.3. Emergency Shutdown Procedures

2.3.1. Electrical Emergency

1. **Press E-Stop immediately** — red mushroom button on control panel and pendant.
2. **Turn main disconnect to OFF** — located at the electrical cabinet — only if it can be reached safely.
3. **Evacuate a 3-meter radius** if sparking, smoke, or unusual odors are present.
4. **From a safe location, call** the maintenance supervisor and the facility emergency response team.
5. **Fight a small fire only if trained and it is safe to do so**, using a CO₂ or dry-chemical extinguisher rated for Class C (electrical) fires. Never use water on electrical equipment.
6. **Do not attempt to restart** until the hazard is eliminated.

2.3.2. Mechanical Emergency (Collision, Jam, Broken Tool)

1. **Press E-Stop** — do not attempt to clear obstruction while powered
2. **Assess for injury** — call medical emergency if personnel involved
3. **Isolate all energy sources** following full LOTO procedure
4. **Document damage** with photos before disturbing evidence
5. **Contact OEM service** for spindle impact assessment if collision occurred

2.3.3. Hydraulic/Coolant Leak



High-pressure fluid injection hazard. A pinhole leak in a pressurized hydraulic line can inject fluid through the skin, causing serious injury, tissue death, or amputation. Never check for leaks with your hand or fingers; use a piece of cardboard or wood. If fluid penetrates the skin, seek medical attention immediately, even if the wound looks minor.

1. **Stop machine immediately** — E-Stop if leak is active/spraying
2. **Contain spill** with absorbent materials and drain pans
3. **Ventilate area** — hydraulic fluid vapors can be hazardous
4. **Check for slip hazards** — barricade wet areas immediately
5. **Report to environmental safety** for disposal of contaminated absorbents

2.4. Risk Assessment by Task

Task	Risk Level	Primary Hazards	Additional Precautions
Spindle bearing lubrication	Medium	Pinch points, rotating parts	Full LOTO; spindle stopped; use clean grease gun and NLGI-2 grease
Way cover inspection	Low	Sharp edges, pinch points	Inspect with machine off; wear cut-resistant gloves
Hydraulic filter change	High	Pressurized fluid, fluid injection, chemical exposure	Full system depressurization; chemical-resistant PPE; never check leaks by hand
Coolant concentration testing	Medium	Chemical exposure, slip hazard	Eye protection; non-slip footwear; ventilation
Backlash measurement	Low	Moving axes during test	Use test mode; maintain clear egress path
Belt tensioning	High	Entanglement, stored energy	Full LOTO; proper belt tension gauge; no loose clothing

Chapter 3. Routine Maintenance Schedule



Intervals assume two-shift operation in clean, indoor conditions. Increase frequency for abrasive materials (cast iron, composites) or heavy coolant carryout. Record each task in the maintenance log.



Coolant concentration is stated in % (volume). A refractometer reads in °Brix; multiply the reading by the coolant's refractometer factor to get concentration: concentration (%) = reading (°Brix) × factor. Example: the fictional IronCool 500 coolant has a factor of 1.0, so a 6–8% target corresponds to a reading of 6–8 °Brix. Use the factor on your coolant's data sheet.

Interval	Task	Area	Tools/Materials	Notes
Daily	Clean chips/swarf; empty conveyors & bins	Enclosure, conveyors	Scraper/brush; PPE	Run chip conveyor and chip flush with doors closed; empty bins from outside the enclosure. Reaching into the enclosure or conveyor requires full LOTO.
Daily	Check coolant level & concentration (6–8%)	Coolant system	Refractometer; premix	Concentration = °Brix × refractometer factor. Top up with premix; skim tramp oil if present.
Daily	Wipe/inspect way covers & wipers	Axes	Lint-free cloth	Replace if torn, dragging, or leaking.
Weekly	Lubricate spindle bearings (grease-lubricated spindle)	Spindle	Grease gun (NLGI-2)	Per OEM lubrication chart: 2–3 pumps per fitting; do not over-pack. Full LOTO.
Weekly	Verify auto-lube reservoir; inspect lines	Ways/balls crews	OEM way oil	Fill to mark; inspect for leaks or blocked metering units.
Weekly	Drain air line water separator; check pressure	Pneumatic s	Drain key; gauge	Maintain 6–8 bar; replace filter element if saturated.

Interval	Task	Area	Tools/Materials	Notes
Monthly	Replace hydraulic filter; check ΔP indicator	Hydraulics	Wrench set; new element	Depressurize first; log ΔP and hours since last change. Replace earlier if the ΔP indicator shows red between scheduled changes.
Monthly	Inspect/tension belts	Spindle/axes	Tension gauge	Replace if frayed/glazed; set to spec.
Quarterly	Verify axis backlash & home repeatability	X/Y/Z	Dial indicator; test macro	Compare to spec; adjust or schedule service.
Quarterly	Test E-Stops, door interlocks, light curtain	Safety systems	Checklist	Document results; correct faults before production.
Semi-Annual	Vibration analysis — spindle & main drives	Spindle, servo motors	Accelerometer; spectrum analyzer	Record baseline at commissioning; $\pm 10\%$ variance requires investigation.
Semi-Annual	Thermal imaging survey	Electrical panels, drives	Thermal camera	Compare with similar components under similar load: $\Delta T > 15\text{ }^{\circ}\text{C}$ = investigate; $\Delta T > 40\text{ }^{\circ}\text{C}$ = immediate repair.
Annual	Spindle runout measurement	Spindle	Dial indicator (0.001 mm res.)	Radial: $< 0.005\text{ mm}$; axial: $< 0.003\text{ mm}$ at tool holder taper.
Annual	Ballscrew backlash verification	X/Y/Z axes	Laser interferometer or dial indicator	$< 0.01\text{ mm}$ at mid-stroke; document drift over time.
Annual	Coolant system deep clean	Coolant system	Cleaning additive; PPE	Drain, flush, disinfect, refill with fresh premix.
18 Months	Way wear measurement	Linear guides	Height gauge; reference surfaces	Max wear: 0.05 mm ; replace if approaching limit.
24 Months	Geometric accuracy check (ISO 10791-2) and circular test (ISO 230-4)	Machine structure	Precision level; straightedge; dial indicators; ballbar	Geometric tests per ISO 10791-2; ballbar circular test per ISO 230-4. Compare with OEM acceptance criteria.



After any maintenance affecting motion, run a short test program and verify part accuracy on a gauge block or test coupon.

3.1. Service Points




Figure 3. Spindle lubrication points (weekly)

- A — upper bearing housing fitting.
- B — front bearing housing fitting.

The CNC-5000 spindle is grease-lubricated. Per the OEM lubrication chart, apply 2–3 pumps of NLGI-2 grease per fitting with the spindle stopped and locked out. Do not over-pack: excess grease raises bearing temperature.




Figure 4. Hydraulic power unit (monthly filter change)

1. Return-line filter housing — replace the element monthly.
2. Differential-pressure (ΔP) indicator — log the reading before and after the filter change.
3. System pressure gauge — verify ≥ 42 bar at idle (see fault E-301).
4. Oil-level sight glass — keep level above the 75% mark.

5. Reservoir drain valve — use for oil sampling and complete drain-down.

Check the ΔP indicator at every monthly visit; if it shows red between scheduled changes, replace the element early.

Chapter 4. Fault Codes

Table 1. Priority scale

Priority	Meaning
Critical	Stop the machine; do not restart; escalate to OEM service immediately.
High	Stop production until the fault is corrected.
Medium	Correct before the next production cycle or shift.
Low	Correct at the next scheduled maintenance.



Fault actions that involve drive terminals or connectors require full LOTO first. Wait at least 5 minutes after isolation and verify < 50 V DC at the DC-bus test points before touching drive terminals.

Code	Meaning	Corrective Action	Priority
E-101	Axis overtravel	Press RESET ; home machine; verify limit switch operation (24 V DC expected); check soft limits in parameters.	Medium
E-102	Spindle overheating	Stop immediately; verify the spindle chiller is running and at set point; clean chiller filter and condenser; check spindle fan; inspect for blocked air passages; allow ≥ 30 min cooldown.	High
E-103	Spindle load excessive	Reduce feed rate by 25%; verify tool sharpness; check workpiece clamping; inspect for chip buildup on cutting tool.	Medium
E-104	Tool changer fault	Verify tool pot alignment; check ATC motor operation; inspect tool retention bolts; cycle ATC manually in test mode.	Medium
E-105	Probe signal lost	Check probe battery (> 6 V); verify cable continuity; clean probe tip contacts; test signal with multimeter (5 V expected).	Low
E-201	X-axis servo fault	Record drive status LEDs; check encoder cable for damage; verify 24 V DC control supply at the drive; after LOTO and DC-bus discharge (< 50 V DC), reseal drive connectors.	High
E-202	Y-axis servo fault	Record drive status LEDs; check encoder cable for damage; verify 24 V DC control supply at the drive; after LOTO and DC-bus discharge (< 50 V DC), reseal drive connectors.	High

Code	Meaning	Corrective Action	Priority
E-203	Z-axis servo fault	Record drive status LEDs; check encoder cable for damage; verify 24 V DC control supply at the drive; after LOTO and DC-bus discharge (< 50 V DC), reseal drive connectors.	High
E-204	Servo following error	Check axis for mechanical binding; verify ballscrew lubrication; inspect coupling for wear; reduce rapid traverse rate 20%.	High
E-205	Encoder communication error	Inspect encoder cable for cuts/pinch; verify encoder supply voltage 5 V DC ± 0.25 V; clean encoder scale if linear type.	High
E-301	Hydraulic pressure low	Verify pump operation; check reservoir level (min 75%); inspect filters for blockage; test pressure at 42 bar minimum.	High
E-302	Hydraulic temperature high	Check oil level; verify cooling fan operation; clean heat exchanger fins; oil temp must be < 60 °C under load.	Medium
E-303	Tool clamp pressure low	Test manual tool release; verify hydraulic pressure ≥ 42 bar; check tool holder for damage; inspect drawbar assembly.	High
E-401	Door interlock failure	Verify all doors fully closed; check interlock switch alignment; test continuity (closed = 0 Ω); inspect door seals.	Medium
E-402	Light curtain interrupted	Clear obstruction from beam path; clean lens surfaces; verify 24 V DC supply; test beam alignment per manual.	Medium
E-403	Emergency stop activated	Identify activated E-Stop button; inspect for mechanical damage; reset all E-Stops; verify control circuit continuity.	High
E-501	Coolant flow insufficient	Clean intake screen; verify pump operation; check flow rate > 15 L/min; inspect nozzles for blockage.	Medium
E-502	Coolant concentration error	Test with refractometer; adjust to 6–8% concentration ($^{\circ}\text{Brix} \times \text{refractometer factor}$); replace if contaminated; check additive mixing system.	Low
E-503	Chip conveyor overload	Clear conveyor jam (full LOTO); inspect for oversized chips; verify conveyor motor current < 8 A; check drive belt tension.	Medium

Code	Meaning	Corrective Action	Priority
E-601	Pneumatic pressure low	Verify supply pressure 6–8 bar; drain water separator; check regulator operation; inspect for air leaks with soap solution.	Medium
E-602	Air filter saturation	Replace filter element; drain moisture; check compressor operation; verify automatic drain valve function.	Low
E-701	Control system fault	Record error details; perform controlled power cycle; check system logs; contact technical support if persistent.	Critical
E-702	Memory backup failure	Replace backup battery immediately; verify parameter retention; reload backup parameters if available.	High

4.1. After-Clear Checklist

1. Clear alarms; **home all axes**.
2. Run a short warm-up cycle (spindle + axes); observe temperatures and loads.
3. Verify part accuracy on a test coupon before resuming production.



Do **not** clear and restart repeatedly without investigation. Recurrent or intermittent faults may indicate wiring damage, failing sensors, or drive issues.

4.2. Escalate to OEM/Service When

- Spindle temperature rises rapidly at idle or faults recur after cooldown.
- Servo faults persist after verifying cables, connectors, and supply voltages.
- Hydraulic pressure fluctuates under steady load or ΔP gauge spikes after filter change.

Chapter 5. Recordkeeping

5.1. Maintenance Log Template

Date	Technician	Task	Parts/Materials	Machine Hours	Signature

5.2. Usage Rules

- Complete entries in **permanent ink**; no erasures. Use single strike-through for corrections and add initials/date.
- Record **machine hours** at the start of each task.
- Note torque values, measurements, and test results (e.g., coolant 7.2% concentration from a 7.2 °Brix reading × factor 1.0; backlash 0.006 mm).
- Attach supporting checklists (E-Stop/door interlock tests) and reference their file IDs in the log.
- After any safety or motion-related maintenance, run a **controlled test program** and record results.

5.3. Retention

Maintain maintenance logs and checklists for **5 years** (or per facility policy). Provide on request to auditors or OEM service.

Chapter 6. References & Standards

- ISO 12100 — Safety of machinery — General principles for design — Risk assessment and risk reduction
- ISO 16090-1 — Machine tool safety
- OSHA 29 CFR 1910.147 — Control of hazardous energy (LOTO)
- IEC 60204-1 — Safety of machinery — Electrical equipment of machines
- NFPA 79 — Electrical Standard for Industrial Machinery
- ISO 4413 — Hydraulic fluid power — General rules and safety requirements
- ISO 8573-1 — Compressed air — Contaminants and purity classes
- ISO 10791-2 — Test conditions for machining centres — Geometric tests
- ISO 230-4 — Test code for machine tools — Circular tests for numerically controlled machine tools

Appendix A: Controlled Document Info

Doc ID: CNC-5000-MNT-EX-01

Revision: 1.0 (Portfolio Sample)

Manufacturer: IronClad Machinery GmbH

Figures: machine overview, LOTO isolation points, spindle lubrication points, hydraulic unit service points