



Informe técnico

CP020 · BBS Mexico · 5 ago 2026

Registro operativo

Proyecto

CP020 · BBS Mexico

Cliente

IMPC Gmbh

Fecha

5 ago 2026

Sistema

Main Assembly Cell PLC

Planta

BBS Saltillo Plant

Área / línea

Assembly Line 2

Estación / máquina

Station 10 - 14 Transfer

Estado

Aprobado

Relacionado con la seguridad

Sí

Registros técnicos

Tipo de sistema

PLC & Safety Controller

Plataforma PLC

**Siemens S7-1500 & Allen
Bradley GuardLogix**

Controlador

CPU 1517F-3 PN/DP

HMI / SCADA

**Siemens WinCC Unified &
FactoryTalk View**

Protocolo de red

**PROFINET / EtherNet/IP
Industrial Gateway**

Versión de software

**TIA Portal v19 / Studio 5000
v35**

Referencia del programa

BBS_MEX_L2_MAIN_REV_3.4

Resumen del cambio

Problema / síntoma

**Intermittent emergency stop
trip on conveyor index transfer**

Diagnóstico / causa raíz

**Dual-channel safety relay pulse
test timing discrepancy
between safety gate and PLC
safety input module**

Cambio realizado

**Adjusted discrepancy time
window in Safety Evaluation
configuration from 50ms to
200ms per manufacturer
recommendation**

Impacto en producción

**Zero unplanned downtime
observed over 4 hours of test
production**

Validación

**Tested 10 consecutive
emergency stop triggers and
re-engaged safety circuit; all
fault codes reset cleanly**

Resultado de validación

**Pass · Fully functional and
within safety SIL3 compliance
standards**

Riesgo abierto

**None identified; hardware and
firmware signatures backed up**

Plan de reversión

**Restore safety project file
BBS_MEX_L2_MAIN_REV_3.3
from local backup PLC SD card**

Cambios técnicos

FECHA	DETALLE	RESUMEN DEL CAMBIO	ESTADO
5 ago 2026	Safety Input Module F-DI 16x24VDC	Updated input filter parameter and discrepancy time window	Aprobado
5 ago 2026	HMI Alarm Banner	Added explicit diagnostic text: Station 12 Gate Discrepancy Fault	Aprobado