



Informe técnico

CP020 · BBS Mexico · 5 ago 2026

Registro operativo

Proyecto CP020 · BBS Mexico	Trabajo realizado por Gabriel Santos
Correo del trabajador gabriel.santos@example.test	Reporte creado por Gabriel Santos
Correo del creador gabriel.santos@example.test	Cliente IMPC Gmbh
Fecha 5 ago 2026	Sistema Main Assembly Cell PLC
Planta BBS Saltillo Plant	Área / línea Assembly Line 2
Estación / máquina Station 10 - 14 Transfer	Estado Aprobado
Relacionado con la seguridad Sí	

Registros técnicos

Tipo de sistema PLC & Safety Controller	Plataforma PLC Siemens S7-1500 & Allen Bradley GuardLogix
---	---

Controlador

CPU 1517F-3 PN/DP

HMI / SCADA

**Siemens WinCC Unified &
FactoryTalk View**

Protocolo de red

**PROFINET / EtherNet/IP
Industrial Gateway**

Versión de software

**TIA Portal v19 / Studio
5000 v35**

Referencia del programa

BBS_MEX_L2_MAIN_REV_3.4

Resumen del cambio

Problema / síntoma

**Intermittent emergency
stop trip on conveyor
index transfer**

Diagnóstico / causa raíz

**Dual-channel safety relay
pulse test timing
discrepancy between
safety gate and PLC
safety input module**

Cambio realizado

**Adjusted discrepancy
time window in Safety
Evaluation configuration
from 50ms to 200ms per
manufacturer
recommendation**

Impacto en producción

**Zero unplanned downtime
observed over 4 hours of
test production**

Validación

**Tested 10 consecutive
emergency stop triggers
and re-engaged safety
circuit; all fault codes
reset cleanly**

Resultado de validación

**Pass · Fully functional and
within safety SIL3
compliance standards**

Riesgo abierto

None identified; hardware and firmware signatures backed up

Plan de reversión

Restore safety project file BBS_MEX_L2_MAIN_REV_3.3 from local backup PLC SD card

Cambios técnicos

FECHA	DETALLE	RESUMEN DEL CAMBIO	ESTADO
5 ago 2026	Safety Input Module F-DI 16x24VDC	Updated input filter parameter and discrepancy time window	Aprobado
5 ago 2026	HMI Alarm Banner	Added explicit diagnostic text: Station 12 Gate Discrepancy Fault	Aprobado