Tenda AC21(V16.03.08.15) has a Stack Buffer Overflow Vulnerability

Product

- 1. product information:
- 2. firmware download:

Affected version

V16.03.08.15

Vulnerability

The stack overfow vulnerability is in /bin/httpd. The vulnerability occurrs in the set_device_name function
which can be accessed through the URL goform/saveParentControlInfo.

```
THUE LAZECATE ZAVELALEUECOUFLOTTULO(TUE 9T)
  2 {
  3
    int result; // $v0
  4 void *ptr; // [sp+18h] [+18h]
  5 char *s; // [sp+1Ch] [+1Ch]
     BYTE *v4; // [sp+20h] [+20h]
    const char *v5; // [sp+24h] [+24h]
    int v6; // [sp+28h] [+28h]
     int v7; // [sp+2Ch] [+2Ch]
    char v8[512]; // [sp+30h] [+30h] BYREF
 10
     char v9[120]; // [sp+230h] [+230h] BYREF
 12
    char v10[128]; // [sp+2A8h] [+2A8h] BYREF
 13
     int v11; // [sp+328h] [+328h] BYREF
 14
15
    memset(v8, 0, sizeof(v8));
     memset(v9, 0, sizeof(v9));
     memset(v10, 0, sizeof(v10));
17
18
     v11 = 0;
19 v5 = (const char *)websGetVar(a1, "deviceId", &unk_4D999C);
20 v4 = (_BYTE *)websGetVar(a1, "deviceName", &unk_4D999C);
21
     if ( *v4 )
       set device name(v4, v5)
22
23
     result = comp
                   Page
    if ( !result
24
```